

21/07/2018

ASS. REC. BY:

REP

CS/FCI/8013835/R19d3

n2

Special Instruction:

Surveyor:

Rensu

ASSIGNMENT (Office)

From (Person):

aws

Lurene juw

of

FCI

Date/Time:

27/7/2018 @ 9:33pm

Estimated Cost:

Bill to:

OD TP/WS/TP RES/OD RES/EVA/INV/MV7CS

To Inspect Vehicle No:

SLV 43962

Insured:

8HC 0734S

at Workshop m/s

cycle & Camigay Kia

Tel:

GS684501/91865202

of

209 Purden Gardens

Policy No:

D18088937MPST

Claim No:

D18005701MPST

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/07/2018

CA / REV / REP. / REV 24 HRS

(DS)

Date/Time:

30/7/18 @ 10:21am

Person Contacted:

Don Bong

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLV 43962 - X

8HC739S - NS/INC18003183/R1vd302

DoA: 14/2/2018

30/7/18 -

called workshop Don say veh still not in yet

31/7/18 -

called Wesp don said vehicle still not in yet

06/8/18 @ 2:47pm

revised to Lurene by email.

14/11/19 @ 4:59pm

confirmed with Jo Jo from fig \$4553, 4 days.
(Red to 1752, 29%)

Ref

REF: FC1

12268

ASSIGNMENT

From: Date: 02082018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLV 4396Z
at Workshop m/s: Cycle & Carriage
of: 209 Pandan Garden

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh: Don

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'DS'

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLV 4396Z Yr Regn: 2017 PL

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA Niro Hybrid 1.6 cc 1580

Colour: BLUE A/C Insured / Std / NI / NA

Sp Reading: 13518 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KWA CC816V35149709

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Disorder / Jammed / Leaked / Burnt or

Brake: Disorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: 21

BS / DUN / EXNOVA / GY / FS / LIZA / MID / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: 24/07/18 D.O.I: 02/08/18

Survey held at: C8C CPH

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 15 JAN 2019

Signature

14/1/2019

Date/Time: File Pass to?

☐ : Preli. Report
☐ : Final Report

Date/Time: File Return to?

2

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp. /\$

☐ Interview /\$

☐ Tech. Insp. /\$

☐ Weekend /\$

Survey Fee

Transportation

☐ S + R /\$

☐ Photos

☐ Other

TOTAL

Report Format: TP

Lump Sum / I.B.P. /\$

4233

145
50
34

229



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18013835/R1qd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 30-07-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 739S	Veh. Inspected	SLV 4396Z
Policy No.		Coverage (\$)	0.00
Claim No.	D18005701MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	30/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	24/07/2018	Inspection Date	02/08/2018
Survey held at	CYCLE & CARRIAGE KIA PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005701MFSH

Date: 06 August 2018

Our Ref: CS/FCI18013835/R1qd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLV 4396Z .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 02/08/2018 at the premises of M/s CYCLE & CARRIAGE . and have the following to report:-

Workshop Estimate Amount	: S\$ <u>4,965.00</u> .
Revised Estimate Amount	: S\$ <u>3,193.00</u> .
"Check" Items Amount	: S\$ <u>470.00</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:
The vehicle sustained damages
at the rear n/s portion.



Yours faithfully

Rasul
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	26-07-2018	Our Ref No. D18005701MFSH
Accident Date	24-07-2018	Claim Type. Third Party
Insured Vehicle	SHC0739S	Third Party Vehicle. SLV4396Z
Survey Location	209 PANDAN GARDENS	
Contact Person.	DON BONG	
Contact No.	65684501/ 0	Fax No. 65651240
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CYCLE & CARRIAGE KIA PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242743)



PRI Documents



Close



PRI Header Details

Claim No	D18005701MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & CYCLE & (
Workshop Name	CYCLE & CARRIAGE KIA PTE LTD (Contact Person : DON BONG)	Survey Location & Contact Details	209 PANDAN GARDENS Mobile: 0 , Phone: 65684501 , Fax: 65651240 EmailId: KIONGHUA.BONG@CYCLECARRIAGE.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC0739S	TP Vehicle No	SLV4396Z
PRI Recieved Date	26-07-2018 06:24:51 PM	Surveyor Appointed Date	27-07-2018 09:32:36 PM	Surveyor Accept Date	30-07-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	30-07-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 14 January 2019 4:59 PM
To: 'Cheng Jo Jo'; Rasul (LKKAUTO); Mei Kwan (LKKAUTO); Admin A; Admin-D (LKKAUTO)
Cc: Andre Chow En De; Songcuan JR Lauro Araos; Loi Ai Ting
Subject: RE: FINALISE - SLV4396Z (KIA) - TP FIRST CAPITAL / DOA: 24/07/2018

Dear Jo Jo,

WITHOUT PREJUDICE

Confirm final fig \$4,253.00 before GST and 4 repair days.

Kindly send the relevant documents to First Capital Insurance.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewse@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Cheng Jo Jo <jojo.cheng@cyclecarriage.com.sg>
Sent: Wednesday, 9 January 2019 10:24 AM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>; Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Cc: Andre Chow En De <andre.chow@cyclecarriage.com.sg>; Songcuan JR Lauro Araos <lauro.songcuan@cyclecarriage.com.sg>; Loi Ai Ting <aiting.loi@cyclecarriage.com.sg>
Subject: FINALISE - SLV4396Z (KIA) - TP FIRST CAPITAL / DOA: 24/07/2018

Hi Rasul,

Attached file for your kind perusal.

Kindly confirm finalise amount at \$ **4,550.71** after GST.

Best Regards,

JoJo Cheng
Customer Service



Exceptional Journeys

Cycle & Carriage Singapore • 209 Pandan Gardens, Singapore 609339
T: +65 6568 4554 • F: +65 6565 1240 • www.cyclecarriage.com.sg

 A member of the Jardine Cycle & Carriage Group

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 6 August 2018 2:47 PM
To: 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005701MFSH/1
Attachments: CSFC118013835R1qd3.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SLV 4396Z.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 30 July 2018 4:51 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005701MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 27 July 2018 9:33 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005701MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System



CERTIFICATE OF INSURANCE

KIA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : NAM SIANLIN NELLIE
 Period of Insurance : 28 Dec 2017 To 27 Dec 2019
 Engine No. : G4LEHS236260
 Chassis No. : KNACC81CVJ5149709

Vehicle No. : SLV4396Z
 Policy No. : 1700091974
 Endorsement No. :
 Issued Date : 07 Jan 2018

ABOUT THE COVER

Make/Model : KIA Niro 1.6

Engine Capacity/Tonnage : 1,580.00 CC

Driver Restriction : NA

Sum Insured : Market Value

Off Peak Car : No

First Year of Registration : 2017

Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

a. The Policyholder

b. Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorized driver only if he/she meets the specified age condition.

c. He/she may an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" (YIDR) if You are or Your Authorized Driver (named or unnamed) is under the age of 21 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Covering for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, competition, racing, or any other use not intended for the purpose of the Motor Vehicle (Third Party Risks and Compensation) Act (Cap. 110) and Section 95 of the Road Transport Act, 1967 (Malaysia).

Loss of Use 1500cc - 1600cc

* Limitations imposed respectively by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Cap. 110) and Section 95 of the Road Transport Act, 1967 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 (Own Damage) - \$800; Theft - \$0; Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$1100

Named Driver and Excess (where applicable)

NAM SIANLIN NELLIE - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

* Cycle & Carriage Body & Paint Centre: Add: 209 Pandan Gardens Singapore 600309 67654501

* Cycle & Carriage Customer Service Centre (For Windscreen claim only): Add: 241 Alexandra Road Singapore 159937 64278939

* Cycle & Carriage Customer Service Centre (For Windscreen claim only): Add: 333 Ubi Rd 3 Singapore 408590 67561000

* For other Approved Reporting Centres and Authorized Repairers, please contact our 24-hour accident emergency hotline at +65 6333 6201. Alternatively, you may call 11 AIG within a 24-hour period.

* AIG 24 Hours App: Simply search and download "AIG 24" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: HL Bank

* We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicle (Third Party Risks and Compensation) Act (Cap. 110) and Section 95 of the Road Transport Act, 1967 (Malaysia) and Motor Vehicle (Third Party Risks) Rules, 1959 (Malaysia).

350-822709

WONGPEI GRACE

23-ALEXANDRA ROAD

SINGAPORE 159939

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Manile

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORIZED REPRESENTATIVE

REPUBLIC OF SINGAPORE DRIVING LICENCE

Expiry Number **S7116226E**

Name
NAM SIANLIN NELLIE

Birth Date: **16 May 1971**
Issue Date: **28 Oct 2003**

000953997D

FOR C&C USE ONLY

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S7116226E**

Name
NAM SIANLIN NELLIE

藍 婫 琳

Race
CHINESE

Date of Birth: **16-05-1971** Sex: **F**

Country of Birth
SINGAPORE

0116134

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors, the weight of which unladen does not exceed 2500 kilograms

PASS DATE
30 Nov 1994

NP 428A

Licence No: **S7116226E**

0116134

APRIC No: **S7116226E**

Blood Group: **O+** Date of Issue: **04-10-1991**

APT BLK 141 BISHAN STREET 12 #07-512
SINGAPORE 570141

NRIC No: **S7116226E** Date: **09/07/2014**

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Ms Nam Sianlin Nellie	Cust No/Name /Ms Nam Sianlin Nellie
Blk 141 Bishan Street 12	Reg No/Reg Date SLV4396Z*1F17/ 28/12/201
#07-512	Date In/Mileage / 0
Singapore 570141	Chassis No KNACC81CVJ5149709
Contact No Mobile: 96840787	Engine No G4LEHS236260
	Make/Model KIA/NIRO 1.6 A G979
	Colour/Trim C3U DEEP CERULEAN B/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	25/07/2018/ 12:29		465 / Tay Jian Ye	32703
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	TO RENEW REAR BUMPER, REPAIR END PANEL, TAILGATE				1100 2200.00
E PNT88000	TO TRANSFER REAR PARKING SENSOR TO NEW PART				60.00
E PNT88000	TO REMOVE AND REFIT REAR BOOT TRIM TO FACILITATE REPAIR				130 150.00
A 54900099	TO REMOVE AND REFIT HIGH TENSION CABLE TO FACILITATE REPAIR				200.00
A 54900099	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				30 50.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST				200.00
M SUNDRY	TO APPLY ANTI CORROSION				40 80.00
M SUNDRY	TO SUPPLY REAR NUMBER PLATE WITH FRAME				74 60.00
M SUNDRY	SUNDRIES			net	20 50.00
M BRACKET ASSY-RR BUMPER SIDE,LH		1.00	25.00	00.00	25.00
M BRACKET ASSY-RR BUMPER SIDE,RH		1.00	25.00	00.00	25.00
M STAY-RR BUMPER LH		1.00	67.00	00.00	67.00
M STAY-RR BUMPER RH		1.00	67.00	00.00	67.00
M BEAM-RR BUMPER		1.00	261.00	00.00	261.00
M COVER-RR BUMPER,UPR		1.00	423.00	00.00	423.00
M REFLECTOR/REFLEX ASSY-RR LH		1.00	104.00	00.00	104.00
M MOULDING ASSY-RR BUMPER SIDE,L		1.00	20.00	00.00	20.00
M COVER-RR BUMPER LWR		1.00	392.00	00.00	392.00
M SKID PLATE-RR BUMPER		1.00	122.00	00.00	122.00
M PIECE-RR BUMPER SIDE,LH		1.00	16.00	00.00	16.00
M COVER-RR BUMPER SIDE UNDER,LH		1.00	27.00	00.00	27.00
M SENSOR ASSY-PARKING ASSIST SYS		1.00	135.00	00.00	135.00
M SENSOR ASSY-PARKING ASSIST SYS		1.00	135.00	00.00	135.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Ms Nam Sianlin Nellie	Cust No/Name /Ms Nam Sianlin Nellie
Blk 141 Bishan Street 12	Reg No/Reg Date SLV4396Z*1F17/ 28/12/201
#07-512	Date In/Mileage / 0
Singapore 570141	Chassis No KNACC81CVJ5149709
Contact No Mobile: 96840787	Engine No G4LEHS236260
	Make/Model KIA/NIRO 1.6 A G979
	Colour/Trim C3U DEEP CERULEAN B/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	25/07/2018/ 12:29		465 / Tay Jian Ye	32703
Description of Goods / Services	Qty	Unit Price	Disc%	Amount	
M EMBLEM-NIRO	1.00	25.00	00.00	25.00	✓
M LOGO-KIA	1.00	42.00	00.00	42.00	✓
M EMBLEM-ECO HYBRID	1.00	29.00	00.00	29.00	✓

Estimate

SURVEYOR NAME: Rome - Hp 90010068SURVEYOR SIGNATURE: RuDATE: 02/08/18 @ 1515REMARKS: 4 days

Resurvey by paint

6/8/18

LKK Auto Consultants hence notify the Repairer of the following:

Confirm & accepted by

- * To resurvey before after spray painting
- * To display damaged part(s) during resurvey
- * Parts prices are subject to confirmation
- * Third party survey is on a "Without Prejudice" basis
- * No illegal modification(s) is allowed
- * Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

7% GST on **Nett** 4,965.00

Total Payable 5,312.55

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

6005



Exceptional Journeys

Surveyor : Rasul
Company : LKK
DOA : 24/07/2018
CSE : Don

VEHICLE NO : SLV4396Z
MODEL : KIA/ NIRO 1.6 A G979
WIP : 32703

Material	:	\$	1,373.00
Labour	:	\$	2,880.00
Sub-Total	:	\$	4,253.00
Less Excess	:	\$	-
Total	:	\$	4,253.00
GST 7%	:	\$	297.71
Grand Total	:	\$	4,550.71
Finalise By/Date	:	<u>JoJo dtd 09/01/2019</u>	

Email :

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 4 WORKING DAYS + 2 Days (1) Weekends
+ 1 Days (1) Public Holiday
TOTAL DAYS REPAIR TOOK = 7

☒ TP Claim FIRST CAPITAL - SHC739S

☐ Claim GIA / LTA fee _____

☒ Claim Loss ☐ Use ☒ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report _____



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MS First Capital Insurance Limited	Cust No/Name /Nam Sianlin Nellie
Motor Claims Department	Reg No/Reg Date SLV4396Z / 28/12/2017
36 Robinson Road #16-01	Date In/Mileage 07/08/2018/ 13771
City House	Chassis/Package KNACC81CVJ5149709 /KC17P
Singapore 068877	Engine No G4LEHS236260
Contact No	Make/Model KIA/NIRO 1.6 A G979
06/08/	Colour/Trim C3U DEEP CERULEAN B/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CTP00080	Cash	09/01/2019/ 10:08	TLD	881 / Jojo Cheng	32703		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							1100.00
RENEW REAR BUMPER, REPAIR END PANEL, REPAIR TAILGATE							60.00
E PNT88000							130.00
TRANSFER REAR PARKING SENSOR TO NEW PART							200.00
E PNT88000							30.00
REMOVE AND REFIT REAR BOOT TRIM TO FACILIATE REPAIR							200.00
A 54900099							30.00
REMOVE AND REFIT HIGH TENSION CABLE TO FACILIATE REPAIR							200.00
A 54900099							40.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							20.00
A 10028901							840.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							200.00
USING HI-SCAN PRO TEST							40.00
M SUNDRY							20.00
APPLY ANTI COROSSION							840.00
M SUNDRY							200.00
SUNDRIES							60.00
E PNT98000							25.00
RESPRAY FRONT BUMPER FACE AND REAR TAILGATE AND AFFECTED PORTION - SUPP							423.00
M SUNDRY							104.00
APPLY ZERTONA COATING ON AFFECTED PORTION - SUPP							20.00
S SPECIALISTJOB							392.00
TO SUPPLY ONE PC OF REAR LICENSE PLATE RECTANGUALR &BLACK							16.00
X BRACKET ASSY-RR BUMPER SIDE,LH				1.00	25.00	00.00	27.00
X COVER-RR BUMPER,UPR				1.00	423.00	00.00	135.00
X REFLECTOR/REFLEX ASSY-RR LH				1.00	104.00	00.00	135.00
X MOULDING ASSY-RR BUMPER SIDE,L				1.00	20.00	00.00	25.00
X COVER-RR BUMPER LWR				1.00	392.00	00.00	16.00
X PIECE-RR BUMPER SIDE,LH				1.00	16.00	00.00	27.00
X COVER-RR BUMPER SIDE UNDER,LH				1.00	27.00	00.00	135.00
X SENSOR ASSY-PARKING ASSIST SYS				1.00	135.00	00.00	135.00
X SENSOR ASSY-PARKING ASSIST SYS				1.00	135.00	00.00	25.00
X EMBLEM-NIRO				1.00	25.00	00.00	

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MS First Capital Insurance Limited	Cust No/Name /Nam Sianlin Nellie
Motor Claims Department	Reg No/Reg Date SLV4396Z / 28/12/2017
36 Robinson Road #16-01	Date In/Mileage 07/08/2018/ 13771
City House	Chassis/Package KNACC81CVJ5149709 /KC17P
Singapore 068877	Engine No G4LEHS236260
Contact No	Make/Model KIA/NIRO 1.6 A G979
06/08/	Colour/Trim C3U DEEP CERULEAN B/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	09/01/2019/ 10:08	TLD	881 / Jojo Cheng	32703

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X LOGO-KIA	1.00	42.00	00.00	42.00
X EMBLEM-ECO HYBRID	1.00	29.00	00.00	29.00
Z TEXT				
FIRST CAPITAL TP CLAIM SHC739S				
DOA:24/07/2018				
SURVEYOR: RASUL LKK 02/08/2018				
Pro Forma				
"Guarantee your warranty, maintain with Cycle & Carriage."				

Parts	1,373.00	Nett	4,253.00
Labour	2,560.00	7% GST on	297.71
Standard Menu	0.00		
Specialist Job	60.00	Total Payable	4,550.71
Diagnostics Job	0.00		
Sundry/Others	260.00		
Total(w/o GST)	4,253.00		

This is not an official tax invoice.
This is a computer generated document, no signature is required.

Car No: SLV 4396Z WIP 32703

ADDITIONAL PARTS CHANGE

S/No	Parts Name	? /Supp	CSA Sign	Photo Taken	Remarks
1	Cover Rear Bumper Lower	? /Supp	DM 8/8		
2	Moulding Assy Rear Bumper Side LH	? /Supp			
3	panache voyager bulgari 12-2000	? /Supp		email to Raul	
4	re-apply zertara	? /Supp		15/8/2018	
5		? /Supp			
6		? /Supp			
7		? /Supp			
8		? /Supp			
9		? /Supp			
10		? /Supp			
11		? /Supp			
12		? /Supp			
13		? /Supp			
14		? /Supp			
15		? /Supp			
16		? /Supp			
17		? /Supp			
18		? /Supp			
19		? /Supp			
20		? /Supp			
DATE 8/8/18 TAKEN BY DM 8/8 Model: Niro 1.6 Surveyor: Rasul - LKK					
PHOTO BEFORE PAINT PHOTO AFTER PAINT PHOTO OF DAMAGED PARTS (DPS) PHOTO OF CELLETE BENCH REMOVE & INSTALL ENGINE REMOVE & INSTALL DASHBOARD PHOTO B4 SUSP & U/C REMOVE email to Raul 15/8/18					



Exceptional Journeys

SUPPLEMENTARY

INSURANCE CO : FIRST CAPITAL INSURANCE LTD

REGISTRATION NO : SLV4396Z

S/N	Description	Qty	Unit Price	Disc%	Amount
LABOUR					
1	RESPARY FRONT BUMPER FACE AND REAR TAILGATE AND AFFECTED PORTION	1.00	840.00	0.00	840.00
2	APPLY ZERTONA COATING ON AFFECTED PORTION	1.00	200.00	0.00	200.00
Total Labour					1,040.00
7 % GST					72.80
Grand Total					<u>1,112.80</u>

Thank You.

Yours faithfully

CYCLE & CARRIAGE KIA PTE LTD

JoJo Cheng

Customer Service

Tel : +65 6568 4554



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18013835/R1qd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 16-01-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 739S	Veh. Inspected	SLV 4396Z	
Policy No.	D18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18005701MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	27/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA NIRO HYBRID 1.6	c.c	1580	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KNACC81CVJ5149709	Colour	BLUE	
Odometer	13518	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	MICHELIN	6 mm	
L/H Front Tyre	205/60 R16	MICHELIN	6 mm	
R/H Rear Tyre	205/60 R16	MICHELIN	6 mm	
L/H Rear Tyre	205/60 R16	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/07/2018	Inspection Date	02/08/2018	
Survey held at	CYCLE & CARRIAGE KIA PTE LTD 209 PANDAN GARDENS SINGAPORE 609339			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 4396Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BRACKET ASSY-RR BUMPER SIDE,LH (SN)	NECESSARY	25.00	25.00
1	BRACKET ASSY-RR BUMPER SIDE,RH (SN)	SERVICEABLE	25.00	-
1	STAY-RR BUMPER LH (SN)	SERVICEABLE	67.00	-
1	STAY-RR BUMPER RH (SN)	SERVICEABLE	67.00	-
1	BEAM-RR BUMPER (SN)	SERVICEABLE	261.00	-
1	COVER-RR BUMPER,UPR (SN)	DEFORMED	423.00	423.00
1	REFLECTOR/REFLEX ASSY-RR LH (SN)	CRACKED	104.00	104.00
1	MOULDING ASSY-RR BUMPER SIDE,L (SN)	SCRATCHED	20.00	20.00
1	COVER-RR BUMPER LWR (SN)	CUT	392.00	392.00
1	SKID PLATE-RR BUMPER (SN)	SERVICEABLE	122.00	-
1	PIECE-RR BUMPER SIDE,LH (SN)	CRACKED	16.00	16.00
1	COVER-RR BUMPER SIDE UNDER,LH (SN)	DEFORMED	27.00	27.00
1	SENSOR ASSY-PARKING ASSIST SYS (SN)	NOT WORKING	135.00	135.00
1	SENSOR ASSY-PARKING ASSIST SYS (SN)	NOT WORKING	135.00	135.00
1	EMBLEM-NIRO (SN)	NECESSARY	25.00	25.00
1	LOGO-KIA (SN)	NECESSARY	42.00	42.00
1	EMBLEM-ECO HYBRID (SN)	NECESSARY	29.00	29.00
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
1	REAR NUMBER PLATE WITH FRAME (SN)	BENT	60.00	60.00
			2,025.00	1,453.00
LABOUR				
TO RENEW REAR BUMPER,REPAIR END PANEL, TAILGATE.			2,200.00	1,100.00
TO TRANSFER REAR PARKING SENSOR TO NEW PART.			60.00	60.00
TO REMOVE AND REFIT REAR BOOT TRIM TO FACILIATE REPAIR.			150.00	130.00
TO REMOVE AND REFIT HIGH TENSION CABLE TO FACILIATE REPAIR.			200.00	200.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM.			50.00	30.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.			200.00	200.00
TO APPLY ANTI COROSSION.			80.00	40.00

Report Ref No. CS/FCI18013835/R1qd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RESPRAY FRONT BUMPER FACE AND REAR TAILGATE AND AFFECTED PORTION. (ADDITIONAL).		840.00	840.00
	APPLY ZERTONA COATING ON AFFECTED PORTION. (ADDITIONAL).		200.00	200.00
			3,980.00	2,800.00
GRAND TOTAL			6,005.00	4,253.00
RECOMMENDED COST OF REPAIRS				4,253.00

Report Ref No. CS/FCI18013835/R1qd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.