

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

30-Jul-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6337 D

1 pc	Front bumper <i>x repair</i>	\$	531.00
1 pc	Front bumper emblem <i>/</i>	\$	44.00
1 pc	Front bumper o/s side retainer <i>x</i>	\$	16.00
1 pc	Front bumper o/s upper bracket <i>x</i>	\$	16.00
1 pc	Front bumper o/s support bracket <i>x</i>	\$	16.00
1 pc	Front o/s fender inner shield <i>x</i>	\$	120.00
1 pc	Front o/s fender <i>/</i>	\$	384.00
1 pc	Front o/s wheel cover <i>/</i>	\$	116.00

\$ 1,243.00

Less 10%

\$ 124.30

\$ 1,118.70

S/NETT

1 pc	Front bumper clips <i>x</i>	\$	48.00
1 set	Front o/s fender inner shield clips <i>x</i>	\$	28.00
1 pc	Front o/s fender sticker <i>x</i>	\$	30.00

Sundry	\$	50.00 20
To check for wiring and to focus head lamps	\$	80.00 x
To check wheel alignment	\$	80.00 x
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 x
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.	\$	400 700.00

To putty and spray painting on front bumper, front o/s fender	\$	500.00 360
To apply rustproofing on the repaired and replaced panels.	\$	80.00 50

\$ 2,894.70

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Kalir 11/11/14
30/7/18 1310h.
3 days
4/5
After Repair photo