

FORM 100

INSURANCE OWNER

Jas

CC

4 Asm

1801

7847

9, ub3

LKK
IDAC

Surveyor:

Tanfiah

DOE

ASSIGNMENT

24/8/2018

Date / Time:

20/7/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No:

SLW 5947K

Name of Insured:

Lim Yow Hui

Insured Tel No:

979 5544

Excess Sec II / SS

W 7/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age

Driver Tel No.:

(V/L: YES / NO)

Claim No:

SEMOPHUM/ 60419

Policy No:

UPH/201798

Make / Model:

TOYOTA

Place of Accident:

WISAPET RD

OI GIA REPORT

YES / NO

TP GIA REPORT

YES / NO

Insured Liability

%

Final ? Yes / No

SLJ 11615



INSRS:
WSP:
Tel:
Liability:
RMKS:

performance



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

21/7/18
TH

SLJ 11615 - X

SLW 5947K - X

* Gmmt/Am

STAGE

DATE / PIC

Non-Reporting Itr (1st)

Non-Reporting Itr (2nd)

Non-Reporting Itr (Final)

Notification Itr of non-pickup

Call OI

After call Itr to OI

28-2-19 J07

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI

Authorization To Act

Release Voucher

Final Repair Bill

Car Rental Invoice

Towing Invoice

ETA / GIA

Medical Bill

PIR

Mandate/Reject Instruction

LRD

Payment Breakdown Form

Post-Repair Photos

Others

28-2-19 @ 12:00 w/ OI CONFIRMED.
AGREED & AWARE

21/8/19 - offer \$19,550.00 (pending acceptance).
2018 - TP counter propose \$19,850.02.
3/9 - settle @ \$19,858.02 by send (pending DV)
DV in file pass Admin to do it.

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: P/P

\$19,624.32

10

days/Reduction

\$18,550.09 @ 51

FINAL SETTLEMENT

Date/Time:

20/8/19 12:30pm

Confirm with:

Caroline

Confirm by:

Final Liability:

%

100

(Agreed / Assessed) BOA 5/9 No: 14

Email

Call

Repair Cost: (W/SS)

\$18,858.02

NO or B 28, Ass. Lia:

Loss of Rental (LOR):

SS

1000

10

days

O1 MOVING OUT

Loss of Use (LOU):

SS

1000

10

days

TP STRAIGHT

Loss of Income (LOI):

SS

1000

10

days

9/9/19

LOR only

LOU only

LOR + LOU

LOR + LOU

(Tick only one)

GIA/TA Search

SS

Claim status: NO/Reject/Private Settle

Medical

SS

Report Format:

TP

Disbursement

SS

(e.g. T1=Independent)

Survey fee:

\$350/-

Legal Cost

SS

Total:

SS

\$18,858.02

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Confirm by:

Payee 1:

SS

\$19,858.02

Name 1:

Performance motors Limited

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

Tanpin

REF:

AKA

U

3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop no: _____

at _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

9/65K.

IDAC Accident Rpt: _____

Consistent? Yes or No

GIA / PR Seen: _____

Consistent? Yes or No

Est. Repairs: _____

10 days

Res: Yes or No

Lum Sum: _____

1-1%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

11 am

Date: _____

Person Contacted: _____

Vehicle IN / OUT

11/1/16

Veh No: SLJ 1161S.

Yr Regr: 2016 July

Type: ☒ Car / ☐ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: BMW 430I

CC 192P

Colour: Grey

A/C Insured / Std / NI / NA

Sp. Reading: 35276

T-Radio: Insured / Std / NI / NA

Engfile: _____

C/Nr: WSA4D920809385724

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/55R19

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____

Rear: _____

R/Bal: 6 mm

R/Bal: 6 mm

L/Bal: 6 mm

L/Bal: 6 mm

D.O.A: _____

D.O.I: 24/8/16 @ 11 am

Survey held at: PML

Des. of Damages: Frt / Rear / O/S ☒ N/S / ☒ U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$ 17,624.32 / - (Red = \$18,155.09 / 51%)

* 12 repair days + 2 sundays + 2 PRS = 14 days.

Date/Time: File Pass to?

☐

Prefl. Report

Days Of Repair:

1)

☐

Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time: File Return to?

Transporter:

2)

Add Fee:

☐

Site Insp: \$

☐

Interview: \$

☐

Tech. Invs: \$

☐

Weekend: \$

1 - 3 - 12

1 - 12

1 - 12

Report Format:

Lump Sum / LB 1-3



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18013843/ub3		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 30-07-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLW 5942K	Veh. Inspected	SLJ 1161S	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	30/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	22/07/2018	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

380, Kampong Arang Road
East Coast Centre
Singapore 438185
Tel. 63190886 (AfterSales)
Fax. 63449772

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190523/530 (Motorrad)
Fax. 64794601 (AfterSales)
64794624 (Motorrad)

Survey only
24.08 11am
owner waiting



GST REG. NO : M2 - 0020081 - X

30 JUL 2018

ESTIMATE

Estimate No. : b1 47861
Date Estimated : 30/07/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Leo Pien Ming
18 Coldstream Avenue

Singapore 459607

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLJ1161S	G385724	05/07/2016	430IA GC	0

DESCRIPTION

To replace front left fender, front left door, rear left door, rear bumper, side sill left, making good of rear left fender and attachments.

4207.50 - 4675 6,800.00

Painting front left fender, front left door, rear left door, rear left fender, rear bumper, side sill left and roof frame.

4740.30 - 5267 5,852.00

To check electrical wiring systems for proper function.

135 - 150 177.00

To replace tyre and wheel rim including balancing. (2x)

144 - 160 188.00

Front and rear left sport rim. (estimate) waiting for quote from supplier.

NN 4,000.00

To replace front left tyre (245/45R19) Yokohama

NN 280 cut 80% 550.00

To transfer lock mechanism from old to new doors including conduct checks on new door power window system for proper functions. (2 doors).

811.80 - 902 1,062.00

To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.

667.80 - 712 873.00

To check steering geometry and conduct wheel alignment according to BMW specification (2x)

811.80 - 902 1,062.00

To remove and install front suspension for inspection and replace damaged parts.

X 2256? 2,655.00

To replace electromechanical power steering including program, initialize steering column adjustment and conduct checks for proper function.

X 752? 885.00

To carry out body cavity preservation.

270 200 236.00

#35779.41

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel: 63190888 (AfterSales)
Fax: 63449771

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190828 (AfterSales)
63190533/510 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 47861
Date Estimated : 30/07/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO. CHASSIS NO. REGN. DATE MODEL MILEAGE
SLJ1161S G385724 05/07/2016 430IA GC 0

DESCRIPTION
(Per panel).

Sundries. *huc*

VALUE

3 ✓ 150.00

Total Labour 1: 24,490.00

DESCRIPTION

HEX NUT M10 CHROME FREE
LH WISHBONE
LH TENSION STRUT W/HYDRAULIC MOUNT
WHEEL HUB WITH BEARING FRT
FRT LH CARRIER
FRT SWING SUPPORT
HEXAGON SCREW WITH FLANGE M10X85
FRT GUIDE SUPPORT
FRT SPRING STRUT
LH TIE ROD
EXCH STEERING BOX ELECTR. (TKP)
HEX NUT WITH FLANGE
HEXAGON NUT WITH COLLAR
RR LH DOOR
FRT LH DOOR
FRT LH FENDER
REAR BUMPER PANEL PRIMED (ZWEIF/LIN)
RR BUMPER LH SIDE GUIDE
RR LH DOOR WEATHERSTRIP
FRT LH DOOR SEALING
AIR DUCT SIDE LH
REAR DOOR JOINT SEAL
LH B PILLAR JOINT SEAL
LH SILL TRIM PRIMED

QTY

PRICE

VALUE

1	1.23	1.23
1	262.20	262.20
1	262.20	262.20
1	465.75	465.75
1	439.10	439.10
1	95.35	95.35
1	6.40	6.40
1	232.00	232.00
1	484.55	484.55
1	282.35	282.35
1	3,583.40	3,583.40
1	2.35	2.35
2	2.35	4.70
1	1,236.60	1,236.60
1	1,236.60	1,236.60
1	682.50	682.50
1	1,133.25	1,133.25
1	48.10	48.10
1	138.00	138.00
1	138.00	138.00
1	44.35	44.35
1	82.80	82.80
1	57.40	57.40
1	314.60	314.60

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date/Time 24/8/18 Excess S\$ _____
Surveyor's Name *Tan Kah* Sign *Tan Kah*
Surveyor's Tel 8748 2249 Authorized Yes / No _____
Authorized Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____
Surveyor's E-mail *tan.kah@performance.com*
No. of Working Days Recommend 10-12 days

Total Parts : 11,233.78

Labour 1 : 24,490.00
Parts : 11,233.78
Labour 2 : 0.00
Excess : 0.00
Total GST @ 7% : 2,500.66
Grand Total : 38,224.44

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **



FINAL REPORT

Estimate No. : b1 47861
Date Estimated : 30/07/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Leo Pien Ming
18 Coldstream Avenue

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 459607

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLJ1161S	G385724	05/07/2016	430IA GC	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front/rear LH doors and attachments, front LH fender and attachments include making good the rear LH fender, rear bumper, LH side skirting, LH roof frame and knocking out dents caused by the accident	4675.00	10.00	4,207.50	
To spray paint front LH fender, front LH door, rear LH door, rear LH fender, rear bumper, LH side skirting and LH roof frame	5267.00	10.00	4,740.30	
To check electrical wiring systems and lightings at the LH section for proper function	150.00	10.00	135.00	
To replace tyre and wheel rim include balancing (2x)	160.00	10.00	144.00	
To supply 8.5x19 N996 MGM S-120 ET35 front LH rim (See owner's receipts)	800.00	0.00	800.00	int ✓
To supply 9.5x19 N996 MGM S-120 ET42 rear LH rim (See owner's receipts)	850.00	0.00	850.00	int ✓
To replace front LH tyre (235/35R19)Yokohama Y0105 (Insurance contributed 80%)	280.00	0.00	280.00	int ✓
To replace rear LH tyre (265/30R19)Yokohama Y0105 (Insurance contributed 80%)	320.00	0.00	320.00	int ✓
To transfer lock mechanism from old to new doors include conducting checks on new doors power window system for proper function (2x)	902.00	10.00	811.80	
To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs	742.00	10.00	667.80	
To check steering geometry and conduct wheel alignment in accordance with BMW specifications (2x)	902.00	10.00	811.80	
* To carry out body cavity preservation (3x) (Per panel)	300.00	10.00	270.00	
Sundries	150.00	0.00	150.00	

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020061-X



FINAL REPORT

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
RR LH DOOR	1,236.60	1.00	3.00	1,199.50
FRT LH DOOR	1,236.60	1.00	3.00	1,199.50
FRT LH FENDER	682.49	1.00	3.00	662.02
RR LH DOOR WEATHERSTRIP	137.80	1.00	3.00	133.67
AIR DUCT SIDE LH	51.49	1.00	3.00	49.95
REAR DOOR JOINT SEAL	82.70	1.00	3.00	80.22
# FRT DOOR JOINT SEAL *	57.35	1.00	3.00	55.63
LH B PILLAR JOINT SEAL	57.35	1.00	3.00	55.63

SUPPLEMENTARY ITEMS

Total Labour :	14,188.20
Total Parts :	3,436.12
Total Labour & Parts :	17,624.32 ✓
Deduction for Excess :	0.00
Total Repair Costs less Excess:	17,624.32
GST @7%:	1,233.70
Grand Total :	18,858.02

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-3020051-X



SUPPLEMENTARY

Estimate No. : b1 47861
Date Estimated : 30/07/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Leo Pien Ming
18 Coldstream Avenue

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 459607

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLJ1161S	G385724	05/07/2016	430IA GC	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# FRT DOOR JOINT SEAL *	57.35	1.00	3.00	55.63 <i>all ✓</i>
-------------------------	-------	------	------	--------------------

Total Labour :	
Total Parts :	55.63
Total Labour & Parts :	55.63

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

260, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190828 (AfterSales)
63190533/530 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)



owner waiting

Appt: repair
24.09.2017

GST REG. NO : M2 - 0020081 - X

ESTIMATE

30 JUL 2018

Estimate No. : b1 47861
Date Estimated : 30/07/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Leo Pien Ming
18 Coldstream Avenue

Singapore 459607

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLJ1161S	G385724	05/07/2016	430IA GC	0

DESCRIPTION

VALUE

To replace front left fender, front left door, rear left door, rear bumper, side sill left, making good of rear left fender and attachments.

4675 6,800.00

Painting front left fender, front left door, rear left door, rear left fender, rear bumper, side sill left and roof frame.

5266 5,852.00

To check electrical wiring systems for proper function.

150 177.00

To replace tyre and wheel rim including balancing. (2x).

160 188.00

Front and rear left sport rim. (estimate) waiting for quote from supplier.

cut ✓ 4,000.00

To replace front left tyre (245/45R19) Yokohama

80% cut ✓ 550.00

To transfer lock mechanism from old to new doors including conduct checks on new door power window system for proper functions. (2 doors).

902 1,062.00

To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.

742 873.00

To check steering geometry and conduct wheel alignment according to BMW specification (2x)

902 1,062.00

To remove and install front suspension for inspection and replace damaged parts.

2256 ? 2,655.00

To replace electromechanical power steering including program, initialize steering column adjustment and conduct checks for proper function.

752 ? 885.00

To carry out body cavity preservation.

200 236.00

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 418180
Tel. 63190888 (AfterSales)
Fax. 63445773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190328 (AfterSales)
63190533/330 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 47861
Date Estimated : 30/07/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLJ1161S	G385724	05/07/2016	430IA GC	0

DESCRIPTION

(Per panel).

VALUE

Sundries.

? 150.00

Total Labour 1: 24,490.00

DESCRIPTION

QTY

PRIC

VALUE

HEX NUT M10 CHROME FREE

1

1.23

? 1.23

LH WISHBONE

1

262.20

? 262.20

LH TENSION STRUT W/HYDRAULIC MOUNT

1

262.20

? 262.20

WHEEL HUB WITH BEARING FRT

1

465.75

? 465.75

FRT LH CARRIER

1

439.10

? 439.10

FRT SWING SUPPORT

1

95.35

? 95.35

HEXAGON SCREW WITH FLANGE M10X85

1

6.40

? 6.40

FRT GUIDE SUPPORT

1

232.00

? 232.00

FRT SPRING STRUT

1

484.55

? 484.55

LH TIE ROD

1

282.35

? 282.35

EXCH STEERING BOX ELECTR. (TKP)

1

3,583.40

? 3,583.40

HEX NUT WITH FLANGE

1

2.35

? 2.35

HEXAGON NUT WITH COLLAR

2

2.35

? 4.70

RR LH DOOR

1

1,236.60

bt 1,236.60

FRT LH DOOR

1

1,236.60

bt 1,236.60

FRT LH FENDER

1

682.50

bt 682.50

REAR BUMPER PANEL PRIMED (ZWEIF/LIN

1

1,133.25

Ry 1,133.25

RR BUMPER LH SIDE GUIDE

1

48.10

? 48.10

RR LH DOOR WEATHERSTRIP

1

138.00

nee 138.00

FRT LH DOOR SEALING

1

138.00

nee 138.00

AIR DUCT SIDE LH

1

44.35

out 44.35

REAR DOOR JOINT SEAL

1

82.80

nee 82.80

LH B PILLAR JOINT SEAL

1

57.40

nee 57.40

LH SILL TRIM PRIMED

1

314.60

Ry 314.60

Total Parts : 11,233.78

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. Claim No.

Date&Time 24/8/18 Excess S\$

Surveyor's Name Tanjil Sign Tanjil

Surveyor's Tel 97445214 Authorised Yes / No

Authorised Date Time

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail tanjil@kwa-tan.com

No. of Working Days Recommend 10-12 days

Labour 1 : 24,490.00

Parts : 11,233.78

Labour 2 : 0.00

Excess : 0.00

Total GST @ 7% : 2,500.66

Grand Total : 38,224.44

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Motor Claims Dept

Certificate No	SD17V03621 /VPC2 /R00
Form	MX1
Date of Issue:	27-JUN-2018
1. Index Mark and Registration No. of Vehicle:	SLJ1161S
2. Chassis number of Vehicle:	WBA4D92080G385724
3. Name of Policyholder:	LEO PIEN MING
4. Effective date of Commencement of Insurance for the purposes of the Act:	10-MAR-2017 00:00 AM
5. Date of Expiry of Insurance:	04-JUL-2019 23:59 PM
6. Persons or Classes of Persons entitled to drive*:	
A) The Policyholder.	
B) Any other person who is driving on the Policyholder's order or with his permission.	
<p>Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.</p> <p>And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.</p>	
7. Limitations as to use*:	
Use only for social, domestic and pleasure purposes and for the Policyholder's business.	
8. The Policy does not cover:	
A) Use for hire or reward.	
B) Use for racing, pace-making, reliability trials or speed-testing.	
C) Use for the carriage of goods (other than samples) in connection with any trade or business.	
D) Use for any purpose in connection with the Motor Trade.	
<p>*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.</p>	
<p>I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).</p>	
<p>For and on behalf of LIBERTY INSURANCE PTE LTD Approved Insurers</p> <p></p> <p>_____ Authorised Signature</p>	
For information only:	
COVERAGE:	Comprehensive, Unlimited Windscreen, NCD Protection
SUM INSURED:	MARKET VALUE AT THE TIME OF LOSS
EXCESS:	Section I: S\$500, Additional Excess For Young & Inexperienced Drivers: S\$2500, Windscreen Excess: S\$0
FINANCE COMPANY:	
PRODUCER NAME:	SD CONTEGO SERVICES

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S75355141



Name

LEO PIEN MING
(LIANG BIANMING)

梁 辨 明

Race

CHINESE

Date of birth

20-11-1975

Sex

M

S75355141

Country of birth

SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number: S75355141

LEO PIEN MING
(LIANG BIANMING)

Birth Date: 20 Nov 1975

Issue Date: 19 May 2006



NRIC No. S75355141



Date of issue

27-11-2006

18 COLDSTREAM AVENUE
SINGAPORE 459607

NRIC No: S75355141

Date: 27/10/2014

3885581

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(E)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of
which unladen does not exceed 2500 kilograms

11 May 1995



NP 428A



redefining / insurance

CLAIM REF :
INSURED :

DISCHARGE VOUCHER

We/I [Leo Pien Ming], NRIC NO. S7535514J hereby agree to accept the sum of dollars [] (S\$) paid to us/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said AXA INSURANCE PTE LTD or their Insured or the driver of motor vehicle no. SLW5942K as a result of an accident along [] on 22.7.2018 of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. SLJ1161S.

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. SLW5942K in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. SLW5942K.

Dated this _____ day of _____ 2017

Claimant's Signature :



NRIC no./ Company Stamp :

Occupation/ Business :

Address :

Telephone No. :

Witness's Name :

Witness's Signature :

Witness's NRIC No. :

PERFORMANCE MOTOR CYCLES
200 Arden Road, #01-01
Singapore 159941
Tel: 6318 0141 (Main)
6318 0151 (Afternoon)

Service Request Details

Claim

S8M00PHM

Reference

None 

Loss Date

July 22, 2018

Request Date

July 30, 2018

Due Date

August 6, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

30/07/2018 @ 12:09pm
Cooline veh not in.

Actions

Next Step

Agree to perform service

Decline WorkAccept Work

Vehicle Information

Incident Vehicle Registration #

SLJ1161S

Make

TPVD BMW

Model

431I GRAN COUPE SR

Service Address

...

Primary Contact/Insured

LIN YONGHUI

BLK 113A MCNAIR ROAD, #28-284, 322113, Singapore

Claim Handler

TAN Jas

6568804844

jas.tan@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 28/02/2019

Survey Details:

Date of loss	22-Jul-18
Date of appointment	30-Jul-18
Date of survey	24-Aug-18
Location of survey	PERFORMANCE MOTORS LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SLJ 11615
Make and Model	B.M.W. 430i GRAN COUPE SR HID NAV HUD
Date of registration	5/7/2016
Excess	
Market Value	\$165,000
Part Rebate	\$83,611
Nett Loss	\$81,389

Repair details:

Initial Estimate	\$ 35,723.78
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 3,436.12
Check items (estimate)	
Labour	\$ 14,188.20
Total	\$ 17,624.32
Lump Sum(if applicable)	\$ -

Number of days for repair	10DAYS
---------------------------	--------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

We have not authorized repairs. INSURED MOVING/REVERSING. TP STRAIGHT.

Mandate:

Liability(TP)		100%
Proposed repair cost	\$	18,858.02
Loss of use	\$	1,600.00
Loss of rental	\$	-
Loss of income	\$	-
LTA search fees	\$	2.00
Others	\$	-
Proposed Total	\$	20,460.02



Re:RE: Re:MANDATE IA

Type

 Question

Message

please offer 10 days for LOU and you may proceed for COR.thanks.

Reply



Jay

AXA Insurance Pte Ltd
8 Shenton Way
#27-01
Singapore 068811
Attention: Motor Claims

"Without Prejudice"

Your Ref :

Our Ref :

Date :

22 February 2019

Subject :

ACCIDENT INVOLVING VEHICLES SLJ1161S & SLW5942K ON 22.07.2018

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:-

Cost of repair	:	S\$	18858.02
Loss of use	:	S\$	1600.00 (S\$100.00 x 16 days)
GIA search fee	:	S\$	2.00
Total	:	S\$	20460.02

A copy of each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair bill & GIA search slip
3. Copy of Certificate of Insurance
4. Copy of Identification Card & Driving License
5. Copy of Letter of Authorisation & Discharge Voucher

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to pml-pbsp@sime-darby.com.sg.

Yours sincerely

Teng Wai Khan

Teng Wai Khan
Customer Service Manager, Body & Paint

Performance Motors
Limited
1800-Call-BMW
(1800-2255-269)

www.pml.com.sg

303 Alexandra Road
Sime Darby
Performance Centre
Singapore 159941
Tel Sales 6319 0100
Tel AfterSales:
6319 0111
Fax 6474 7770

315 Alexandra Road
#01-01
Sime Darby
Business Centre
Singapore 159944
Tel Sales 6319 0511
Tel AfterSales:
6319 0527
Fax 6479 6624

290
Kampong Arang Rd
East Coast Centre
Singapore 438180
Tel AfterSales:
6319 0888
Fax 6344 1332

Registered office:
305 Alexandra Road
#02-01
Vantage
Automotive Centre
Singapore 159942

Co. Reg. No:
197401559W



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

28 FEBRUARY 2019

LIN YONGHUI
113A MCNAIR RD
#28-284
SINGAPORE 322113

Dear Sir/ Mdm

OUR REF : CC4/ASM18013843/T1jb3
YOUR REF : SLW 5942K
ACCIDENT INVOLVING SLW 5942K AND SLJ 1161S ALONG/AT WISHART ROAD ON
22/07/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from **PERFORMANCE MOTORS LIMITED** acting on behalf of the owner of SLJ 1161S against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in our favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to joyirene@ikkauto.com within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Driver's Work Permit
- Employment Letter/ Authorisation letter from your company
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 2409 or email us at joyirene@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely

JOY IRENE
Case Handler
DID: 6841 2409
FAX: 6741 4108
EMAIL: joyirene@lkkauto.com

Cc *AXA Insurance Pte Ltd
(Motor Claims Dept)*

Performance Motors Limited

A member of the Sime Darby Group



LETTER OF AUTHORISATION

ACCIDENT INVOLVING SLJ11615 & SLW5942K ON 22.07.2018


I, Leo Pim Ming owner of Vehicle Registration No. SLJ11615
hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and
settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all
documents whatsoever in relation to this matter and to accept and receive any payment
due to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation
on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if
the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement
amount in respect of such claim shall constitute the full discharge of my claim in respect of
such loss and damage.

Signed by:


Name: LEO PIM MING (LAW BLANKET) (Date) 23/07/2018
NRIC No.: S7535514I

In the presence of:


Name: _____ (Date) _____
NRIC No.: _____

Inthiran A/L. Thirassany
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 150941



redefining / insurance

CLAIM REF : 58M00PTM
INSURED : LIN Yonghui

DISCHARGE VOUCHER

We/I Leo Pien Ming, NRIC NO. S7535514I hereby agree to accept the sum of dollars [NINETEEN THOUSAND EIGHT HUNDRED FIFTY EIGHT DOLLARS AND CENTS TWO ONLY (\$\$ 19,858.02) paid to us/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said AXA INSURANCE PTE LTD or their Insured or the driver of motor vehicle no. SLW5942K as a result of an accident along WISHART ROAD on 22.7.2018 of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. SLJ 1161S].

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. SLW5942K in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. SLW5942K.

Dated this 29 day of AUG 2019

Claimant's Signature

[Signature]
S 7535514 I

NRIC no./ Company Stamp

Occupation/ Business

Address

18 COLDSTREAM AVENUE, SINGAPORE 459607

Telephone No.

97515331

Witness's Name

Witness's Signature

Witness's NRIC No.

[Signature]
PERFORMANCE MOTORCYCLES LIMITED
303 Alexandra Road
Singapore 119941
Tel: 6319 0100 (Sales)
6319 0111 (Aftercare)



103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

290, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel: 63190988 (AfterSales)
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190528 (AfterSales)
63190533/536 (Motorrad)
Fax: 64794601 (AfterSales)
64794624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1301712	Page No. : 1 of 2
Date IN : 25/09/2018	Invoice Number : 2067695 / WSB
Cust. Svc. Advisor: Inthiran A/L Thurasamy	Invoice Date : 20/02/2019
	Payment Terms : 30 Days From Invoice
	Invoice By : Sharon Heng

- CUSTOMER INFORMATION -

Dr Leo Pien Ming
18 Coldstream Avenue

Singapore 459607

- INVOICE TO - 238

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO. SLJ1161S	CHASSIS NO. G385724	REGN. DATE 05/07/2016	MODEL 430IA GC	MILEAGE 37488
-----------------------	------------------------	--------------------------	-------------------	------------------

--- LABOUR I ---	Retail Price	DISC%	NETT
To replace front left fender, both left doors & attachments etc including to make good the rear left fender, rear bumper, left side skirting, left roof frame and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job.	4,675.00	10.00	4,207.50
To respray front left fender, front left door, rear left door, rear left fender, rear bumper, left side skirting and left roof frame etc.	5,267.00	10.00	4,740.30
To check electrical wiring systems and lightings at the left section for proper function.	150.00	10.00	135.00
To replace front left tyre and wheel rim, rear left tyre and wheel rim include balancing.	160.00	10.00	144.00
To supply front left wheel rim (by owner)	800.00	0.00	800.00
To supply rear left wheel rim (by owner)	850.00	0.00	850.00
To supply front left tyre (80%) (by owner)	280.00	0.00	280.00
To supply rear left tyre(80%) (by owner)	320.00	0.00	320.00
To transfer lock mechanism from old to new both left doors including conduct checks on new door power window system for proper functions.	902.00	10.00	811.80
To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.	742.00	10.00	667.80
To check steering geometry and conduct wheel alignment according to BMW specification (2x)	902.00	10.00	811.80
To carry out body cavity preservation.	300.00	10.00	270.00
Sundries.	150.00	0.00	150.00
INS CLAIMS : ACCIDENT REPAIR, DIRECT SETTLEMENT.	0.00	0.00	0.00
DATE OF ACCIDENT : 23.7.2018. 3RD PARTY CAR : SLW5942K.			
YOUR REF NO : NIL.			
VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO CONSULTANTS PTE LTD ON 24.8.2018. AUTHORISED REPAIR BY MS THIN THIN HLAING FROM LKK ON 14.8.2018 VIA E-MAIL.			
PROPOSE LOSS OF USE = \$100X16. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.	0.00	0.00	0.00
GIA SEARCH FEE = \$2.00.	0.00	0.00	0.00

Total Labour 1: 14,188.20

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. W2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159943
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

240, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190886 (AfterSales)
Fax. 63445773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/536 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1301712	Page No. : 2 of 2
Date IN : 25/09/2018	Invoice Number : 2067695 / WSB
Cust. Svc. Advisor: Inthiran A/L Thurasamy	Invoice Date : 20/02/2019
	Payment Terms : 30 Days From Invoice
	Invoice By : Sharon Heng

P A R T S		Qty	Retail Price	DISC%	NETT
FRT LH DOOR		1	1,236.60	3.00	1,199.50
RR LH DOOR		1	1,236.60	3.00	1,199.50
FRT LH FENDER		1	682.50	3.00	662.02
RR LH DOOR WEATHERSTRIP		1	137.80	3.00	133.67
REAR DOOR JOINT SEAL		1	82.70	3.00	80.22
LH B PILLAR JOINT SEAL		1	57.35	3.00	55.63
FRT DOOR JOINT SEAL		1	57.35	3.00	55.63
AIR DUCT SIDE LH		1	51.50	3.00	49.95
Total Parts :					3,436.12
L A B O U R 2			Retail Price	DISC%	NETT
			0.00	0.00	0.00
Total Labour 2:					0.00

Labour Charges :	11,788.20	Total Labour & Parts Charges :	S\$ 17,624.32
Parts Charges :	3,436.12	Less Insurance Excess :	S\$ 0.00
Lubricant/Misc :	2,400.00	Invoice Total Amount Exclude GST :	S\$ 17,624.32
		GST @ 7% :	S\$ 1,233.70
		Invoice Total Amount Include GST :	S\$ 18,858.02

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 18,858.02**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLW 5942K (Insd veh)	Model:	B.M.W. 430i
	SLJ 1161S (TP veh)		
Date of Accident:	22/07/2018		

Global Sum Settlement	: [] Yes	[X] No
Repair Estimate	: \$	40,733.84
Final Repair Cost	: \$	18,858.02
Loss of Use	: \$	1,000.00 10days at \$100.00 per day
Rental (if any)	: \$	days
LTA / GIA Search Fee	: \$	0.00

Others:	: \$	0.00
---------	------	------

	: \$	
Final Settlement Sum	: \$	19,858.02

Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
BOLA Liability: _____ 100 _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____ _____	

Payment Instruction: Payee's Breakdown		
1)	PERFORMANCE MOTORS LIMITED	: \$ 19,858.02

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

17/09/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18013843/T1gb3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 17-09-2019



ATTN: JAS TAN

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLW 5942K	Veh. Inspected	SLJ 1161S
Policy No.	VPA/P2077982	Coverage (\$)	0.00
Claim No.	S8M00PHM	Excess (\$)	0.00
Assign From		Assign Date	30/07/2018

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 430i	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WBA4D92080G385724	Colour	GREY
Odometer	35246	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/35 R19	YOKOHAMA	6 mm
L/H Front Tyre	245/35 R19	YOKOHAMA	6 mm
R/H Rear Tyre	245/35 R19	YOKOHAMA	6 mm
L/H Rear Tyre	245/35 R19	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S PORTION AND UNDERCARRIAGE.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/07/2018	Inspection Date	24/08/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 1161S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT LEFT TYRE (245/45R19) YOKOHAMA (SN) (CONSISTENT)	NOT NECESSARY	550.00	-
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	150.00	150.00
1	HEX NUT M10 CHROME FREE (SN) (CONSISTENT)	NOT NECESSARY	1.23	-
1	LH WISHBONE (SN) (CONSISTENT)	NOT NECESSARY	262.20	-
1	LH TENSION STRUT W/HYDRAULIC MOUNT (SN) (CONSISTENT)	NOT NECESSARY	262.20	-
1	WHEEL HUB WITH BEARING FRT (SN) (CONSISTENT)	NOT NECESSARY	465.75	-
1	FRT LH CARRIER (SN) (CONSISTENT)	NOT NECESSARY	439.10	-
1	FRT SWING SUPPORT (SN) (CONSISTENT)	NOT NECESSARY	95.35	-
1	HEXAGON SCREW WITH CHROME M10X85 (SN) (CONSISTENT)	NOT NECESSARY	6.40	-
1	FRT GUIDE SUPPORT (SN) (CONSISTENT)	NOT NECESSARY	232.00	-
1	FRT SPRING STRUT (SN) (CONSISTENT)	NOT NECESSARY	484.55	-
1	LH TIE ROD (SN) (CONSISTENT)	NOT NECESSARY	282.35	-
1	EXCH STEERING BOX ELECTR (TKP) (SN) (CONSISTENT)	NOT NECESSARY	3,583.40	-
1	HEX NUT WITH FLANGE (SN) (CONSISTENT)	NOT NECESSARY	2.35	-
2	HEXAGON NUT WITH COLLAR (SN) (CONSISTENT)	NOT NECESSARY	4.70	-
1	RR LH DOOR (SN) (CONSISTENT)	BENT	1,236.60	1,199.50
1	FRT LH DOOR (SN) (CONSISTENT)	BENT	1,236.60	1,199.50
1	FRT LH FENDER (SN) (CONSISTENT)	BENT	682.50	662.02
1	REAR BUMPER PANEL PRIMED (ZWEIF/LIN) (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	1,133.25	-
1	RR BUMPER LH SIDE GUIDE (SN) (CONSISTENT)	NOT NECESSARY	48.10	-
1	RR LH DOOR WEATHERSTRIP (SN) (CONSISTENT)	NECESSARY	138.00	133.67
1	FRT LH DOOR SEALING (SN) (CONSISTENT)	NOT NECESSARY	138.00	-
1	AIR DUCT SIDE LH (SN) (CONSISTENT)	CUT	49.95	49.95
1	REAR DOOR JOINT SEAL (SN) (CONSISTENT)	NECESSARY	82.80	80.22
1	LH B PILLAR JOINT SEAL (SN) (CONSISTENT)	NECESSARY	57.40	55.63
1	LH SILL TRIM PRIMED (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	314.60	-
1	FRONT LH RIM (SN) (CONSISTENT) (ADDITIONAL)	CUT	800.00	800.00

Report Ref No. CC4/ASM18013843/T1gb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR LH RIM (SN) (CONSISTENT) (ADDITIONAL)	CUT	850.00	850.00
1	FRONT LH TYRE (SN) (CONSISTENT) (ADDITIONAL)	CUT	280.00	280.00
1	REAR LH TYRE (SN) (CONSISTENT) (ADDITIONAL)	CUT	320.00	320.00
1	FRT DOOR JOINT SEAL (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	55.63	55.63
1	FRONT AND REAR LEFT SPORT RIM (ESTIMATE) WAITING FOR QUOTE FROM SUPPLIER (SN) (CONSISTENT)	NOT NECESSARY	4,000.00	-
			18,245.01	5,836.12
	LABOUR			
	TO REPLACE FRONT LEFT FENDER ,FRONT LEFT DOOR ,REAR LEFT DOOR ,REAR BUMPER ,SIDE SILL LEFT ,MAKING GOOD OF REAR LEFT FENDER AND ATTACHMENTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER PANEL LH SILL TRIM PRIMED .		6,800.00	4,207.50
	PAINTING FRONT LEFT FENDER ,FRONT LEFT DOOR ,REAR LEFT DOOR ,REAR LEFT FENDER ,REAR BUMPER ,SIDE SILL LEFT AND ROOF FRAME.		5,852.00	4,740.30
	TO CHECK ELECTRICAL WIRING SYSTEMS.FOR PROPER FUNCTION.		177.00	135.00
	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING.		188.00	144.00
	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOORS INCLUDING CONDUCT CHECKS ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION (2 DOORS).		1,062.00	811.80
	TO REMOVE AND INSTALL REAR HAT-TRAY ,REAR SEAT ,CARPET AND ROOF TOP LINING TO FACILITATE REPAIRS.		873.00	667.80
	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION .		1,062.00	811.80
	TO REMOVE AND INSTALL FRONT SUSPENSION FOR INSPECTION AND REPLACE DAMAGED PARTS.	NOT NECESSARY	2,655.00	-
	TO REPLACE ELECTROMECHANICAL POWER STEERING INCLUDING PROGRAM ,INITIALIZE STEERING COLUMN ADJUSTMENT AND CONDUCT CHECKS FOR PROPER FUNCTION.	NOT NECESSARY	885.00	-

Report Ref No. CC4/ASM18013843/T1gb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CARRY OUT BODY CAVITY PRESERVATION.(PER PANEL).		270.00	270.00
			19,824.00	11,788.20
GRAND TOTAL			38,069.01	17,624.32
RECOMMENDED COST OF REPAIRS				17,624.32

Report Ref No. CC4/ASM18013843/T1gb3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	S8M00PHM
Reference	CC4/ASM18013843/711gb3a2
Loss Date	22 July 2018
Report Date	23 Jul 2018 2:38:18 PM
Request Date	21 September 2018
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step:

Wait for: Approve Invoice

Add Invoice

Vehicle Information	
Incident Vehicle Registration #	SLJ11615
Make	TPVO BMW
Model	431i GRAN COUPE SR
Service Address	
...	
Primary Contact/Insured	

Primary Contact/Insured	LIN YONGHUI BLK 113A MCNAIR ROAD, #2B-28A, 322113, Singapore
Claim Handler	TAN Jia 6568804944 jia.tan@axa.com.sg

Additional Instructions

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
Document Type	Document SubType					
<div>+ Upload Documents</div>						
NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED		
LKKInvoice1.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	17 September 2019		

NAME PAYMENT BREAKDOWN_LKK.pdf	Forms / Claim Documents	Sub-Type Others	AXA AUTO CONSULTANTS PTE LTD (TP)	DATE 17 September 2019
LODI.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 September 2019
LKKinspection.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 September 2019
LKKAdjustment1a.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 September 2019
DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	17 September 2019
AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	PCA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	17 September 2019
WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	17 September 2019
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	17 September 2019
TP EMAIL REPLY.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	22 July 2019
EMAIL FROM PERFORMANCE.pdf	Letters and Correspondence	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	12 June 2019
SURVEY PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	1 March 2019
SURVEY PHOTOS-LKK.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 February 2019
MANDATE IS - PMAL - SL11515.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 February 2019
Video - Accident.AVI	Evidence	Videos	TAN Jis	28 February 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 Video - Accident-1.AVI	Evidence	Videos	TAN Jia	28 February 2019

 TP ESTIMATE- MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	27 August 2018
---	---------------------	----------------------	--------------------------------------	-------------------

 TP PML-EMAIL REMINDER.msg	Letters and Correspondence	Workshop	RATAN BHOSALE Pragati	8 August 2018
---	-------------------------------	----------	-----------------------	---------------

 TP PML-EMAIL RECEIVED FROM WORKSHOP WITH ESTIMATE.msg	Other	Other	DHIWAR Namrata	30 July 2018
--	-------	-------	----------------	--------------

 SUW5942K INSD GIA REPORT.PDF	Reports & Statement	GIA Report	DHIWAR Namrata	30 July 2018
--	---------------------	------------	----------------	--------------