

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)Survey only
24.08 11am
owner waiting

GST REG. NO : M2 - 0020081 - X

30 JUL 2018

E S T I M A T EEstimate No. : b1 47861
Date Estimated : 30/07/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -Leo Pien Ming
18 Coldstream Avenue

Singapore 459607

- ACCOUNT - 40000Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLJ1161S	G385724	05/07/2016	430IA GC	0

DESCRIPTIONVALUE

To replace front left fender, front left door, rear left door, rear bumper, side sill left, making good of rear left fender and attachments.

4675 8,800.00

Painting front left fender, front left door, rear left door, rear left fender, rear bumper, side sill left and roof frame.

5266 5,852.00

To check electrical wiring systems for proper function.

150 177.00

To replace tyre and wheel rim including balancing. (2x).

160
188.00

Front and rear left sport rim. (estimate) waiting for quote from supplier.

cut ✓ 4,000.00

To replace front left tyre (245/45R19) Yokohama

80%
cut ✓ 550.00

To transfer lock mechanism from old to new doors including conduct checks on new door power window system for proper functions. (2 doors).

902 1,062.00

To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.

772 873.00

To check steering geometry and conduct wheel alignment according to BMW specification (2x)

902 1,062.00

To remove and install front suspension for inspection and replace damaged parts.

2256. ? 2,655.00

To replace electromechanical power steering including program, initialize steering column adjustment and conduct checks for proper function.

752. ? 885.00

To carry out body cavity preservation.

200 236.00

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No.	: b1 47861	Page No. : 2 of 5
Date Estimated	: 30/07/2018	
Prepared By	: Inthiran A/L Thurasamy	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLJ1161S	G385724	05/07/2018	430IA GC	0

DESCRIPTION
(Per panel).

Sundries.

VALUE

? 150.00

Total Labour 1: 24,490.00

DESCRIPTION

HEX NUT M10 CHROME FREE
LH WISHBONE
LH TENSION STRUT W/HYDRAULIC MOUNT
WHEEL HUB WITH BEARING FRT
FRT LH CARRIER
FRT SWING SUPPORT
HEXAGON SCREW WITH FLANGE M10X85
FRT GUIDE SUPPORT
FRT SPRING STRUT
LH TIE ROD
EXCH STEERING BOX ELECTR. (TKP)
HEX NUT WITH FLANGE
HEXAGON NUT WITH COLLAR
RR LH DOOR
FRT LH DOOR
FRT LH FENDER
REAR BUMPER PANEL PRIMED (ZWEIF/LIN)
RR BUMPER LH SIDE GUIDE
RR LH DOOR WEATHERSTRIP
FRT LH DOOR SEALING
AIR DUCT SIDE LH
REAR DOOR JOINT SEAL
LH B PILLAR JOINT SEAL
LH SILL TRIM PRIMED

QTY PRIC

1 1.23
1 262.20
1 262.20
1 465.75
1 439.10
1 95.35
1 6.40
1 232.00
1 484.55
1 282.35
1 3,583.40
1 2.35
2 2.35
1 1,236.60
1 1,236.60
1 682.50
1 1,133.25
1 48.10
1 138.00
1 138.00
1 44.35
1 82.80
1 57.40
1 314.60

VALUE

? 1.23
? 262.20
? 262.20
? 465.75
? 439.10
? 95.35
? 6.40
? 232.00
? 484.55
? 282.35
? 3,583.40
? 2.35
? 4.70
bt 1,236.60
bt 1,236.60
bt 682.50
Ry 1,133.25
? 48.10
nee 138.00
nee 138.00
out 44.35
nee 82.80
nee 57.40
Ry 314.60

Total Parts : 11,233.78

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date & Time 24/8/18	Excess S\$ _____
Surveyor's Name Tanjiah	Sign _____
Surveyor's Tel 2744 5249	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No	
Surveyor's E-mail tanjiah@pml.com	
No. of Working Days Recommend 10-12 days	

Labour 1	:	24,490.00
Parts	:	11,233.78
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	2,500.66
Grand Total	:	38,224.44

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **