PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

26-Jul-18

ESTIMATE REPAIR BILL FOR HYUNDAI 130(A) WAGON REGN NO: SHB 8056 G

1 pc	Rear windscreen moulding 🔀		\$	64.10	
1 pc	Emblem I30		\$	27.80	
1 pc	Emblem CRDI		\$	29.40	
1 pc	Emblem Hyundai 🔀		\$	29.40	
1 pc	Rear bumper		\$	811.11	
1 pc	Rear bumper sponge		\$	79.20	
1 pc	Rear bumper reinforcement '		\$	815.64	
1 pc	Rear bumper reinforcement centre		\$	79.20	
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20		\$	104.40	
2 pcs	pcs Rear bumper n/s & o/s reflector @\$107.50		\$	215.00	
			\$	2,255.25	
		Less 20%	\$	451.05	
			\$	1,804.20	
S/NETT	u do ho	ance notify	7		
1 set	Rear bumper clips LKK Auto Consultants he the Repairer of the follow		\$	48.00	
1 set	Reverse sensor the Repairer of	ay painting	\$	280.00	200
1 set	Tailgate sticker • To display damaged parties	- Frantian	\$	100.00	
1 pc	Tailgate sticker Rear bumper top protector • To display damages paired to c • Parts prices are subject to c • Third party survey is on a "V • Third party survey is on a "V	A Life London	\$	80.00	10
	No illegal modification(3) is	and and	1		- 0
	Sundry Supplementary item(s) musing subject to final approval is subject to final approval.	No illegal modification(s) is another. Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		50.00	20
	To dismantle and replace reverse sensor and test systempairer		\$	80.00	20
	To dismantle and refit the inner component into new tailgate,				
	test wiper motor and water etc		\$	120.00	7
	To labour charge for dismantle and renew the accident				
	damaged parts. Including to knock-out, straighten, repair,			300	>
	reshape of the end panel etc		\$	550.00	
	To putty and spray painting on the root humber tailante lever			360	
	To putty and spray painting on the rear bumper, tailgate lower garnish, end panel		\$	600.00	-
	~				
	To apply rustproofing on the repaired and replaced panels		\$	120.00	_
		Total	\$	3,832.20	
		Kalin 19	IK		
	(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)	100000			
	(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)	1 27/7/	8	0945 hrs	
	THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE 7 Ports				
	ANY UNFORESEEN DAMAGES. Befor Paint place				
		PP	0	11	
		Refor	dist	promo	
		0			