



(06/11/13) wef

ASS. REC. BY:

REF:

LPC

457K

## ASSIGNMENT

From: Date: 30/07/2018

Estimated Cost:

OT / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLG 7610P

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS <sup>1 up</sup>

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLG 7610P Yr Regn: 2016 / 09

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA COROLLA 4x16 1.5 c.c. 1496

Colour: BLUE A/C: Insured / Std / NI / NA

Sp. Reading: 113105 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: NRE 1610021672

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/60R15

R: 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Achilles

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 26/07/18 D.O.I. 30/07/18

Survey held at VERMOGEN

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$14,196.25

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ )

☐ : Preli. Report☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$ )☐ : Interview (\$ )☐ : Tech. Invs (\$ )☐ : Weekend (\$ )

Survey Fee:

Transportation:

\$ + RS, \$

Photos

Others

TOTAL

L157 4,900.00 (Rem \$4,296.25 / 65.48)



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |   |                           |            |   |
|--|---|---------------------------|------------|---|
| LONPAC INSURANCE BHD   |   | Ref : CC4/LPC18013851/fb3 |            |   |
| 300 BEACH ROAD<br>#17-04/07 THE CONCOURSESINGAPORE 199555  |   | Date : 30-07-2018         |            |  |
|  |   | Code : LPC2               |            |   |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |   |                           |            |   |
| Insured Veh.   | GBE 2849E   | Veh. Inspected            | SLG 7610P  |   |
| Policy No.   |   | Coverage (\$)             | 0.00       |   |
| Claim No.  |   | Excess (\$)               | 0.00       |   |
| Assign From  |   | Assign Date               | 30/07/2018 |   |
| <b>2. Vehicle Particulars &amp; Condition</b>  |   |                           |            |   |
| Make & Model   |   | c.c                       | 0          |   |
| Engine No.   | HIDDEN  | Year of Reg.              |            |   |
| Chassis No.  |   | Colour                    |            |   |
| Odometer   | -   | Steering                  |            |   |
| Brakes   |   | Modification              |            |   |
| General  |   |                           |            |   |
| <b>3. Conditions of Tyres</b>  |   |                           |            |   |
|  | Size  | Make                      | Balance    |   |
| R/H Front Tyre   |   |                           | mm         |   |
| L/H Front Tyre   |   |                           | mm         |   |
| R/H Rear Tyre  |   |                           | mm         |   |
| L/H Rear Tyre  |   |                           | mm         |   |
| <b>4. Description of Damages</b>   |   |                           |            |   |
|  |   |                           |            |   |
| <b>5. General Information</b>  |   |                           |            |   |
| Accident Date  | 26/07/2018  | Inspection Date           |            |   |
| Survey held at   | VERMOGEN ACE PTE LTD<br>1 BUKIT BATOK CRESCENT<br>#04-54/55 WCEGA PLAZA<br>SINGAPORE 658064 |                           |            |   |
| <b>5a. Remarks</b>   |   |                           |            |   |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                           |            |   |



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised  
Our ref: CC4/LPC18013851/R1fb3

Date: 02.08.2018

The Motor Claims Department  
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SLG7610P**


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 30.07.2018 at the premises of M/s Vermogen Ace Pte Ltd and have the following to report:-

|                          |       |           |
|--------------------------|-------|-----------|
| Workshop Estimate Amount | : S\$ | 12,996.25 |
| Revised Estimate Amount  | : S\$ | 5,468.50  |
| "Check" Items Amount     | : S\$ | 424.50    |
| Market Value             | : S\$ | -         |
| LTA Reimbursement Value  | : S\$ | -         |
| Nett Value               | : S\$ | -         |

**Description of Damage:**

The vehicle sustained damages at the  
O/S Front portion



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 7 days

Yours faithfully,

MOHD. RASUL  
**Licensed Appraiser**



# SLG7610P

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)  
6 Benoi Sector, Singapore (629904)  
Tel : 6358 3031 | Fax No : 6694 4929

## ACCIDENT REPAIR ESTIMATE

TP INSURER : LONPAC  
OWN INSURER : AIG  
CLAIM TYPE : TP  
Date of Accident : 26-Jul-2018

Vehicle Reg. No. : SLG7610P  
Vehicle Reg. Date: 12-Oct-2016  
Make / Model : T. COROLLA AXIO 1.5X CVT  
Engine No. : 2NR8672947  
Chassis No. : NRE1610021672

## COST OF CLAIMS

Parts Cost / List Items : \$ 12,395.00  
Plus/Less 25% \$ 3,098.75  
Total Cost / List : \$ 9,296.25  
Special Nett Items : \$ -  
Total Parts Amount : \$ 9,296.25  
Total Labour Amount : \$ 3,700.00  
Gross Total : \$ 12,996.25 14196.25  
GST % : 7% \$ 909.74  
Nett Amount : \$ 13,905.99

### Surveyor Name and Company :

RASUL CLKK

Date of survey : 30/07/18 @ 1745

Part by Part / Lump Sum : 7 days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email : \_\_\_\_\_

Fax No : \_\_\_\_\_

HP No : 90010068

This claim is handled by : EZEL

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLG7610P  
 Vehicle Reg. Date: 10/12/2016  
 Make / Model : T. COROLLA AXIO 1.5X CVT ABS D/AIRBAG  
 Engine No. : 2NR8672947  
 Chassis No. : NRE1610021672

PAGE 1

Estimates on Parts

| No | Qty  | PARTICULARS                          | CONDITION | AMOUNT      | S/N    | ADJUSTED AMOUNT |
|----|------|--------------------------------------|-----------|-------------|--------|-----------------|
| 1  | 1    | FRONT BUMPER                         | DE ✓      | \$ 570.00   | 490 ✓  |                 |
| 2  | 1    | FRONT BUMPER SPONGE                  | ? CR4 ✓   | \$ 80.00    | ✓ 48   |                 |
| 3  | 1    | FRONT BUMPER FOGLAMP GARNISH RH      | X SUC     | \$ 75.00    | X      |                 |
| 4  | 2    | FRONT BUMPER SIDE RETAINER           | re ✓      | \$ 85.00    | ✓      |                 |
| 5  | 1    | FRONT BUMPER CLIP SET                | re ✓      | \$ 50.00    | ✓      |                 |
| 6  | 1    | FRONT BUMPER REINFORCEMENT           | X 1/2 re  | \$ 340.00   | X      |                 |
| 7  | 1    | FRONT BUMPER GRILLE                  | X 1/2 re  | \$ 420.00   | X      |                 |
| 8  | 1    | HEADLAMP RH                          | PRO ✓     | \$ 1,800.00 | 1600 ✓ |                 |
| 9  | 1    | HEADLAMP RH LOWER BRACKET            | ? X re    | \$ 85.00    | X      |                 |
| 10 | 1    | HEADLAMP RH GARNISH                  | X SUC     | \$ 180.00   | X      |                 |
| 11 | 1    | HEADLAMP RH PANEL                    | re ✓      | \$ 98.00    | ✓      |                 |
| 12 | 1    | FRONT FENDER RH                      | TORN ✓    | \$ 675.00   | ✓      |                 |
| 13 | 1    | FRONT FENDER INNER SHIELD RH         | DE ✓      | \$ 185.00   | ✓      |                 |
| 14 | 1    | FRONT FENDER INNER SHIELD CLIP - SET | re ✓      | \$ 50.00    | ✓      |                 |
| 15 | 1    | RADIATOR AIRGUIDE RH                 | X         | \$ 187.00   | X      |                 |
| 16 | 1    | FRONT RIM RH                         | X         | \$ 550.00   | X      |                 |
| 17 | 1    | FRONT RIM HUB CAP RH                 | X         | \$ 189.00   | X      |                 |
| 18 | 1    | FRONT SHOCK ABSORBER RH              | ? X       | \$ 432.00   | X      |                 |
| 19 | 1    | FRONT SHOCK ABSORBER TOP MOUNTING RH | X         | \$ 121.00   | X      |                 |
| 20 | 1    | FRONT SHOCK ABSORBER DUST COVER RH   | X         | \$ 47.00    | X      |                 |
| 21 | 1    | FRONT SHOCK ABSORBER BEARING RH      | X re      | \$ 65.00    | X      |                 |
| 22 | 1    | FRONT SHOCK ABSORBER STOPPER         | X         | \$ 38.00    | X      |                 |
| 23 | 1    | FRONT KNUCKLE ARM RH                 | X         | \$ 673.00   | X      |                 |
| 24 | 1    | FRONT WHEEL BEARING RH               | X         | \$ 107.00   | X      |                 |
| 25 | 1    | FRONT WHEEL HUB RH                   | X         | \$ 237.00   | X      |                 |
| 26 | 1    | FRONT LOWER ARM RH                   | X         | \$ 545.00   | X      |                 |
| 27 | 1    | Front door RH                        | re re     | \$ 1,363.00 | X      |                 |
| 28 | 1    | Front door power window mechanism    | X         | \$ 724.00   | X      |                 |
| 29 | 1    | Front door weatherstrip RH           | X         | \$ 195.00   | X      |                 |
| 30 | 1    | Front door top hinge RH              | X re      | \$ 85.00    | X      |                 |
| 31 | 1    | Front door bottom hinge RH           | X         | \$ 85.00    | X      |                 |
| 32 | 1    | Front grille                         | CR4 ✓     | \$ 710.00   | 390 ✓  |                 |
| 33 | 1    | Front grille emblem - logo           | re ✓      | \$ 68.00    | ✓      |                 |
| 34 | 1    | Front grille rubber                  | re ✓      | \$ 105.00   | ✓      |                 |
| 35 | 1set | Front grille clips                   | re ✓      | \$ 50.00    | ✓      |                 |
| 36 | 1    | Bonnet                               | re re     | \$ 720.00   | X      |                 |
| 37 | 1    | Bonnet hinge RH                      | X 1/2 re  | \$ 54.00    | X      |                 |
| 38 | 1    | Washer tank                          | re ✓      | \$ 112.00   | ✓      |                 |
| 39 | 1    | Washer tank neck                     | X re      | \$ 65.00    | X      |                 |
| 40 | 1    | Washer tank motor                    | X re      | \$ 175.00   | X      |                 |

Headlamp LH - CR4 ✓ 1600 ✓

Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible]



Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

FINALIZATION FORM

ATTN TO:

LKK-RASUL

Surveyor Name and Company

Date of Accident : 26/7/2018

BILL TO:

LONPAC

TP Insurer

VEHICLE REG. NO.

TYPE OF CLAIM:

TP

**SLG7610P**

Make / Model :

OLLA AXIO 1.5X CVT ABS D/AIRBA

COST OF CLAIMS

Parts Cost / List : \$ 4,638.00

Supp. Parts : \$ 1,800.00 *1600*

Special Nett : \$ -

Total Parts : \$ 4,828.50

Total Labour : \$ 2,050.00

TOTAL REPAIR COST : \$ 6,878.50

|                         |    |                 |                |
|-------------------------|----|-----------------|----------------|
| Total Parts Cost/List : | \$ | <u>6,438.00</u> | <i>5458</i>    |
| Plus / Less : 25%       | \$ | <u>1,609.50</u> |                |
| Total :                 | \$ | <u>4,828.50</u> | <i>4093.50</i> |

|                         |    |                 |
|-------------------------|----|-----------------|
| Lump Sum Discount : 20% | \$ | <u>1,375.70</u> |
| Lump Sum Amount:        | \$ | <u>5,502.80</u> |

Final Lump Sum Amount : \$ 5,500.00

Submitted by / Date : MINOKO

No. of Repair Days: 7

Confirmed by / Date : \_\_\_\_\_

*4093.50*  
*2050.00*  
*6143.50*  
*20%*  
*4914.80*

*4,900*



Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLG7610P  
 Vehicle Reg. Date: 12/10/2016  
 Make / Model : T. COROLLA AXIO 1.5X CVT ABS D/AIRBAG  
 Engine No. : 2NR8672947  
 Chassis No. : NRE1610021672

PAGE 1

Estimates on Parts

| No | Qty  | PARTICULARS                          | CONDITION | AMOUNT      | S/N | ADJUSTED AMOUNT |
|----|------|--------------------------------------|-----------|-------------|-----|-----------------|
| 1  | 1    | FRONT BUMPER                         |           | \$ 570.00   |     | \$ 570.00       |
| 2  | 1    | FRONT BUMPER SPONGE                  |           | \$ 80.00    |     | \$ 80.00        |
| 3  | 1    | FRONT BUMPER FOGLAMP GARNISH RH      |           | \$ 75.00    |     |                 |
| 4  | 2    | FRONT BUMPER SIDE RETAINER           |           | \$ 85.00    |     | \$ 85.00        |
| 5  | 1    | FRONT BUMPER CLIP SET                |           | \$ 50.00    |     | \$ 50.00        |
| 6  | 1    | FRONT BUMPER REINFORCEMENT           |           | \$ 340.00   |     |                 |
| 7  | 1    | FRONT BUMPER GRILLE                  |           | \$ 420.00   |     |                 |
| 8  | 1    | HEADLAMP RH                          |           | \$ 1,800.00 |     | \$ 1,800.00     |
| 9  | 1    | HEADLAMP RH LOWER BRACKET            |           | \$ 85.00    |     |                 |
| 10 | 1    | HEADLAMP RH GARNISH                  |           | \$ 180.00   |     |                 |
| 11 | 1    | HEADLAMP RH PANEL                    |           | \$ 98.00    |     | \$ 98.00        |
| 12 | 1    | FRONT FENDER RH                      |           | \$ 675.00   |     | \$ 675.00       |
| 13 | 1    | FRONT FENDER INNER SHIELD RH         |           | \$ 185.00   |     | \$ 185.00       |
| 14 | 1    | FRONT FENDER INNER SHIELD CLIP - SET |           | \$ 50.00    |     | \$ 50.00        |
| 15 | 1    | RADIATOR AIRGUIDE RH                 |           | \$ 187.00   |     |                 |
| 16 | 1    | FRONT RIM RH                         |           | \$ 550.00   |     |                 |
| 17 | 1    | FRONT RIM HUB CAP RH                 |           | \$ 189.00   |     |                 |
| 18 | 1    | FRONT SHOCK ABSORBER RH              |           | \$ 432.00   |     |                 |
| 19 | 1    | FRONT SHOCK ABSORBER TOP MOUNTING RH |           | \$ 121.00   |     |                 |
| 20 | 1    | FRONT SHOCK ABSORBER DUST COVER RH   |           | \$ 47.00    |     |                 |
| 21 | 1    | FRONT SHOCK ABSORBER BEARING RH      |           | \$ 65.00    |     |                 |
| 22 | 1    | FRONT SHOCK ABSORBER STOPPER         |           | \$ 38.00    |     |                 |
| 23 | 1    | FRONT KNUCKLE ARM RH                 |           | \$ 673.00   |     |                 |
| 24 | 1    | FRONT WHEEL BEARING RH               |           | \$ 107.00   |     |                 |
| 25 | 1    | FRONT WHEEL HUB RH                   |           | \$ 237.00   |     |                 |
| 26 | 1    | FRONT LOWER ARM RH                   |           | \$ 545.00   |     |                 |
| 27 | 1    | Front door RH                        |           | \$ 1,363.00 |     |                 |
| 28 | 1    | Front door power window mechanism    |           | \$ 724.00   |     |                 |
| 29 | 1    | Front door weatherstrip RH           |           | \$ 195.00   |     |                 |
| 30 | 1    | Front door top hinge RH              |           | \$ 85.00    |     |                 |
| 31 | 1    | Front door bottom hinge RH           |           | \$ 85.00    |     |                 |
| 32 | 1    | Front grille                         |           | \$ 710.00   |     | \$ 710.00       |
| 33 | 1    | Front grille emblem - logo           |           | \$ 68.00    |     | \$ 68.00        |
| 34 | 1    | Front grille rubber                  |           | \$ 105.00   |     | \$ 105.00       |
| 35 | 1set | Front grille clips                   |           | \$ 50.00    |     | \$ 50.00        |
| 36 | 1    | Bonnet                               |           | \$ 720.00   |     |                 |
| 37 | 1    | Bonnet hinge RH                      |           | \$ 54.00    |     |                 |
| 38 | 1    | Washer tank                          |           | \$ 112.00   |     | \$ 112.00       |
| 39 | 1    | Washer tank neck                     |           | \$ 65.00    |     |                 |
| 40 | 1    | Washer tank motor                    |           | \$ 175.00   |     |                 |

Tel : 6358 3031 | Fax No : 6694 4929

NRE1610021672

### Estimates on Labour

[illegible]

## Poh Kin (LKKAUTO)

---

**From:** Shu Pei (LKKAUTO)  
**Sent:** Thursday, 2 August 2018 5:51 PM  
**To:** 'GERALD POH WEE BIN'  
**Cc:** 'MT\_Claim\_SG'; Admin A; Poh Kin (LKKAUTO)  
**Subject:** RE: Accident involving SLG7610P & GBE2849E ( Your Insured ) on 26/07/2018 - PLEASE ARRANGE TP SURVEY  
**Attachments:** TP ESTIMATE- MARKED.PDF; Preliminary\_Advice.pdf  
**Categories:** clear

### WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SLG 7610P at M/s Vermogen Ace Pte Ltd.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice

Our case handler in-charge is Poh Kin and he can be contacted at DID: 6841-2132.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Friday, 27 July 2018 4:03 PM  
**To:** 'GERALD POH WEE BIN' <[geraldpoh@lonpac.com](mailto:geraldpoh@lonpac.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'MT\_Claim\_SG' <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
**Subject:** RE: Accident involving SLG7610P & GBE2849E ( Your Insured ) on 26/07/2018 - PLEASE ARRANGE TP SURVEY

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**Nivitha (LKK Auto)**

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Friday, 27 July 2018 3:45 PM  
**To:** admin-d@lkkauto.com  
**Cc:** MT\_Claim\_SG; pila@vermogen-group.com  
**Subject:** FW: Accident involving SLG7610P & GBE2849E ( Your Insured ) on 26/07/2018 - PLEASE ARRANGE TP SURVEY  
**Attachments:** SLG7610P.PDF

3.58pm @ 27/07/2018  
Vehicle In  
person @ pila  
arrange on 30/07/2018

Our Ref : 17/18/18/VP05/020791

Dear Pila,

Kindly proceed to conduct the survey and revert to them on liability.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** pila@vermogen-group.com [mailto:pila@vermogen-group.com]

**Sent:** Friday, 27 July, 2018 3:25 PM

**To:** MT\_Claim\_SG; ericwoo

**Subject:** Accident involving SLG7610P & GBE2849E ( Your Insured ) on 26/07/2018 - PLEASE ARRANGE TP SURVEY

Dear officer in-charge,

Refer to above attachment kindly arrange our client's vehicle for pre-repair survey at **Vermogen Ace Pte Ltd** here at **6 Benoi Sector**.

**\*VEHICLE IN WORKSHOP\***

Beside, we would like to check for the liability on this matter.

Kindly check & revert to us as soon as possible.

Thanks & regards,

Pila

**Vermogen Ace Pte Ltd**

1 Bukit Batok Crescent

#05-23 Wcega Plaza

Singapore 658064

Tel: 6358 3031

Fax: 6694 4929

## Poh Kin (LKKAuto)

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Friday, 28 December 2018 10:37 AM  
**To:** Poh Kin (LKKAuto)  
**Cc:** MT\_Claim\_SG  
**Subject:** FW: SEEK MANDATE; ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. GBE 2849E(OI) AND SLG 7610P(TP) ON 26-07-2018; LKK ref : CC4/LPC18013851/R1fb3; Lonpac ref: 17/18/18/VP05/020791  
**Attachments:** DV.pdf

Dear Poh Kin

Attached copy of DV for your attention.

Kindly close your file and submit your bill to us.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



---

**From:** GERALD POH WEE BIN  
**Sent:** Thursday, 6 December, 2018 8:52 AM  
**To:** 'Poh Kin (LKKAuto)'  
**Cc:** 'mt\_claim@lonpac.com'  
**Subject:** RE: SEEK MANDATE; ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. GBE 2849E(OI) AND SLG 7610P(TP) ON 26-07-2018; LKK ref : CC4/LPC18013851/R1fb3; Lonpac ref: 17/18/18/VP05/020791

Dear Poh Kin,

Kindly proceed as proposed.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** Poh Kin (LKKAuto) [mailto:pohkin@lkkauto.com]  
**Sent:** Wednesday, 28 November, 2018 7:27 PM  
**To:** GERALD POH WEE BIN  
**Cc:** MT\_Claim\_SG; Admin A  
**Subject:** SEEK MANDATE; ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. GBE 2849E(OI) AND SLG 7610P(TP) ON 26-07-2018; LKK ref : CC4/LPC18013851/R1fb3; Lonpac ref: 17/18/18/VP05/020791  
**Importance:** High

Our Ref: CC4/LPC18013851/R1fb3

## Poh Kin (LKKAuto)

---

**From:** pila@vermogen-group.com  
**Sent:** Thursday, 6 December 2018 11:26 AM  
**To:** Poh Kin (LKKAuto)  
**Subject:** RE: Our Ref: CC4/LPC18013851/fb3; Your Ref: SLG 7610P

**Categories:** clear

Without Prejudice

Dear Poh Kin,

We accepted your below offer with settlement amount **\$5,895.00**.

Kindly send us the Discharge Voucher as soon as possible.

Thanks & regards,  
Pila

---

**From:** Poh Kin (LKKAuto) <pohkin@lkkauto.com>  
**Sent:** Thursday, December 6, 2018 11:22 AM  
**To:** pila@vermogen-group.com; 'Minoko Chan' <minoko@vermogen-group.com>  
**Subject:** RE: Our Ref: CC4/LPC18013851/fb3; Your Ref: SLG 7610P  
**Importance:** High

### WITHOUT PREJUDICE

Our Ref: CC4/LPC18013851/R1fb3  
Your Ref: SLG 7610P

Dear Pila,

### ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE GBE 2849E AND SLG 7610P ON 26/07/2018

We refer to the above matter.

Towards an amicable settlement and without admission of liability to our Insured's part, we have instruction to offer settlement as below:

|                                    |                            |
|------------------------------------|----------------------------|
| 1. Cost of Repair (w/GST)          | S\$ 5,243.00               |
| 2. Loss of Use (\$60.00 x 10 days) | S\$ 600.00                 |
| 3. Towing fee                      | S\$ 50.00                  |
| 4. GIA search fee                  | <u>S\$ 2.00</u>            |
|                                    | <b><u>S\$ 5,895.00</u></b> |

Kindly confirm acceptance.

Your prompt reply will be very much appreciated.

## Poh Kin (LKKAUTO)

---

**From:** Poh Kin (LKKAUTO)  
**Sent:** Thursday, 6 December 2018 11:22 AM  
**To:** 'pila@vermogen-group.com'; 'Minoko Chan'  
**Subject:** RE: Our Ref: CC4/LPC18013851/fb3; Your Ref: SLG 7610P

**Importance:** High

### WITHOUT PREJUDICE

Our Ref: CC4/LPC18013851/R1fb3  
Your Ref: SLG 7610P

Dear Pila,

### ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE GBE 2849E AND SLG 7610P ON 26/07/2018

We refer to the above matter.

Towards an amicable settlement and without admission of liability to our Insured's part, we have instruction to offer settlement as below:

|                                    |                     |
|------------------------------------|---------------------|
| 1. Cost of Repair (w/GST)          | S\$ 5,243.00        |
| 2. Loss of Use (\$60.00 x 10 days) | S\$ 600.00          |
| 3. Towing fee                      | S\$ 50.00           |
| 4. GIA search fee                  | S\$ 2.00            |
|                                    | <b>S\$ 5,895.00</b> |

Kindly confirm acceptance.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Poh Kin, Chong (Mr)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2132 | email: [pohkin@lkkauto.com](mailto:pohkin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*



## Poh Kin (LKKAUTO)

---

**From:** pila@vermogen-group.com  
**Sent:** Thursday, 11 October 2018 10:57 AM  
**To:** Poh Kin (LKKAUTO); 'Minoko Chan'  
**Cc:** Admin A; Rasul (LKKAUTO)  
**Subject:** RE: Our Ref: CC4/LPC18013851/fb3; Your Ref: SLG 7610P  
**Attachments:** doc11454420181011105300.pdf

**Categories:** clear

Without Prejudice

Dear Poh Kin,

Refer to above mentioned matter, we would like to direct settlement with you.

Could we settle our claim as below:

|                |                                   |
|----------------|-----------------------------------|
| Cost of repair | - \$ 5,243.00                     |
| Loss of Usage  | - \$ 1,100.00 ( \$100 X 11 days ) |
| Towing fee     | - \$ 50.00                        |
| GIA            | - \$ 2.00                         |
| Total          | \$ 6,395.00                       |

Kindly check and revert to us as soon as possible.

Thanks & regards,

Pila

**Vermogen Ace Pte Ltd**

1 Bukit Batok Crescent

#05-23 Wcega Plaza

Singapore 658064

Tel: 6904 4596

---

**From:** Poh Kin (LKKAUTO) <pohkin@lkkauto.com>

**Sent:** Thursday, October 11, 2018 10:47 AM

**To:** Pila Ng <pila@vermogen-group.com>; Tezano Exequiel Dawal <ezel.t@vermogen-group.com>; Minoko Chan <minoko@vermogen-group.com>

**Cc:** Admin A <admin-a@lkkauto.com>; Rasul (LKKAUTO) <Rasul@lkkauto.com>

**Subject:** RE: Our Ref: CC4/LPC18013851/fb3; Your Ref: SLG 7610P

**Importance:** High

Without Prejudice

Our Ref: CC4/LPC18013851/R1fb3

Your Ref: SLG 7610P

## Poh Kin (LKKAUTO)

---

**From:** Poh Kin (LKKAUTO)  
**Sent:** Thursday, 11 October 2018 10:47 AM  
**To:** Pila Ng; Tejano Exequiel Dawal; Minoko Chan  
**Cc:** Admin A; Rasul (LKKAUTO)  
**Subject:** RE: Our Ref: CC4/LPC18013851/fb3; Your Ref: SLG 7610P

**Importance:** High

### Without Prejudice

Our Ref: CC4/LPC18013851/R1fb3  
Your Ref: SLG 7610P

Dear Sir/Madam,

### ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE GBE 2849E AND SLG 7610P ON 26/07/2018

We refer to the above matter.

For COR, our surveyor had recommended amount at L/S **\$4,900.00** (before GST) with 7 repair days.

Please note that: All finalisation is subject to our Principal insurer's approval.

\*\*\* Kindly forward your LOD with all the relevant documents(ie: final repair bill, authorisation to act, rental receipt) to us (LKK) for our necessary action.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Poh Kin, Chong (Mr)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2132 | email: [pohkin@lkkauto.com](mailto:pohkin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK  
Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read

## Poh Kin (LKKAUTO)

---

**From:** Poh Kin (LKKAUTO)  
**Sent:** Thursday, 2 August 2018 12:59 PM  
**To:** 'pila@vermogen-group.com'  
**Cc:** Hsiao Tong (LKKAUTO); Admin A  
**Subject:** Our Ref: CC4/LPC18013851/fb3; Your Ref: SLG 7610P

**Importance:** High

### Without Prejudice

Our Ref: CC4/LPC18013851/fb3  
Your Ref: SLG 7610P

Dear Pila,

### ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE GBE 2849E AND SLG 7610P ON 26/07/2018

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Poh Kin, Chong (Mr)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2132 | email: [pohkin@lkkauto.com](mailto:pohkin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK  
Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

## Poh Kin (LKKAUTO)

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Thursday, 6 December 2018 8:52 AM  
**To:** Poh Kin (LKKAUTO)  
**Cc:** MT\_Claim\_SG  
**Subject:** RE: SEEK MANDATE; ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. GBE 2849E(OI) AND SLG 7610P(TP) ON 26-07-2018; LKK ref : CC4/LPC18013851/R1fb3; Lonpac ref: 17/18/18/VP05/020791

Dear Poh Kin,

Kindly proceed as proposed.

Best Regards  
Gerald Poh  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** Poh Kin (LKKAUTO) [mailto:pohkin@lkkauto.com]  
**Sent:** Wednesday, 28 November, 2018 7:27 PM  
**To:** GERALD POH WEE BIN  
**Cc:** MT\_Claim\_SG; Admin A  
**Subject:** SEEK MANDATE; ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. GBE 2849E(OI) AND SLG 7610P(TP) ON 26-07-2018; LKK ref : CC4/LPC18013851/R1fb3; Lonpac ref: 17/18/18/VP05/020791  
**Importance:** High

Our Ref: CC4/LPC18013851/R1fb3  
Your Ref: 17/18/18/VP05/020791

Dear Gerald,

### ROAD TRAFFIC ACCIDENT INVOLVING GBE 2849E (OI) AND SLG 7610P (TP) ALONG SPOONER ROAD OUTDOOR CARPARK ON 26/07/2018

We refer to the above matter.

Liability: The accident occurred when our insured collided into third party parked vehicle while moving off from parking lot. Liability is down against our Insured.

Summary to offer to third party repairer, Vermogen ACE Pte Ltd is as follows: -

|                           | Claimed Amount                   | Revised Amount                |
|---------------------------|----------------------------------|-------------------------------|
| 1. Cost of Repair (w/GST) | \$ 15,189.99 (\$14,196.25 + 7%)  | \$ 5,243.00 (\$4,900.00 + 7%) |
| 2. Loss of Use            | \$ 1,100.00 (\$100.00 x 11 days) | \$ 600.00 (\$60.00 x 10 days) |
| 3. Towing fee             | \$ 50.00                         | \$ 50.00                      |
| 4. GIA search fee         | \$ 2.00                          | \$ 2.00                       |
| <b>Total</b>              | <b>\$16,341.99</b>               | <b>\$ 5,895.00</b>            |

**\*\*07 days recommendation for repair + 2 days PRI + 1 day weekend = 10 days**

## Poh Kin (LKKAUTO)

**From:** Poh Kin (LKKAUTO)  
**Sent:** Wednesday, 28 November 2018 7:27 PM  
**To:** 'GERALD POH WEE BIN'  
**Cc:** 'MT\_Claim\_SG'; Admin A  
**Subject:** SEEK MANDATE; ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. GBE 2849E(OI) AND SLG 7610P(TP) ON 26-07-2018; LKK ref : CC4/LPC18013851/R1fb3; Lonpac ref: 17/18/18/VP05/020791  
**Attachments:** LKK ADJUSTMENT REPORT.pdf; LKK INSPECTION REPORT.pdf; LKK RESURVEY PHOTO-AFTER REPAIR.pdf; LKK SURVEY PHOTO.pdf; TP LOD- SLG 7610P.pdf  
**Importance:** High

Our Ref: CC4/LPC18013851/R1fb3  
Your Ref: 17/18/18/VP05/020791

Dear Gerald,

### ROAD TRAFFIC ACCIDENT INVOLVING GBE 2849E (OI) AND SLG 7610P (TP) ALONG SPOONER ROAD OUTDOOR CARPARK ON 26/07/2018

We refer to the above matter.

Liability: The accident occurred when our insured collided into third party parked vehicle while moving off from parking lot. Liability is down against our Insured.

Summary to offer to third party repairer, Vermogen ACE Pte Ltd is as follows: -

|                           | Claimed Amount                   | Revised Amount                |
|---------------------------|----------------------------------|-------------------------------|
| 1. Cost of Repair (w/GST) | \$ 15,189.99 (\$14,196.25 + 7%)  | \$ 5,243.00 (\$4,900.00 + 7%) |
| 2. Loss of Use            | \$ 1,100.00 (\$100.00 x 11 days) | \$ 600.00 (\$60.00 x 10 days) |
| 3. Towing fee             | \$ 50.00                         | \$ 50.00                      |
| 4. GIA search fee         | \$ 2.00                          | \$ 2.00                       |
| <b>Total</b>              | <b>\$16,341.99</b>               | <b>\$ 5,895.00</b>            |

**\*\*07 days recommendation for repair + 2 days PRI + 1 day weekend = 10 days**

Relevant supporting claim documents are attached herewith for your perusal and reference.

The above is for your approval.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18013851/R1fb3s2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 07-01-2019



Code : LPC2

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                      |                |            |
|--------------|----------------------|----------------|------------|
| Insured Veh. | GBE 2849E            | Veh. Inspected | SLG 7610P  |
| Policy No.   | Z/17/VC00/100748     | Coverage (\$)  | 0.00       |
| Claim No.    | 17/18/18/VP05/020791 | Excess (\$)    | 0.00       |
| Assign From  | GERALD POH           | Assign Date    | 27/07/2018 |

### 2. Vehicle Particulars & Condition

|              |                         |              |            |
|--------------|-------------------------|--------------|------------|
| Make & Model | TOYOTA COROLLA AXIO 1.5 | c.c          | 1496       |
| Engine No.   | HIDDEN                  | Year of Reg. | 2016       |
| Chassis No.  | NRE1610021672           | Colour       | BLUE       |
| Odometer     | 113105                  | Steering     | IN ORDER   |
| Brakes       | IN ORDER                | Modification | SPORTS RIM |
| General      | FAIR                    |              |            |

### 3. Conditions of Tyres

|                | Size      | Make     | Balance |
|----------------|-----------|----------|---------|
| R/H Front Tyre | 195/60R15 | ACHILLES | 6 mm    |
| L/H Front Tyre | 195/60R15 | ACHILLES | 6 mm    |
| R/H Rear Tyre  | 195/60R15 | ACHILLES | 6 mm    |
| L/H Rear Tyre  | 195/60R15 | ACHILLES | 6 mm    |

### 4. Description of Damages

|   |
|---|
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.<br>DAMAGES SEE DETAILS. |
|---|

### 5. General Information

|                |                      |                 |            |
|----------------|----------------------|-----------------|------------|
| Accident Date  | 26/07/2018           | Inspection Date | 30/07/2018 |
| Survey held at | 6 BENOI SECTOR       |                 |            |
| Repairer       | VERMOGEN ACE PTE LTD |                 |            |

### 5a. Remarks

|  |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

### 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 7 Working Days |
|-------------------------------------|----------------|

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 7610P**

| Qty | Description of Parts                 | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--------------------------------------|----------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>   |                      |                           |                   |
| 1   | FRONT BUMPER                         | DEFORMED             | 570.00                    | 400.00            |
| 1   | FRONT BUMPER SPONGE                  | CRACKED              | 80.00                     | 80.00             |
| 1   | FRONT BUMPER FOGLAMP GARNISH RH      | SERVICEABLE          | 75.00                     | -                 |
| 2   | FRONT BUMPER SIDE RETAINER           | NECESSARY            | 85.00                     | 85.00             |
| 1   | SET FRONT BUMPER CLIP                | NECESSARY            | 50.00                     | 50.00             |
| 1   | FRONT BUMPER REINFORCEMENT           | SERVICEABLE          | 340.00                    | -                 |
| 1   | FRONT BUMPER GRILLE                  | SERVICEABLE          | 420.00                    | -                 |
| 1   | HEADLAMP RH                          | BROKEN               | 1,800.00                  | 1,600.00          |
| 1   | HEADLAMP RH LOWER BRACKET            | SERVICEABLE          | 85.00                     | -                 |
| 1   | HEADLAMP RH GARNISH                  | SERVICEABLE          | 180.00                    | -                 |
| 1   | HEADLAMP RH PANEL                    | BENT                 | 98.00                     | 98.00             |
| 1   | FRONT FENDER RH                      | TORN                 | 675.00                    | 675.00            |
| 1   | FRONT FENDER INNER SHIELD RH         | DEFORMED             | 185.00                    | 185.00            |
| 1   | SET FRONT FENDER INNER SHIELD CLIP   | NECESSARY            | 50.00                     | 50.00             |
| 1   | RADIATOR AIRGUIDE RH                 | NOT NECESSARY        | 187.00                    | -                 |
| 1   | FRONT RIM RH                         | NOT NECESSARY        | 550.00                    | -                 |
| 1   | FRONT RIM HUB CAP RH                 | NOT NECESSARY        | 189.00                    | -                 |
| 1   | FRONT SHOCK ABSORBER RH              | NOT NECESSARY        | 432.00                    | -                 |
| 1   | FRONT SHOCK ABSORBER TOP MOUNTING RH | NOT NECESSARY        | 121.00                    | -                 |
| 1   | FRONT SHOCK ABSORBER DUST COVER RH   | NOT NECESSARY        | 47.00                     | -                 |
| 1   | FRONT SHOCK ABSORBER BEARING RH      | NOT NECESSARY        | 65.00                     | -                 |
| 1   | FRONT SHOCK ABSORBER STOPPER         | NOT NECESSARY        | 38.00                     | -                 |
| 1   | FRONT KNUCKLE ARM RH                 | NOT NECESSARY        | 673.00                    | -                 |
| 1   | FRONT WHEEL BEARING RH               | NOT NECESSARY        | 107.00                    | -                 |
| 1   | FRONT WHEEL HUB RH                   | NOT NECESSARY        | 237.00                    | -                 |
| 1   | FRONT LOWER ARM RH                   | NOT NECESSARY        | 545.00                    | -                 |
| 1   | FRONT DOOR RH                        | TO REPAIR SEE LABOUR | 1,363.00                  | -                 |
| 1   | FRONT DOOR POWER WINDOW MECHANISM    | NOT NECESSARY        | 724.00                    | -                 |
| 1   | FRONT DOOR WEATHERSTRIP RH           | NOT NECESSARY        | 195.00                    | -                 |
| 1   | FRONT DOOR TOP HINGE RH              | NOT NECESSARY        | 85.00                     | -                 |

Report Ref No. CC4/LPC18013851/R1fb3s2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts   | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|----------------------|---------------------------|-------------------|
| 1   | FRONT GRILLE   | CRACKED              | 710.00                    | 300.00            |
| 1   | FRONT GRILLE EMBLEM - LOGO   | NECESSARY            | 68.00                     | 68.00             |
| 1   | FRONT GRILLE RUBBER  | NECESSARY            | 105.00                    | 105.00            |
| 1   | SET FRONT GRILLE CLIPS   | NECESSARY            | 50.00                     | 50.00             |
| 1   | BONNET   | TO REPAIR SEE LABOUR | 720.00                    | -                 |
| 1   | BONNET HINGE RH  | SERVICEABLE          | 54.00                     | -                 |
| 1   | WASHER TANK  | DEFORMED             | 112.00                    | 112.00            |
| 1   | WASHER TANK NECK   | NOT NECESSARY        | 65.00                     | -                 |
| 1   | WASHER TANK MOTOR  | NOT NECESSARY        | 175.00                    | -                 |
| 1   | FRONT DOOR BOTTOM HINGE RH   | NOT NECESSARY        | 85.00                     | -                 |
| 1   | HEADLAMP LH (ADDITIONAL)   | CRACKED              | 1,600.00                  | 1,600.00          |
|     | LESS 25% DISCOUNT  |                      | -3,498.75                 | -1,364.50         |
|     |  |                      | 10,496.25                 | 4,093.50          |
|     | <b>LABOUR</b>  |                      |                           |                   |
|     | TO KNOCK JACK OUT DAMAGED PARTS, PANEL BEATING WELDING, ALIGN, REFIX & TO REPLACE ACCIDENT PARTS, FRONT PORTION RH. INCLUSIVE OF THE REPAIR OF FRONT DOOR RH AND BONNET. |                      | 1,500.00                  | 700.00            |
|     | TO PUTTY, RESPRAY PAINTING AND POLISH AFFECTED AREAS. FRONT PORTION RH.  |                      | 1,500.00                  | 1,100.00          |
|     | TO CHECK AND RECTIFY WIRING AFTER DISCONNECT AND RECONNECT.  |                      | 100.00                    | 30.00             |
|     | TO DO WHEEL ALIGNMENT.   |                      | 150.00                    | 60.00             |
|     | TO RUST PROOF AFFECTED AREAS.  |                      | 150.00                    | 60.00             |
|     | TO REMOVE & REFIT UNDERCARRIAGE TO ASSIST WORK LOAD.   |                      | 300.00                    | 100.00            |
|     |  |                      | 3,700.00                  | 2,050.00          |
|     | <b>GRAND TOTAL</b>   |                      | <b>14,196.25</b>          | <b>6,143.50</b>   |
|     | <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDTION)</b>   |                      |                           | <b>4,900.00</b>   |

Report Ref No. CC4/LPC18013851/R1fb3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.