



SLG7610P

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : LONPAC
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 26-Jul-2018

Vehicle Reg. No. : SLG7610P
Vehicle Reg. Date: 12-Oct-2016
Make / Model : T. COROLLA AXIO 1.5X C
Engine No. : 2NR8672947
Chassis No. : NRE1610021672

COST OF CLAIMS

Parts Cost / List Items : \$ 12,395.00
Plus/Less 25% \$ 3,098.75
Total Cost / List : \$ 9,296.25
Special Nett Items : \$ -
Total Parts Amount : \$ 9,296.25
Total Labour Amount : \$ 3,700.00
Gross Total : \$ 12,996.25
GST % : 7% \$ 909.74
Nett Amount : \$ 13,905.99

Surveyor Name and Company :

RASUL (LKK)

Date of survey : 30/07/18 @ 1745

Part by Part / Lump Sum : 7 days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email : _____

Fax No : _____

HP No : 90010068

This claim is handled by : EZEL

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLG7610P
 Vehicle Reg. Date: 10/12/2016
 Make / Model : T. COROLLA AXIO 1.5X CVT ABS D/AIRBAG
 Engine No. : 2NR8672947
 Chassis No. : NRE1610021672

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	FRONT BUMPER	DE ✓	\$ 570.00		
2	1	FRONT BUMPER SPONGE	?	\$ 80.00		
3	1	FRONT BUMPER FOGLAMP GARNISH RH	X	\$ 75.00		
4	2	FRONT BUMPER SIDE RETAINER	re -	\$ 85.00		
5	1	FRONT BUMPER CLIP SET	re -	\$ 50.00		
6	1	FRONT BUMPER REINFORCEMENT	X	\$ 340.00		
7	1	FRONT BUMPER GRILLE	X	\$ 420.00		
8	1	HEADLAMP RH	Pro ✓	\$ 1,800.00		
9	1	HEADLAMP RH LOWER BRACKET	? X	\$ 85.00		
10	1	HEADLAMP RH GARNISH	X	\$ 180.00		
11	1	HEADLAMP RH PANEL	re -	\$ 98.00		
12	1	FRONT FENDER RH	Torn -	\$ 675.00		
13	1	FRONT FENDER INNER SHIELD RH	DE ✓	\$ 185.00		
14	1	FRONT FENDER INNER SHIELD CLIP - SET	re -	\$ 50.00		
15	1	RADIATOR AIRGUIDE RH	X	\$ 187.00		
16	1	FRONT RIM RH	X	\$ 550.00		
17	1	FRONT RIM HUB CAP RH	X	\$ 189.00		
18	1	FRONT SHOCK ABSORBER RH	?	\$ 432.00		
19	1	FRONT SHOCK ABSORBER TOP MOUNTING RH	X	\$ 121.00		
20	1	FRONT SHOCK ABSORBER DUST COVER RH	X	\$ 47.00		
21	1	FRONT SHOCK ABSORBER BEARING RH	X	\$ 65.00		
22	1	FRONT SHOCK ABSORBER STOPPER	X	\$ 38.00		
23	1	FRONT KNUCKLE ARM RH	X	\$ 673.00		
24	1	FRONT WHEEL BEARING RH	X	\$ 107.00		
25	1	FRONT WHEEL HUB RH	X	\$ 237.00		
26	1	FRONT LOWER ARM RH	X	\$ 545.00		
27	1	Front door RH	repair ✓	\$ 1,363.00		
28	1	Front door power window mechanism	X	\$ 724.00		
29	1	Front door weatherstrip RH	X	\$ 195.00		
30	1	Front door top hinge RH	X	\$ 85.00		
31	1	Front door bottom hinge RH	X	\$ 85.00		
32	1	Front grille	CRA ✓	\$ 710.00		
33	1	Front grille emblem - logo	re -	\$ 68.00		
34	1	Front grille rubber	re -	\$ 105.00		
35	1set	Front grille clips	re -	\$ 50.00		
36	1	Bonnet	repair ✓	\$ 720.00		
37	1	Bonnet hinge RH	re -	\$ 54.00		
38	1	Washer tank	re -	\$ 112.00		
39	1	Washer tank neck	X	\$ 65.00		
40	1	Washer tank motor	X	\$ 175.00		

Headlamp LH - OK ✓

Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible]