

Surveyor

REF: CSI / LAW17017147 / R116-1

Special Instruction:

HS: \$11750.00

ASSIGNMENT (Office)

From (Person): Linda Anua of Linda Anua Law Date/Time: 02092017

Estimated Cost: Bill to:

Third Parties:

Claimant:

Surveyor: Automax & Formiteum

Workshop: Eng Soon Painting

OD/IP Re-inspection / Evaluation

To Inspect Vehicle No: SBU 8219A Insured: SGS 2457U

at Workshop m/s: Eng Soon Painting Tel: 6760 6271

of: Bk & Yew Tee Ind Est 393-J

Policy No: MC/MC6717/2017 Claim No: MT/0408760-002/RD/CK

Sum Insured: Excess:

Make of Veh: D.O.A. 20072016

(Client's Record)

SJE

H.O.D. Endorsement/Date

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red \$ / %; Original 14 days)

Date/Time: 1/11/17 Submit Final Fig LS 6650, 6 days (Red \$ 5100 / 43 %; Original days)

Date/Time	Action/Instruction
	SBU 8219A - x
	SGS 2457U - x
5/2/18	To re-open & amend report Amend to LS \$3750
07/02/18	1st closed date = 06/11/2017, reopen by Kim beoz has to amend LS from \$6650 to \$3750
8/2/18	check with Rasul LS \$3800

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

3/17/18 To re-submit LS \$4150 (Red 7600, 64%), 6 days

Para(3) : Nett Value

No Charge.

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

350

- | | | | |
|----------------------------|--------------|--------------|----------------|
| 1) Date/Time 1/11 - typist | File Pass to | 2) Date/Time | File Return to |
| 3) Date/Time | File Pass to | 4) Date/Time | File Return to |
| 5) Date/Time | File Pass to | 6) Date/Time | File Return to |

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/07/2016 20:21
Date Of Accident	20/07/2016 07:05
Exact Location Of Accident	CLEMENTI AVE 6 TO AYE (INFRONT OF BUS STOP B20019
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBU8219A
Insured/Policyholder	
Name Of Registered Owner	MOHAMAD SAIFUL BIN MOHAMAD HALID
NRIC No	S8703978A
Email Address	saiful.halid@gmail.com
Mobile Phone No	(LOCAL) +65-83288395
Alternative Phone No	Office-83288395

Vehicle Particulars

Manufacturer	MAZDA
Model	RX-8-1.3
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Private Car
Insurance Company	
Name of Insurance Company	Lompac Insurance Bhd
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	Z16VP05009478
Cover Note Number	

Driver

Name of Driver	MOHAMAD SAIFUL BIN MOHAMAD HALID
NRIC No	S8703978A
Date Of Birth	20/02/1987
Occupation	Outdoor
Date Of Driving Pass	05/08/2009
Driving Experience	6 Years And 11 Months
Gender	Male
Mobile Number	(Local) +65-83288395
Fax Number	
Contact Number	Office-83288395
Email Address	saiful.halid@gmail.com

Address	BLK 467C CHOA CHU KANG AVE 5 # 04- 117
Postcode	683487
Was driver an employee of the Insured's Company	No
If No, Relationship of the Driver with the Insured	Owner
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	Collision- Head to Rear (TP Hit Insured)
Weather Conditions	Raining
Road Surface	Wet

Other Information

Was any foreign vehicle involved in this accident?	No
Was any body injured in the Accident?	No
Was any other material or property damaged?	Yes
Was there any video captured by Car Camera?	No
Number of Passengers (including Driver)	2

Details of Police Action

Was the accident reported to the police?	No
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	No
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN. REPAIR AT SENG HONG KEE CO

Are accident photos available for attachment?	Yes
---	-----

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGS2457U
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	RABIATULADAWIYAH
NRIC/Passport Number	S9139923G
Contact Number	93883314
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (including Driver)	
Details of Witness	
Name	
Phone Number	
Email Address	

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Please note that you might be able to submit an Own Damage Claim under own policy within 14 days.

() Claim Own Damage

Claim TP
21/7/16
12:05hrs

() Reporting Only

Claim OD/TP at other workshop

SENK HOAG KEE CO

Sketch Plan #2 Pg.1

Describe Circumstances of the Accident


While entering the AVE towards City from Clementi AVE,
heavily traffic due to heavy rain, a long queue
of traffic waiting to slowly enter AVE. At stationary
position, CAR B hit my rear with strong impact.
Stop at road shoulder to exchange particulars.
CAR B admitted to his daughter fault.

Declaration

(We declare the foregoing particulars are true in every respect.

 21/7/16
19:00hrs
Policyholder's Signature / Date &
Time

 21/7/16
Driver's Signature (if driver is not the policyholder) / Date
& Time


Witnessed by Reporting Officer
Personnel

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/07/2016 16:48
Date Of Accident	20/07/2016 07:00
Exact Location Of Accident	SLIP RD FROM CLEMENTI AVE 6 TO AYE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGS2457U
Insured/Policyholder	
Name Of Registered Owner	YAHYA BIN HASSAN
NRIC No	S1617929I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93883314
Alternative Phone No	Office-NOPHONE

Vehicle Particulars

Manufacturer	HONDA
Model	FIT 1.3 A
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Reporting Only
Vehicle Category	Private Car

Insurance Company

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	
Cover Note Number	

Driver

Name of Driver	RABIATULADAWYAH BINTE YAHYA
NRIC No	S9139923G
Date Of Birth	07/11/1991
Occupation	Indoor
Date Of Driving Pass	01/04/2016
Driving Experience	0 Year And 3 Month
Gender	Male
Mobile Number	(Local) +65-98552189
Fax Number	
Contact Number	
Email Address	rabiatuladawiyah0711@gmail.com

Address	BLK 112 TECK WHYE LANE #07-626
Postcode	680112
Was driver an employee of the Insured's Company	No
If No, Relationship of the Driver with the Insured	Children
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	Unknown - REFER TO SKETCH PLAN
Weather Conditions	Raining
Road Surface	Wet

Other Information

Was any foreign vehicle involved in this accident?	No
Was any body injured in the Accident?	No
Was any other material or property damaged?	Yes
Was there any video captured by Car Camera?	No
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	No
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	No
If Yes, against whom?	

Circumstances of Accident

Are accident photos available for attachment?	Yes
---	-----

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SBU8219A
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	MOHAMAD SAIFUL BIN MOHAMAD HALID
NRIC/Passport Number	
Contact Number	83288395
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]
Policyholder's Signature / Date & Time

[Signature]
Driver's Signature (If driver is not the policyholder) / Date & Time

[Stamp]
Witnessed by Reporting Centre Personnel


Sketch Plan




Describe Circumstances of the Accident		LICENSE PLATE NUMBER: 54S24574	
ACCIDENT DATE: 20/07/2016	CONTACT NUMBER: 9865 2189		
ACCIDENT TIME: 07:02 AM	EMAIL: rabiataladawiyah0711@gmail.com		
LOCATION: Slip road from Clementi Avenue 6 to AYE Expressway			
AS I was approaching the slip road from Clementi Avenue 6 towards the Ayer Rajah Expressway (AYE), a black Mazda RX8 was in front of my car. The car had managed to pass the slip road after it moving and was moving towards the merging lane to the AYE. I had lightly pressed the accelerator pedal. However, I thought that the car moved forward. However, it did not move as expected. I did my best to jam-break my car in time. Yet, it was not enough. My car banged into the car in front of.			
NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY.			
PLEASE CHECK YOUR POLICY FOR MORE INFORMATION.			
Please state:			
☐ Claim Own Policy ☐ Claim Third Party ☐ Claim OD/TP at other workshop ☒ Reporting Only			

Declaration

We declare the foregoing particulars are true in every respect.


 Policyholder's Signature / Date & Time


 Driver's Signature (If driver is not the policyholder) / Date & Time


 Witnessed by Reporting Centre Personnel

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road, #07-280, Singapore 470110
Mobile: 9855 6579 Email: automaxsurvey@gmail.com
Registration No: 53110062J

Report Ref: TP16070027

Date: 19 DEC 2016

Mohamad Saiful Bin Mohd Halid
c/o Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677969

THIRD PARTY SURVEY
ACCIDENT OCCURED ON 20 July 2016

Workshop Name and Address

Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677969

As per your instruction dated
We have carried out a physical inspection on the said
We enclosed herewith our report and findings as follows:

18 November 2015

with regard to the above matter.
SBU 8219 A

1. VEHICLE PARTICULARS

Registration No : SBU 8219 A
Model : MAZDA RX 8
Year / Capacity : 2007 / 1308 cc
Chassis No : SE3P142235

Engine No : 13B529050
Mileage : 108 070km
Colour : Metallic Black

2. TYRES CONDITION

	Size
FRONT O/S :	195/65/R15
REAR O/S :	195/65/R15
FRONT N/S :	195/65/R15
REAR N/S :	195/65/R15

Make	Balance	Rim
Pirelli	9.00 mm	Sport
Pirelli	9.00 mm	Sport
Pirelli	9.00 mm	Sport
Pirelli	9.00 mm	Sport

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road : #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 14 working days to complete
5. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.
6. Should you discover any discrepancy in the report, please kindly notify us within 1 week, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : SBU 8219 A

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (\$\$)	Our Revised Estimation (\$\$)
-----	-------------------	-----------	----------------------------	-------------------------------

List Items

1 pc	Rear bumper	distorted	\$ 1,164.50	\$ 1,164.50
2 pcs	Rear bumper side retainer	bent/distorted	\$ 90.00	\$ 90.00
2 pcs	Rear bumper side attachment	distorted	\$ 130.00	\$ 130.00
1 pc	Rear bumper center retainer	distorted	\$ 280.00	\$ 280.00
2 pcs	Rear bumper clips	necessary	\$ 28.00	\$ 28.00
1 pc	Rear bumper reinforcement	bent/distorted	\$ 767.00	\$ 767.00 X <i>SVC</i>
2 pcs	Rear bumper clips	necessary	\$ 20.00	\$ 20.00
1 pc	Boot lid	bent/distorted	\$ 1,733.00	\$ 1,733.00 R
1 pc	Boot lid weatherstrip	wrapped	\$ 386.00	\$ 386.00 X <i>SVC</i>
1 pc	Boot lid lock	distorted	\$ 320.00	\$ 320.00 X <i>SVC</i>
1 pc	Boot lid lock striker	bent/distorted	\$ 150.00	\$ 150.00 X <i>SVC</i>
1 pc	Boot lid badge	necessary	\$ 68.00	\$ 68.00
1 pc	Boot lid emblem "Mazda"	necessary	\$ 38.00	\$ 38.00
1 pc	Boot lid emblem "RX 8"	necessary	\$ 38.00	\$ 38.00
1 pc	Boot lid outer garnish	distorted	\$ 183.00	\$ 183.00 X <i>SVC</i>
4 pcs	Boot lid outer garnish clips	necessary	\$ 35.20	\$ 35.20 X <i>AN</i>
1 pc	Rear end panel	bent/distorted	\$ 531.50	\$ 531.50
1 pc	Rear end panel top trim	deformed	\$ 339.10	\$ 339.10
4 pcs	Rear end panel top trim clips	necessary	\$ 34.00	\$ 34.00
1 pc	Exhaust silencer	bent	\$ 4,250.00	\$ 4,250.00 <i>SVC</i>
3 pcs	Exhaust silencer hook	distorted	\$ 150.00	\$ 150.00 <i>SVC</i>
2 pcs	Rear number plate lamp	deformed	\$ 126.00	\$ 126.00
2 pcs	Taillamp	damaged	\$ 950.00	\$ 950.00 X <i>SVC</i>
6 pcs	Taillamp clips	necessary	\$ 24.00	\$ 24.00 X <i>AN</i>

Parts Sub-Total \$ 11,835.30 \$ 11,835.30 7287.10
 Discount 20.00% \$ 2,367.06 \$ 2,367.06 208
 \$ 9,468.24 \$ 9,468.24 5829.68

Vehicle Number : SBU 8219 A

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (\$\$)	Our Revised Estimation (\$\$)
-----	-------------------	-----------	----------------------------	-------------------------------

Special Nett Items

1 pc	Rear number plate w casing	bent/distorted	\$ 125.00	\$ 125.00
1 pc	Rear bumper lower spoiler	deformed	\$ 650.00	\$ 650.00
2 pcs	Rear bumper exhaust chrome sleeve	Damaged	\$ 287.80	\$ 287.80

Special Nett Sub-Total \$ 1,062.80 \$ 1,062.80

Spare Parts Total \$ 10,531.04 \$ 10,531.04

1062.80

LABOUR COST


S/No	JOB DESCRIPTIONS	Workshop Estimation (\$\$)	Our Revised Estimation (\$\$)
------	------------------	----------------------------	-------------------------------

Spare Parts Total c/f \$ 10,531.04 \$ 10,531.04

1	To check wiring system	\$ 150.00	\$ 120.00 ³⁰
2	To tuff coat affected areas	\$ 180.00	\$ 150.00 ⁴⁰
3	To remove and refix interior upholstery	\$ 180.00	\$ 180.00 ⁸⁰
4	To remove & replace exhaust silencer	\$ 350.00	\$ 320.00 ⁸⁰
5	To remove & transfer bootlid mechanism	\$ 220.00	\$ 200.00 ^{X NA}
6	To respray affected areas	\$ 1,600.00	\$ 1,400.00 ⁶⁰⁰
7	To renew damaged parts, straighten and repair and aligned all parts	\$ 2,000.00	\$ 1,800.00 ⁶⁰⁰
Total		15,211.04	14,681.04 ¹⁴³⁰

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of:

\$ 11,750.00


Fong Kok Hing
Qualified Appraiser

5829.68
1062.80
1430.00
8322.48
20%
6657.98
43-6,650
6 days

FormTeam Consultancy Pte Ltd

No.33, Ubi Ave 3
#02-15, Vertex
Singapore 408568

Tel : (65) 6509 1788
Fax : (65) 6509 6221

Email: monitorsurvey@fta.com.sg

Co.Reg No: 200819280D

GST Reg No: 200619280D

Our Reference : RRN16-072726/PRS/YH/ADJ/YH/lp

Your Reference: MT/0908760-002

Date : 17-Jan-2017

Motor Claims Department
NTUC Income Insurance Co-operative Limited
73 Bras Basah Road
#05-01 NTUC Trade Union House
Singapore 189556

Attention : Ms Rajeswary

Dear Sir/Mdm.

SURVEY OF VEHICLE NO. SBU 8219A

Pursuant to your instruction on 12-January-2017.

We recommend a repair cost of **\$3,500.00** (see report) based on lump sum repair and
the estimated duration of repairs would take **05 days**

We also enclosed our note of charges for your consideration.

Thank you for this assignment.

Your faithfully

FormTeam Consultancy Pte Ltd
Adjusters & Surveyors (Licensed Appraiser)



Ng You Han
Automobile Appraiser

(Email : yhng@fta.com.sg)

Encl. Survey Report

FormTeam Consultancy Pte Ltd

AUTOMOBILE ASSESSMENT REPORT

Page No. 1

Our Reference : RKN16-072726/PRS/YH/ADJ/YH/lp

Your Reference: MT/0908760-002

Date : 17-Jan-17

Attention : Ms Rajeswary

TO : Motor Claims Department
NTUC Income Insurance Co-operative Limited
73 Bras Basah Road
#05-01 NTUC Trade Union House
Singapore 189556

Assessment of Vehicle No : SBU 8219A
Date of Accident : 20-June-2016
Date of Inspection : 26-July-2016
Address of Inspection : 4 Woodlands Road 393J Yew Tee Industrial Estate S 677978

We have carried out a physical assessment of SBU 8219A at M/S Eng Soon Painting Services according to your instructions on 26-July-2016, dismantled items on 27-July-2016, post repair survey on 10-August-2016 and are pleased to submit our report herewith.

1. VEHICLE PARTICULARS

Registration No. : SBU 8219A
Make & Model : Mazda RX-8 1.3A
Year of Registration : 2007
Engine Capacity : 1308 cc
Chassis No. : SE3P142235
Engine No. : 13B529050
Colour : Black
Mileage (km) : 108070

2. VEHICLE CONDITION

Body Paint : Fair
Steering : Serviceable
Foot Brake : Serviceable
Parking Brake : Serviceable

3. TYRE PARTICULARS & CONDITION

Front

RH Make/Size : Hankook 225/45ZR18 - 80%
LH Make/Size : Hankook 225/45ZR18 - 80%

Rear

RH Make/Size : Hankook 225/45ZR18 - 80%
LH Make/Size : Hankook 225/45ZR18 - 80%

Note : % denotes the remaining percentage of the tyre


FormTeam Consultancy Pte Ltd

Our Reference : RRN16-072726/PRS/YH/ADJ/YH/lp
Your Reference : MT/0908760-002
Vehicle Number : SBU 8219A

Page No. 2

4. DESCRIPTION OF DAMAGE

At the time of inspection, this vehicle sustained damages to the **Rear** portion. Please see attached scheduled for details.



5. REMARKS

Market Value : -
Salvage Value : -
Repair Limit (Nett Loss) : -
Repairer's estimate : **Not Provided**
Nett Saving : -
Excess : -
Sum Insured : -
Our adjusted amount : \$ 3,500.00
Estimated Repair Days : 05 days

Additional photographs will be submitted upon request by our principal.

Pursuant to your instruction, we have **NOT AUTHORIZED** repair.

The assessment was conducted on a "**Without Prejudice**" basis.

If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by **FormTeam Consultancy Pte Ltd** for any reliance on this report by any third party, unless with the permission of the addressee.

FormTeam Consultancy Pte Ltd

Our Reference : RRN16-072726/PRS/YH/ADJ/YH/lp
Your Reference : MT/0908760-002
Vehicle Number : SBU 8219A

Page No. 3

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (\$\$)	CORP. ASSESSMENT (\$\$)
PARTS (LIST ITEMS)				
1	Rear Bumper	Distorted		1,164.50
2	Rear Bumper Side Retainer	Bent / Distorted		90.00
2	Rear Bumper Side Attachment	Distorted		130.00
1	Rear Bumper Center Retainer	Distorted		280.00
2	Rear Bumper Clips	Necessary		28.00
2	Rear Bumper Clips	Necessary		20.00
1	Boot Lid Badge	Necessary		68.00
1	Boot Lid Emblem "Mazda"	Necessary		38.00
1	Boot Lid Emblem "RX 8"	Necessary		38.00
1	Rear End Panel	Bent / Distorted		531.50
1	Rear End Panel Top Trim	Deformed		339.10
4	Rear End Panel Top Trim Clips	Necessary		34.00
2	Rear Number Plate Lamp	Deformed		126.00
			-	2,887.10
	Less Discount :	20%	-	577.42
	Parts Total :		-	2,309.68
SPECIAL NETT ITEMS				
1	Rear Number Plate W Casing	Bent / Distorted		125.00
1	Rear Bumper Lower Spoiler	Deformed		650.00
	Special Nett Total :		-	775.00
	Parts Total :		-	3,084.68

FormTeam Consultancy Pte Ltd

Page No. 4


Our Reference : RRN16-072726/PRS/YH/ADJ/YH/lp
 Your Reference : MT/0908760-002
 Vehicle Number : SBU 8219A

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	LABOUR		
1	To rewire rear portion.		30.00
2	To remove, refix roof and trims.		80.00
3	To remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.		600.00
4	To putty and respray painting on affected areas.		600.00
	Labour Total :	-	1,310.00
	TOTAL (PARTS & LABOUR) :	-	4,394.68

The final adjusted Lump Sum contract amount is

\$3,500.00

(SINGAPORE DOLLARS THREE THOUSAND FIVE HUNDRED ONLY)


 Frankie Pang
 AMSAE(AUST), AMIRTE, AMSOE,
 MASPACI, MSAAA
 Licensed Appraiser


 Ng You Han
 Automobile Appraiser



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBU 8219A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DISTORTED	1,164.50	1,164.50
2	REAR BUMPER SIDE RETAINER	BENT / DISTORTED	90.00	90.00
2	REAR BUMPER SIDE ATTACHMENT	DISTORTED	130.00	130.00
1	REAR BUMPER CENTER RETAINER	DISTORTED	280.00	280.00
2	REAR BUMPER CLIPS	NECESSARY	28.00	28.00
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	767.00	-
2	REAR BUMPER CLIPS	NECESSARY	20.00	20.00
1	BOOT LID	TO REPAIR SEE LABOUR	1,733.00	-
1	BOOT LID WEATHERSTRIP	SERVICEABLE	386.00	-
1	BOOT LID LOCK	SERVICEABLE	320.00	-
1	BOOT LID LOCK STRIKER	SERVICEABLE	150.00	-
1	BOOT LID BADGE	NECESSARY	68.00	68.00
1	BOOT LID "MAZDA"	NECESSARY	38.00	38.00
1	BOOT LID EMBLEM "RX 8"	NECESSARY	38.00	38.00
1	BOOT LID OUTER GARNISH	SERVICEABLE	183.00	-
4	BOOT LID OUTER GARNISH CLIPS	NOT NECESSARY	35.20	-
1	REAR END PANEL	BENT / DISTORTED	531.50	531.50
1	REAR END PANEL TOP TRIM	DEFORMED	339.10	339.10
4	REAR END PANEL TOP TRIM CLIPS	NECESSARY	34.00	34.00
1	EXHAUST SILENCER SVC	BENT	4,250.00	4,250.00 X
3	EXHAUST SILENCER HOOK SVC	DISTORTED	150.00	150.00 X
2	REAR NUMBER PLATE LAMP	DEFORMED	126.00	126.00
2	TAILLAMP	SERVICEABLE	950.00	-
6	TAILLAMP CLIPS	NOT NECESSARY	24.00	-
	LESS 20% DISCOUNT		-2,367.06	-1,457.42
			9,468.24	5,829.68
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE W CASING (SN)	BENT / DISTORTED	125.00	125.00
1	REAR BUMPER LOWER SPOILER (SN)	DEFORMED	650.00	650.00
2	REAR BUMPER EXHAUST CHROME SLEEVE (SN)	DAMAGED	287.80	287.80
			1,062.80	1,062.80

Report Ref No. CS1/LAW17017147/R1vbs2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO CHECK WIRING SYSTEM.		150.00	30.00
	TO TUFF COAT AFFECTED AREAS.		180.00	40.00
	TO REMOVE AND REFIX INTERIOR UPHOLSTERY.		180.00	80.00
	TO REMOVE & REPLACE EXHAUST SILENCER.		350.00	NN - 80.00
	TO REMOVE & TRANSFER BOOTLID MECHANISM.	NOT NECESSARY	220.00	-
	TO RESPRAY AFFECTED AREAS.		1,600.00	600.00
	TO RENEW DAMAGED PARTS, STRAIGHTEN AND REPAIR AND ALIGNED ALL PARTS. INCLUSIVE OF THE REPAIR OF BOOT LID.		2,000.00	600.00
			4,680.00	1,430.00
	GRAND TOTAL		15,211.04	8,322.48

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,650.00
---	--	--	-----------------

Report Ref No. CS1/LAW17017147/R1vbs2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Vehicle Number : SBU 8219 A

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (\$)	Our Revised Estimation (\$)
-----	-------------------	-----------	--------------------------	-----------------------------

<u>List Items</u>				
1 pc	Rear bumper	distorted	\$ 1,164.50	\$ 1,164.50
2 pcs	Rear bumper side retainer	bent/distorted	\$ 90.00	\$ 90.00
2 pcs	Rear bumper side attachment	distorted	\$ 130.00	\$ 130.00
1 pc	Rear bumper center retainer	distorted	\$ 280.00	\$ 280.00
2 pcs	Rear bumper clips	necessary	\$ 28.00	\$ 28.00
1 pc	Rear bumper reinforcement	bent/distorted	\$ 767.00	\$ 767.00
2 pcs	Rear bumper clips	necessary	\$ 20.00	\$ 20.00
1 pc	Boot lid	bent/distorted	\$ 1,733.00	\$ 1,733.00
1 pc	Boot lid weatherstrip	wrapped	\$ 386.00	\$ 386.00
1 pc	Boot lid lock	distorted	\$ 320.00	\$ 320.00
1 pc	Boot lid lock striker	distorted	\$ 150.00	\$ 150.00
1 pc	Boot lid badge	necessary	\$ 68.00	\$ 68.00
1 pc	Boot lid emblem "Mazda"	necessary	\$ 38.00	\$ 38.00
1 pc	Boot lid emblem "RX 8"	necessary	\$ 38.00	\$ 38.00
1 pc	Boot lid outer garnish	distorted	\$ 183.00	\$ 183.00
4 pcs	Boot lid outer garnish clips	necessary	\$ 35.20	\$ 35.20
1 pc	Rear end panel	necessary	\$ 531.50	\$ 531.50
1 pc	Rear end panel top trim	bent/distorted	\$ 339.10	\$ 339.10
4 pcs	Rear end panel top trim clips	deformed	\$ 34.00	\$ 34.00
1 pc	Exhaust silencer	necessary	\$ 4,250.00	\$ 4,250.00
3 pcs	Exhaust silencer hook	bent	\$ 150.00	\$ 150.00
2 pcs	Rear number plate lamp	distorted	\$ 126.00	\$ 126.00
2 pcs	Tailamp	deformed	\$ 950.00	\$ 950.00
6 pcs	Tailamp clips	damaged	\$ 24.00	\$ 24.00
		necessary		
Parts Sub-Total			\$ 11,835.30	\$ 11,835.30
Discount 20.00%			\$ 2,367.06	\$ 2,367.06
			\$ 9,468.24	\$ 9,468.24

Vehicle Number : SBU 8219 A

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (\$)	Our Revised Estimation (\$)
-----	-------------------	-----------	--------------------------	-----------------------------

<u>Special Net Items</u>				
1 pc	Rear number plate w casing	bent/distorted	\$ 125.00	\$ 125.00
1 pc	Rear bumper lower spoiler	deformed	\$ 650.00	\$ 650.00
2 pcs	Rear bumper exhaust chrome sleeve	Damaged	\$ 287.80	\$ 287.80
Special Net Sub-Total			\$ 1,062.80	\$ 1,062.80
Spare Parts Total			\$ 10,531.04	\$ 10,531.04

LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (\$)	Our Revised Estimation (\$)
------	------------------	--------------------------	-----------------------------

Spare Parts Total of \$ 10,531.04 \$ 10,531.04

- To check wiring system
- To tuff coat affected areas
- To remove and refix interior upholstery
- To remove & replace exhaust silencer
- To remove & transfer bootlid mechanism
- To respray affected areas
- To renew damaged parts, straighten and repair and aligned all parts @

\$ 150.00	\$ 120.00	30	30
\$ 180.00	\$ 150.00	70	40
\$ 180.00	\$ 160.00	60	80
\$ 350.00	\$ 320.00	X	X
\$ 220.00	\$ 200.00	80	X
\$ 1,600.00	\$ 1,400.00	800	600
\$ 2,000.00	\$ 1,800.00	800	600

Total 15,211.04 14,681.04

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of:

\$ 11,750.00

Fong Kok Hong
Qualified Appraiser

6 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBU 8219A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DISTORTED	1,164.50	1,164.50
2	REAR BUMPER SIDE RETAINER	BENT / DISTORTED	90.00	90.00
2	REAR BUMPER SIDE ATTACHMENT	DISTORTED	130.00	130.00
1	REAR BUMPER CENTER RETAINER	DISTORTED	280.00	280.00
2	REAR BUMPER CLIPS	NECESSARY	28.00	28.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	767.00	-
2	REAR BUMPER CLIPS	NECESSARY	20.00	20.00
1	BOOT LID	TO REPAIR SEE LABOUR	1,733.00	-
1	BOOT LID WEATHERSTRIP	NOT NECESSARY	386.00	-
1	BOOT LID LOCK	SERVICEABLE	320.00	-
1	BOOT LID LOCK STRIKER	NOT NECESSARY	150.00	-
1	BOOT LID BADGE	NECESSARY	68.00	68.00
1	BOOT LID EMBLEM "MAZDA"	NECESSARY	38.00	38.00
1	BOOT LID EMBLEM "RX 8"	NECESSARY	38.00	38.00
1	BOOT LID OUTER GARNISH	NOT NECESSARY	183.00	-
4	BOOT LID OUTER GARNISH CLIPS	NOT NECESSARY	35.20	-
1	REAR END PANEL	BENT / DISTORTED	531.50	531.50
1	REAR END PANEL TOP TRIM	DEFORMED	339.10	339.10
4	REAR END PANEL TOP TRIM CLIPS	NECESSARY	34.00	34.00
1	EXHAUST SILENCER	NOT NECESSARY	4,250.00	-
3	EXHAUST SILENCER HOOK	NOT NECESSARY	150.00	-
2	REAR NUMBER PLATE LAMP	DEFORMED	126.00	126.00
2	TAILLAMP	NOT NECESSARY	950.00	-
6	TAILLAMP CLIPS	NOT NECESSARY	24.00	-
	LESS 20% DISCOUNT		-2,367.06	-577.42
			9,468.24	2,309.68
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE W CASING (SN)	BENT / DISTORTED	125.00	125.00
1	REAR BUMPER LOWER SPOILER (SN)	DEFORMED	650.00	650.00

Report Ref No. CS1/LAW17017147/Cvbs2-1

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR BUMPER EXHAUST CHROME SLEEVE (SN)	DENTED	287.80	287.80
			1,062.80	1,062.80
	LABOUR			
	TO CHECK WIRING SYSTEM.		150.00	30.00
	TO TUFF COAT AFFECTED AREAS.		180.00	70.00
	TO REMOVE AND REFIX INTERIOR UPHOLSTERY.		180.00	60.00
	TO REMOVE & REPLACE EXHAUST SILENCER.	NOT NECESSARY	350.00	-
	TO REMOVE & TRANSFER BOOTLID MECHANISM.		220.00	80.00
	TO RESPRAY AFFECTED AREAS.		1,600.00	800.00
	TO RENEW DAMAGED PARTS, STRAIGHTEN AND REPAIR AND ALIGNED ALL PARTS. INCLUSIVE OF THE REPAIR OF BOOT LID.		2,000.00	800.00
			4,680.00	1,840.00
GRAND TOTAL			15,211.04	5,212.48
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,150.00

Report Ref No. CS1/LAW17017147/Cvbs2-1

HO LEONG CHUAN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.