



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref:

Type of Claim : TPVehicle No. : SKQ8099TMake & Model : MAZDA 3 4-DOOR SEDANYear of Manufacture : 2014Chassis No. : JM6BM42A8F0155588Ins Company : III / LONPAC

Engine No. : _____

Excess : _____

Policy No. : _____

Date of Accident : 21/07/2018

Time of Accident : _____

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimate**Case Owner : Andrew

Signature : _____

Parts (a) Cost / List Price Items \$ 2,419.51Plus/Less 20% \$ 483.90Total of Cost / List \$ 1,935.61(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 280.00Total Parts Cost (Appendix A) \$ 2,215.61Labour (Appendix B) \$ 2,080.00Total Repair Cost \$ 4,295.61

Contact No

Frt Counter Operation

6383 7466 - Patrick Tia

6383 7730 - Brenda Ng

6383 7890 - Rohani

braddell_cr@sparkcarcare.com

Workshop Operation

63837656 - Ngo Toh Wee

63837362 - Andrew Goh

63838115 - William Wang

braddell_operation@sparkcarcare.com

Ukk Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Gino Q: p - 82860282Company : UkkSurvey conducted on : 30/7/18 at _____**Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 2 day(s)(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

part by part.
before paint photos

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SKQ8099T Case Owner : Andrew

Make & Model : MAZDA 3 4-DOOR SEDAN Year Manufacture : 2014

Chassis No : JM6BM42A8F0155588 Engine No : 0

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear bumper <i>de</i>	1		\$ 1,074.80			
2	Rear bumper side retainer LH <i>X</i>	1		\$ 36.10			
3	Rear bumper side retainer RH <i>X</i>	1		\$ 36.10			
4	Rear bumper clips <i>de</i>	10		\$ 28.00			
5	Rear bumper reinforcement ?	1		\$ 537.30			
6	Rear bumper sponge ?	1		TBA			
7	Rear bumper lower garnish <i>X</i>	1		TBA			
8	Rear bumper tow cover RH <i>X</i>	1		\$ 16.21			
9	Rear bumper reflector LH <i>X</i>	1		\$ 50.40			
10	Rear bumper reflector RH <i>X</i>	1		\$ 50.40			
11	Rear end panel <i>X</i>	1		\$ 505.10			
12	Rear end panel top garnish <i>X</i>	1		\$ 85.10			
13	Reverse sensor <i>X</i>	1				\$ 280.00	
14	0	0					
15	0	0					
16	0	0					
17	0	0					
18	0	0					
19	0	0					
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax:62844284,62815767

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.