

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/TP/0866/2018/PH  
**Date** : 30-Jul-18

**Vehicle not in workshop. Kindly arrange for survey.**

**Your insured vehicle no : SLP 3445 D**

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mr Hay Hui Hoon  
**Address** : 43 Conway Circle  
Singapore 558281

**Telephone** : (HP) 81826963  
**Type of Claim** : Third Party claims  
**Policy No.** : 2100343978-04000  
**Vehicle No** : **SGF 7772 U**  
**Model Code** : Audi A3 Sportback 1.4 TFSI  
**Model / Year** : Jun-13  
**Engine No** : CMB 135362  
**Chassis No** : WAUZZZ8V1DA057998  
**Mileage** :  
**Date In** :  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 30-Jul-18  
**Place of Accident** : Havelock Road(infront four point hotel)

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SGF 7772 U.

<u>S/N</u>	<u>Nature of Jobs</u>		<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove and transfer rear parking aid. Check function.	S/N	\$ 280.00	✓
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall parts removed.		\$ <del>900.00</del> 500	
3	To respray rear bumper and rear lid.		\$ <del>1,400.00</del> 1100	
4	To carry out diagnostic check.	S/N	\$ 192.00	✓
<b>TOTAL LABOUR CHARGES</b>			<b>: \$ <u>2,772.00</u></b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SGF 7772 U.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>ok</i>	\$	1,619.00 ✓
2	REAR BUMPER FIXING PARTS	\$	166.00 ✗
3	REAR BUMPER GUIDE SECTION-LH/RH <i>2 NT</i>	2 \$	28.00 ✗
4	LOCKING MECHANISM <i>?</i>	2 \$	22.00 ✗
5	SPOILER <i>NT</i>	\$	206.00 ✗
6	SIDE REINFORCEMENT <i>NT</i>	\$	501.00 ✗
7	BRACKET <i>?</i>	\$	11.00 ✗
8	BRACKET-RH <i>NT</i>	\$	11.00 ✗
9	GUIDE SECTION - LH/RH <i>NT</i>	2 \$	114.00 ✗
10	SENSOR - INNER/OUTER <i>NT</i>	2 \$	421.00 ✗
11	PACKING ADHESIVE <i>NT</i>	\$	15.00 ✓
12	AUDI EMBLEM CHROME <i>NT</i>	\$	108.00 ✓
13	A3' EMBLEM <i>?</i>	\$	83.00 ✓
15	TFSI' EMBLEM <i>?</i>	\$	83.00 ✓
16	CAR PLATE <i>NT</i>	S/N \$	25.00 ✗
17	SUNDRIES <i>?</i>	\$	300.00 ?
<b>TOTAL SPARE PARTS</b>		:	<b>\$ 3,713.00</b>
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 2,772.00</b>
<b>GRAND TOTAL</b>		:	<b>\$ 6,485.00</b>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : Adrian King  
Surveyed Date : 03/08/18  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : Not Authorised, 04 Days

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant