Tech. Invs (\$

Weekend (\$

Report Format:

Lump Sum / I.B.I: (\$ 6,032.74 P/P)

Others

TOTAL

MVA318096640 / VAC - Kaki Bukit ENTRY DATE & TIME, 26/07/2010 14:49 SUBMITTED BY: Nomain! Bite About Majid

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2 This Form must be completed by the Policyholder and/or the Authorised Driver
- 3 information provided must be as truthful and accurate as possible. Any wilful misreproportation of witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
- 6 This report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties
- 7. By the indigement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

ACCI	DENT	STA	TEN	IEN'	T
			_		

Date Of Report

26/07/2018 14:49

Date Of Accident

25/07/2018 18:55

Exact Location Of Accident

BOUNDARY ROAD

Country/State of Loss

SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SCZ5455R

Insured/Policyholder

Name Of Registered Owner

BOB YAP CHENG CHEE

NRIC No.

S1766713J

Email Address

NOEMAIL

Mobile Phone No

(LOCAL) +65-96616765

Alternative Phone No.

OTHERS-96616765

Vehicle Particulars

Manufacturer

Madel

COOPER'S 5DR FWD LED ABS NAV

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company

MS FIRST CAPITAL INSURANCE LTD

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

D-18089952MVPC (COMP)

Cover Note Number

Driver

Name of Driver

YAP YU HAN, BRENNAN

NRIC No

S9704248I

Date Of Birth

01/02/1997

Occupation Date Of Driving Pass

OUTDOOR 19/05/2017

Driving Experience

1 YEAR AND 2 MONTHS

Gender

Mobile Number

MALE

Fax Number

(LOCAL) +65-81252502

Contact Number

EMail Address

NOEMAIL

Page 1 of 15

Address

22 RICHARDS PLACE

Postcode

546349

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

CHILDREN

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles involved in the accident

NO 3

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station Police Station Name

TRAFFIC POLICE DIVISION HQ

Police Station Address

ROAD: 10 UBI AVENUE 3, POSTCODE: 408865, COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: 65470000 - FAX NO:

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

WITH TRAFFIC POLICE

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

QX226M

Vehicle Make/Model/Colour

TOYOTA COROLLA ALTIS 1.6 AUTO

Details Of Properties

Vehicle Category

GOVERNMENT

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

UNKNOWN

Vehicle Make/Model/Colour

VAN

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- Allege in agent correctly the details of the addition to speed up the claims process.
- I This Firm must be sumpleted by the Policyholder and/or the Authorised Driver
- 4. Interpretar an accorded must be as truthful and accurate at possible. Any wilful misropresentation or withhomes of material facts true according to accurate so repudiate policy liability.
- Short on the acceptance of the Europay anaronce companies is not an admission of policy hability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- If the readit will be formarded by the insurers of the GIA Records Management Centre established by the General insurance established by the General insurance interested parties.
- 7. Sy the lodgment of the report to the insurer, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

understand acknowledge, agree and consent that

- Interest the workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclorer and/or process my personal data/personal information set out in this [form] and enyother personal information provided by me or possessed by my ansurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Ministery Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - 1-1 directioning, handling, undried feating with any claims including the settlement of the claims and any necessary investigations reliating to the claims.
 - (19) investigating one account and/or my claims;
 - mild carrying out and/or disting with my instructions or responding to any enquiries by me,
 - (iv) edimenstering my claims (according the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) comotiving with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all unurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawvers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Pecconal information masy can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents/including their lastice (flaw firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (ii) any Presimentation nation, will also be collected and used to compile claims instary for the purpose of fraud detection constigration and management in present and all future claims.
- (iii) the information or independ above may be shared / disclosed
 - If not of insurer canal, of only other than parties that assist in evaluating, rivestigating, controlling or managing transregulations, low or too proper and government agenties as reasonably required for the purposes studied, or
 - active complying with recipe enough model by regulations, sizes or court orders.

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4

Singapore 415933
Tel: 67416697 Fax: 67492305
#Email: reacks@singnar.com.sa

Name:

The physics of the control of the co

SKETCHPLLN

SEZEMSSA -OX226M

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Defet to Date and at	
Refer to police report	
T - MA	
ECLARATION	TOAC KAKI BUKIT (VAC)

decrees the lighting that culture are thus an every resource

23 Kaki Bukit Ave 4 Singapore 415933 Tel: 57416697 Fax: 674923US Email: vackb@singnet.com.sn

The state of the second

white a section of the section 45 640

<u> ...</u> er se chago no





Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

1 of 3 Report No. T/20180726/7000

REPORT OF A TRAFFIC ACCIDENT

	ne Report I 018 01:59	Made:	Vide Report No.: F/20180725/0225	Station Diary No.:
Informa	nt's Partic	ulars		
	f Informant: HAN, BRE		Address: 29A RICHARDS PLACE SING	GAPORE 546382
	/ ID No.: O / S97042	481	Contact No.: Home/Office:	Mobile: 81252502
National SINGAF	lity: PORE CITIZ	EN	Email: brennanyap@hotmail.com	
Sex: Male	Age: 21	Date of Birth: 01/02/1997	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupat Student	ion:		Driving Licence Information: Class:	Date of Expiry:

General Infor	mation of the Accider	nt		
Type of Accident:	Non-Injury Police Vehicle	Drink Drive: No	Date/Time of Accident: 25/07/2018 18:55	Type of Location Straight Road
Location:			1 2010112010 10100	
BOUNDARY	ROAD			
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collis Between Mov	lon: ing Vehicles - Head To	Rear	a	Anyone conveyed by ambulance:

Details of V	ehicle Invo	lved				
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
QX226M	Car				Slightly Damaged	2
SCZ5455R	Car					0

Details of Person Involved		
Any Pedestrian Involved: No		
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA	





2 of 3

Report No. T/20180726/7000

Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

CONTINUATION OF REPORT

Driver				
Name	Jasrianto Bin Jasni	l l	D No.	S8732153C
Related Vehicle	QX226M (Car)	(Contact No.	NIL
Hospital/Clinic	NIL	L	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discha	rge NIL	
No. of Days gran	ted Medical Leave NIL	Degree of In	jury NIL	
Driver				
Name	YAP YU HAN, BRENNAN	11	D No.	S9704248I
Related Vehicle	SCZ5455R (Car)	C	Contact No.	81252502
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discha	rge NIL	
No. of Days grant	led Medical Leave NIL	Degree of In	jury NIL	

Brief Details.

I was driving normally when the car in front slowed down, I slowed down as well but the police car behind me didn't manage to slow down in time and crashed into my car. This was the first bang. The car behind the police car also couldn't stop in time and banged into the police car which then caused the police car to bang into me a second time.

We were travelling on boundary road and 1 van, 1 police car, 1 car was involved in the accident.

I had a video camera that was capturing everything but it was taken by the traffic police for further insepction





Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 3 of 3 Report No. T/20180726/7000

CONTINUATION OF REPORT

Sketch Plan Informant is not able to provide sketch plan

Authentication Stamp

NP168

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 26/07/2018 01:59
Officer In Charge Of Case: TP / TPIB / LIM JUN HUI, ADRIAN Contact No.: 65476350	Classification Of Case:



SINGAPORE POLICE FORCE ACKNOWLEDGEMENT SLIP

Ref: Report No:F	20180725 0225		
I.	Sot 7102	and sonother	400
	(Recipient's Name, Cont	act No. / NRIC or Passpo	ort No. / Rank and No.)
of		97	
	(Address / F	Police Station / NPC / NPI	P)
hereby acknowledge re	eceipt of the below mention	ed items of:	
Alberta Description	82 49 02 CHAR		
2			
3			
4			
5			
6			
7			
8	/		
9			
10			
			20-
rom			I84248I
of	(Name, NHIC or	Passport No. / Rank and	1 No.)
	(Address / Pr	olice Station / NPC / NPP	7)
on 25	17(18 at	18 55	
(Date)	eat -	(Time)	
Witnessed by / * Hande	d over by:	Rec	eived by:
* Delete if applicable)			12
æ.			X
(Signature)	-	Signature
Breunan Yap	597042481		Bot 7122000 downton to
(Name, NRIC or Passport N	o. / Rank and No.)	(Name, Contac	ct No. / NRIC or Passport No. / Rank and No.
Other Remarks:			

REPUBLIC OF SINGAPORE DENTITY CARD NO. \$97042481





Norma

YAP YU HAN, BRENNAN

of :

宇

CHINESE

Date of birth 01-02-1997

SINGAPORE

O2-1997 M try of birth Intans

REPUBLIC OF SINGAPORE ADRIVING LICENCE

WASHE STATE S 9 7 0 4 2 4 8 1

VAP YU HAN, BRENNAN

RVE Date: 01 Feb 1997

Date: Date: 19 May 2017

4965706



ISS No. S97042481

03-08-2012

22 RICHARDS PLACE SINGAPORE 546349 NRIC No. 597042481

Date:18/07/2018

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES)


EFFECTIVE DATE

Class 3.A Motor cars without clutch pedals (Auto) with unladen 19 May 2017 weight < 3000kg with << 7 passengers, exclusive of driver; and other motor vehicles without clutch pedals with unladen weight << 2500kg

NP 428A



SKETCHPLAN



ESCHIBE CIRCOM21	ANCES OF THE ACCIDENT	
Dofe to	2-146-140-14	
Keit to	poice report	
-		
The state of the s		
MOITARA		
decision the larest ting	Mary Charles and D. To the Gold Per Bents	Z3 Kaki Bukit (VAC
	63-	Singapore 415933 Tel: 57416697 Fax: 6749230
HILDER TO A COLUMN	The Cart and	Email: vackb@singner.com.s
Con	* 4 * 4 * 1	THE STATE OF THE STATE OF
	the feet of the form of the	





1 of 3 Report No. T/20180726/7000

Police Station Of Origin; Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

REPORT OF A TRAFFIC ACCIDENT

	ne Report M 018 01:59	Made:	Vide Report No.: F/20180725/0225	Station Diary No.:
Informa	nt's Partic	ulars		
	Informant: HAN, BRE		Address: 29A RICHARDS PLACE SING	GAPORE 546382
	/ ID No.: D / S97042	481	Contact No.: Home/Office:	Mobile: 81252502
National SINGAP	ity: ORE CITIZ	EN	Email: brennanyap@hotmail.com	
Sex: Male	Age: 21	Date of Birth: 01/02/1997	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupat Student	ion:		Driving Licence Information: Class:	Date of Expiry:

Type of Accident:	Non-Injury Police Vehicle	Drink Drive: No	Date/Time of Accident: 25/07/2018 18:55	Type of Location Straight Road
Location: BOUNDARY	ROAD	Road Surface:		Road Speed Limit:
weamer.				HOAG SOMEOUT INTO
Weather: Clear		Dry		50 Km/h

Details of Vehicle Involved										
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger				
QX226M	Car				Slightly Damaged	2				
SCZ5455R	Car					0				

Details of Person Involved		
Any Pedestrian Involved: No		
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA	





2 of 3

Report No. T/20180726/7000

Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

CONTINUATION OF REPORT

Driver					
Name	Jasrianto Bin Jasni		ID No.		S8732153C
Related Vehicle	QX226M (Car)		Conta	ct No.	NIL
Hospital/Clinic	NIL		Class Driving Licens Expiry	g e &	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Disch	arge	NIL	
No. of Days gran	ted Medical Leave NIL	Degree of	Injury	NIL	
Driver					
Name	YAP YU HAN, BRENNAN		ID No.		S9704248I
Related Vehicle	SCZ5455R (Car)		Conta	ct No.	81252502
Hospital/Clinic	NIL		Class Driving Licend Expiry	g e &	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Disch	arge	NIL	
No. of Days gran	ted Medical Leave NIL	Degree of	Injury	NIL	

Brief Details.

I was driving normally when the car in front slowed down, I slowed down as well but the police car behind me didn't manage to slow down in time and crashed into my car. This was the first bang. The car behind the police car also couldn't stop in time and banged into the police car which then caused the police car to bang into me a second time.

We were travelling on boundary road and 1 van, 1 police car, 1 car was involved in the accident.

I had a video camera that was capturing everything but it was taken by the traffic police for further insepction





3 of 3

Report No. T/20180726/7000

Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

CONTINUATION OF REPORT

Sketch	Dian

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 26/07/2018 01:59
Officer In Charge Of Case: TP / TPIB / LIM JUN HUI, ADRIAN Contact No.: 65476350	Classification Of Case:

Authentication Stamp NP168



SINGAPORE POLICE FORCE

ACKNOWLEDGEMENT SLIP

Ref: Report No: F	20180725 0	225		
l,	S ₆	t Trace	Donathan	400
	(Recipient's Na	me, Contact No.	/ NRIC or Passpo	rt No. / Rank and No.)
of	(Ac	idress / Polico St	ation / NPC / NPI	2)
				,
hereby acknowledge red			ns of:	
De 18080	45 02 onther	48		
2				
0				
				EXVEST-
rom				, 89704248I
	(Name,		rt No. / Rank and	No.)
		355	5455R	
1	(Add	dress / Police Sta	tion / NPC / NPP)
n 351	*(18 a	at	18 55	
(Date)			(Time)	
·			100	
Vitressed by / * Handed Delete if applicable)	over by:		Rece	eived by:
				1/
æ.				X.
				<u> </u>
(Signature)				Signature
Breunan Yap				Bot Times during to
Name, NRIC or Passport No	. / Rank and No.)		(Name, Contac	t No. / NRIC or Passport No. / Rank and No
ther Remarks:				
mer nemarks.				

REPUBLIC OF SINGAPORE



104541



YAP YU HAN, BRENNAN

潘

叶宇

HINESE

CHINESE Day of birth

01-02-1997 Country of bush SINGAPORE



4858708



**** \$97042481

The second secon

Date of teams 03-08-2012

22 RICHARDS PLACE SINGAPORE 546349

NRIC No. \$97642481

Dete:18/07/2018

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES)

EFFECTIVE DATE

Class 3A Motor cars without clutch pedals (Auto) with unladen 19 May 2017 weight < 3000kg with << 7 passengers, exclusive of driver; and other motor vehicles without clutch pedals with unladen weight << 2500kg

NP 428A





EUROKARS HABITAT PTE LTD NO:12 SUNGEI KADUT, SINGAPORE 729648 ESTIMATE COST OF REPAIRS



SPF ACCIDENT CLAIMS SECTION

NAME:

Mr Yap Cheng Ghee Bob

WIP:

20758

AUTOMOTIVE ENGG & MGMT DIV POLICE LOGISTICS DEPARTMENT

ADDRESS :

22 Richards Place Singapore 546349 EXCESS: DATE:

30.07.2018

NO. 1 MOUNT PLEASANT ROAD

BLOCK 8 OLD POLICE ACADEMY SINGAPORE 298333

TEL:

91053684 Ms 4ap: 96616765

MOTOR CLAIMS / FAX 64784848 ATTN.: JOBI THOMAS 6360 2446 CONTACT PERSON: DATE IN : SCZ5455R VEH NO : TP AGAINST QX226M TYPE OF CLAIM: MILEAGE : WMWX5720102B60388 CHASSIS NO:

ODE	L: F55 COOPER 5	DATE REG.:	26.03.2015	POLICY NO. :			-	
	No.		NATURE OF WO	ORKS				
/NO		Pa	rts Description		_	1		
			QTY		REVISED	_	RICES	1
1	REAR BUMPER		1	M51.12.7.380.036		\$		CR
2	TOWING COVER	MINE -	1	M51.31.7.380.037		\$	46.44	Ca
3	REAR BUMPER LOWER CHROME		1	M51.12.7.365.073	-	\$	186.19	ne
4	REAR BUMPER LOWER GRILLE		1	M51.12.7.365.075		5	91.38	B
5	LOGO "COOPER S"		1	M51.14.2.755.618		5	66,50	1
6	TAIL LIGHT LH		1	M63.21.7.297.413		5		csu
7	TAIL LIGHT CHROME RING RH		1	M63.21.7.351.431		\$	59.00	101
8	TAIL LIGHT CHROME RING LH		1	M63.21.7.351.432		5	59.00	1
9	BLIND RIVET		10	M07.14.7.411.141		\$	36.30	2
10	REAR BUMPER FOG LIGHT		1	M63.24.7.350.007		\$	65.25	,
	SENSOR PARKASSIST (PAINTED)		1	M66.20.9.302.469		5	475.81	
12	SENSOR PARKASSIST (BLACK)		1	B66.20.9.274.428		5	310.88	Kal
13	SENSOR		4	B66.20.9.283.203		\$	25.24	1
14	TAIL PIPE CHROME		2	M18.30.8.606.004		\$	262.26	,5
15	REAR BUMPER GUIDE LH		1	M51.12.7.318.755		\$	108.94	1
16	CLIP		4	M07.14.2.754.954		5	6.24	10
17	REAR BUMPER REINFORCEMENT		1	M51.12.7.300.788		\$	505.94	
18	REINFORCMENT SEAL		2	B51.12.7.300.789		5	10.88	?
19	HEX NUT		4	807.14.7.266.441		\$	14.52	:
				TOTAL DARKE	_	s	3,666.71	
_				TOTAL PARTS		s		1
_				TOTAL PARTS COST		\$	3,666.71	1
								-
		Labour Descrip	ption			-		1
		CO A OTHER DAMAG	ED BARTS & TO R	FPAIR TAILGATE		5	2,100.00	-1
1	TO REMOVE / REPLACE REAR BUMP		ED PARTS & TO K	EL CHILD TEACHER				1
_	AREAS AFFECTED BY THE ACCIDENT							
2	TO RESPRAY REAR BUMPER & TAILS	ATE.				Ś	1,800.00	11
3	TO CARRY-OUT BODY CAVITY PRESE	RVATION.				\$	250 00	T
						s	500.00	-
- 4	TO TRANSFER THE REVERSE SENSOR	0.						-14

			_		1.4	250:00
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		_		5	250:00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.				\$	350:00
7	SUNDRIES.		NETT		\$	100.00
_		TOTAL LABOUR	5		5	5,350.00
		TOTAL PARTS	\$		\$	3,666.71
		TOTAL	s		\$	9,016.71
		LESS EXCESS	\$	-	5	
		TOTAL AFTER EXCESS	\$		1	
		GST 7%	\$		5	

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

NAZ CKK LKK Auto Consultar - nue notify the Repairer or ththe Repairer of the swing:

To resulting before a way painting 6/8/18 1030 To display demaged (+ i(s) running resurvey. Parts prices are subject to confirmation. Third party survey is on a "Without Prejudice" basis * No Rec - 15 - 800 " - 15 april 24 dem, simust be resurve and and AFFER RE wyv. all scytoval from insurance Company 4-5 \$ 2 DAYS owledged by Repairer ature: BEFORE PAINT PHOTO 67418434



TO CARRY-OUT BODY CAVITY PRESERVATION.

TO TRANSFER THE REVERSE SENSORS.

EUROKARS HABITAT PTE LTD

NO:12 SUNGEI KADUT, SINGAPORE 729648 ESTIMATE COST OF REPAIRS



250.00

500.00 420

\$

20758 WIP: Mr Yap Cheng Ghee Bob NAME : SPF ACCIDENT CLAIMS SECTION EXCESS: ADDRESS : 22 Richards Place **AUTOMOTIVE ENGG & MGMT DIV** DATE: 30.07.2018 Singapore 546349 POLICE LOGISTICS DEPARTMENT NO. 1 MOUNT PLEASANT ROAD 91053684 Ms 4ap: 96616765 TEL: BLOCK 8 OLD POLICE ACADEMY SINGAPORE 298333 MOTOR CLAIMS / FAX 64784848 ATTN. : JOBI THOMAS 6360 2446 CONTACT PERSON: DATE IN: SCZ5455R VEH NO : TP AGAINST QX226M TYPE OF CLAIM: MILEAGE : CHASSIS NO: WMWX5720102860388 DATE REG.: 26.03.2015 POLICY NO. : MODEL: F55 COOPER S NATURE OF WORKS Parts Description S/NO PRICES REVISED QTY 953.19 \$ M51.12.7.380.036 1 REAR BUMPER 46.44 5 M51.31.7.380.037 1 TOWING COVER 186.19 1 M51.12.7.365.073 REAR BUMPER LOWER CHROME 3 91.38 5 1 M51.12.7.365.075 REAR BUMPER LOWER GRILLE 4 66.50 s 1 M51.14.2.755.618 LOGO "COOPER S" 382.75 KSUC 5 1 M63.21.7.297.413 TAIL LIGHT LH 6 59.00 S 1 M63.21.7.351.431 TAIL LIGHT CHROME RING RH 59.00 M63.21.7.351.432 1 TAIL LIGHT CHROME RING LH 36.30 M07.14.7.411.141 10 BLIND RIVET 9 X SU 65.25 \$ 1 M63.24.7.350.007 10 REAR BUMPER FOG LIGHT 475.81 5 M66.20.9.302.469 1 SENSOR PARKASSIST (PAINTED) 310.88 X SVC B66.20.9.274.428 SENSOR PARKASSIST (BLACK) 1 25.24 5 866 20.9.283.203 4 SENSOR 13 \$ 262.26 SCR 2 M18.30.8.606.004 TAIL PIPE CHROME 108.94 \$ M51.12.7.318.755 REAR BUMPER GUIDE LH 6.24 5 4 M07.14.2.754.954 16 CLIP 505.94 5 M51.12.7.300.788 1 REAR BUMPER REINFORCEMENT 10.88 5 2 851.12.7.300.789 REINFORCMENT SEAL 18 5 14.52 807.14.7.266.441 HEX NUT 19 3,666.71 \$ TOTAL PARTS 5 \$ 3,666.71 TOTAL PARTS COST **Labour Description** 2,100.00 -1680 TO REMOVE / REPLACE REAR BUMPER & OTHER DAMAGED PARTS & TO REPAIR TAILGATE AREAS AFFECTED BY THE ACCIDENT. 5 1,800.00 TO RESPRAY REAR BUMPER & TAILGATE 2

						7
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.				5	250:00
		70			e	350:00
б	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.				1	330.00
7	SUNDRIÉS.		NETT		s	100.00
		TOTAL LABOUR	\$		\$	5,350.00
		TOTAL PARTS	\$		\$	3,666.71
		TOTAL	\$		\$	9,016.71
		LESS EXCESS	S		5	
		TOTAL AFTER EXCESS	\$	19	1	
		GST 7%	\$		\$	
		GRAND TOTAL	5		\$	

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

NAZ CKK LKK Auto Consultar - nue notify the Repairer of the lawing:

To resurvey before 1 lawing: the Repairer of the 6/8/18 1030 To display damaged t + ((s) during recurvey. Parts prices are subject to confirmation. Third party survey is on a "Wahout Prejudice" basis while the service above a present demon must be resurred and AFFER RE evyc . I at proval from Insurance Company 4-5 \$ 2 DAYS owledged by Repairer ature: BEFORE PAINT PHOTO 67418434



EUROKARS HABITAT PTE LTD NO:12 SUNGEI KADUT, SINGAPORE 729648 FINALIZATION COST OF REPAIRS



SPF ACCIDENT CLAIMS SECTION

NAME:

Mr Yap Cheng Ghee Bob

WIP:

20758

AUTOMOTIVE ENGG & MGMT DIV

ADDRESS:

22 Richards Place

EXCESS:

POLICE LOGISTICS DEPARTMENT

NO. 1 MOUNT PLEASANT ROAD

TEL:

Singapore 546349

DATE:

30.07.2018

BLOCK 8 OLD POLICE ACADEMY SINGAPORE 298333 ATTN.:

MOTOR CLAIMS / FAX 64784848

91053684

JOBI THOMAS 6360 2446 CONTACT PERSON: DATE IN: SCZ5455R VEH NO: TP AGAINST QX226M TYPE OF CLAIM: WMWXS720102B60388 MILEAGE: CHASSIS NO:

26.03.2015

MODE	L: F55 COOPER S	DATE REG.: 26.03.201	5 POLICY NO. :		136	V 90 -4	33-3	_
		NATURE OF	WORKS		150			
s/NO		Parts Description	<u>n</u>		1772	200	de	
		QTY			RE	VISED	795 475	RICES
1	REAR BUMPER	1	M51.12.7.380.036	VERA	\$	953.19	\$	953.19
2	TOWING COVER	1	M51.31.7.380.037	1 CRA	\$	46.44	\$	46.44
3	REAR BUMPER LOWER CHROME	1	M51.12.7.365.073	~ ALC	\$	186.19	\$	186.19
4	REAR BUMPER LOWER GRILLE	1	M51.12.7.365.075	-BT	\$	91.38	\$	91.38
5	LOGO "COOPER S"	1	M51.14.2.755.618	- ALC	\$	66.50	\$	66.50
6	TAIL LIGHT LH	1	M63.21.7.297.413	XSUL	\$	Mar.	\$	382.75
7	TAIL LIGHT CHROME RING RH	1	M63.21.7.351.431	/CLA	\$	59.00	\$	59.00
8	TAIL LIGHT CHROME RING LH	1	M63.21.7.351.432	Xnn	5	1000	\$	59.00
9	BLIND RIVET	10	M07.14.7.411.141	/ALC	\$	36.30	\$	36.30
10	REAR BUMPER FOG LIGHT	1	M63.24.7.350.007	XSUC	\$	120,23	\$	65.25
11	SENSOR PARKASSIST (PAINTED)	1	M66.20.9.302.469	X SYL	\$	8 W ()	\$	475.81
12	SENSOR PARKASSIST (BLACK)	1	B66.20.9.274.428	XSUL	\$	437 (21)	\$	310.88
13	SENSOR	4	B66.20.9.283.203	Mi	\$	25.24	\$	25.24
14	TAIL PIPE CHROME	2	M18.30.8.606.004	SCR	\$	262.26	\$	262.26
15	REAR BUMPER GUIDE LH	1	M51.12.7.318.755	XSUL	\$	Page 1	\$	108.94
16	CUP	4	M07.14.2.754.954	/ruc	\$	6.24	\$	6.24
17	REAR BUMPER REINFORCEMENT	1	M51.12.7.300.788	X SUL	5	200	5	505.94
18	REINFORCMENT SEAL	2	B51.12.7.300.789	XAA	\$	964.0	\$	10.88
19	HEX NUT	4	807.14.7.266.441	X SUL	\$	2000年	\$	14.52
					12	200.30	1.85	
			TOTAL PARTS		\$	1,732.74	\$	3,666.71
					-	HOLDERY &	\$	
			TOTAL PARTS COST		\$	1,732.74	\$	3,666.71
		Labour Description			- 5			
1	TO REMOVE / REPLACE REAR BUMPE	R & OTHER DAMAGED PARTS & TO	REPAIR TAILGATE	/	\$	1,680.00	\$	2,100.00
	AREAS AFFECTED BY THE ACCIDENT.				338		27	
					18	1 000 00		1 800 00
2	TO RESPRAY REAR BUMPER & TAILGA	ATE,			\$	1,600.00	\$	1,800.00
3	TO CARRY-OUT BODY CAVITY PRESER	VATION.		/	\$	150.00	s	250.00
4	TO TRANSFER THE REVERSE SENSORS	\$0		~	\$	420.00	\$	500.00

	(4)		-		-	- 7
0						121 7
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$	150.00	\$	250.00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		\$	250.00	\$	350.00
7	SUNDRIES.	/	\$	50.00	\$	100.00
		TOTAL LABOUR	\$	4,300.00	\$	5,350.00
		TOTAL PARTS	\$	1,732.74	\$	3,666.7
		TOTAL	\$	6,032.74	\$	9,016.7
		LESS EXCESS	\$		5	
		TOTAL AFTER EXCESS	\$	6,032.74		
		GST 7%	\$	422.29	\$	
		GRAND TOTAL	\$	6,455.03	\$	

NUMBER OF DAYS: 4 WORKING DAYS(EXCLUDE WAITING FOR PARTS, SURVEY, AUTHORIZATION, SATURDAY, SUNDAY AND PUBLIC HOLIDAY)

LKK Auto Consultants hence notify

- the Repairer of the following:
- To resurvey before/after spray painting
 To display demand a state of the s
- To display damaged part(s) during resurvey
- * Parts prices are subject to confirmation
- * Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LineT		Product	Description	Quantity	Price	Disc%	Tot	al
LINE	_		BODY REPAIRS	0	0	0	\$	
2		CST M51.12.7.380.036		1	953.19	0	\$	953.19
		M51.31.7.380.037		1	46.44		\$	46.44
		M51.12.7.365.073		1	186.19	0	\$	186.19
5		M51.12.7.365.075		1	91.38	0	\$	91.38
		M51.14.2.755.618		1	66.5	0	\$	66.50
8		M63.21.7.351.431	Chrome ring,	1	59		-	59.00
10		M07.14.7.411.141	Blind rivet	10	3.63		_	36.30
		B66.20.9.283.203	Decoupling r	4	6.31	0	\$	25.24
		M18.30.8.606.004		2	101.10		_	262.26
		M07.14.2.754.954		4	1.56	0	\$	6.24

\$ 1,732.74



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Date: 10-10-2018

Affiliated to Federation Internationale Des Experts En Automobile

Ref : CS/SPF18013862/Nsbs2 AUTOMOTIVE ENGINEERING & MGT DIVISION

ACCIDENT CLAIM SECTION (SINGAPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE

ACADEMYSINGAPORE 298333



1.	Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	QX 226M	Veh. Inspected	SCZ 5455R			
	Policy No.		Coverage (\$)	0.00			
	Claim No.	AEMD/105/009/2018/092	Excess (\$)	0.00			
	Assign From	ABDUL RAHMAN	Assign Date	31/07/2018			
2.	Vehicle Particulars & Condition						
	Make & Model	MINI COOPER S	c.c	1998			
	Engine No.	HIDDEN	Year of Reg.	2015			
	Chassis No.	WMWXS720102B60388	Colour	GREY			
	Odometer	40446	Steering	IN ORDER			
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM			
	General	FAIR					
3.		Conc	litions of Tyres				
		Size	Make	Balance			
	R/H Front Tyre	205/45R17	MICHELIN	6 mm			
	L/H Front Tyre	205/45R17	MICHELIN	6 mm			
	R/H Rear Tyre	205/45R17	MICHELIN	6 mm			
	L/H Rear Tyre	205/45R17	MICHELIN	6 mm			
4.		Descrip	otion of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.						
	DAMAGES SEE D	ETAILS.					
5.	General Information						
	Accident Date	25/07/2018	Inspection Date	06/08/2018			
	Survey held at	EUROKARS HABITAT PTE L	.TD				
		NO.12 SUNGEI KADUT AVE SINGAPORE 729648					
5a.	Remarks						
	A)THE INSPECTION B)IN ACCORDAN	ON WAS CONDUCTED ON A"V CE TO YOUR INSTRUCTIONS	VITHOUT PREJUDICE" BA , WE HAVE NOT AUTHORI	SIS. SED REPAIRS.			
5b. Estimate Days of Repair							



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCZ 5455R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS	3		
1	REAR BUMPER	CRACKED	953.19	953.19
1	TOWING COVER	CRACKED	46.44	46.44
1	REAR BUMPER LOWER CHROME	NECESSARY	186.19	186.19
- 1	REAR BUMPER LOWER GRILLE	BENT	91.38	91.38
1	LOGO "COOPER S"	NECESSARY	66.50	66.50
1	TAIL LIGHT LH	SERVICEABLE	382.75	1-
- 1	TAIL LIGHT CHROME RING RH	CRACKED	59.00	59.00
1	TAIL LIGHT CHROME RING LH	NOT NECESSARY	59.00	5-
10	BLIND RIVET	NECESSARY	36.30	36.30
1	REAR BUMPER FOG LIGHT	SERVICEABLE	65.25	-
1	SENSOR PARKASSIST (PAINTED)	SERVICEABLE	475.81	-
1	SENSOR PARKASSIST (BLACK)	SERVICEABLE	310.88	14
	SENSOR	NECESSARY	25.24	25.24
2	TAIL PIPE CHROME	SCRATCHED	262.26	262.26
1	REAR BUMPER GUIDE LH	SERVICEABLE	108.94	
4	CLIP	NECESSARY	6.24	6.24
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	505.94	
2	REINFORCMENT SEAL	NOT NECESSARY	10.88	-
4	HEX NUT	SERVICEABLE	14.52	
			3,666.71	1,732.74
	SPECIAL NETT ITEMS			
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
			100.00	50.00
	LABOUR			
	TO REMOVE/REPLACE REAR BUMPER & OTHER DAMAGED PARTS & TO REPAIR TAILGATE AREAS AFFECTED BY THE ACCIDENT.		2,100.00	1,680.00
	TO RESPRAY REAR BUMPER & TAILGATE.		1,800.00	1,600.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.		250.00	150.00
	TO TRANSFER THE REVERSE SENSORS.		500.00	420.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	150.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	250.00
			5,250.00	4,250.00
	GRAND TOTAL		9,016.71	6,032.74

RECOMMENDED COST OF REPAIRS	6,032.74
-----------------------------	----------

Report Ref No. CS/SPF18013862/Nsbs2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.