

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION Ref: CS/SPF18013862/Nsbs2				
ACCIDENT CLAIM SECTION (SINGAPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333			Date: 10-10-2018	
ATTN: ABDUL RAHMAN Co			Code: SPF	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	QX 226M	Veh. Inspected	SCZ 5455R
	Policy No.		Coverage (\$)	0.00
	Claim No.	AEMD/105/009/2018/092	Excess (\$)	0.00
	Assign From	ABDUL RAHMAN	Assign Date	31/07/2018
2. Vehicle Particulars & Condition				
	Make & Model	MINI COOPER S	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	WMWXS720102B60388	Colour	GREY
	Odometer	40446	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/45R17	MICHELIN	6 mm
	L/H Front Tyre	205/45R17	MICHELIN	6 mm
	R/H Rear Tyre	205/45R17	MICHELIN	6 mm
	L/H Rear Tyre	205/45R17	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
	DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	25/07/2018	Inspection Date	06/08/2018
	Survey held at	EUROKARS HABITAT PTE LTD		
		NO.12 SUNGEI KADUT AVE SINGAPORE 729648		
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Estimate Days of Repair

4 Working Days