

ASS. REC. BY:

REF: CS/GAI18013867/Kvd307 Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Rachel Tan

of GAI

Date/Time: 31/7/18 @ 9.49am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: 8HC 5779T

Insured: FBK 34204

at Workshop m/s Trans-Cab

Tel: 62876666

of No. 2 AMK sf. 63

Policy No:

Claim No: CLMOMVM00000339

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 27/07/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time: 9.51am 31/7/18

Person Contacted: Candy

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	8HC 5779T - CS/FCI13012348/UvdI DOA: 8/7/2013
	FBK 3420 U-X
2/8/18	Email preli revised to Rachel

ASS. REC. BY:

REF:

GAZ

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP ☒ WS ☒ TP RES ☒ OD RES ☒ EVA ☒ INV ☒ MV

To inspect Vehicle No:

at Workshop m/s

Tans Cob

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2 1/2 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHC 5779

Yr Regn:

07, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Perout Latitude

c.c

1995

Colour:

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

385175

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VI-1ABL15AUC

281634

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Giti

Front

R/Bal.

5

mm

Rear

R/Bal.

9

mm

L/Bal.

5

mm

L/Bal.

9

mm

D.O.A.

27/7/18

D.O.I.

31/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear d/s

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2/8

File pass to Catherine

2/8/18

61 Reg 8 56501

(Reel 60,697-53, 919)

RECEIVED 03 AUG 2018

Date/Time, File Pass to?



Prell. Report

1)



Final Report

Date/Time, File Return to?

2)

3/8 - typist

Days Of Repair:

2 1/2

Resurvey No. of Trip:

-

Survey Fee:

150

Transportation:

S + RS \$1

Fees:

Others:

TOTAL

150

Report Format:

Lump Sum / I.B.I. (\$

TP  
56501

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
GREAT AMERICAN INSURANCE COMPANY		Ref : CS/GAI18013867/Kvd3	
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Date : 31-07-2018	
		Code : GAI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	FBK 3420U	Veh. Inspected	SHC 5779T
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	RACHEL TAN	Assign Date	31/07/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	27/07/2018	Inspection Date	31/07/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Friday, 3 August 2018 11:50 AM  
**To:** 'Tan, Rachel'  
**Cc:** SUR  
**Subject:** RE: ARRANGE FOR SURVEY SHC5779T against FBK3420U GA - DOA: 27.07.2018

Dear Rachel,

Noted with thanks.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Tan, Rachel <Rachel.Tan@sg.gaig.com>  
**Sent:** Friday, 3 August 2018 11:25 AM  
**To:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Subject:** RE: ARRANGE FOR SURVEY SHC5779T against FBK3420U GA - DOA: 27.07.2018

CLMOMVM000000339

Regards  
Rachel Tan  
Executive, Motor Claims, Great American Insurance Company  
Tel: 6804 7846

---

**From:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Sent:** Friday, August 3, 2018 10:59 AM  
**To:** Tan, Rachel <Rachel.Tan@sg.gaig.com>  
**Subject:** [External] FW: ARRANGE FOR SURVEY SHC5779T against FBK3420U GA - DOA: 27.07.2018

Dear Rachel,

Please provides us the claim number.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Veron Chen (LKKAuto)  
**Sent:** Thursday, 2 August 2018 4:16 PM  
**To:** 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: ARRANGE FOR SURVEY SHC5779T against FBK3420U - DOA: 27.07.2018

Dear Rachel,

Enclosed preliminary revised of vehicle SHC 5779T  
Date of survey: 1/8/2018  
Number of days : 2.5 days

**Please provides us the claim number.**

Best Regards,  
Veron Chen | Case Handler  
LKK Auto Consultants Pte Ltd  
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

**From:** Admin-D (LKKAuto)  
**Sent:** Tuesday, 31 July 2018 10:00 AM  
**To:** 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>; assignments <assignments@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: ARRANGE FOR SURVEY SHC5779T against FBK3420U - DOA: 27.07.2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,  
G.Nivitha | Admin  
LKK Auto Consultants Pte Ltd  
Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

**From:** Tan, Rachel [mailto:Rachel.Tan@sg.gaig.com]  
**Sent:** Tuesday, 31 July 2018 9:49 AM  
**To:** candy.kong@transcab.com.sg  
**Cc:** LKK Assignments <assignments@lkkauto.com>  
**Subject:** FW: ARRANGE FOR SURVEY SHC5779T against FBK3420U - DOA: 27.07.2018

Without Prejudice

Dear Candy  
Our client has not reported accident, we will appoint LKK for survey on without prejudice basis.

Dear LKK  
Please accept assignment, thank you

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

-----Original Message-----

From: Candy Kong <candy.kong@transcab.com.sg>

Sent: Tuesday, July 31, 2018 9:47 AM

To: Tan, Rachel <Rachel.Tan@sg.gaig.com>

Cc: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>; Ng, Sharon  
<Sharon.Ng@sg.gaig.com>

Subject: [External] ARRANGE FOR SURVEY SHC5779T against FBK3420U - DOA:  
27.07.2018

Dear all,

Sorry , kindly see attach.

Please arrange for survey as below :

FBK3420U - 27.07.2018 at 1600Hrs - SHC5779T

Lunch time : 12pm - 1pm.

Kindly pls dun arrange survey during lunch time.

"We Agree to let your In-house surveyor assess/ survey our vehicle with  
estimate."

Thks & Rdgs

Candy Kong

Claims Service Assistant

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Thursday, 2 August 2018 4:16 PM  
**To:** 'Tan, Rachel'  
**Cc:** SUR  
**Subject:** RE: ARRANGE FOR SURVEY SHC5779T against FBK3420U - DOA: 27.07.2018  
**Attachments:** SHC 5779T PRELI REVISED.pdf

Dear Rachel,

Enclosed preliminary revised of vehicle SHC 5779T

Date of survey: 1/8/2018

Number of days : 2.5 days

**Please provides us the claim number.**

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAuto)

Sent: Tuesday, 31 July 2018 10:00 AM

To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>; assignments <assignments@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: ARRANGE FOR SURVEY SHC5779T against FBK3420U - DOA: 27.07.2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Tan, Rachel [mailto:Rachel.Tan@sg.gaig.com]

Sent: Tuesday, 31 July 2018 9:49 AM

To: candy.kong@transcab.com.sg

Cc: LKK Assignments <assignments@lkkauto.com>

Subject: FW: ARRANGE FOR SURVEY SHC5779T against FBK3420U - DOA: 27.07.2018

Without Prejudice

Dear Candy

Our client has not reported accident, we will appoint LKK for survey on

without prejudice basis.

Dear LKK

Please accept assignment, thank you

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

-----Original Message-----

From: Candy Kong <candy.kong@transcab.com.sg>

Sent: Tuesday, July 31, 2018 9:47 AM

To: Tan, Rachel <Rachel.Tan@sg.gaig.com>

Cc: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>; Ng, Sharon

<Sharon.Ng@sg.gaig.com>

Subject: [External] ARRANGE FOR SURVEY SHC5779T against FBK3420U - DOA:  
27.07.2018

Dear all,

Sorry , kindly see attach.

Please arrange for survey as below :

FBK3420U - 27.07.2018 at 1600Hrs - SHC5779T

Lunch time : 12pm - 1pm.

Kindly pls dun arrange survey during lunch time.

"We Agree to let your In-house surveyor assess/ survey our vehicle with  
estimate."

Thks & Rdgs

Candy Kong

Claims Service Assistant

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination,





Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: PLEASE ADVISED  
Our ref: CS/GAI18013867/Kvd3

Date: 02/8/2018

The Motor Claims Department  
M/s: GREAT AMERICAN INSURANCE COMPANY

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO. SHC 5779T**


We thank you for your instruction on 31/7/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 1/8/2018 at the premises of M/s TRANS-CAB AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$66,347.53
Revised Estimate Amount	: S\$5,650.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

**Description of Damage:**

The vehicle sustained damages at the rear o/s poriton.



Comments/Present Status:  
Damages Consistent

Yours faithfully,

Kenneth Kong  
**Licensed Appraiser**

## Nivitha (LKK Auto)

---

**From:** Tan, Rachel <Rachel.Tan@sg.gaig.com>  
**Sent:** Tuesday, 31 July 2018 9:49 AM  
**To:** candy.kong@transcab.com.sg  
**Cc:** LKK Assignments  
**Subject:** FW: ARRANGE FOR SURVEY SHC5779T against FBK3420U - DOA: 27.07.2018  
**Attachments:** img-731091742.pdf

Without Prejudice

Dear Candy

Our client has not reported accident, we will appoint LKK for survey on without prejudice basis.

Dear LKK

Please accept assignment, thank you

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

-----Original Message-----

From: Candy Kong <candy.kong@transcab.com.sg>

Sent: Tuesday, July 31, 2018 9:47 AM

To: Tan, Rachel <Rachel.Tan@sg.gaig.com>

Cc: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>; Ng, Sharon <Sharon.Ng@sg.gaig.com>

Subject: [External] ARRANGE FOR SURVEY SHC5779T against FBK3420U - DOA: 27.07.2018

Dear all,

Sorry , kindly see attach.

Please arrange for survey as below :

FBK3420U - 27.07.2018 at 1600Hrs - SHC5779T

Lunch time : 12pm - 1pm.

Kindly pls dun arrange survey during lunch time.

"We Agree to let your In-house surveyor assess/ survey our vehicle with estimate."

Thks & Rdgs

Candy Kong

Claims Service Assistant

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 3878K

**Vehicle Details**

Vehicle No.: SHC5779T

Vehicle to be Exported: Yes

Intended De-registration Date: 30 Jul 2018

Vehicle Make: RENAULT

Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour: Red

Manufacturing Year: 2015

Engine No.: M9R8839C002800

Chassis No.: VF1ABL15AUC281634

Maximum Power Output: 127.0 kW (170 bhp)

Open Market Value: \$19,998.00

Original Registration Date: 10 Jul 2015

First Registration Date: 10 Jul 2015

Transfer Count: 0

Actual ARF Paid: \$19,998.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 09 Jul 2023

PARF Rebate Amount: \$14,998.00

**Intended COE Rebate Details**

COE Expiry Date: 09 Jul 2023

COE Category: A - Car up to 1600cc &amp; 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$53,004.00

COE Rebate Amount: \$32,735.00

**Total Rebate Amount: \$47,733.00****Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 30 Jul 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	30/07/2018 13:45
Date Of Accident	27/07/2018 16:00
Exact Location Of Accident	PIE SLIP ROAD TOWARDS SIMEI AVENUE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHC5779T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666
<b>Vehicle Particulars</b>	
Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	
<b>Driver</b>	
Name of Driver	PEE NGIAP HENG
NRIC No	S1253235J
Date Of Birth	08/03/1957
Occupation	OUTDOOR
Date Of Driving Pass	11/03/1977
Driving Experience	41 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90610812
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	BLK 469 TAMPINES ST 44 #12-164
Postcode	520469
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : UNKNOWN - +61405217927 GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TAMPINES CHANGKAT NPP
Police Station Address	ROAD: 109 TAMPINES STREET 11 , POSTCODE: 521109 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7819999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE SEE ATTACH POLICE REPORT : S/D REF : 03

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBK3420U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	SHAHRIZAN BIN OSMAN

NRIC/Passport Number	S9136276G
Contact Number	92283767
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# Sketch Plan #2 Pg. 1

## SKETCH PLAN

Pine Strip Road

Pine Street

Smei Avenue

A = SHC 5797  
B = FBK 34204

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attach police Report

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Annex D

NOTICE OF REPORTING



This is to confirm that PEE NGIAP HENG NRIC/FIN: S1253235J, residing at Blk 469 Tampines Street 44 #12-164 hp: 90610812, has reported to the Police, a non-injury traffic accident which occurred at PIE Expressway near Simei Ave on 27/07/2018 at 1600hrs involving the following vehicles:

- i) SHC5779T (complainant)
- ii) FBK3420U (Shahrizan Bin Osman NRIC: S9136276G Contact : 92283767)

2 If this accident was reported to the Police within 24 hours of its occurrence, he/she has complied with Sec 84(2) of the Road Traffic Act, Cap 276.

Brief facts : Complainant informed that while he was along the slip road merging onto PIE expressway at simei ave , suddenly a motorcycle from behind hit the back of complainant's vehicle , Nobody was injured .



Rank/ Name of Issuing Officer: SGT T140123 Darren Woo

Date: 27/07/2018

Time: 1830hrs

S/D ref: 03

Police Post/ Unit: Changkat NPP

**Changkat NPP**  
Block 109 Tampines Street 11  
#01-261 Singapore 521109  
Tel: 1800-7819999

Original - to be issued to informant  
Duplicate - to be submitted to Traffic Police

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5779T****AAD1807-272***Not Authorised  
C/Sing @ 56501*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

**SHC 5779T**

VF1ABL15AUC281634

RENAULT

LATITUDE

27.7.2018

**GREAT AMERCIA****PART****LIST**

- 1 1 BUMPER COVER REAR
- 2 1 BUMPER LOWER REAR
- 3 1 BUMPER BRACKET CTR REAR
- 4 1 BUMEP R BRACKET SIDE RH REAR
- 5 1 BUMEP R RETAINER RH REAR
- 6 1 BUMPER REFLECTOR RH
- 7 1 BUMEP R BRACKET SIDE LH REAR
- 8 1 BUMEP R RETAINER LH REAR
- 9 1 BUMPER REFLECTOR LH
- 10 1 BUMPER BEAM REAR
- 11 1 BUMPER BEAM BRACKET LH REAR
- 12 1 BUMPER BEAM BRACKET RH REAR
- 13 1 BOOT REAR
- 14 1 BOOT FINISHER
- 15 1 BOOT WHEATERSTRIP
- 16 1 BOOT REFLECTOR LAMP LH
- 17 1 BOOT REFLECTOR LAMP RH
- 18 1 BOOT BADGE 'RENAULT'
- 19 1 BOOT BADGE
- 20 1 BOOT STRUT LH
- 21 1 BOOT STRUT RH
- 22 1 BOOT HINGE LH
- 23 1 BOOT HINGE RH
- 24 1 BOOT INNER TRIM
- 25 1 BOOT SWITCH
- 26 1 BOOT LOCK
- 27 1 BOOT LOCK CATCH
- 28 2 LICENCE PLATE LAMP
- 29 2 BOOT RUBBER PLUG

\$	<i>Bu</i>	1,108.46	✓
\$	<i>nd l w</i>	768.84	✓
\$	<i>Sn</i>	113.47	X
\$	<i>Sn</i>	135.97	X
\$	<i>Sn</i>	44.99	X
\$	<i>Sn</i>	43.61	X
\$	<i>Sn</i>	135.97	X
\$	<i>Sn</i>	44.99	X
\$	<i>Sn</i>	43.61	X
\$	<i>B</i>	777.52	✓
\$	<i>R</i>	225.95	X
\$	<i>R</i>	225.95	X
\$	<i>R</i>	2,872.68	✓
\$	<i>Sn</i>	470.06	X
\$	<i>Sn</i>	323.05	X
\$	<i>Sn</i>	493.35	X
\$	<i>CM</i>	493.35	✓
\$	<i>R</i>	225.36	✓
\$	<i>R</i>	225.36	✓
\$	<i>Sn</i>	276.08	} X
\$	<i>Sn</i>	276.08	
\$	<i>R</i>	367.84	
\$	<i>R</i>	367.84	
\$	<i>Sn</i>	586.45	
\$	<i>Sn</i>	168.13	
\$	<i>R</i>	202.67	
\$	<i>R</i>	74.40	
\$	<i>Sn</i>	50.52	}
\$	<i>Sn</i>	221.81	

11266 36

**Trans-cab Auto Services Pte Ltd**

AAD1807-272

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5779T

30	1 FENDER PANEL REAR LH	\$	R	3,299.13	}
31	1 WHEELARCH REAR LH	\$	Sn	543.47	
32	1 FENDER PANEL INNER TRIM REAR RH	\$	Sn	671.45	
33	1 FENDER PANEL REAR RH	\$	R	3,299.13	
34	1 WHEELARCH REAR RH	\$	Sn	543.47	
35	1 TAILLAMP RH	\$	Sn	552.55	
36	1 TAILLAMP PANEL RH	\$	R	986.70	
37	1 TAILLAMP LH	\$	Sn	552.55	
38	1 TAILLAMP PANEL LH	\$	R	986.70	
39	1 OUTER PANEL REAR (End Panel)	\$	R	1,471.77	
40	1 OUTER PANEL REAR (End Panel)TRIM	\$	Sn	404.56	
41	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	
42	1 SPARE WHEEL PANEL TRIM	\$	Sn	612.21	
43	1 EXHAUST REAR	\$	R	7,489.05	
44	1 EXHAUST CAP REAR	\$	R	230.49	
45	1 CHASSIS PANEL REAR RH	\$	R	3,766.43	
46	1 KUCKLE ARM REAR RH L70Y	\$	Sn	736.67	
47	1 BRAKE DISC REAR L70Y	\$	Sn	525.91	
48	1 WHEEL HUB NUT L70Y	\$	Sn	51.11	
49	1 WHEEL HUB CAP L70Y	\$	Sn	57.82	
50	1 ABS SENSOR REAR RH L70Y	\$	Sn	255.75	
51	1 REAR AXLE L70Y	\$	Sn	4,167.03	
52	1 AXLE ARM RH L70Y	\$	Sn	117.22	
53	1 LOWER ARM REAR RH L70Y	\$	Sn	905.99	
54	1 ABSORBER REAR	\$	Sn	389.75	
55	1 STABILIZER BAR REAR RH	\$	Sn	604.65	
56	1 BRAKE CALIPER REAR RH	\$	Sn	1,300.67	
57	1 WHEEL HOUSING PANEL REAR RH	\$	R	4,682.09	
58	1 CHASSIS PANEL REAR RH	\$	R	3,766.43	

X

49160.63

<b>TOTAL</b>	\$	<b>56,525.01</b>
<b>10%</b>	\$	<b>5,652.50</b>
	\$	<b>50,872.51</b>

56525.01

5652.50

50872.51

**Special Nett**

1 1SET PARKING AID	\$	Sn	700.00	X
2 1SET REAR BUMPER CLIP	\$	R	66.00	—
3 1SET BUMPER BRACKET CTR CLIP	\$	R	33.00	—
4 1SET BUMPER BRACKET SIDE CLIP RH RR	\$	R	10.00	X

**Trans-cab Auto Services Pte Ltd**

AAD1807-272

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5779T

5 1SET BUMPR RETAINER RH CLIP RR	\$	na	20.00	X
6 1SET BUMPR BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7 1SET BUMPR RETAINER CLIP LH RR	\$	na	20.00	X
8 1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9 1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10 1 EXHAUST MOUNTING REAR	\$	Sh	17.82	X
11 1SET BOOT FINISHER CLIP	\$	na	24.20	X
12 1 BOOT STICKER "Trans-cab"	\$	na	30.00	—
13 1 BOOT STICKER "6555-3333"	\$	na	30.00	—
14 1 BOOT INNER TRIM CLIP	\$	na	45.00	} X
15 1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	
16 1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	
17 1 FENDER INNER TRIM CLIP LH	\$	na	28.00	
18 1 FENDER INNER TRIM CLIP LH	\$	na	28.00	
19 1 TAILLAMP CLIP RH	\$	na	5.00	
20 1 TAILLAMP CLIP LH	\$	na	5.00	
21 2 REAR WINDSCREEN SELANT	\$	na	80.00	
22 1 WINDSCREEN MOULDING	\$	na	100.00	
23 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
24 1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sh	385.00	}
25 1 SPARE TYRE	\$	Sh	330.00	
26 1 RIGHT REAR TYRE	\$	Sh	330.00	
27 1 RIGHT REAR TYRE RIM	\$	Sh	380.00	

TOTAL \$ 2,935.02

TOTAL PARTS \$ 53,807.53

**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	440
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	400
To Rust-Proofing Of The Affected Areas.	\$	170.00	30

## Trans-cab Auto Services Pte Ltd

AAD1807-272

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5779T

To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	na	170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	↪	170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	↪	170.00 X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	↪	170.00 X
To supply and re-do rear luggage floor panel insulation padding.	\$	↪	380.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	↪	380.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	↪	170.00 X
To check steering geometry and computer wheel alignment	\$	↪	220.00 X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	↪	380.00 X

**TOTAL \$ 12,540.00**

12920

**Over All Total \$ 66,347.53**

66727.51

**(LUMP SUM)  
Repair Days**

**20 DAYS**  
*2 1/2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:


Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY		Ref : CS/GAI18013867/Kvd3e2		
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Date : 03-09-2018		
		Code : GAI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	FBK 3420U	Veh. Inspected	SHC 5779T	
Policy No.		Coverage (\$)	0.00	
Claim No.	CLMOMVM000000339	Excess (\$)	0.00	
Assign From	RACHEL TAN	Assign Date	31/07/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	VF1ABL15AUC281634	Colour	METALLIC WHITE / RED	
Odometer	385175	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	5 mm	
L/H Front Tyre	215/60 R16	GITI	5 mm	
R/H Rear Tyre	215/60 R16	GITI	9 mm	
L/H Rear Tyre	215/60 R16	GITI	9 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	27/07/2018	Inspection Date	01/08/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2.500 Working Days		





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 5

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5779T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BUMPER COVER REAR	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR	DENTED / CUT	768.84	768.84
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BOOT REAR	BENT	2,872.68	2,872.68
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP	SERVICEABLE	323.05	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH	CRACKED	493.35	493.35
1	BOOT BADGE 'RENAULT'	NECESSARY	225.36	225.36
1	BOOT BADGE	NECESSARY	225.36	225.36
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-

Report Ref No. CS/GAI18013867/Kvd3e2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR RH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	OUTER PANEL REAR (END PANEL)	TO REPAIR SEE LABOUR	1,471.77	-
1	OUTER PANEL REAR (END PANEL) TRIM	SERVICEABLE	404.56	-
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	TO REPAIR SEE LABOUR	2,189.88	-
1	SPARE WHEEL PANEL TRIM	SERVICEABLE	612.21	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
1	CHASSIS PANEL REAR RH	TO REPAIR SEE LABOUR	3,766.43	-
1	KNUCKLE ARM REAR RH L70Y	SERVICEABLE	736.67	-
1	BRAKE DISC REAR L70Y	SERVICEABLE	525.91	-
1	WHEEL HUB NUT L70Y	SERVICEABLE	51.11	-
1	WHEEL HUB CAP L70Y	SERVICEABLE	57.82	-
1	ABS SENSOR REAR RH L70Y	SERVICEABLE	255.75	-
1	REAR AXLE L70Y	SERVICEABLE	4,167.03	-
1	AXLE ARM RH L70Y	SERVICEABLE	117.22	-
1	LOWER ARM REAR RH L70Y	SERVICEABLE	905.99	-
1	ABSORBER REAR	SERVICEABLE	389.75	-

Report Ref No. CS/GAI18013867/Kvd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	STABILIZER BAR REAR RH	SERVICEABLE	604.65	-
1	BRAKE CALIPER REAR RH	SERVICEABLE	1,300.67	-
1	WHEEL HOUSING PANEL REAR RH	TO REPAIR SEE LABOUR	4,682.09	-
1	CHASSIS PANEL REAR RH	TO REPAIR SEE LABOUR	3,766.43	-
	LESS 10% DISCOUNT		-5,652.50	-647.16
			50,872.49	5,824.41
	<b>SPECIAL NETT ITEMS</b>			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	BOOT STICKER "TRANS-CAB" (SN)	NECESSARY	30.00	30.00
1	BOOT STICKER "6555-3333" (SN)	NECESSARY	30.00	30.00
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	SPARE TYRE RIM (ROUE 7J 16H 2547) (SN)	SERVICEABLE	385.00	-

Report Ref No. CS/GAI18013867/Kvd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPARE TYRE (SN)	SERVICEABLE	330.00	-
1	RIGHT REAR TYRE (SN)	SERVICEABLE	330.00	-
1	RIGHT REAR TYRE RIM (SN)	SERVICEABLE	380.00	-
			2,935.02	225.00
	<b>LABOUR</b>			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	440.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET LH REAR, BUMPER BEAM BRACKET RH REAR, BOOT HINGE LH, BOOT HINGE RH, BOOT LOCK, BOOT LOCK CATCH, FENDER PANEL REAR LH, FENDER PANEL REAR RH, TAILLAMP PANEL RH, TAILLAMP PANEL LH, OUTER PANEL REAR (END PANEL), SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL), EXHAUST REAR, EXHAUST CAP REAR, CHASSIS PANEL REAR RH, }		4,200.00	400.00
	WHEEL HOUSING PANEL REAR RH AND CHASSIS PANEL REAR RH. }		-	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-

Report Ref No. CS/GAI18013867/Kvd3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607196R GST Reg. No. 19-9607196-R

Page No.: 5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
			12,920.00	990.00
GRAND TOTAL			66,727.51	7,039.41
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,650.00

Report Ref No. CS/GAI18013867/Kvd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.