

22/03/2002

ASS. REC. BY:

REF:

CS/FCI18013868/Uvd3et

Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

From (Person):

CWS

Sithara

of

FCI

Date/Time:

30/7/18 @ 7.25pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SLB 4559B

Insured:

SHC 7841H

at Workshop m/s

Kah Motor

Tel:

6614 5687

of

15 Ubi Road 4

Policy No.:

Claim No.:

D18005744MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/07/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time: 31/7/18 @ 9.40 am

Person Contacted:

Mr. Hew

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLB 4559B - X

SHC 7841H - X

1/8/18

Email preli revised to FCI

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLB 4559Bat Workshop m/s Leh m/sof lied

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 6714.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 15 days Res.: Yes or NoLum Sum: 131 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLB 4559B Yr Regn: 4 16Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or GAMake: Herde city C.C. 1497Colour: white A/C: Insured / Std / NI / NASp. Reading: 24788 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRMGM66606P000440Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Ni / S/Rim / STD A/Rim orTyre Size: F: 145/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 28/7/18 D.O.I. 31/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
22/8/18	LTA 4559B 7 yrs 9 mths. Reg 7800 next 21/8/99 confirmed liability of 13650.84 with Any. (Red 4158.47, 2390)
	RECEIVED 20 AUG 2018
	RECEIVED 11 SEP 2018 extend w

Date/Time, File Pass to?

☐ : Prel. ReportDays Of Repair: 15

1)

☐ : Final ReportResurvey No. of Trip: 2

Date/Time, File Return to?

2) 20/8 - typistAdd Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Report Format: CWSLump Sum / I.B.I. (\$) 13,650.84

Survey Fee:

Transportation:

S-RS-SI

Photos 580

Others

21/8/18

TOTAL

7x15

1704105

50

50450

173

598



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18013868/Uvd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 31-07-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7841H	Veh. Inspected	SLB 4559B
Policy No.		Coverage (\$)	0.00
Claim No.	D18005744MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	31/07/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	28/07/2018	Inspection Date	31/07/2018
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Job Sheet (/ClaimWS/Surveyor/JobSheet/242808)



PRI Documents



Close



PRI Header Details

Claim No	D18005744MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & KAH MOTI
Workshop Name	KAH MOTOR CO SDN BHD (Contact Person : TW LIEW)	Survey Location & Contact Details	15 UBI ROAD 4 Mobile: 0 , Phone: 65145687 , Fax: 67480770 EmailId: TWLIEW@HONDA.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC7841H	TP Vehicle No	SLB4559B
PRI Recieved Date	30-07-2018 03:55:32 PM	Surveyor Appointed Date	30-07-2018 07:24:53 PM	Surveyor Accept Date	

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	31-07-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

MOTOR SURVEY ASSIGNMENT

Date	30-07-2018	Our Ref No. D18005744MFSH
Accident Date	28-07-2018	Claim Type. Third Party
Insured Vehicle	SHC7841H	Third Party Vehicle. SLB4559B
Survey Location	15 UBI ROAD 4	
Contact Person.	TW LIEW	
Contact No.	65145687/ 0	Fax No. 67480770
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KAH MOTOR CO SDN BHD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 1 August 2018 2:30 PM
To: 'Claim Workflow System'
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005744MFSH/1, SLB 4559B
Attachments: SLB 4559B PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLB 4559B
Date of survey: 31/7/2018
Number of days : 15 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 31 July 2018 9:48 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005744MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 30 July 2018 7:25 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005744MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18005744MFSH

Our ref: CS/FCI18013868/Uvd3

DATE: 1/8/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO. SLB 4559B


We thank for your instruction on 30/7/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 31/7/2018 at the premises of M/s KAH MOTOR CO SDN BERHAD and have the following to report:-

Workshop Estimate Amount	: S\$17,809.31
Revised Estimate Amount	: S\$13,511.15
"Check" Items Amount	: S\$2,496.41
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion. The chassis frame affected due to collision.



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5514Z
Vehicle Details	
Vehicle No.:	SLB4559B
Vehicle to be Exported:	No
Intended De-registration Date:	31 Jul 2018
Vehicle Make:	HONDA
Vehicle Model:	CITY 1.5 SV CVT
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	L15Z12720065
Chassis No.:	MRHGM6660GP000440
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$18,503.00
Original Registration Date:	08 Apr 2016
First Registration Date:	08 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$13,503.00 6751
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Apr 2026
PARF Rebate Amount:	\$10,127.00
Intended COE Rebate Details	
COE Expiry Date:	07 Apr 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,504.00
COE Rebate Amount:	\$34,974.00
Total Rebate Amount:	\$45,101.00
Message	

The information contained herein is correct as at 31 Jul 2018

OK

SELL YOUR CAR YOURSELF

Get listed until it's sold + we will handle all the paperwork!

POST AN AD NOW!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 5 Years Coe Renewal Toyota Vios 1.5a

\$2000 Downpayment Monthly
From \$488 Onwards. Lowest
3.68%P.A@GV Cars Financing
GV Credit Pte Ltd StarAd

VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND

HOTLINE: 6741 9997

[View our cars](#)

Browse by Category

Sort by Date Posted 20 results/page

9 vehicles

Honda City

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Honda City		Any	Any	2016	Any	Any	Any	Available
	Honda City	Honda City 1.5A SV	\$69,800	\$7,870 /yr	24-Aug-2016	1,497 cc	24,648 km	Sedan	Available
Price Just Reduced! Selling Cheapest In The Market! No Gimmicks. Accident Free. Fully Serviced By Kah Motors. Trade In And High Loan Available! Call Our Friendly Sales Person Now To Make Your Appointm...									
Mayfair Motoring									
Posted: 31-Jul-2018 Tags: 2016 Honda City, Honda City, Honda, City, Used Honda									
	Honda City	Honda City 1.5A SV	\$72,800	\$8,560 /yr	04-May-2016	1,497 cc	22,345 km	Sedan	Available
0% Down Payment Available Monthly \$1288 Or Up To 90% Loan, Flexible Bank/In House Loan Available, Subject To Approval! Fully Maintained By Kah Motor Under 5 Years Warranty Program. Buy With A Peace Of...									
AL Autocar Pte Ltd									
Posted: 28-Jul-2018 Tags: 2016 Honda City, Honda City, Honda, City, Used Honda									
	Honda City	Honda City 1.5A SV	\$72,800	\$8,430 /yr	20-Jun-2016	1,497 cc	28,700 km	Sedan	Available
Kah Motor Unit With Full Serviced History. Manufacturer Warranty Till June 2021. 160 Point Vehicle Inspection Done. Extremely Well Maintained By One Owner. Smooth Running Engine And Gearbox. Balloon M...									
Inchcape Pre-Owned									
Posted: 28-Jul-2018 Tags: 2016 Honda City, Honda City, Honda, City, Used Honda									
	Honda City	Honda City 1.5A SV	\$68,800	\$8,050 /yr	03-May-2016	1,497 cc	25,600 km	Sedan	Available
\$7K Drive Away! \$930 Monthly. Well Maintained, Low Mileage. Under Agent Warranty.									
Posted: 23-Jul-2018 Tags: 2016 Honda City, Honda City, Honda, City, Used Honda									
Car Buying Car Selling Car Ownership									
Car Aftermarket On The Move Lifestyle									
	Honda City	Honda City 1.5A SV	\$65,800	\$7,570 /yr	17-May-2016	1,497 cc	-	Sedan	Available
Just 1 Owner! Servicing And Grooming Package Available! Fuel Economy Of 15Km/L! Sporty Sedan That Comes With Extensive List Of Standard Equipment For Your Safety And Entertainment! Buy It From Us With...									
Dickson Automobile									
Posted: 23-Jul-2018 Tags: 2016 Honda City, Honda City, Honda, City, Used Honda									
	Honda City	Honda City 1.5A VTEC	\$69,800	\$7,990 /yr	03-Aug-2016	1,497 cc	34,000 km	Sedan	Available
5 Years Agent Warranty, Agent Serviced Too. Definitely Immaculate Condition Both Exterior And Interior. It's On Way, Therefore Please Check Status By Calling Or Texting Mobile Line For A Viewing Appoi...									
Henly Enterprises Co									
Posted: 21-Jul-2018 Tags: 2016 Honda City, Honda City, Honda, City, Used Honda									
Compare	Honda City	Honda City 1.5A SV (OPC)	\$61,000	\$7,120 /yr	21-Mar-2016	1,497 cc	7,800 km	Sedan	Available

Bidded Carplates For Sale!

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/07/2018 14:08
Date Of Accident	28/07/2018 11:55
Exact Location Of Accident	SERANGOON RD (NEAR TO BOON KENG RD MRT TAXI STAND)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB4559B
Insured/Policyholder	
Name Of Registered Owner	CHUA OON CHENG CAROL @ CAROL YAP
NRIC No	S1535514Z
Email Address	CHUA_OON_CHENG_CAROL@MOE.EDU.SG
Mobile Phone No	(LOCAL) +65-96391979
Alternative Phone No	OTHERS-NOPHONE

Vehicle Particulars

Manufacturer	HONDA
Model	CITY-1.5 VTEC (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USED
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	CHUA OON CHENG CAROL @ CAROL YAP
NRIC No	S1535514Z
Date Of Birth	10/06/1962
Occupation	INDOOR
Date Of Driving Pass	12/03/1986
Driving Experience	32 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96391979
Fax Number	
Contact Number	OTHERS-NOPHONE
Email Address	CHUA_OON_CHENG_CAROL@MOE.EDU.SG

Address	76 SIANG KUANG AVE
Postcode	347985
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHMENT REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC7841H
Vehicle Make/Model/Colour	/ TAXI / YELLOW
Details Of Properties	FRONT
Vehicle Category	TAXI
Name of Driver	TAN YOU MONG
NRIC/Passport Number	S2589818D
Contact Number	94847860
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Vehicle No SLB 4559B**SKETCH PLAN**

Annex D

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Please continue to Annex E

Vehicle No SLB 4559B

Annex E

Describe Circumstances of the Accident

I was travelling along Serangoon Road (towards upper Serangoon Road)
Suddenly there was a loud bang & I was thrown forward.

I stopped the car & came out of the car.

We pulled the car to the side (outside Tekong Seng Guan Store) to
exchange details & to take photograph of damage

Declaration

We declare the foregoing particulars are true in every respect.

Chua Joo Keng
28/7/18

Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SLB4559B
Chassis No : MRHGM6660GP000440
Model : CITY 1.5SV CVT 2016
Owner's Name : CHUA OON CHENG CAROL
Ins Policy No :
Date of Accident : 28/7/2018

Document No. : SQT18003156
Date : 28. Jul 2018
Customer No. : WZF002
Svc Advisor : LIEW THYE WEI
Engine No : L15Z12720065
Date | Time : 28. Jul 2018 2:32:33 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: CHUA OON CHENG CAROL @ CAROL YAP OWNER INSURER: LIBERTY INSURANCE ACC DATE: 28/07/18 SURVEYED BY: DATE: REF NO: TP INSURER: MS FIRST CAPITAL INS. LIMITED TP VEH: SHC7841H						
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	11	180.00		180.00	12.60	192.60
			Sum Ext. Service		180.00	12.60	192.60
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	3	11.20	25	25.20	1.76	26.96
73227-T9A-T00	RUBBER CWINDSHIELD DAMPER	1	17.30	25	12.97	0.91	13.88
91501-S70-003	FASTENER BW/SHIELD	2	3.20	25	4.80	0.34	5.14
91536-SS0-J01	FASTENER AW/SHIELD	2	3.50	25	5.25	0.37	5.62
91568-TF0-003	CLIPFR.WINDSHIELD.UPPER.	2	2.80	25	4.20	0.29	4.49
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
04655-T9A-T00ZZ	PANEL SETRR.FLOOR	1	408.80	25	306.60	21.46	328.06
65513-T9A-T00ZZ	STIFFENERRR.JACK UP	1	93.10	25	69.82	4.89	74.71
65540-T9A-T10ZZ	STIFFENER COMPR.RR.FRAME	1	165.00	25	123.75	8.66	132.41
65590-T9A-T10ZZ	STIFFENER COMPL.RR.FRAME	1	165.00	25	123.75	8.66	132.41
65770-T9A-T00ZZ	CROSSMEMBER COMPR.RR.FLOOR RR.	1	109.10	25	81.82	5.73	87.55
65612-T9A-T00ZZ	FRAME BR.RR.	1	75.30	25	56.47	3.95	60.42
65619-T9A-T00ZZ	FLANGERR.FRAME END	2	39.50	25	29.62	2.07	31.69
65662-T9A-T00ZZ	FRAME BL.RR.	1	79.20	25	59.40	4.16	63.56
66100-T9A-T50ZZ	PANEL COMPR.	1	323.90	25	242.92	17.00	259.92
04636-T9A-T00ZZ	PANEL SETR.RR.OUTSIDE	1	1134.80	25	851.10	59.58	910.68
63320-T9A-T00ZZ	GUTTER COMPR.RR.	1	70.40	25	52.80	3.70	56.50
04646-T9A-T00ZZ	PANEL SETL.RR.OUTSIDE	1	1134.80	25	851.10	59.58	910.68

Not Authorised
HWA
3-17/18
Take photo before parking.

11 1 180.00 180.00 12.60 192.60
Sum Ext. Service 180.00 12.60 192.60
11 3 11.20 25 25.20 1.76 26.96
1 17.30 25 12.97 0.91 13.88
2 3.20 25 4.80 0.34 5.14
2 3.50 25 5.25 0.37 5.62
2 2.80 25 4.20 0.29 4.49
1 60.00 60.00 4.20 64.20
1 408.80 25 306.60 21.46 328.06
1 93.10 25 69.82 4.89 74.71
1 165.00 25 123.75 8.66 132.41
1 165.00 25 123.75 8.66 132.41
1 109.10 25 81.82 5.73 87.55
1 75.30 25 56.47 3.95 60.42
2 39.50 25 29.62 2.07 31.69
1 79.20 25 59.40 4.16 63.56
1 323.90 25 242.92 17.00 259.92
1 1134.80 25 851.10 59.58 910.68
1 70.40 25 52.80 3.70 56.50
1 1134.80 25 851.10 59.58 910.68

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Registration No : SLB4559B

Chassis No : MRHGM6660GP000440

Model : CITY 1.5SV CVT 2016

Owner's Name : CHUA OON CHENG CAROL

Ins Policy No. :

Date of Accident : 28/7/2018

Document No. : SQT18003156 Page 2

Date : 28. Jul 2018

Customer No. : WZF002

Svc Advisor : LIEW THYE WEI

Engine No : L15Z12720065

Date | Time : 28. Jul 2018 2:32:33 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
63720-T9A-T00ZZ	GUTTER COMP L.RR.	1	70.40	25	52.80	3.70	56.50
75450-SDE-T00	OUTLET ASSYRR.AIR	1	29.00	25	21.75	1.52	23.27
68500-T9A-T30ZZ	LID COMPTRUNK	1	444.50	25	333.37	23.34	356.71
68610-T9A-T00ZZ	HINGE COMPR.TRUNK	1	67.90	25	50.92	3.56	54.48
68660-T9A-T00ZZ	HINGE COMPL.TRUNK	1	67.90	25	50.92	3.56	54.48
74865-T9A-T01	WEATHERSTRIPTRUNK LID	1	71.60	25	53.70	3.76	57.46
74851-T2A-003	LOCK ASSYTRUNK	1	89.90	25	67.42	4.72	72.14
74890-T9A-T11	GARNISH ASSYRR.LICENSE	1	62.00	25	46.50	3.26	49.76
71501-T9A-T00ZZ	FACERR.BUMPER	1	463.70	25	347.77	24.34	372.11
71503-T9A-T00	COVERRR.BUMPER EX.PIPE	1	9.60	25	7.20	0.50	7.70
71593-T9A-J00	SPACER R.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-T9A-J00	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
33505-T9A-T01	REFLECTOR ASSYR.RR.	1	14.80	25	11.10	0.78	11.88
33555-T9A-T01	REFLECTOR ASSYL.RR.	1	14.80	25	11.10	0.78	11.88
91505-TM8-003	CLIPBUMPER	4	2.00	25	6.00	0.42	6.42
75722-T9A-T00	EMBLEMRR.CITY	1	11.30	25	8.47	0.59	9.06
75701-T9A-000	EMBLEM H	1	11.00	25	8.25	0.58	8.83
75725-T9A-T00	EMBLEMRR.I-VTEC	1	11.90	25	8.92	0.62	9.54
84640-T9A-T01ZA	LINING ASSYRR.PANEL	1	66.60	25	49.95	3.50	53.45
84651-T9A-T21ZA	LINING ASSYL.TRUNK SIDE	1	47.30	25	35.47	2.48	37.95
84601-T9A-T21ZA	LINING ASSYR.TRUNK SIDE	1	46.90	25	35.17	2.46	37.63
84521-T9A-T10	LID COMPSPARE TIRE	1	43.70	25	32.77	2.29	35.06
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
33500-T9A-T01	TAILLIGHT ASSYR.	1	205.70	25	154.27	10.80	165.07
34150-T9A-T01	LIGHT ASSYR.LID	1	72.80	25	54.60	3.82	58.42
33550-T9A-T01	TAILLIGHT ASSYL.	1	205.70	25	154.27	10.80	165.07
34155-T9A-T01	LIGHT ASSYL.LID	1	72.80	25	54.60	3.82	58.42
34106-SNB-T01	LENSCOMP.	2	10.70	25	16.05	1.12	17.17
34105-SNB-003	HOUSING COMP	2	12.40	25	18.60	1.30	19.90
38387-TZ5-A01	ANTENNA ASSYL.F.	1	58.10	25	43.57	3.05	46.62

Printed on 28/7/2018 3:39:19 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

Registration No : SLB4559B
 Chassis No : MRHGM6660GP000440
 Model : CITY 1.5SV CVT 2016
 Owner's Name : CHUA OON CHENG CAROL
 Ins Policy No. :
 Date of Accident : 28/7/2018

Document No. : SQT18003156
 Date : 28. Jul 2018
 Customer No. : WZF002
 Svc Advisor : LIEW THYE WEI
 Engine No : L15Z12720065
 Date | Time : 28. Jul 2018 2:32:33 PM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
74940-SZW-003	BUZZER ASSYSMART <i>one</i>	1	60.10	25 ✓	45.07	3.15	48.22
72841-SH3-315	OILSHEET <i>one</i>	1	39.90	25 ✓	29.92	2.09	32.01
Sum Item					5109.31	357.62	5,466.93
BOSUN	SUNDRIES	1	40.00 <i>one 20</i>		40.00	2.80	42.80
BOJSE	BODY JOINT SEALANT.	1	300.00 <i>one</i>		300.00	21.00	321.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00	17.50	267.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	80.00		80.00	5.60	85.60
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	300.00		300.00	21.00	321.00
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	450.00 <i>320</i>		450.00	31.50	481.50
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	250.00		250.00	17.50	267.50
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	180.00		180.00	12.60	192.60
BOMISC1	REMOVE, REPLACE AND INSTALL SMART ENTRY SENSOR.	1	450.00 <i>300</i>		450.00	31.50	481.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	120.00		120.00	8.40	128.40
BKRP02M	CUT OFF & RENEW RR PANEL, FLOOR AND BOTH FENDER. <i>560</i>	1	6000.00 <i>4480</i>		6000.00	420.00	6420.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) <i>450</i>	1	4000.00 <i>3100</i>		4000.00	280.00	4280.00
Sum Labor					12520.00	876.40	13,396.40

Survey By Marcus LohDate & Time 31/7/18 @ 11am.Excess Status not affectedSignature Thapelo Bhepary.*14-15 day.*

17795.89
Total Amount 17,809.31 1,246.62 19,055.93

Total (Inclusive of GST) 19,055.93

Printed on 28/7/2018 3:39:19 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZF002 / MS FIRST CAPITAL
 Chassis No: MRHGM6660GP000440
 License No: SLB4559B
 Mileage: 24788
 Engine No: L15Z12720065

Document No: SVO18045078
 Printed By: ARYCHUA
 Order Date: 2. August 2018
 Order Time: 8:58:10 AM
 Service Advisor: ARY CHUA WAI NGEN

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount incld	Amount	GST
	TP DIRECT SETTLEMENT (J/NO: 70979) OWNER: CHUA OON CHENG CAROL @ CAROL YAP OWNER INSURER: LIBERTY INSURANCE ACC DATE: 28/07/18 SURVEYED BY: MARCUS (LKK) DATE: 31/7/18 @ 11.00AM REF NO: D18005744MFSH TP INSURER: MS FIRST CAPITAL INS. LIMITED TP VEH: SHC7841H							
73127-TY0-000	RUBBER CWINDOWSHIELD DAMPER	3	11.20	25	25.20	1.76		26.96
73227-T9A-T00	RUBBER CWINDOWSHIELD DAMPER	1	17.30	25	12.97	0.91		13.88
91501-S70-003	FASTENER BW/SHIELD	2	3.20	25	4.80	0.34		5.14
91536-SS0-J01	FASTENER AW/SHIELD	2	3.50	25	5.25	0.37		5.62
91568-TF0-003	CLIPFR.WINDOWSHIELD.UPPER.	2	2.80	25	4.20	0.29		4.49
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20		64.20
04655-T9A-T00ZZ	PANEL SETRR.FLOOR	1	408.80	25	306.60	21.46		328.06
65513-T9A-T00ZZ	STIFFENERRR.JACK UP	1	93.10	25	69.82	4.89		74.71
65540-T9A-T10ZZ	STIFFENER COMPR.RR.FRAME	1	165.00	25	123.75	8.66		132.41
65590-T9A-T10ZZ	STIFFENER COMPL.RR.FRAME	1	165.00	25	123.75	8.66		132.41
65770-T9A-T00ZZ	CROSSMEMBER COMPRR.FLOOR RR.	1	109.10	25	81.82	5.73		87.55
65612-T9A-T00ZZ	FRAME BR.RR.	1	75.30	25	56.47	3.95		60.42
65619-T5A-300ZZ	FLANGERR.FRAME END	2	10.80	25	16.20	1.13		17.33
65662-T9A-T00ZZ	FRAME BL.RR.	1	79.20	25	59.40	4.16		63.56
66100-T9A-T50ZZ	PANEL COMPRR.	1	323.90	25	242.92	17.00		259.92
04646-T9A-T00ZZ	PANEL SETL.RR.OUTSIDE	1	1,134.80	25	851.10	59.58		910.68
63720-T9A-T00ZZ	GUTTER COMP L.RR.	1	70.40	25	52.80	3.70		56.50
68500-T9A-T30ZZ	LID COMPTRUNK	1	444.50	25	333.37	23.34		356.71
74865-T9A-T01	WEATHERSTRIPTRUNK LID	1	71.60	25	53.70	3.76		57.46
74851-T2A-003	LOCK ASSYTRUNK	1	89.90	25	67.42	4.72		72.14
71501-T9A-T00ZZ	FACERR.BUMPER	1	463.70	25	347.77	24.34		372.11
71503-T9A-T00	COVERRR.BUMPER EX.PIPE	1	9.60	25	7.20	0.50		7.70
71593-T9A-J00	SPACER R.RR.BUMPER SIDE	1	11.50	25	8.62	0.60		9.22
71598-T9A-J00	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60		9.22
91505-TM8-003	CLIPBUMPER	4	2.00	25	6.00	0.42		6.42
75722-T9A-T00	EMBLEMRR.CITY	1	11.30	25	8.47	0.59		9.06
75701-T9A-000	EMBLEM H	1	11.00	25	8.25	0.58		8.83
75725-T9A-T00	EMBLEMRR.I-VTEC	1	11.90	25	8.92	0.62		9.54
84640-T9A-T01ZA	LINING ASSYRR.PANEL	1	66.60	25	49.95	3.50		53.45
84521-T9A-T10	LID COMPSARE TIRE	1	43.70	25	32.77	2.29		35.06
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40		342.40
33500-T9A-T01	TAILLIGHT ASSYR.	1	205.70	25	154.27	10.80		165.07
34150-T9A-T01	LIGHT ASSYR.LID	1	72.80	25	54.60	3.82		58.42
33550-T9A-T01	TAILLIGHT ASSYL.	1	205.70	25	154.27	10.80		165.07
34155-T9A-T01	LIGHT ASSYL.LID	1	72.80	25	54.60	3.82		58.42
74940-SZW-003	BUZZER ASSYSMART	1	60.10	25	45.07	3.15		48.22
72841-SH3-315	OILSHEET	1	39.90	25	29.92	2.09		32.01
	SUM PARTS:				3,850.84	269.53		4,120.37
BOSUN	0672	1	20.00		20.00	1.40		21.40

WD = 15



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZF002 / MS FIRST CAPITAL
Chassis No: MRHGM6660GP000440
License No: SLB4559B
Mileage: 24788
Engine No: L15Z12720065

Document No: SVO18045078
Printed By: ARYCHUA
Order Date: 2. August 2018
Order Time: 8:58:10 AM
Service Advisor: ARY CHUA WAI NGEE

	SUNDRIES						
BOJSE	0672	1	300.00	300.00	21.00	321.00	
	BODY JOINT SEALANT.						
BOBC	EXT-YBH	1	100.00	100.00	7.00	107.00	
	BODY UNDERSIDE COATING (N)						
BP00R	EXT-YBH	1	250.00	250.00	17.50	267.50	
	APPLY BODY UNDERSIDE COATING (N).						
BML02I	EXT-YJ	1	80.00	80.00	5.60	85.60	
	INSPECT RR LIGHTING MECHANISMS.						
	PERFORM WATER						
	TEST.(N)						
BG02D	EXT-YJ	1	300.00	300.00	21.00	321.00	
	REMOVE & INSTALL RR. WINDSCREEN.						
	(N)						
BMI02D	EXT-YJ	1	320.00	320.00	22.40	342.40	
	REMOVE & INSTALL SPEAKER BOARD						
	RR SEATS TRUNK						
	LININGS GARNISHES & ETC.(N)						
BKOT00R	EXT-YJ	1	250.00	250.00	17.50	267.50	
	REMOVE & RENEW RR FLOOR						
	INSULATOR.(N)						
BMF00D	EXT-YJ	1	180.00	180.00	12.60	192.60	
	RREMOVE & INSTALL FUEL TANK FUEL						
	PIPES.(N)						
BOMISC1	EXT-YJ	1	300.00	300.00	21.00	321.00	
	REMOVE, REPLACE AND INSTALL						
	SMART ENTRY SENSOR.						
	RESET MEMORY. (N)						
BA02R	EXT-YJ	1	120.00	120.00	8.40	128.40	
	REMOVE & RENEW REVERSE						
	SENSORS-4 PCS (N)						
BKRP02M	EXT-YJ	1	4,480.00	4,480.00	313.60	4,793.60	
	CUT OFF & RENEW RR PANEL, FLOOR						
	AND BOTH FENDER.						
	RENEW DAMAGE PARTS.						
BP06R	EXT-YBH	1	3,100.00	3,100.00	217.00	3,317.00	
	SPRAY PAINTING ON REPAIRED OR						
	REPLACED AREAS. (6P)						

SUM LABOUR: 9,800.00 686.00 10,486.00

TOTAL SGD 13,650.84 955.53 14,606.37

Total Payable (SGD) 14,606.37

GST Amount is calculated from individual line(s)

Veron Chen (LKKAUTO)

From: Ary Chua <arychua@honda.com.sg>
Sent: Saturday, 18 August 2018 10:51 AM
To: Marcus Chua (LKKAUTO); Admin A; Admin-D (LKKAUTO)
Cc: Liew Thye Wui; Faeaz
Subject: Finalise TPDS: SLB4559B (Liberty) & SHC7841H (MSFCI) DOA: 28/07/2018@11.55AM
Attachments: 4158_001.pdf

Hi Marcus Chua,

Kindly Finalise TPDS: SLB4559B (Liberty) & SHC7841H (MSFCI) DOA: 28/07/2018@11.55AM

Final Repair Costs (include GST)	\$13,650.84 + (\$955.53) = \$14,606.37
Repair Period* (Working Day)	15

***NOTES: The Repair Not Includes Public Holiday & Sunday.**

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thank you.

Best Regards,

Ary Chua Wai Ngee

Bodyshop Service Advisor Kah Motor Co.Sdn.Bhd.15 Ubi Road 4 Singapore 408610

E-mail: arychua@honda.com.sg Fax: 67480770 DID:68465673 H/P:81006306



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18013868/Uvd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 17-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7841H	Veh. Inspected	SLB 4559B	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18005744MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	30/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CITY (A)	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MRHGM6660GP000440	Colour	WHITE	
Odometer	24788	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R16	BRIDGESTONE	7 mm	
L/H Front Tyre	185/55 R16	BRIDGESTONE	7 mm	
R/H Rear Tyre	185/55 R16	BRIDGESTONE	7 mm	
L/H Rear Tyre	185/55 R16	BRIDGESTONE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. THE CHASSIS FRAME AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/07/2018	Inspection Date	31/07/2018	
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 4559B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	WHEEL ALIGNMENT X4 (SN)	NOT NECESSARY	180.00	-
3	RUBBER CWINDSHIELD DAMPER (SN)	NECESSARY	25.20	25.20
1	RUBBER CWINDSHIELD DAMPER (SN)	NECESSARY	12.97	12.97
2	FASTENER BW/SHIELD (SN)	NECESSARY	4.80	4.80
2	FASTENER AW/SHIELD (SN)	NECESSARY	5.25	5.25
2	CLIPFR.WINDSHIELD.UPPER. (SN)	NECESSARY	4.20	4.20
1	WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00
1	PANEL SETRR.FLOOR (SN)	CRUMPLED / BENT	306.60	306.60
1	STIFFENERRR.JACK UP (SN)	BENT	69.82	69.82
1	STIFFENER COMPR.RR.FRAME (SN)	BENT	123.75	123.75
1	STIFFENER COMPL.RR.FRAME (SN)	BENT	123.75	123.75
1	CROSSMEMBER COMPRR.FLOOR.RR (SN)	BUCKLED	81.82	81.82
1	FRAME BR.RR. (SN)	BADLY DENTED	56.47	56.47
2	FLANGEFR.FRAME END (SN)	DISTORTED	16.20	16.20
1	FRAME BL.RR. (SN)	DISTORTED	59.40	59.40
1	PANEL COMPRR (SN)	BADLY DENTED	242.92	242.92
1	PANEL SETR.RR.OUTSIDE (SN)	TO REPAIR SEE LABOUR	851.10	-
1	GUTTER COMPR.RR (SN)	TO REPAIR SEE LABOUR	52.80	-
1	PANEL SETL.RR.OUTSIDE (SN)	BADLY DENTED / WARPED	851.10	851.10
1	GUTTER COMP L.RR (SN)	BENT	52.80	52.80
1	OUTLET ASSYRR.AIR (SN)	NOT NECESSARY	21.75	-
1	LID COMPTRUNK (SN)	DISTORTED	333.37	333.37
1	HINGE COMPR.TRUNK (SN)	NOT NECESSARY	50.92	-
1	HINGE COMPL.TRUNK (SN)	NOT NECESSARY	50.92	-
1	WEATHERSTRIPTRUNK LID (SN)	TWISTED	53.70	53.70
1	LOCK ASSYTRUNK (SN)	TWISTED / JAMMED	67.42	67.42
1	GARNISH ASSYRR.LICENSE (SN)	NOT NECESSARY	46.50	-
1	FACERR.BUMPER (SN)	DISTORTED	347.77	347.77
1	COVERRR.BUMPER EX PIPE (SN)	TWISTED	7.20	7.20

Report Ref No. CS/FCI18013868/Uvd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPACER R.RR. BUMPER SIDE (SN)	BENT	8.62	8.62
1	SPACERL.RR.BUMPER SIDE (SN)	BENT	8.62	8.62
1	REFLECTOR ASSYR.RR. (SN)	NOT NECESSARY	11.10	-
1	REFLECTOR ASSYL.RR (SN)	NOT NECESSARY	11.10	-
4	CLIPBUMPER (SN)	NECESSARY	6.00	6.00
1	EMBLEMRR.CITY (SN)	NECESSARY	8.47	8.47
1	EMBLEM H (SN)	NECESSARY	8.25	8.25
1	EMBLEMRR.I-VTEC (SN)	NECESSARY	8.92	8.92
1	LINING ASSYRR PANEL (SN)	DISTORTED	49.95	49.95
1	LINING ASSYL.TRUNK SIDE (SN)	NOT NECESSARY	35.47	-
1	LINING ASSYR.TRUNK SIDE (SN)	NOT NECESSARY	35.17	-
1	LID COMPSPARE TIRE (SN)	TORN	32.77	32.77
4	ACT RR.SENSOR	SHORTED	320.00	320.00
1	TAILLIGHT ASSYR. (SN)	CRACKED	154.27	154.27
1	LIGHT ASSYR.LID (SN)	CRACKED	54.60	54.60
1	TAILLIGHT ASSYL (SN)	CRACKED	154.27	154.27
1	LIGHT ASSYL.LID (SN)	CRACKED	54.60	54.60
2	LENSCOMP (SN)	NOT NECESSARY	16.05	-
2	HOUSING COMP	NOT NECESSARY	18.60	-
1	ANTENNA ASSYL.F (SN)	NOT NECESSARY	43.57	-
1	BUZZER ASSYSMART (SN)	CRACKED	45.07	45.07
1	OILSHEET (SN)	NECESSARY	29.92	29.92
1	SUNDRIES (SN)	NECESSARY	40.00	20.00
			5,315.89	3,870.84
	LABOUR			
	BODY JOINT SEALANT.		300.00	300.00
	BODY UNDERSIDE COATING.		100.00	100.00
	APPLY BODY UNDERSIDE COATING.		250.00	250.00
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER.		80.00	80.00
	REMOVE & INSTALL RR WINDSCREEN.		300.00	300.00
	REMOVE & INSALL SPEAKER BOARD RR SEATS TRUNK.		450.00	320.00
	REMOVE & RENEW RR FLOOR INSULATOR.		250.00	250.00

Report Ref No. CS/FCI18013868/Uvd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & INSTALL FUEL TANK PIPES.		180.00	180.00
	REMOVE, REPLACE AND INSTALL SMART ENTRY SENSOR.		450.00	300.00
	REMOVE & RENEW REVERSE SENSOR.		120.00	120.00
	CUT OFF & RENEW RR PANEL, FLOOR AND BOTH FENDER. INCLUSIVE OF THE REPAIR OF PANEL SETR.RR.OUTSIDE AND GUTTER COMPR.RR.		6,000.00	4,480.00
	SPRAY PAINTING ON REPAIRED OR REPLACE AREAS. (6P)		4,000.00	3,100.00
			12,480.00	9,780.00
	GRAND TOTAL		17,795.89	13,650.84
RECOMMENDED COST OF REPAIRS				13,650.84

Report Ref No. CS/FCI18013868/Uvd3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.