



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving 1 2016 MERCEDES E200 AVANT GARDE
(SLG9427P)

Date of Loss 26 July 2018

Time of Loss 18.50

Loss Description SLG9427P (INSD) C/W SKA174X

Comment

Workshop Details

Total Rebate Amount 95758

Nett Loss Amount \$96,242.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (OD)

Days of work completion * 223



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SLG9427P

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

19/10/2016



Mileage

18353

Age of Vehicle

1

Driver Details

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2016	2016
Make	MERCEDES	MERCEDES BENZ
Model	E200 AVANT GARDE	E200 AVG (R18 LI

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	FARHAN TYEBALLY TYEBALLY	
Date of Birth	15 October 1990	dd/mm/yyyy
Age	28	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		▼
Type of Paint		
Chassis No	WDD2130422A060357	WDD2130422A0
Engine No	27492030696051	27492030696051
Engine Capacity		1991
Sum Insured	0	0
Market Value	0	192000

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	▼
Driving Experience	8	
Driver License #		
License Type		▼
License Issue Date	1 January 2011	dd/mm/yyyy 
License Expiration Date		dd/mm/yyyy 
Address	18 PARBURY AVENUE, 467293, Singapore	
Address type	Personal Correspondence	▼

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Male	
Marital status	Unknown	
Identification #	S9038085J	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

31/07/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

400

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Fair ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

245/45 R18

Rear Tyre Size

245/45 R18

Front left side

PIRELLI6mm

Rear left side

PIRELLI6mm

Front right side

PIRELLI6mm

Rear right side

PIRELLI6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Parts

Add Approve Deny Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		1	1			LH/ FRONT DOOR			Bent	1954.96				1954.96	Reviewing	
		2	1			LH/ FRONT DOOR WEATHERSTRIP			Necessary	280.72				280.72	Reviewing	
		3	1			LH/ FRONT DOOR INSULATION			Necessary	32.68				32.68	Reviewing	
		4	1			LH/ FRONT DOOR ORNAMENTAL MOULDING			Necessary	89.01				89.01	Reviewing	
		5	1			LH/ FRONT DOOR SEALING RAIL			Necessary	95.9				95.9	Reviewing	
		6	1			LH/ FRONT DOOR TOP ORNAMENTAL TRIM			Necessary	149.82				149.82	Reviewing	

Labour

Add Approve Deny Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
------	-------	-------------------------	-----------	------------	---------------	-------	-----------------	---------	--------

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH	480	0	0	Reviewing		
		2		RESPRAY LH/FRONT DOOR	600	0	0	Reviewing		
		3		USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD	380	0	0	Reviewing		
		4		REMOVE & TRANSFER DOOR MECHANICAL & ELECTRICAL INSTALL TO NEW DOOR	400	0	0	Reviewing		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE



1

DAYS
OF
REPAIR
: 3
DAYS

Reviewing





SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount

\$4,063.09

Claim Amount

\$4,063.09

CATEGORY

ESTIMATE

REVISED AMOUNT

Spare Parts

\$2,603.09

\$2,603.09

Labour

\$1,860.00

\$1,860.00

Excess

-\$400.00

-\$400.00

[Submit for Review](#)