

ASS. REC. BY:

REF: cs/MSG18013873/Kvd3

Special Instruction:

Survivor:
merimen Kenneth

ASSIGNMENT (Office)

From (Person): Catherine Chia of MSIG

Date/Time: 31/7/18 @ 11:51am

Estimated Cost:

Bill to:

OD / IP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLV 3299C

Insured: YN 7046C

at Workshop m/s Lian Hong Seng Motor

Tel: 6484 3683

of 81k 5035, AMK Ind. Park 2# 01-345

Policy No: A29068646 MKC

Claim No: 565597

Sum Insured:

Excess:

Make of Veh:

D.O.A. 22/07/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

cup

H.O.D. Endorsement:

Date/Time: 12:09pm @ 31/7/18

Person Contacted:

Apple

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLV 3299C - X

YN 7046C - X

1/8/18

@ 3:02pm Informed Apple net value \$23000, will check

2/8/18

@ 10:33am Apple will check with MSIG liability first

3/8/18

Send preli revised via merimen

ASS. REC. BY:

REF: MSG/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s Lian Lory Bay

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$85k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 24 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLV329PC Yr Regn: 12, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Make: Kia Cars A1 Wagon c.c. 1685

Colour: M. Brown A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAI4U815VJ7195404

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD ATRM or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Nexen

Front

R/Bal. 4 mm

L/Bal. 4 mm

D.O.A. 22/7/18

Rear

R/Bal. 8 mm

L/Bal. 8 mm

D.O.I. 31/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1/8</u>	<u>File pass to Catherine</u>
<u>13/8/18 @ 4:43pm</u>	<u>Apple said still pending from msg reply</u>
<u>16/8/18 @ 5:26pm</u>	<u>Informed Christina MV: \$85K (Est)</u>
<u>9/10/18 @ 10:29am</u>	<u>Apple said pending for spare parts (air-freight)</u>
<u>16/10/18 @ 11:11am</u>	<u>Confirmed LS \$25000 with Apple (Real 97, 95.89, 80%)</u>

Note: MV: \$85K (Est) LTA: \$61,621 NV: \$23,379

RECEIVED 16 OCT 2018

Date/Time, File Pass to?

- : Prell. Report
- : Final Report

Days Of Repair: 24

Resurvey No. of Trip: 1

Date/Time, File Return to?

1) 16/10 - typist

- Add Fee: : Site Insp (\$)
- : Interview (\$)
- : Tech Invs (\$)
- : Weekend (\$)

Survey Fee:	<u>300</u>
Transportation:	
S - RS - SI	
Fixturs	
Others	<u>10</u>
TOTAL	<u>310</u>

Report Format: _____

Lump Sum / I.B.I: (\$ 25,000/-)

merimen



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18013873/Kvd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 31-07-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 7046C	Veh. Inspected	SLV 3299C
Policy No.	A29068646MKC	Coverage (\$)	0.00
Claim No.	565597	Excess (\$)	0.00
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	31/07/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	22/07/2018	Inspection Date	31/07/2018
Survey held at	LIAN HONG SENG MOTOR WORKS BLK 5035 ANG MO KIO IND.PARK 2 #01-345 SINGAPORE 569537		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Jul 2018		31 Jul 2018 11:51 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	POWERCOM ENGINEERING WORKS PTE. LTD., Co. Reg. No.: 200820640C								
Main Claimant:	BIS MOTORING PTE. LTD., Co. Reg. No.: 201735055D								
Vehicle Reg. No.:	SLV3299C	Date of Loss:	22/07/2018 15:00 - :59 [6 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 565597	Policy/Cover Note No.:	A29068646MKC (TP, Fire & Theft) Coverage: 09/02/2018 - 08/02/2019						
Vehicle Reg. No. (Insured):	YN7046C	Policy No. (Claimant):							
		Excess:							
Repairer:	Lian Hong Seng Motor Works - Ang Mo Kio (HQ) BLK 5035 ANG MO KIO IND.PARK 2 #01-345, 569537 Ang Mo Kio - Tel: 64843683 96159830 96754083								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 01/08/2018]								
Driver/Custodian (Insured):	MOHADEB (), NRIC: G8368463T, Tel: +6581395697								
Adj Asg. Remarks:	liability: 50/50. TP agree with SJE - Assign LKK Auto Consultants Pte Ltd. Request to survey today (31/07/2018).								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: LHS MotorWorks <lhsautotrading@gmail.com>
Sent: Tuesday, 14 August 2018 3:21 PM
To: SUR
Subject: Fwd: Accident Involving Vehicle No : SLV 3299C & YN 7046C DOA: 22.07.2018 - your ref: 565597

Hi,
Fya,
Thanks

Have a nice day...

Best Regards,
Apple Sim

Lian Hong Seng Motor Works
Blk 5035, Ang mo Kio Industrial Park 2
#01-345, Singapore 569538
Tel : +65 6484 3683 Fax : +65 6612 7495
Email : LHSAutoTrading@gmail.com

----- Forwarded message -----

From: Lionel Tan <lionel_tan@sg.msig-asia.com>
Date: Tue, Aug 14, 2018 at 2:59 PM
Subject: RE: Accident Involving Vehicle No : SLV 3299C & YN 7046C DOA: 22.07.2018 - your ref: 565597
To: lhsautotrading@gmail.com <lhsautotrading@gmail.com>

WITHOUT PREJUDICE

Dear Sir/Madam,

Liability is clear in your client favour and you can direct settle with us.

Please note that Loss of Use/Loss of Rental is strictly to our surveyor's recommendation on the duration of repairs, Saturdays included.

Kindly forward your claim documents via email to claims@sg.msig-asia.com and/or post to our office, quoting our reference.

Thank you

Best Regards,

Lionel Tan

Executive, Claims Services (Motor)

D: +65 6643 1307 | F: +65 6225 7402 | lionel_tan@sg.msig-asia.com

From: LHS MotorWorks [<mailto:lhsautotrading@gmail.com>]

Sent: Tuesday, August 14, 2018 10:32 AM

To: Catherine Thia <catherine_thia@sg.msig-asia.com>

Subject: Re: Accident Involving Vehicle No : SLV 3299C & YN 7046C DOA: 22.07.2018 - your ref: 565597

Hi Ms.Thia ,

Please advise us this claim liability.

Kindly revert back soonest possible.

Thanks

(Urgent)

Have a nice day...

Best Regards,

Apple Sim

Lian Hong Seng Motor Works

Blk 5035, Ang mo Kio Industrial Park 2

#01-345, Singapore 569538

Tel : +65 6484 3683 Fax : +65 6612 7495

Email : LHSAutoTrading@gmail.com

On Thu, Aug 2, 2018 at 1:45 PM LHS MotorWorks <lhsautotrading@gmail.com> wrote:

Dear Sir/Madam ,

We enclose herewith attached of video footage for your further action.

Please advise us this claim liability is it clear?

Kindly revert back us soonest possible.

Thanks

(Urgent)

 WhatsApp Video 2018-07-27 at 12.55.07.mp4

Have a nice day...

Best Regards,

Apple Sim

Lian Hong Seng Motor Works

Blk 5035, Ang mo Kio Industrial Park 2

#01-345, Singapore 569538

Tel : +65 6484 3683 Fax : +65 6612 7495

Email : LHSAutoTrading@gmail.com

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Catherine Thia Shi Yi	Date: 03 Aug 2018

Preliminary Advice

Insured Vehicle No	: YN7046C		
TP Vehicle No	: SLV3299C	Accident Date	: 22/07/2018
Make	: KIA CARENS	Assignment Date	: 31/07/2018
Date of Inspection	: 31/07/2018	Est. Duration of Repair	: 24.00
Inspection At	: LIAN HONG SENG MOTOR WORKS - ANG MO KIO (HQ) BLK 5035 ANG MO KIO IND.PARK 2 #01-345 SINGAPORE 569537		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion. The undercarriage and body structure affected due to collision and parts claimed are consistent to the accident.

	Repairer's Estimate (Gross)	:S\$	122,295.89
	Revised Amount	:S\$	36,933.89
	Check Items (Estimated)	:S\$	80,071.03
	Total	:S\$	117,004.92
	Lump Sum Repair	:S\$	

Total Loss Consideration

	New for Old Value	:S\$	
	Pre-Accident Value	:S\$	
	COE / PARF Rebate	:S\$	
	Salvage Value	:S\$	
	Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5055D
Vehicle Details	
Vehicle No.:	SLV3299C
Vehicle to be Exported:	No
Intended De-registration Date:	01 Aug 2018
Vehicle Make:	KIA
Vehicle Model:	CARENS 1.7 DCT DIESEL 5DR FWD
Primary Colour:	Brown
Manufacturing Year:	2017
Engine No.:	D4FDHH547612
Chassis No.:	KNAHU815VJ7195404
Maximum Power Output:	104.0 kW (139 bhp)
Open Market Value:	\$19,822.00
Original Registration Date:	28 Dec 2017
First Registration Date:	28 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$14,822.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Dec 2027
PARF Rebate Amount:	\$11,116.00
Intended COE Rebate Details	
COE Expiry Date:	27 Dec 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,711.00
COE Rebate Amount:	\$50,505.00
Total Rebate Amount:	\$61,621.00

The information contained herein is correct as at 01 Aug 2018

OK



Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

New 5 Years Coe Renewal Toyota Estima 2.4A



\$5800 Downpayment Monthly From \$938 Onwards. Lowest 3.68%P.A@GV Cars Financing GV Credit Pte Ltd StarAd



Browse by Category

Sort by Date Posted 20 results/page

2 vehicles

kia carens

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	kia carens		Any	Any	2016	Any	Any	Any	Available
	Kia Carens	2.0A	\$79,800	\$8,980 /yr	21-Mar-2016	1,999 cc	19,754 km	MPV	Available
\$2000 Republic Auto Warranty Workshop Credit. Maintained By Cycle & Carriage, Still Under Warranty By Cycle Carriage Until Mar 2021, Almost Brand New Condition And Well Taken Care By 1 Owner. Buy With... Republic Auto Posted: 30-Jul-2018 Tags: 2016 Kia Carens, Kia Carens, Kia, Carens, Used Kia									
	Kia Carens	2.0A	\$83,900	\$9,780 /yr	19-Jan-2016	1,999 cc	35,000 km	MPV	Available
Economical 7-Seater MPV. Blue Kia Carens 2.0A With Premium Black Leather Upholstery Owned By Just 1 Owner Selling Due To Upgrading. Still Under Warranty By Cycle & Carriage. Well Maintained With Very ... Posted: 25-May-2018 Tags: 2016 Kia Carens, Kia Carens, Kia, Carens, Used Kia									

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classified for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used kia carens, kia carens Singapore, used kia carens Singapore, used kia carens, used vehicles Singapore or even buy used kia carens Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap Terms of Service | Privacy Policy | Personal Data Protection Statement
©2004-2018 sgCarMart. All rights reserved.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 5055D

Vehicle Details

Vehicle No.: SLV3299C
Vehicle to be Exported: Yes
Intended De-registration Date: 27 Jul 2018
Vehicle Make: KIA
Vehicle Model: CARENS 1.7 DCT DIESEL 5DR FWD
Primary Colour: Brown
Manufacturing Year: 2017
Engine No.: D4FDHH547612
Chassis No.: KNAHU815VJ7195404
Maximum Power Output: 104.0 kW (139 bhp)
Open Market Value: \$19,822.00
Original Registration Date: 28 Dec 2017
First Registration Date: 28 Dec 2017
Transfer Count: 0
Actual ARF Paid: \$14,822.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 27 Dec 2027
PARF Rebate Amount: \$11,116.00

Intended COE Rebate Details

COE Expiry Date: 27 Dec 2027
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$53,711.00
COE Rebate Amount: \$42,968.00
Total Rebate Amount: \$54,084.00

The information contained herein is correct as at 27 Jul 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/07/2018 14:41
Date Of Accident	22/07/2018 15:30
Exact Location Of Accident	BUKIT BATOK WEST AVE 6 / BUKIT BATOK WEST AVE 8
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLV3299C
Insured/Policyholder	
Name Of Registered Owner	BIS MOTORING PTE. LTD.
Co Reg No	201735055D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-85098196

Vehicle Particulars

Manufacturer	KIA
Model	CARENS 1.7 DCT DIESEL 5DR FWD
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5096898757 PREMIUM
Cover Note Number	

Driver

Name of Driver	MUHAMMAD NIDZAMUDDIN BIN M ASARI
NRIC No	S8526975E
Date Of Birth	25/08/1985
Occupation	OUTDOOR
Date Of Driving Pass	30/11/2005
Driving Experience	12 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81456998
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	BLK 146 BUKIT BATOK WEST AVE 6 #10-343
Postcode	650146
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : MUHAMMAD NADHIR HILMI BIN MUHAMMAD NIDZAMUDDIN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT BATOK NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 21 BUKIT BATOK EAST AVE 4 , POSTCODE: 659840 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-6659999 - FAX NO: 66655793
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN7046C
Vehicle Make/Model/Colour	MINI FE639ETOSRDE
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MOHADEB
NRIC/Passport Number	G8368463T
Contact Number	81395697

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name MUHAMMAD NIDZAMUDDIN BIN M ASARI
Approximate Age
Injuries Sustain CHEST PAIN, LEFT EAR BUZZING, LEFT HIP PAIN, NECK PAIN
Injured person in which vehicle? SLV3299C
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? YES
Address
Postcode

DETAILS OF INJURED PERSON 2

Name •MUHAMMAD NADHIR HILMI BIN MUHAMMAD NIDZAMUDDIN
Approximate Age
Injuries Sustain
Injured person in which vehicle? SLV3299C
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? YES
Address
Postcode

Sketch Plan Pg. 1

RECEIVED 21/03/2018 16:46
TEL 6749 2305

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

27 JUL 2018

IDAC KAKI BUKIT (VAC)
 23 Kaki Bukit Ave 4
 Singapore 415933
 Tel: 67416697 Fax: 67492305
 Email: vackb@singnet.com.sg


Report made by the Insurer's Signature
 Name:
 NRIC/FIN No.:

Sketch Plan #2 Pg. 1

RECEIVED 21/03/2018 16:46
-65 8868 0742

21-03-18 16:30

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to the Police Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

27 JUL 2018

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@singnet.com.sg

Reporting Name:
NRIC/FIN No.:



Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/07/2018 03:03	Vide Report No.:	Station Diary No.: 11
--	------------------	--------------------------

Informant's Particulars			
Name of Informant: MUHAMMAD NIDZAMUDDIN BIN M ASARI		Address: APT BLK 146 BUKIT BATOK WEST AVENUE 6 #10-343 SINGAPORE 650146	
ID Type / ID No.: NRIC NO / S8526975E		Contact No.: Home/Office: Mobile: 81456998	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 32	Date of Birth: 25/08/1985	Type of Informant: Driver
Race: Boyanese		Language:	Institution / School Name:
Occupation: PRIVATE HIRER DRIVER		Driving Licence Information: Class: 2B,2A,2,3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 22/07/2018 15:30	Type of Location: X-Junction
Location: Along Road 1 BUKIT BATOK WEST AVENUE 6				
Approaching the junction between bukit batok west avenue 6 and bukit batok west avenue 8.				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision:				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLV3299C	Car				Seriously Damaged	1
YN7046C	Lorry					0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

Report No. T/20180723/2008

CONTINUATION OF REPORT

Driver			
Name	MUHAMMAD NIDZAMUDDIN BIN M ASARI	ID No.	S8526975E
Related Vehicle	NIL	Contact No.	81456998
Hospital/Clinic	NATIONAL UNIVERSITY HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	22/07/2018	Date Discharge	22/07/2018
No. of Days granted Medical Leave	03	Degree of Injury	NIL
Driver			
Name	Mohadeb	ID No.	G8368463T
Related Vehicle	NIL	Contact No.	81395697
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 22/07/2018 at around 1530hrs I was driving along Bukit batok west avenue 6 approaching the junction between Bukit batok west avenue 6 and Bukit batok west avenue 8. As the traffic was still lit green I was trying to cross the junction, at the moment I heard a bike horn. I tried to find out from where the sound was coming from at that moment a lorry (YN7046C) travelling along Bukit batok west 8 was driving past in front of me. As I did not have enough time to react I ended up colliding with the vehicle. We spun out of control and blocked the path along Bukit batok west avenue 8. When we spun out of control the lorry went on to hit a nearby traffic light.

There was a motorcyclist namely Hairil, H/P: 83180259, who came down to help and he called the ambulance. He is also a witness to the incident. Me and my Son (Muhammad Nadhir Hilmi) aged 12 were conveyed to the NUH. I suffered some discomfort in the chest area, left hip, I have some buzzing noises in my ear. I was given 3 days of MC, MC reference: NUH18187635

I like to highlight that I had the right of way at the moment of the accident.

My car has in-car camera, and it recorded the incident.

Traffic police and ambulance were at the scene.



**SINGAPORE
POLICE FORCE**



T/20180723/2008

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

3 of 4

Report No. T/20180723/2008

CONTINUATION OF REPORT



Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

Report No. T/20180723/2008

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: J/ Sgt 2 PRAKASH S/O SANGHA	
Signature Of Interpreter: Not applicable	
Officer In Charge Of Case: TP / GIT / Staff Sgt MOHAMMAD ZULKARNIAN BIN 4 SAMSUDIN Contact No: 65476429	

Signature Of Informant:	
Date/Time: 23/07/2018 03:03	
Classification Of Case:	

Authentication Stamp
NP158
Signature :
Singapore Police Force

Not Authorized
 C1 Lyn @ ?, Till 011 ??

Kenneth
 96910663

[Signature]
 6/8/18

LIAN HONG SENG

MOTOR WORKS

5035 ANG MO KIO INDUSTRIAL PARK 2
 #01-345 SINGAPORE 569538

DATE: 22/7/2018
 VEHICLE NO: SLV3299C
 MODEL: KIA CAREN
 ACCIDENT DATE:
 TYPE OF CLAIM: TP
 CLAIM ADVISOR:

ESTIMATE

ATTN:

DESCRIPTION	QTY	LIST PRICE
PARTS		
FRONT WINDSCREEN	1	CM \$ 1,126.50
FRONT WINDSCREEN MOULDING	1	M \$ 188.60
RH FRONT WINDSCREEN PILLAR	1	R \$ 653.10
LH FRONT WINDSCREEN PILLAR	1	REPAIR
FRONT WIPER GARNISH	1	CM \$ 456.10
FRONT WIPER ARM	2	\$ ^{SL} 150.60
FRONT WIPER BLADE	2	\$ ^{SL} 44.80
FRONT WIPER LINKAGE	1	\$ ^{IR} 347.10
FRONT BONNET	1	R \$ 1,043.70
FRONT BONNET LOCK	1	R \$ 213.20
FRONT BONNET LOCK CABLE	1	JM \$ 134.10
FRONT BONNET STOPPER	2	MT \$ 22.40
FRONT BONNET STAND	1	\$ ^{MT} 98.70
FRONT BONNET STAND CLIP	1	\$ ^M 14.10
FRONT BONNET STAND GOMMET	1	\$ ^{MT} 15.20
FRONT GRILLE	1	M ¹ \$ 416.70
FRONT GRILLE CHROME MOULDING	1	M ¹ \$ 256.50
FRONT GRILLE CLIPS	10	M \$ 30.00
FRONT EMBLEM	1	M ¹ \$ 75.40
FRONT BUMPER	1	M ¹ \$ 785.30
FRONT BUMPER CLIPS	10	M \$ 30.00
FRONT BUMPER RETAINER	2	CM \$ 144.60
FRONT BUMPER BRACKET	2	\$ ^R 188.60
FRONT BUMPER LOWER CENTRE GRILL	1	M ¹ \$ 289.40
FRONT BUMPER LOWER SPOILER	1	M ¹ \$ 365.10
FRONT SENSOR	4	\$ ^{SL} 788.40
FRONT SENSOR HOLDER	4	\$ ^{SL} 84.80
FRONT SENSOR HARNESS	1	\$ 3,167.50
FRONT BUMPER SPONGE	1	M ¹ \$ 215.30
FRONT REINFORCEMENT	1	R \$ 465.60
SUPPORT PANEL	1	R \$ 784.50

[Handwritten checkmarks and symbols in the right margin]

LIAN HONG SENG

MOTOR WORKS

5035 ANG MO KIO INDUSTRIAL PARK 2
#01-345 SINGAPORE 569538

DATE: 22/7/2018
VEHICLE NO: SLV3299C
MODEL: KIA CAREN

DESCRIPTION	QTY	UNIT	PRICE	TOTAL
HORN	2	PCS	\$ 196.80	
HEADLAMP PANEL	2	Assembled	\$ 674.20	
HEADLAMP	2	Br	\$ 2,146.40	
FOGLAMP	2	MIS	\$ 520.60	
FOGLAMP COVER	2	MIS	\$ 166.40	
RH FRONT FENDER	1	Br	\$ 541.50	
RH FRONT FENDER INNER SHIELD	1	CM	\$ 211.30	
RH FRONT FENDER INNER SHIELD CLIPS	10	IN	\$ 30.00	
RH FRONT FENDER INNER PANEL	1	Br	\$ 298.70	
RH FRONT FENDER INNER GARNISH	1	CM	\$ 187.50	
RH FRONT WHEEL HOUSE	1	Br	\$ 891.30	
RH FRONT CHASSIS	1	R	\$ 1,325.70	
RH FRONT CHASSIS BRACKET	1	R	\$ 199.40	
RH FRONT QUARTER GLASS	1	Shorter	\$ 351.20	
RH FRONT QUARTER GLASS CHROME MOULDING	1	Br	\$ 243.50	
RH FRONT A PILLAR	1			REPAIR
RH FRONT DOOR	1	R	\$ 1,097.50	
RH FRONT ABSORBER TOP MOUNTING	1	Br	\$ 198.70	
RH FRONT ABSORBER	1	Br	\$ 348.10	
RH FRONT KNUCKLE ARM	1	Br	\$ 332.10	
RH FRONT LOWER ARM	1		\$ 298.70	
RH FRONT TIE ROD END	1		\$ 199.60	
RH FRONT TIE ROD	1		\$ 178.60	
RH FRONT WHEEL HUB	1		\$ 312.10	
RH FRONT WHEEL HUB BEARING	1		\$ 211.20	
RH FRONT DRIVE SHAFT	1		\$ 1,435.10	
RH FRONT STABILIZER LINK	1		\$ 167.50	
RH FRONT ABS SENSOR	1		\$ 324.70	
STABILIZER BAR	1		\$ 423.10	
STABILIZER BAR BUSH	2		\$ 122.40	
FRONT CROSSMEMBER	1		\$ 1,243.80	
FRONT CROSSMEMBER BUSH	4		\$ 242.40	
LH FRONT ABSORBER TOP MOUNTING	4		\$ 198.70	
LH FRONT ABSORBER	1		\$ 348.10	
LH FRONT KNUCKLE ARM	1	Br	\$ 332.10	
LH FRONT LOWER ARM	1	Br	\$ 298.70	
LH FRONT TIE ROD END	1	Br	\$ 199.60	

Handwritten notes and markings on the right side of the invoice, including checkmarks, 'X', and 'Senx'.

16097.30

LIAN HONG SENG

MOTOR WORKS

5035 ANG MO KIO INDUSTRIAL PARK 2
#01-345 SINGAPORE 569538

DATE: 22/7/2018
VEHICLE NO: SLV3299C
MODEL: KIA CAREN

LH FRONT TIE ROD	1		\$	178.60	} Su A
LH FRONT WHEEL HUB	1		\$	312.10	
LH FRONT WHEEL HUB BEARING	1		\$	211.20	
LH FRONT DRIVE SHAFT	1		\$	1,435.10	
LH FRONT STABILIZER LINK	1		\$	167.50	
LH FRONT ABS SENSOR	1		\$	324.70	}
STEERING RACK	1	BH	\$	3,547.10	
ENGINE LOWER DASH COVER	1	CM		321.40	—
ENGINE LOWER DASH COVER CLIPS	10	M	\$	30.00	—
LH FRONT FENDER	1	BH	\$	541.50	—
LH FRONT FENDER INNER SHIELD	1	CM	\$	211.30	—
LH FRONT FENDER INNER SHIELD CLIPS	10	M	\$	30.00	—
LH FRONT FENDER INNER PANEL	1	M	\$	298.70	X
LH FRONT FENDER INNER GARNISH	1	Su	\$	187.50	X
LH FRONT WHEEL HOUSE	1			REPAIR	
LH FRONT CHASSIS	1			REPAIR	
LH FRONT CHASSIS BRACKET	1	M	\$	199.40	X
LH FRONT QUARTER GLASS CHROME MOULDING	1	Sr	\$	243.50	X
LH FRONT A PILLAR	1			REPAIR	
LH FRONT DOOR	1			REPAIR	
CONDENSER	1	BH	\$	976.10	—
CONDENSER AIRGUIDE	2	CM	\$	212.40	—
CONDENSER FAN COWLING	1	CM	\$	297.60	—
CONDENSER FAN BLADE	1		\$	155.60	} Su X
CONDENSER FAN MOTOR	1		\$	312.10	
SUCTION PIPE	1		\$	410.70	}
LIQUID PIPE	1		\$	378.30	
DISCHARGE PIPE	1		\$	399.50	}
RADIATOR	1	1 hour hrs		988.40	
RADIATOR UPPER BUSH	2		\$ Su	44.40	X
RADIATOR LOWER BUSH	2		\$ Su	44.20	
RADIATOR TOP BRACKET	2	BH	\$	42.80	—
RADIATOR FAN COWLING	1	CM	\$	297.60	—
RADIATOR FAN MOTOR	1	M	\$	155.60	—
RADIATOR FAN BLADE	1	D, 1	\$	312.10	—
RADIATOR TOP HOSE	1		\$ T	166.70	—
RADIATOR BOTTOM HOSE	1	Su	\$	165.70	X

13590.40

LIAN HONG SENG

MOTOR WORKS

5035 ANG MO KIO INDUSTRIAL PARK 2
#01-345 SINGAPORE 569538

DATE: 22/7/2018
VEHICLE NO: SLV3299C
MODEL: KIA CAREN

RESERVE TANK	1	RM \$	236.70
INTERCOOLER	1	RM \$	1,032.40
INTERCOOLER HOSE	2	\$Sen	264.20
WIPER TANK	1	RM \$	134.10
WIPER TANK MOTOR	2	\$Sen	227.60
INLET MANIFOLD	1	CM \$	945.50
O2 SENSOR	1	\$Sen	211.30
ABS PUMP	1	\$Sen	2,586.30
AIR CLEANER BOX	1	CM \$	431.50
AIR DUCT	1	CM \$	221.30
BATTERY TRAY	1	\$Sen	189.40
BATTERY BRACKET	1	R \$	155.60
FUSE BOX	1	Sen \$	2,904.10
FUSE BOX WIRE HARNESS	1	R \$	2,884.40
ENGINE TOP COVER	1	CM \$	342.90
ENGINE OIL LIP STICK	1	Sen \$	188.30
ENGINE MOUNTING SET	3	\$	1,266.90
ENGINE MOUNTING BRACKET SET	3	\$	1,124.60
ALTERNATOR	1	\$	1,342.10
WATER PUMP	1	\$	543.80
FAN BELT	1	\$	101.20
TENSIONER	1	\$	294.50
TENSIONER BEARING	1	\$	150.40
TIMING COVER	1	\$	211.60
FRONT IMPACT SENSOR	1	\$	396.80
FRONT DRIVER AIRBAG	1	Auth \$	1,347.80
FRONT AIR BAG COCK SPRING	1	RM \$	453.10
FRONT AIRBAG CONTROL UNIT	1	Auth \$	1,774.80
FRONT PASSENGER AIRBAG	1	Auth \$	1,453.20

Handwritten checkmarks and notes on the right side of the table, including "See X" and various symbols.

108

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

23416.40

LIAN HONG SENG

MOTOR WORKS

5035 ANG MO KIO INDUSTRIAL PARK 2
#01-345 SINGAPORE 569538

DATE: 22/7/2018
VEHICLE NO: SLV3299C
MODEL: KIA CAREN

FRONT DASHBOARD	1	<i>Th</i>	\$ 1,173.10	<i>✓</i>
FRONT SEAT BELT	2	<i>Th</i>	\$ 1,446.20	<i>✓</i>
FRONT SEAT BELT BUCKLE	2	<i>Sm</i>	\$ 986.40	<i>✗</i>
FRONT WINDSCREEN PILLAR INNER GARNISH	2	<i>R</i>	\$ 422.60	<i>✗</i>
ENGINE ASSY	1	<i>Sm</i>	\$ 34,231.70	<i>✗</i>
GEAR BOX ASSY	1	<i>Sm</i>	\$ 19,864.50	<i>✗</i>

TOTAL: \$ 123,912.10
DISCOUNT 10%: \$ 12,391.21
\$ 111,520.89

38124 50
124233-50
111810-15

S/NET

FRONT WINDSCREEN SEALANT	1	<i>Nu</i>	\$ 100.00	<i>40sm</i>
COOLANT	1	<i>Nu</i>	\$ 100.00	<i>20sm</i>
ENGINE OIL	1	<i>NuS</i>	\$ 150.00	<i>✗</i>
ATF OIL	1	<i>Nu</i>	\$ 150.00	<i>40sm</i>
OIL FILTER	1	<i>\$ Nu</i>	\$ 20.00	<i>✗</i>
FRONT NUMBER PLATE	1	<i>NuS</i>	\$ 45.00	<i>✓</i>
FRONT PANEL SEALANT	1	<i>NuS</i>	\$ 80.00	<i>✓</i>
IU STICKER	1	<i>Nu</i>	\$ 45.00	<i>20sm</i>
BATTERY	1	<i>\$ Sm</i>	\$ 180.00	<i>✗</i>
BRAKE FLUID	1	<i>\$ Sm</i>	\$ 50.00	<i>✗</i>
FRONT TYRE	2	<i>\$ Sm</i>	\$ 45.00	<i>✗</i>
TOTAL			\$ 965.00	

LABOUR

LABOUR	PRICE
LABOUR FOR FACILITATE REPAIR - FRONT PORTION	\$ 3,000.00
TO RESPRAT AFFECTED AREAS - FRONT PORTION	\$ 2,800.00
TO CHECK AND RECONNECT ALL NECESSARY WIRING	\$ 50.00
TO REMOVE AND REFIT AC CONDENSER INCLUDING TOP UP AC GAS	\$ 150.00
TO REMOVE AND REFIT RADIATOR INCLUDING WATER PRESSURE TEST	\$ 150.00
TO REMOVE AND REFIT FRONT WINDSCREEN	\$ 150.00
TO REMOVE AND REFIT RH FRONT QUARTER GLASS	\$ 100.00

2200l
1400l
✓
100l
50l
120l
40l

LIAN HONG SENG

MOTOR WORKS

5035 ANG MO KIO INDUSTRIAL PARK 2
#01-345 SINGAPORE 569538

DATE: 22/7/2018
VEHICLE NO: SLV3299C
MODEL: KIA CAREN

TO REMOVE AND REFIT ENGINE, ENGINE MOUNTING FOR FACILITATE REPAIR	\$	350.00	<i>2801</i>
TO REMOVE AND REFIT GEAR BOX	\$	80.00	<i>✓</i>
TO REMOVE AND REFIT ABS PUMP	\$	300.00	<i>1201</i>
TO REMOVE AND REFIT FRONT AIRBAG	\$	350.00	<i>2501</i>
TO REMOVE AND REFIT AIRBAG CONTROL UNIT AND RESET	\$	350.00	<i>2201</i>
TO REMOVE REFIT FRONT DASHBOARD	\$	350.00	<i>2501</i>
TO REMOVE AND REFIT FRONT SEAT BELT AND BUCKLE AND REFIT SEAT BELT WARNING LIGHT	\$	250.00	<i>1201</i>
TO REMOVE AND REFIT BOTH FRONT UNDERCARRIAGE INCLUDING CROSSMEMBER	\$	500.00	<i>3201</i>
TO REMOVE AND REFIT FRONT ABS SENSOR	<i>Ans</i>	250.00	<i>X</i>
TO BLEED AND TEST BRAKING SYSTEM	\$	100.00	<i>201</i>
TO STRAIGHTEN AND ALIGN FRONT FRAME CHASSIS	\$	350.00	<i>2501</i>
SUNDARIES	<i>Ans</i>	80.00	<i>X</i>
RUST PROOFING	\$	100.00	<i>✓</i>
TOTAL: \$		9,810.00	
TOTAL: \$		122,295.89	

122 585.15

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Jul 2018		31 Jul 2018 11:51 Edit Adj Rpt	S\$25,000.00 Edit Estimates	S\$25,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	POWERCOM ENGINEERING WORKS PTE. LTD. , Co. Reg. No.: 200820640C								
Main Claimant:	BIS MOTORING PTE. LTD. , Co. Reg. No.: 201735055D								
Vehicle Reg. No.:	SLV3299C	Date of Loss:	22/07/2018 15:00 - :59 [6 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 565597	Policy/Cover Note No.:	A29068646MKC (TP, Fire & Theft) Coverage: 09/02/2018 - 08/02/2019						
Vehicle Reg. No. (Insured):	YN7046C	Policy No. (Claimant):							
		Excess:							
Repairer:	Lian Hong Seng Motor Works - Ang Mo Kio (HQ) BLK 5035 ANG MO KIO IND.PARK 2 #01-345, 569537 Ang Mo Kio - Tel: 64843683 96159830 96754083								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 30/08/2018]								
Driver/Custodian (Insured):	MOHADEB (), NRIC: G8368463T, Tel: +6581395697								
Adj Asg. Remarks:	liability: 50/50. TP agree with SJE - Assign LKK Auto Consultants Pte Ltd. Request to survey today (31/07/2018).								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLV3299C (565597)
 [YN7046C]
 TP
 BIS MOTORING PTE. LTD.
 Jul 22 2018 3:00PM
 [POWERCOM ENGINEERING WORKS PTE. LTD.]
 Lian Hong Seng Motor Works - Ang Mo Kio

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page v <input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/08/18 14:32	Video - Accident	Load MP4	<input type="checkbox"/>
Assessment Reports			1 per page v <input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	31/07/18 09:11	Accident Statement <small>From: SC - Reg. No: YN7046C, Claimant: POWERCOM ENGINEERING WORKS PTE. LTD.</small>	Load HTM	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/08/18 12:53	Adjuster Immediate Advice	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page v <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/08/18 14:39	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	01/08/18 14:39	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	01/08/18 14:39	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	01/08/18 14:39	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	01/08/18 14:39	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	01/08/18 14:39	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	01/08/18 14:39	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	01/08/18 14:39	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	01/08/18 14:39	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	01/08/18 14:39	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	01/08/18 14:39	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12	01/08/18 14:39	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
13	01/08/18 14:39	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
14	01/08/18 14:39	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
15	01/08/18 14:39	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
16	01/08/18 14:39	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
17	01/08/18 14:39	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
18	01/08/18 14:39	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
19	01/08/18 14:39	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
20	01/08/18 14:39	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
21	01/08/18 14:39	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
22	01/08/18 14:39	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
23	01/08/18 14:39	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
24	01/08/18 14:39	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
25	01/08/18 14:39	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
26	01/08/18 14:39	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
27	01/08/18 14:39	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
28	01/08/18 14:39	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
29	01/08/18 14:39	General View	Load JPG	<input checked="" type="checkbox"/>
30	01/08/18 14:39	General View	Load JPG	<input checked="" type="checkbox"/>
31	01/08/18 14:39	General View	Load JPG	<input checked="" type="checkbox"/>
32	01/08/18 14:39	General View	Load JPG	<input checked="" type="checkbox"/>
33	01/08/18 14:39	General View	Load JPG	<input checked="" type="checkbox"/>
34	01/08/18 14:39	General View	Load JPG	<input checked="" type="checkbox"/>
35	01/08/18 14:39	General View	Load JPG	<input checked="" type="checkbox"/>
36	01/08/18 14:39	General View	Load JPG	<input checked="" type="checkbox"/>
37	01/08/18 14:39	General View	Load JPG	<input checked="" type="checkbox"/>
38	16/10/18 11:57	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	16/10/18 11:57	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	16/10/18 11:57	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	16/10/18 11:57	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	16/10/18 11:57	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	31/07/18 09:07	TP agree with SJE - assign LKK - Request to survey today (31.7.2018)	Load PDF	
2	31/07/18 09:10	TP Police report	Load PDF	
3	31/07/18 09:11	TP PRI - Send surveyor listing	Load PDF	
4	31/07/18 09:13	SLV3299C e-file report	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18013873/KVD3E2
Date: 23/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: A29068646MKC
Claimant Vehicle No : SLV3299C	Insured Vehicle No : YN7046C
Date of Loss: 22/07/2018	Nature of Claim: TP Claim No: 565597

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLV3299C	Engine No: D4FDHH547612
Make & Model: KIA CARENS, 1.7 D DCT 5DR FWD (A)	Chassis No: KNAHU815VJ7195404
Reg. Date: 28/12/2017 (Man. Year: 2017)	Odometer: 0 km
Colour: Metallic Brown	
Engine Capacity: 1685 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16	Rear Tyre Size: 205/55 R16
Front Left Side: Nexen 4 mm	Rear Left Side: Nexen 8 mm
Front Right Side: Nexen 4 mm	Rear Right Side: Nexen 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	112,855.15	30,963.89	81,891.26	72.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,730.00	5,970.00	3,760.00	38.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	122,585.15	36,933.89	85,651.26	69.87
Approved Total (Overridden) (S\$)		25,000.00		
Nett Amount (S\$)	122,585.15	25,000.00	97,585.15	79.61

INSPECTION

Date of Assignment:	31/07/2018	
Date Inspected:	31/07/2018 Inspected At:	Lian Hong Seng Motor Works - Ang Mo Kio (HQ) BLK 5035 ANG MO KIO IND.PARK 2 #01-345 Singapore 569537
Estimated Period of Repair:	24.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$85,000.00(EST)-LTA REIMBURSEMENT VALUE: \$61,621.00=NETT VALUE: \$23,379.00

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 23 Oct 2018)
Parts: M1-MPV	KIA CARENS 1.7 D DCT 5DR FWD (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV3299C)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN	Cracked	1,126.50 FL	*1,126.50 FL
2	1		*FRONT WINDSCREEN MOULDING	Necessary	188.60 FL	*188.60 FL
3	1		*RH FRONT WINDSCREEN PILLAR	Bent	653.10 FL	*653.10 FL
4	1		*LH FRONT WINDSCREEN PILLAR (NPA)	Repair	0.00 FL	*- FL
5	1		*FRONT WIPER GARNISH	Cracked	456.10 FL	*456.10 FL
6	2		*FRONT WIPER ARM	Serviceable	150.60 FL	*- FL
7	2		*FRONT WIPER BLADE	Serviceable	44.80 FL	*- FL
8	1		*FRONT WIPER LINKAGE	Repair	347.10 FL	*- FL
9	1		*FRONT BONNET	Bent	1,043.70 FL	*1,043.70 FL
10	1		*FRONT BONNET LOCK	Bent	213.20 FL	*213.20 FL
11	1		*FRONT BONNET LOCK CABLE	Jammed	134.10 FL	*134.10 FL
12	2		*FRONT BONNET STOPPER	Missing	22.40 FL	*22.40 FL
13	1		*FRONT BONNET STAND	Distorted	98.70 FL	*98.70 FL
14	1		*FRONT BONNET STAND CLIP	Necessary	14.10 FL	*14.10 FL
15	1		*FRONT BONNET STAND GROMMET	Missing	15.20 FL	*15.20 FL
16	1		*FRONT GRILLE	Missing	416.70 FL	*416.70 FL
17	1		*FRONT GRILLE CHROME MOULDING	Missing	256.50 FL	*256.50 FL
18	10		*FRONT GRILLE CLIPS	Necessary	30.00 FL	*30.00 FL
19	1		*FRONT EMBLEM	Missing	75.40 FL	*75.40 FL
20	1		*FRONT BUMPER	Missing	785.30 FL	*785.30 FL
21	10		*FRONT BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
22	2		*FRONT BUMPER RETAINER	Cracked	144.60 FL	*144.60 FL
23	2		*FRONT BUMPER BRACKET	Bent	188.60 FL	*188.60 FL
24	1		*FRONT BUMPER LOWER CENTRE GRILLE	Missing	289.40 FL	*289.40 FL
25	1		*FRONT BUMPER LOWER SPOILER	Missing	365.10 FL	*365.10 FL
26	4		*FRONT SENSOR	Serviceable	788.40 FL	*- FL
27	4		*FRONT SENSOR HOLDER	Serviceable	84.80 FL	*- FL
28	1		*FRONT SENSOR HARNESS	Repair	3,167.50 FL	*- FL
29	1		*FRONT BUMPER SPONGE	Missing	215.30 FL	*215.30 FL
30	1		*FRONT REINFORCEMENT	Bent	465.60 FL	*465.60 FL
31	1		*SUPPORT PANEL	Bent	784.50 FL	*784.50 FL
32	2		*HORN	Dented	196.80 FL	*196.80 FL
33	2		*HEADLAMP PANEL	Repeated	674.20 FL	*- FL
34	2		*HEADLAMP	Broken	2,146.40 FL	*2,146.40 FL
35	2		*FOGLAMP	Missing	520.60 FL	*520.60 FL
36	2		*FOGLAMP COVER	Missing	166.40 FL	*166.40 FL
37	1		*RH FRONT FENDER	Bent	541.50 FL	*541.50 FL
38	1		*RH FRONT FENDER INNER SHIELD	Cracked	211.30 FL	*211.30 FL
39	10		*RH FRONT FENDER INNER SHIELD CLIPS	Necessary	30.00 FL	*30.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*RH FRONT FENDER INNER PANEL	Bent	298.70 FL	*298.70 FL
41	1		*RH FRONT FENDER INNER GARNISH	Cracked	187.50 FL	*187.50 FL
42	1		*RH FRONT WHEEL HOUSE	Bent	891.30 FL	*891.30 FL
43	1		*RH FRONT CHASSIS	Repair	1,325.70 FL	*- FL
44	1		*RH FRONT CHASSIS BRACKET	Repair	199.40 FL	*- FL
45	1		*RH FRONT QUARTER GLASS	Shattered	351.20 FL	*351.20 FL
46	1		*RH FRONT QUARTER GLASS CHROME MOULDING	Bent	243.50 FL	*243.50 FL
47	1		*RH FRONT A PILLAR (NPA)	Repair	0.00 FL	*- FL
48	1		*RH FRONT DOOR	Repair	1,097.50 FL	*- FL
49	1		*RH FRONT ABSORBER TOP MOUNTING	Bent	198.70 FL	*198.70 FL
50	1		*RH FRONT ABSORBER	Bent	348.10 FL	*348.10 FL
51	1		*RH FRONT KNUCKLE ARM	Bent	332.10 FL	*332.10 FL
52	1		*RH FRONT LOWER ARM	Serviceable	298.70 FL	*- FL
53	1		*RH FRONT TIE ROD END	Serviceable	199.60 FL	*- FL
54	1		*RH FRONT TIE ROD	Serviceable	178.60 FL	*- FL
55	1		*RH FRONT WHEEL HUB	Serviceable	312.10 FL	*- FL
56	1		*RH FRONT WHEEL HUB BEARING	Serviceable	211.20 FL	*- FL
57	1		*RH FRONT DRIVE SHAFT	Serviceable	1,435.10 FL	*- FL
58	1		*RH FRONT STABILIZER LINK	Serviceable	167.50 FL	*- FL
59	1		*RH FRONT ABS SENSOR	Serviceable	324.70 FL	*- FL
60	1		*STABILIZER BAR	Serviceable	423.10 FL	*- FL
61	2		*STABILIZER BAR BUSH	Serviceable	122.40 FL	*- FL
62	1		*FRONT CROSSMEMBER	Serviceable	1,243.80 FL	*- FL
63	4		*FRONT CROSSMEMBER BUSH	Serviceable	242.40 FL	*- FL
64	4		*LH FRONT ABSORBER TOP MOUNTING	Serviceable	198.70 FL	*- FL
65	1		*LH FRONT ABSORBER	Serviceable	348.10 FL	*- FL
66	1		*LH FRONT KNUCKLE ARM	Bent	332.10 FL	*332.10 FL
67	1		*LH FRONT LOWER ARM	Serviceable	298.70 FL	*- FL
68	1		*LH FRONT TIE ROD END	Serviceable	199.60 FL	*- FL
69	1		*LH FRONT TIE ROD	Serviceable	178.60 FL	*- FL
70	1		*LH FRONT WHEEL HUB	Serviceable	312.10 FL	*- FL
71	1		*LH FRONT WHEEL HUB BEARING	Serviceable	211.20 FL	*- FL
72	1		*LH FRONT DRIVE SHAFT	Serviceable	1,435.10 FL	*- FL
73	1		*LH FRONT STABILIZER LINK	Serviceable	167.50 FL	*- FL
74	1		*LH FRONT ABS SENSOR	Serviceable	324.70 FL	*- FL
75	1		*STEERING RACK	Bent / Jammed	3,547.10 FL	*3,547.10 FL
76	1		*ENGINE LOWER DASH COVER	Cracked	321.40 FL	*321.40 FL
77	10		*ENGINE LOWER DASH COVER CLIPS	Necessary	30.00 FL	*30.00 FL
78	1		*LH FRONT FENDER	Buckled	541.50 FL	*541.50 FL
79	1		*LH FRONT FENDER INNER SHIELD	Cracked	211.30 FL	*211.30 FL
80	10		*LH FRONT FENDER INNER SHIELD CLIPS	Necessary	30.00 FL	*30.00 FL
81	1		*LH FRONT FENDER INNER PANEL	Repair	298.70 FL	*- FL
82	1		*LH FRONT FENDER INNER GARNISH	Serviceable	187.50 FL	*- FL
83	1		*LH FRONT WHEEL HOUSE (NPA)	Repair	0.00 FL	*- FL
84	1		*LH FRONT CHASSIS (NPA)	Repair	0.00 FL	*- FL
85	1		*LH FRONT CHASSIS BRACKET	Repair	199.40 FL	*- FL
86	1		*LH FRONT QUARTER GLASS CHROME MOULDING	Serviceable	243.50 FL	*- FL
87	1		*LH FRONT A PILLAR (NPA)	Repair	0.00 FL	*- FL
88	1		*LH FRONT DOOR (NPA)	Repair	0.00 FL	*- FL
89	1		*CONDENSER	Bent	976.10 FL	*976.10 FL
90	2		*CONDENSER AIRGUIDE	Cracked	212.40 FL	*212.40 FL
91	1		*CONDENSER FAN COWLING	Cracked	297.60 FL	*297.60 FL
92	1		*CONDENSER FAN BLADE	Serviceable	155.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
93	1		*CONDENSER FAN MOTOR	Serviceable	312.10 FL	*- FL
94	1		*SUCTION PIPE	Serviceable	410.70 FL	*- FL
95	1		*LIQUID PIPE	Serviceable	378.30 FL	*- FL
96	1		*DISCHARGE PIPE	Serviceable	399.50 FL	*- FL
97	1		*RADIATOR	Housing Broken	988.40 FL	*988.40 FL
98	2		*RADIATOR UPPER BUSH	Serviceable	44.40 FL	*- FL
99	2		*RADIATOR LOWER BUSH	Serviceable	44.20 FL	*- FL
100	2		*RADIATOR TOP BRACKET	Bent	42.80 FL	*42.80 FL
101	1		*RADIATOR FAN COWLING	Cracked	297.60 FL	*297.60 FL
102	1		*RADIATOR FAN MOTOR	Jammed	155.60 FL	*155.60 FL
103	1		*RADIATOR FAN BLADE	Distorted	312.10 FL	*312.10 FL
104	1		*RADIATOR TOP HOSE	Torn	166.70 FL	*166.70 FL
105	1		*RADIATOR BOTTOM HOSE	Serviceable	165.70 FL	*- FL
106	1		*RESERVE TANK	Dented	236.70 FL	*236.70 FL
107	1		*INTERCOOLER	Bent	1,032.40 FL	*1,032.40 FL
108	2		*INTERCOOLER HOSE	Serviceable	264.20 FL	*- FL
109	1		*WIPER TANK	Dented	134.10 FL	*134.10 FL
110	2		*WIPER TANK MOTOR	Serviceable	227.60 FL	*- FL
111	1		*INLET MANIFOLD	Cracked	945.50 FL	*945.50 FL
112	1		*O2 SENSOR	Serviceable	211.30 FL	*- FL
113	1		*ABS PUMP	Serviceable	2,586.30 FL	*- FL
114	1		*AIR CLEANER BOX	Cracked	431.50 FL	*431.50 FL
115	1		*AIR DUCT	Cracked	221.30 FL	*221.30 FL
116	1		*BATTERY TRAY	Serviceable	189.40 FL	*- FL
117	1		*BATTERY BRACKET	Repair	155.60 FL	*- FL
118	1		*FUSE BOX	Serviceable	2,904.10 FL	*- FL
119	1		*FUSE BOX WIRE HARNESS	Repair	2,884.40 FL	*- FL
120	1		*ENGINE TOP COVER	Cracked	342.90 FL	*342.90 FL
121	1		*ENGINE OIL LIP STICK	Serviceable	188.30 FL	*- FL
122	3		*SET ENGINE MOUNTING	Serviceable	1,266.90 FL	*- FL
123	3		*SET ENGINE MOUNTING BRACKET	Serviceable	1,124.60 FL	*- FL
124	1		*ALTERNATOR	Serviceable	1,342.10 FL	*- FL
125	1		*WATER PUMP	Serviceable	543.80 FL	*- FL
126	1		*FAN BELT	Serviceable	101.20 FL	*- FL
127	1		*TENSIONER	Serviceable	294.50 FL	*- FL
128	1		*TENSIONER BEARING	Serviceable	150.40 FL	*- FL
129	1		*TIMING COVER	Serviceable	211.60 FL	*- FL
130	1		*FRONT IMPACT SENSOR	Serviceable	396.80 FL	*- FL
131	1		*FRONT DRIVER AIRBAG	Burst	1,347.80 FL	*1,347.80 FL
132	1		*FRONT AIR BAG COCK SPRING	Necessary	453.10 FL	*453.10 FL
133	1		*FRONT AIRBAG CONTROL UNIT	Necessary	1,774.80 FL	*1,774.80 FL
134	1		*FRONT PASSENGER AIRBAG	Burst	1,453.20 FL	*1,453.20 FL
135	1		*FRONT DASHBOARD	Torn	1,173.10 FL	*1,173.10 FL
136	2		*FRONT SEAT BELT	Jammed	1,446.20 FL	*1,446.20 FL
137	2		*FRONT SEAT BELT BUCKLE	Serviceable	986.40 FL	*- FL
138	2		*FRONT WINDSCREEN PILLAR INNER GARNISH	Repair	422.60 FL	*- FL
139	1		*ENGINE ASSY	Serviceable	34,231.70 FL	*- FL
140	1		*GEAR BOX ASSY	Serviceable	19,864.50 FL	*- FL
141	1		*FRONT WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
142	1		*COOLANT	Necessary	100.00 FS	*20.00 FS
143	1		*ENGINE OIL	Not Necessary	150.00 FS	*- FS
144	1		*ATF OIL	Necessary	150.00 FS	*40.00 FS
145	1		*OIL FILTER	Not Necessary	20.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
146	1		*FRONT NUMBER PLATE	Missing	45.00 FS	*45.00 FS
147	1		*FRONT PANEL SEALANT	Necessary	80.00 FS	*80.00 FS
148	1		*IU STICKER	Necessary	45.00 FS	*20.00 FS
149	1		*BATTERY	Serviceable	180.00 FS	*- FS
150	1		*BRAKE FLUID	Serviceable	50.00 FS	*- FS
151	2		*FRONT TYRE	Serviceable	45.00 FS	*- FS
152	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	125,278.50	34,377.10
- List Item Discount on L Items 10.00/10.00% (S\$)	12,423.35	3,413.21
Total Parts (S\$)	112,855.15	30,963.89

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR FACILITATE REPAIR - FRONT PORTION	New	3,000.00	2,200.00
2	TO RESPRAY AFFECTED AREAS - FRONT PORTION	New	2,800.00	1,400.00
3	TO CHECK AND RECONNECT ALL NECESSARY WIRING	New	50.00	50.00
4	TO REMOVE AND REFIT AC CONDENSER INCLUDING TOP UP GAS	New	150.00	100.00
5	TO REMOVE AND REFIT RADIATOR INCLUDING WATER PRESSURE TEST	New	150.00	50.00
6	TO REMOVE AND REFIT FRONT WINDSCREEN	New	150.00	120.00
7	TO REMOVE AND REFIT RH FRONT QUARTER GLASS	New	100.00	40.00
8	TO REMOVE AND REFIT ENGINE, ENGINE MOUNTING FOR FACILITATE REPAIR	New	350.00	280.00
9	TO REMOVE AND REFIT GEAR BOX	New	80.00	80.00
10	TO REMOVE AND REFIT ABS PUMP	New	300.00	120.00
11	TO REMOVE AND REFIT FRONT AIRBAG	New	350.00	250.00
12	TO REMOVE AND REFIT AIRBAG CONTROL UNIT AND RESET	New	350.00	220.00
13	TO REMOVE REFIT FRONT DASHBOARD	New	350.00	250.00
14	TO REMOVE AND REFIT FRONT SEAT BELT AND BUCKLE AND REFIT SEAT BELT WARNING LIGHT	New	250.00	120.00
15	TO REMOVE AND REFIT BOTH FRONT UNDERCARRIAFE INCLUDING CROSSMEMBER	New	500.00	320.00
16	TO REMOVE AND REFIT FRONT ABS SENSOR	New	250.00	0.00
17	TO BLEED AND TEST BRAKING SYSTEM	New	100.00	20.00
18	TO STRAIGHTEN AND ALIGN FRONT FRAME CHASSIS	New	350.00	250.00
19	RUST PROOFING	New	100.00	100.00
Gross Labour Cost (\$\$)			9,730.00	5,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >