

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

30-Jul-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6065 M

1 pc	Front o/s wheel cover @ \$116.00 ✓	\$ 116.00
1 pc	Front bumper ✓	\$ 531.00
1 pc	Front bumper emblem ✓	\$ 44.00
2 pcs	Front bumper n/s & o/s side retainer @\$16.00 <i>n/s x o/s?</i>	\$ 32.00
1 pc	Front o/s fender ✓	\$ 384.00
1 pc	Front o/s fender inner shield ✓	\$ 120.00
1 pc	o/s head lamp @ \$1028.00 ✓	\$ 1,028.00
	<i>Front o/s door X repair</i>	\$ 2,255.00
	Less 10%	\$ 225.50
		\$ 2,029.50

S/NETT

1 set	Front bumper clips ✓	\$ 48.00
1 set	Front o/s fender inner shield clips ✓	\$ 28.00
1 pc	Front o/s fender sticker X	\$ 30.00
1 set	os door stickers ✓	\$ 100.00
	Sundry	\$ 50.00 20
	To check wheel alignment	\$ 80.00 X
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 50
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of front o/s door, etc.	\$ 700.00 460
	To putty and spray painting on bonnet, front bumper, front o/s fender, front o/s door, X	\$ 800.00 5% 50
	To apply rustproofing on the repaired and replaced panels.	\$ 120.00 50

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Kalvin 10/11/18
30/7/18 1330h
3 Rep.
45
Adnan Repair p Ltd