



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

TP INSURER: India International Insurance Pte Ltd (HQ)
Comfort Transportation Pte Ltd

Singapore

Lkk - Marcus

01/8/18 C 1045h

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP040072018
Policy No:		Date of Loss:	27/07/2018
Vehicle Reg. No.:	SCE73C	Driveable?	YES
Party At Fault:	UNKNOWN		
Driver (TP):	BOEY SHINMIN, NATALIE JANICE	Driver (Insured):	MUSTAFFA BIN ISNAIN

Make/Model:	AUDI A5, 1.8 SPORTSBACK TFSI MU (A)	Vehicle Reg. Date:	30/01/2013
Vehicle Colour:	PURPLE	Gen Condition:	GOOD
Engine No:	CJE022012	Chassis No:	WAUZZZ8T9DA003850
Odometer:	0 KM		

Paint Type:	
List Item Discount:	10.00 %
Total Loss?	NO
Est. Duration of Repair (day)	5

not Admit
take photo After repair
5 Aug 18 H S

Present Location: TAN LIM MOTOR PTE LTD (DEFU)

COST OF CLAIMS

		Amount
Parts	• To resurvey before/after spray painting	14,998.25
Miscellaneous Items	• To display damaged part(s) during resurvey	10.00
Labour	• Parts prices are subject to confirmation	
Paintwork Labour	• Third party survey is on a "Without Prejudice" basis	3,280.00
Towing	• No illegal modification(s) is allowed	1,000.00
	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	0.00
Acknowledged by Repairer		Gross Total (S\$)
Signature:		+ GST 7.00% (S\$)
Date:		Nett Amount (S\$)

This claim is handled by: LAM WEI SHONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 30 Jul 2018)**Parts:** 143 **AUDI A5 1.8 SPORTSBACK TFSI MU (A) (Catalogue:Merimen Singapore 1.0)****Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Tan Lim Motor Pte Ltd/SCE73C/30/07/2018 13:17**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*left rear door <i>30350</i>	10.00	0.00	*2,122.20 FL ✓
2	1		*left rear door power window motor <i>30350</i>	10.00	0.00	*246.65 FL
3	1		*left rear door regulator <i>30350</i>	10.00	0.00	*394.25 FL ✓
4	1		*left rear door weatherstrip <i>30350</i>	10.00	0.00	*158.90 FL ✓
5	1		*left rear door outer weatherstrip chrome moulding <i>30350</i>	10.00	0.00	*274.40 FL ✓
6	1		*left rear door outer handle inner base <i>11 X</i>	10.00	0.00	*233.65 FL ✓
7	2		*left rear door rubber stoppers <i>11 X</i>	10.00	0.00	*11.00 FL ✓
8	1		*left rear door hinge top <i>11 X</i>	10.00	0.00	*166.45 FL
9	1		*left rear door hinge bottom <i>11 X</i>	10.00	0.00	*163.95 FL
10	1		*left rear door checker/arrestor <i>11 X</i>	10.00	0.00	*89.45 FL
11	1		*left rear door inner trimboard <i>11 X</i>	10.00	0.00	*1,418.05 FL
12	1		*left rear door audio speaker <i>11 X</i>	10.00	0.00	*103.45 FL
13	1		*left rear door inner lock <i>11 X</i>	10.00	0.00	*411.75 FL
14	1		*left rear door inner lock striker <i>11 X</i>	10.00	0.00	*63.85 FL
15	2		*left rear door rubber grommet <i>11 X</i>	10.00	0.00	*18.00 FL
16	1		*left rear fender <i>2 X</i>	10.00	0.00	*1,958.20 FL
17	1		*left rear fender 1/4 glass sealant <i>11 X</i>	0	0.00	*100.00 FS
18	1		*left rear fender 1/4 glass weatherstrip <i>11 X</i>	10.00	0.00	*434.15 FL
19	1		*left rear wheel rim 18 <i>607/24</i>	10.00	0.00	*1,911.45 FL
20	1		*left rear wheel rim tyre - 245/402R18 <i>500</i>	0	0.00	*550.00 FS
21	1		*left rear shock absorber <i>11 X</i>	10.00	0.00	*1,437.85 FL
22	1		*left rear lower arm <i>11 X</i>	10.00	0.00	*125.55 FL
23	1		*left rear upper arm <i>11 X</i>	10.00	0.00	*593.25 FL
24	1		*left rear castor arm <i>11 X</i>	10.00	0.00	*909.20 FL
25	1		*left rear wheel knuckle <i>11 X</i>	10.00	0.00	*1,045.55 FL
26	1		*rear windscreen glass weatherstrip <i>11 X</i>	10.00	0.00	*818.05 FL
27	1		*rear windscreen glass sealant <i>11 X</i>	0	0.00	*200.00 FS
28	1		*rear windscreen glass inner sponge seal <i>11 X</i>	0	0.00	*120.00 FS
29	1		*left rear wheel bearing with hub <i>11 X</i>	10.00	0.00	*477.70 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	16,556.95
- List Item Discount on L Items (S\$)	1,558.70
Total Parts (S\$)	14,998.25

Tan Lim Motor Pte Ltd/SCE73C/30/07/2018 13:17. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer) <i>mer</i>	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	Putty and spray painting of the affected portion. <i>900</i>	New	1,000.00
<u>Labour Items</u>			
2	To remove and refit rear windscreen glass. <i>11</i>	New	250.00
3	To rust-proofing of the affected areas.	New	200.00
4	To check steering geometry and computer wheel alignment.	New	150.00
5	To transfer of left rear door fittings and perform water seepage test.	New	180.00
6	To transfer of tyre, rim and on wheel balancing.	New	50.00
7	To drop left rear axle and suspension assy, remove and renewal of necessary parts, to conduct final checking and testing.	New	750.00
8	To conduct diagnosetic test and recall and reset error codes.	New	500.00
9	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	New	1,200.00
Gross Labour Cost (S\$)			4,280.00

Tan Lim Motor Pte Ltd/SCE73C/30/07/2018 13:17. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

51 Defu Lane 10 Singapore 539216
 Tel : 6858 5151 (24 hours) Fax : 6858 0877
 email@tlmotor.com.sg www.tlmotor.com.sg
 Co. Reg. No.: 199503965M GST Reg. No. : M2-8922054-2