

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 2128C

DATE 27/7/2018 16:24

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>X repair</i>			\$ 603.60
	Rear Bumper Clips <i>X</i>			\$ 22.00
	SUB TOTAL			\$ 625.60
	LESS 20%			\$ 125.12
	DISCOUNTED TOTAL			\$ 500.48
	Rear Bumper Advertisement Logo ✓			\$ 50.00 Nett
	Rear Bumper Rubber Mat <i>X</i>			\$ 50.00 Nett
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00 Nett
				\$ 300.00
	Labour Charge			
	Panel Beating			\$ 350.00 <i>100</i>
	Spray Painting Charge			\$ 250.00 <i>200</i>
	Wiring Charge			\$ 50.00 <i>X</i>
	R/Refix Reverse Sensor			\$ 120.00 <i>X</i>
	TOTAL LABOUR			\$ 770.00
	ESTIMATE TOTAL			\$ 1,570.48
<i>Ka/ln 16/04</i> <i>30/7/18 1000 hrs.</i> <i>2 Pys.</i> <i>P/P</i> <i>After Repair P/Lt</i> LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "without prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				