

REPAIR ESTIMATE

VEHICLE NO : SHB 6330C

30/7/2018 10:16

MAKE :

MODEL : TOYOTA PRIUS

ALG.
LKIC
Jm

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
REAR BUMPER <i>X Repol</i>			\$ 458.60
REAR BUMPER RE-INFORCEMENT ?			\$ 322.30
REAR BUMPER UNDER COVER ✓			\$ 552.60
REAR BUMPER SIDE RETAINER ?			\$ 112.70
REAR BUMPER SPONGE X			\$ 143.40
REAR BUMPER TOWING COVER X			\$ 82.70
REAR BUMPER CLIPS ✓			\$ 22.00
RETAINER, REAR BUMPER, SIDE, LH X			\$ 94.80
SEAL, REAR BUMPER SIDE, LH X			\$ 148.40
TAIL LAMP ASSY (UPPER) (LH) X			\$ 557.90
TAIL LAMP ASSY (LOWER) (LH) X			\$ 548.40
SUB TOTAL			\$ 3,043.80
LESS 25%			\$ 760.95
DISCOUNTED TOTAL			\$ 2,282.85
REAR BUMPER REVERSE SENSOR X			\$ 135.70
REAR BUMPER RUBBER MAT X			\$ 50.00
			\$ 185.70
LABOUR CHARGE			
Panel Beating			\$ 350.00 200
Spray Painting Charge			\$ 250.00 200
Wiring Charge			\$ 50.00 X
Remove/Refix Reverse Sensor			\$ 120.00 X
TOTAL LABOUR			\$ 770.00
ESTIMATE TOTAL			\$ 3,238.55

NETT
NETT

Consultants hence notify
the Repairer of the following:
To resurvey before/after spray painting
To display damaged panel during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modifications is allowed
• Supplementary items must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Kalvin 10/10/14
30/7/18 1035hrs
2 Days
PIP
After Repair photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.