

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 7117J

DATE 30/7/2018 12:26

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid ✓			\$ 1,681.40
	Boot Lid Lock Upper ✕			\$ 137.90
	Boot Lid Lock Lower ✕			\$ 31.70
	Boot Lid 'H' Emblem ✓			\$ 27.20
	Boot Lid CRDI Plate ✓			\$ 41.00
	Bootlid Moulding ✕			\$ 85.00
	Bootlid i40 Emblem ✓			\$ 41.00
	Bootlid Lower Garnish ✕ <i>repair</i>			\$ 398.00
	Rear Bumper ✓			\$ 603.60
	Rear Bumper Reinforcement ✓			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) ?	\$	180.00	\$ 360.00
	Rear Bumper Side Bracket ?	\$	49.00	\$ 98.00
	Rear Bumper Clips ✓			\$ 22.00
	Rear Bumper Sponge ✓			\$ 143.40
	Rear Bumper Under Cover ✓			\$ 225.00
	Rear Bumper Reflector Lamp (RH) ✓			\$ 32.00
	Rear Panel ✕ <i>repair</i>			\$ 592.30
	Rear Panel Garnish ?			\$ 57.70
	Rear Panel Lower Panel ✕ <i>repair</i>			\$ 495.50
	<i>Rear Fender (RH) ✕ repair</i>			
	<i>Rear RH Exhaust ✓</i>			
	SUB TOTAL			\$ 5,577.05
	LESS 20%			\$ 1,115.41
	DISCOUNTED TOTAL			\$ 4,461.64
	Boot Lid Comfort Logo & Tel No. Sticker ✓			\$ 30.00
	Rear Bumper Reverse Sensor ✓			\$ 135.70
	Rear Bumper Rubber Mat ✓			\$ 50.00
				\$ 215.70
	Labour Charge			
	Panel Beating			\$ 850.00 600
	Spray Painting Charge			\$ 750.00 600
	Wiring Charge			\$ 50.00 20
	Tuff Kote			\$ 50.00 20
	Towing Fees			\$ 60.00
	Remove/Refix Reverse Sensor			\$ 120.00 30
	TOTAL LABOUR			\$ 1,880.00
	ESTIMATE TOTAL			\$ 6,557.34
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

TOTAL LABOUR

ESTIMATE TOTAL

Kalvin LKK
30/7/18 1506
JR
PIP
Before Repair

LKK/kalvin

PbyP

Like

AIG