

1000000

INS. CASE OWNER:

He Grace

CC 4 LR / AIG1801

3898, K p639

LKK:

IDAC:

Surveyor:

Kenneth

DOI:

ASSIGNMENT

Date / Time:

21/7/18

Registered in Merimen:

21/7/18

Pre-assign / CCU / FTE

SLF 1984R



Insured Vehicle No.:

SLF 1984R

Name of Insured:

LR

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A:

26/7/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

MANHO GHEAN S/O KENHSON

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

WPI5MM1456

Policy No.:

99999904

Make / Model:

MANOH

Place of Accident:

NEWTON CIRCLE

OI GIA REPORT: YES / NO:

YES

TP GIA REPORT: YES / NO

YES

Insured Liability:

%

Final ? Yes / No

SLT 6A18R



INSRS:

WSP:

Tel:

Liability:

RMKS:

Bh Anto



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

1/6/18

UNT

8/8/18

4/9/18

25-09-18

21/1/19

SLT 6A18R - 4

TP -> OI cut lane
OIO -> TP cut lane
Sent letter to OI (50/50)

No evidence from TP.

BASED ON OBSERVATION OF AVAILABLE FACTS, TP'S VERSION IS MORE CREDIBLE, HOWEVER NO CONCRETE PROOF FROM BOTH PARTIES TO SUPPORT THEIR RESPECTIVE VIEW, SO 50% LIABILITY IS BEST SETTLEMENT.

File -> Shaper to close

STAGE	DATE / PIC
Non-Reporting hr (1st):	
Non-Reporting hr (2nd):	
Non-Reporting hr (Final):	
Notification hr (if non-pickup):	
Call OI:	21/7/18 (By email)
After call hr to OI:	
Documentation Check List:	Handler Typist
Notification hr (if non-pickup):	
After call hr to OI:	
Authorisation To Act:	
Release Voucher:	
Final Repair Bill:	
Car Rental Invoice:	
Towing Invoice:	
LTA / GIA:	
Medical Bill:	
PIR:	
Mandate/Reject Instruction:	
LOD:	
Payment Breakdown Form:	
Post-Repair Photos:	
Others:	

PRELIMINARY ADVICE		Date/Time:	Sent By:	
FINALIZATION		Date/Time:	Confirm with:	
Repair Cost:	S\$	(days)	Reduction:	%
FINAL SETTLEMENT		Date/Time:	Confirm with:	
Final Liability:	%	50	(Agreed / Assessed)	BOLA S/N No. : NIL.
Repair Cost:	S\$	1792.25		
Loss of Use (LOU):	S\$	321.00	(6 days)	X 11W
Loss of Income (LOI):	S\$	(5 x days)		
LOR only	<input type="checkbox"/>	LOU only	<input type="checkbox"/>	LOR + LOU
GIA/LTA Search	S\$	2.45	[Tick only one]	
Medical:	S\$	-		
Disbursement:	S\$	-	(e.g. Tow/ Independent)	
Legal Cost:	S\$	-		
Total:	S\$	2120.70	Global Sum S\$: 2120.00	
FINAL PAYMENT		Date/Time:	Confirm with:	
Payee 1:	S\$	2120.70	Name 1:	BH Auto Services Pte Ltd
Payee 2: (Strike if N.A.)	S\$		Name 2:	
Payee 3: (Strike if N.A.)	S\$		Name 3:	

CERTIFIED

1) Claim status: Non-Report/Private Settle
2) Report Format:
3) Survey fee: 4320

ASS. REC. BY:

REF: AIG-1

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OO (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$18k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
2/8	File pass to Customer

LIS \$3350 (Ret # 6263.446571)

Veh No: SLT 6918R Yr Regn: 12, 98

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda RX8 cc 1308

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 72585 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: PE3p 301657

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / 8Rim / STD A/Rim or

Tyre Size: F: 245/40R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal: 9 mm

L/Bal: 9 mm

D.O.A: 28/7/18

Rear

R/Bal: 9 mm

L/Bal: 9 mm

D.O.I: 1/8/18

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

N/S R & L

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

\$ - RS. \$

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC4/LCR18013898/pb3

78 SHENTON WAY #08-16
CHARTIS BUILDINGS SINGAPORE 079120

Date : 31-07-2018



Code : LCR

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLK 1989R	Veh. Inspected	SLT 6918R
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	31/07/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	28/07/2018	Inspection Date	
Survey held at	BH AUTO SERVICES PTE LTD BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

AIG Asia Pacific Insurance Pte. Ltd
AIG Building
78 Shenton Way #08-16
Singapore (079120)
ATTN: MOTOR CLAIM DEPARTMENT
Tel : 6419 3000 Fax : 6835 7416
DEAR SIR / MADAM :

Not Authorised
11 Sep 833501
Runny After Repair

ACCIDENT REPAIR ON: SLT6918R

Date: 01/08/2018

MODEL : MAZDA RX-8 1.3A

Page : 1 of 2

POLICY NO : GA289048/1

CHASSIS NO : SE3P301657

YEAR OF MANUFACTURE : 2008

DATE / TIME OF ACCIDENT: 28/07/2018 Time: 2110Hrs at Along Scotts Rd Twds Newton@Newton circus

THIRD PARTY VEHICLE NO: SLK1989R

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
		S\$		S\$
1 Front fender LH	1	752.00	Dented	752.00 ✓
2 Front fender shield front section LH	1	139.00	Cut	139.00 ✓
3 Front fender shield rear section LH	1	159.00	Cut	159.00 ✓
4 Front fender shield clips	12	4.00	Necessary	48.00 ✓
5 Front fender lamp LH	1	187.00	Scratches	187.00 ✓
6 Front wheel rim LH	1	1,350.00	Torn	1,350.00 ✓
7 Front absorber LH	1	420.00	Bented	420.00 ✗
8 Front lower arm LH	1	576.00	Bented	576.00 ✗
9 Front knuckle arm LH	1	380.00	Bented	380.00 ✗
10 Front knuckle arm bearing LH	1	672.00	Necessary	672.00 ✗
11 Front tie rod LH	1	125.00	Bented	125.00 ✗
12 Front tie rod end LH	1	153.00	Bented	153.00 ✗
13 Front door LH	1	1,225.00	Dented	1,225.00 ✓
14 Front door hinge upper LH	1	43.00	Bented	43.00 ✗
15 Front door hinge lower LH	1	43.00	Bented	43.00 ✗
16 Front door frame pillar sticker LH	1	93.00	Necessary	93.00 ✓
17 Front door weatherstrip LH	1	108.00	Necessary	108.00 ✗
18 Rocker panel LH	1	950.00	Dented	950.00 ✗

\$3627 - 20%
= \$2901.60

Sub-Total: 7,423.00
Less: 20% discount - 1,484.60
Total Parts after 20% discount: 5,938.40

Special Nett Items

1 Anti-rust coating	3	80.00	240.00
2 Front tyre LH	1	285.00	285.00
			525.00

\$60

Total Parts: 6,463.40

Labour Charges For LH Side Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	500l	1,250.00
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	600l	1,250.00
3	Provide skill labour to disconnect and check electrical wiring	20l	60.00
4	Remove and reinstall cushions, seats, backrest, inner trim, garnish, roof lining and or upholstery to facilitate repairs	nn	150.00
5	Dismantle and transfer door fittings and mechanism to new door/facilitate repair		80.00
6	Provide skill labour to check and re-adjust wheel alignment		80.00
7	Provide skill labour to remove and replace/refit front LH undercarriage	nn	200.00
8	Provide skill labour to remove and replace/balancing wheel rim with tyre		80.00

Total Labour:

\$1260

Total Parts & Labour:

3,150.00

GST 7%

9,613.40

Grand Total:

672.94

10,286.34

Estimate Repair Duration

10 days

ACCIDENT VEHICLE OF : SLT6918R

Page : 2 of 2

5 days

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: WEN ZHENG

Part : \$ 2901.60

Survey attended by:

S/N : \$ 60.00

Name : HennrichCompany : LKICDate : 1/8/18Time : 1.05pmContact No : 96810663

Email : _____

Labour : \$ 1260.00

Total : \$ 4221.60 - 20%

= \$ 3377.28

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

AIG Asia Pacific Insurance Pte. Ltd

AIG Building

78 Shenton Way #08-16

Singapore (079120)

ATTN: MOTOR CLAIM DEPARTMENT

Tel : 6419 3000 Fax : 6835 7416

DEAR SIR / MADAM :

*Not Authorised
11 Sep 8?
Penny After Pains*

ACCIDENT REPAIR ON: SLT6918R

MODEL : MAZDA RX-8 1.3A

POLICY NO : GA289048/1

CHASSIS NO : SE3P301657

YEAR OF MANUFACTURE : 2008

DATE / TIME OF ACCIDENT: 28/07/2018 Time: 2110Hrs at Along Scotts Rd Twds Newton@Newton circus

THIRD PARTY VEHICLE NO: SLK1989R

Date: 01/08/2018

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts		Quantity	Unit Price	Condition	Amount
S/N			SG		SG
1	Front fender LH	1	752.00	Dented	752.00 ✓
2	Front fender shield front section LH	1	139.00	Cut	139.00 x
3	Front fender shield rear section LH	1	159.00	Cut	159.00 ✓
4	Front fender shield clips	12	4.00	Necessary	48.00 ✓
5	Front fender lamp LH	1	187.00	Scratches	187.00 ✓
6	Front wheel rim LH	1	1,350.00	Torn	1,350.00 ✓
7	Front absorber LH	1	420.00	Bented	420.00 ?
8	Front lower arm LH	1	576.00	Bented	576.00 ?
9	Front knuckle arm LH	1	380.00	Bented	380.00 ?
10	Front knuckle arm bearing LH	1	672.00	Necessary	672.00 ?
11	Front tie rod LH	1	125.00	Bented	125.00 ?
12	Front tie rod end LH	1	153.00	Bented	153.00 ?
13	Front door LH	1	1,225.00	Dented	1,225.00 ✓
14	Front door hinge upper LH	1	43.00	Bented	43.00 x
15	Front door hinge lower LH	1	43.00	Bented	43.00 x
16	Front door frame pillar sticker LH	1	93.00	Necessary	93.00 ✓
17	Front door weatherstrip LH	1	108.00	Necessary	108.00 ?
18	Rocker panel LH	1	950.00	Dented	950.00 x

Sub-Total: 7,423.00

Less: 20% discount - 1,484.60

Total Parts after 20% discount: 5,938.40

Special Nett Items

- Anti-rust coating
- Front tyre LH

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

80.00 240.00 601
285.00 285.00 ?
525.00

Total Parts: 6,463.40

Labour Charges For LH Side Portion

1	Provide skill labour to remove all damaged parts, panel beat , cut & weld if necessary and align all panel and reinstall all damaged parts.	1,250.00	5001
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	1,250.00	6001
3	Provide skill labour to disconnect and check electrical wiring	60.00	201
4	Remove and reinstall cushions, seats, backrest, inner trim, garnish, roof lining and or upholstery to facilitate repairs	150.00	nn x
5	Dismantle and transfer door fittings and mechanism to new door/facilitate repair	80.00	601
6	Provide skill labour to check and re-adjust wheel alignment	80.00	601
7	Provide skill labour to remove and replace/refit front LH undercarriage	200.00	?
8	Provide skill labour to remove and replace/balancing wheel rim with tyre	80.00	201

Total Labour:**3,150.00****Total Parts & Labour:****9,613.40****GST 7%****672.94****Grand Total:****10,286.34****Estimate Repair Duration****10 days**ACCIDENT VEHICLE OF : **SLT6918R**

Page : 2 of 2

5 days

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: WEN ZHENG

Survey attended by:

Name : Kenneth
Company : LKLC
Date : 1/8/18
Time : 1.05pm
Contact No : 96810663
Email : _____

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended De-registration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

QP Paid:

COE Rebate Amount:

Total Rebate Amount:

Foreign Identification Number

9076W

SLT6918R

Yes

30 Jul 2018

MAZDA

RX-8 1.3 A

White

2008

13B544608

SE3P301657

154.0 kW (206 bhp)

\$25,978.00

12 Dec 2008

12 Dec 2008

4

\$25,978.00

Yes

11 Dec 2018

\$12,989.00

11 Dec 2018

A - Car (1600cc & below)

10

\$7,721.00

\$280.00

\$13,269.00

The information contained herein is correct as at 30 Jul 2018

OK

SELL

USED CAR PARTS
& ACCESSORIES *online!*

CAR CARE & MAINTENANCE

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 5 Years Cpe Renewal Honda Stream 1.8A



\$2500 Downpayment Monthly
From \$888 Over 60 Months. Lowest
3.66% P.A. JALV Car Financing
GV Credit Pte Ltd. See Us!



Browse by Category

Sort by Date Posted 20 results/page

Advanced Search

7 vehicles

Mazda RX-8

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mazda RX-8	Any	Any	2008	Any	Any	Any	Available
	Mazda RX-8 Type S 1.3M	\$22,800	N.A	16-Dec-2008	1,308 cc	218,000 km	Sports	Available
Fully Overhaul Engine And Gearbox. Service Records And Custom Tune At MG. Custom Sprayed Matt Black. No Consignment And Dealers.								
Posted: 29-Jul-2018 Tags: 2008 Mazda RX-8, Mazda RX-8, Mazda, RX-8, Used Mazda								
	Mazda RX-8 1.3A (New 5-yr COE)	\$39,000	\$7,800 /yr	20-Aug-2008	1,308 cc	114,800 km	Sports	Available
100 KG Lighter And 20 BHP More. 170 BHP/ton, Powerful And Responsive. ECU Remapped. New Facelift Model, R-magic Full Bodyfit. 18" Genuine Advan RS Rims, Twin Knight Sport Legal Exhaust. Carbon Fiber B...								
Posted: 20-Jul-2018 Tags: 2008 Mazda RX-8, Mazda RX-8, Mazda, RX-8, Used Mazda								
	Mazda RX-8 1.3A (New 10-yr COE)	\$60,000	\$6,000 /yr	01-Sep-2008	1,308 cc	116,000 km	Sports	Available
Extremely Well Taken Care Of By Previous Owner! With New Leather Upholstery! RX-8 Is One Of The Most Unique And Practical Coupe With 4 Doors That You Don't Want To Missed! Flexible Bank Or In House Lo...								
Monster Motors Pte Ltd								
Posted: 18-Jul-2018 Tags: 2008 Mazda RX-8, Mazda RX-8, Mazda, RX-8, Used Mazda								
	Mazda RX-8 1.3A	\$23,888	N.A	03-Oct-2008	1,308 cc	46,800 km	Sports	Available
Only Owner Very Low Mileage 46,800km As 1 Drive Company Car. Original Imported From Japan M's Customs Bodykit. Those Similar Bodykits Outside Are My Replica Seriously. Please Do Not Compare My Car Wit...								
Posted: 13-Jul-2018 Tags: 2008 Mazda RX-8, Mazda RX-8, Mazda, RX-8, Used Mazda								
<div> <div>Car Buying</div> <div>Car Aftermarket</div> </div> <div> <div>Car Selling</div> <div>On The Move</div> </div> <div> <div>Car Ownership</div> <div>Lifestyle</div> </div> <div> <div>Buy Terms Online</div> <div>Latest Special Offers from Transport</div> </div>								
	Mazda RX-8 1.3M (COE till 02/2028)	\$66,800	\$6,980 /yr	23-Feb-2008	1,308 cc	-	Sports	Available
Depre At Only \$6.8k. Well Taken Care By Owner. Excellent Condition! Loan Available! Call Us Now To View This Beauty								
Posted: 14-Jun-2018 Tags: 2008 Mazda RX-8, Mazda RX-8, Mazda, RX-8, Used Mazda								
	Mazda RX-8 1.3A	\$23,888	N.A	13-Nov-2008	1,308 cc	-	Sports	Available
Serviced Regularly At Rotary Specialist RMS. Very Well Maintained By Owner. Full Service Records Available. Perfect For COE Renewal.								
Posted: 06-Jun-2018 Tags: 2008 Mazda RX-8, Mazda RX-8, Mazda, RX-8, Used Mazda								
	Mazda RX-8 1.3M Type S (COE till 02/2028)	\$67,000	\$7,000 /yr	22-Feb-2008	1,308 cc	133,761 km	Sports	Available
Accident Free JDM RX8 Type S, Well Taken Care Owner, Rarely Driven And Always Parked Under Shelter, Many Wear And Tear Parts Changed. New HID Head Light, New Battery, New Coolant Tank, New Fuel Valve ...								
Monster Motors Pte Ltd								
2008 Mazda RX-8, Mazda RX-8, Mazda, RX-8, Used Mazda								

Compare

Hsiao Tong (LKKAUTO)

From: BHAS - Bernard Kee <bernard.kee@bhauto.com.sg>
Sent: Tuesday, 7 August 2018 5:30 PM
To: Hsiao Tong (LKKAUTO); BHAS - Jacelyn Loh
Cc: BHAS - Moo Wen Zheng; BHAS - Anthony Lau; Admin A
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLK1989R AND SLT6918R ON 28/07/2018 *LKK REF: CC4/LCR18013898/Kpb3

Dear Hsiao Tong

Our insured driver reported that your client cut into his lane and hit our vehicle.

Kindly let us have evidences (ie: video footage/ scene photos / PIR) in order for us to look into the matter.

In that case we do it as 50/50 can ?

Thank you

Best Regards,

Bernard Kee

 **BH AUTO SERVICES PTE LTD**

(W) +65-6559 8945 (F) +65-6269 2404 (M) +65 9747 8383

Bernard.kee@bhauto.com.sg <http://www.bhauto.com.sg>

From: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Sent: Tuesday, 7 August 2018 5:14 PM
To: BHAS - Jacelyn Loh <jacelyn.loh@bhauto.com.sg>
Cc: BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>; BHAS - Anthony Lau <anthony.lau@bhauto.com.sg>; BHAS - Bernard Kee <bernard.kee@bhauto.com.sg>; Admin A <admin-a@lkkauto.com>
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLK1989R AND SLT6918R ON 28/07/2018 *LKK REF: CC4/LCR18013898/Kpb3

Without Prejudice

Hi Jacelyn,

We refer to the above matter.

Please be informed that liability is unclear. Our insured driver reported that your client cut into his lane and hit our vehicle.

Kindly let us have evidences (ie: video footage/ scene photos / PIR) in order for us to look into the matter.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: BHAS - Jacelyn Loh <jacelyn.loh@bhauto.com.sg>

Sent: Tuesday, 7 August 2018 4:24 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>; BHAS - Anthony Lau <anthony.lau@bhauto.com.sg>; BHAS - Bernard Kee <bernard.kee@bhauto.com.sg>

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLK1989R AND SLT6918R ON 28/07/2018

Dear Madam, **urgent**

Kindly advise on this liabilities status. thanks

Sketch Plan #2

Describe Circumstances of the Accident

ON 28/7/2018 at about 840 PM WAS I
 DRIVING ALONG BT TIMAH RD
 TOWARDS NEWTON CROSS TO EXIT AT NEWTON RD
 WHILE MANOEUVERING THE NEWTON CROSS
 SETBACKER SUDDENLY CUT INTO MY LANE
 WHICH WAS A STRAIGHT LANE TOWARDS NEWTON RD
 SETBACKER COULD HAVE GONE STRAIGHT IN IF
 INSTEAD OF EASILY CUTTING INTO MY LANE
 BECAUSE THE TRAFFIC INTENT AT AIN WPS WAS
 CLEARLY.



Thank You & Best Regards,
 Jacelyn Loh

BH AUTO SERVICES PTE LTD

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singaopre:575636

(T) +65-6559 8944 /8940 (F) +65-6515 3144 / +65-6269 2404

Email: Jacelyn.loh@bhauto.com.sg

Website: <http://www.bhauto.com.sg>

From: BHAS - Jacelyn Loh

Sent: Monday, 30 July 2018 5:49 PM

To: 'Mithoosingh, Aashweenjeetkaur' <Aashweenjeetkaur.Mithoosingh@aig.com>; Tan, Lily (AIG) <Lily.Tan@aig.com>; Fong, Andy-SY <Andy-SY.Fong@aig.com>; Kaur, Baljit <Baljit.Kaur@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Md Ishak, Mohd Imran <Imran.Ishak@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>

Cc: BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>; BHAS - Anthony Lau <anthony.lau@bhauto.com.sg>; BHAS - Bernard Kee <bernard.kee@bhauto.com.sg>

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLK1989R AND SLT6918R ON 28/07/2018

Dear sir / mdm,

We choose below surveyor: LKK Auto Consultants Pte Ltd

Ps- vehicle currently IN our workshop.

Thank You & Best Regards,

Jacelyn Loh

BH AUTO SERVICES PTE LTD

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singapore: 575636

(T) +65-6559 8944 / 8940 (F) +65-6515 3144 / +65-6269 2404

Email: jacelyn.loh@bhauto.com.sg

Website: <http://www.bhauto.com.sg>

From: Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>

Sent: Monday, 30 July 2018 1:33 PM

To: BHAS - Jacelyn Loh <jacelyn.loh@bhauto.com.sg>

Cc: Tan, Lily (AIG) <Lily.Tan@aig.com>; Fong, Andy-SY <Andy-SY.Fong@aig.com>; Kaur, Baljit <Baljit.Kaur@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Md Ishak, Mohd Imran <Imran.Ishak@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLK1989R AND SLT6918R ON 28/07/2018

Without Prejudice

Your Reference : SLT6918R

Our Reference : SLK1989R

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Fong Soon Yee	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Aashweenjeet Kaur (Aashween)
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: BHAS - Jacelyn Loh [<mailto:jacelyn.loh@bhauto.com.sg>]
Sent: Monday, July 30, 2018 1:05 PM
To: AIG SGP, Claims-Survey
Cc: BHAS - Moo Wen Zheng; BHAS - Anthony Lau; BHAS - Bernard Kee
Subject: pre repair inspection (OUR VEHICLE - SLT6918R / YOUR VEHICLE - VSLK1989R)

To: the officer in charge

Dear sir, mdm,

I would like to arrange surveyor on of the above mentioned accident vehicle.

Ps- vehicle currently not in our workshop.

Appreciate awaiting for your favourable reply asap. Please kindly assist.

Greatly appreciate it. Thank you and have a nice day

Thank You & Best Regards,

Jacelyn Loh

 **BH AUTO SERVICES PTE LTD**

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singapore: 575636

(T) +65-6559 8944 / 8940 (F) +65-6515 3144 / +65-6269 2404

Email: Jacelyn.loh@bhauto.com.sg

Website: <http://www.bhauto.com.sg>

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Hsiao Tong (LKKAUTO)

From: Ng, Hai-Chuan <Hai-Chuan.Ng@aig.com>
Sent: Monday, 20 August 2018 11:00 AM
To: Hsiao Tong (LKKAUTO); Vivian Lau (LKKAUTO)
Subject: CLaim No: 2411522314SG

Dear both,

We refer to the above.

Please establish liability prior to settlement.

Thank you.

Regards,

Ng Hai Chuan
AIG
Senior Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way AIG Building #08-16 Singapore 079120

Tel +(65)6419 1994| Fax +68357416

Hai-Chuan.Ng@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Hsiao Tong (LKKAUTO)

From: Ng, Hai-Chuan <Hai-Chuan.Ng@aig.com>
Sent: Monday, 28 January 2019 3:32 PM
To: Hsiao Tong (LKKAUTO)
Cc: Ng, Grace-TA
Subject: RE: Claim No: 2411522314SG *LKK REF: CC4/LCR18013898/Kpb3

Importance: High

Dear Hsiao Tong,

Please proceed to settle at 50%.

Do note that Grace has taken over this matter from us.

Thank you.

Regards,

Ng Hai Chuan

AIG

Senior Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way AIG Building #08-16 Singapore 079120

Tel +(65)6419 1994

Hai-Chuan.Ng@aig.com | www.aig.sg

AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards.
[Click here to find out more.](#)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Monday, January 28, 2019 3:00 PM
To: Ng, Hai-Chuan
Subject: RE: Claim No: 2411522314SG *LKK REF: CC4/LCR18013898/Kpb3

Hi Mr Ng,

We refer to our below email.

Kindly let us have your instruction.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Thursday, 6 December 2018 12:18 PM

To: 'hai-chuan.ng@aig.com' <hai-chuan.ng@aig.com>

Subject: RE: Claim No: 2411522314SG *LKK REF: CC4/LCR18013898/Kpb3

Hi Mr Ng,

We refer to our below email.

Kindly let us have your instruction.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Saturday, 3 November 2018 9:44 AM

To: 'hai-chuan.ng@aig.com' <hai-chuan.ng@aig.com>

Subject: RE: Claim No: 2411522314SG *LKK REF: CC4/LCR18013898/Kpb3

Hi Mr Ng,

We refer to the above matter.

Third party reported that accident happened at Newton Flyover. There was no details on how the accident happen. Based on third party sketch plan, it seems like OID changed lane and hit onto his car.

OID reported that third party cut into his lane and resulted the accident.

There was no video footage from both parties.

Based on OID scene photo, the position of third party vehicle remained on lane 2 after collision which suggests that third party was on lane 2 before collision. Otherwise he should have remained on lane 3 after side swipe. The vehicle sustained denting indicate that it has received impact force from another party involved.

The above are merely an observation without any concrete evidence produced by either party. Therefore, we would like to propose 50/50 settlement.

Kindly let us have your comments/ instruction after reviewing the case.

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng, Hai-Chuan <Hai-Chuan.Ng@aig.com>

Sent: Monday, 20 August 2018 11:00 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>

Subject: CLaim No: 2411522314SG

Dear both,

We refer to the above.

Please establish liability prior to settlement.

Thank you.

Regards,

Ng Hai Chuan

AIG

Senior Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way AIG Building #08-16 Singapore 079120

Tel +(65)6419 1994| Fax +68357416

Hai-Chuan.Ng@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies

or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

BH AUTO SERVICES PTE LTD

BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636

Tel: 6559 8944 Fax: 6269 2404

CO. REG. NO. 200917512K

GST REG NO. 200917512K

PLEASE QUOTE OUR FILE REFERENCE WHEN REPLYING

Your Reference: SLK1989R

Our Reference: SLT6918R

Date: 07/09/2018

M/s AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#07-16
Singapore 079120

BY EMAIL ONLY

Attention: Claims Department

CLAIMANT: HAND GREGORY LEWIS

PROPERTY DAMAGED CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 28/07/2018 ALONG SCOTT RD TWDS NEWTOW @ NEWTON CIRCUS INVOLVING VEHICLE NO SLT6918R & SLK1989R

We act for HAND GREGORY LEWIS who was the owner of motor vehicle no. SLT6918R.

We are instructed by the above named to claim damages against you/your insured in connection with a road traffic accident on 28/07/2018 involving our client's vehicle registration number SLT6918R and vehicle registration number SLK1989R driven by you/your insured at the material time.

We are instructed that the accident was caused by you/your insured's negligent driving and /or management of your/you insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

1	Cost of Repair (Included 7% GST)	\$ 3584.50
2	Loss of Rental (\$120.00 x 6days) GST 7%	\$ 770.40
3	LTA Search Fee	\$ 7.45
	Total :	\$ 4362.35

We enclose a copy of each of the following documents for your consideration:-

- (a) GIA/ Police report lodged by driver of;
- (b) Final Repair Bill
- (c) Rental Invoice / Loss Of Use
- (d) LTA Search Fee Invoice
- (e) Letter Of Authorization

Kindly revert to our client's claim within the next 7 days.

Yours faithfully,

YUN SHI

(O): 6559 8944 (F): 6269 2404

Email: yunshi.chan@bhauto.com.sg



Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Tuesday, 29 January 2019 10:41 AM
To: 'BHAS - Jacelyn Loh'
Cc: BHAS - Moo Wen Zheng; BHAS - Bernard Kee; BHAS - Chan Yun Shi; Admin A
Subject: RE: CHECKING OF LIABILITY - ACCIDENT INVOLVING OUR INSURED VEHICLE SLK1989R AND SLT6918R ON 28/07/2018 *LKK REF: CC4/LCR18013898/Kpb3

Without Prejudice

Dear Sirs/Mdm,

We are of the opinion that this is a case of conflicting versions. There is no concrete evidence (ie: Video footage) yet to support either party's version. Enclosed herewith in this email is a copy of our insured's accident report for your perusal.

Strictly without admission of liability whatever, but with a view towards a resolutions of your client's claim in the above matter without resort to litigation, we propose settlement at a global sum of **\$2,120.00(all-in)**.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: BHAS - Jacelyn Loh <jacelyn.loh@bhauto.com.sg>
Sent: Tuesday, 15 January 2019 6:23 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Cc: BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>; BHAS - Bernard Kee <bernard.kee@bhauto.com.sg>; BHAS - Chan Yun Shi <yunshi.chan@bhauto.com.sg>
Subject: RE: CHECKING OF LIABILITY - ACCIDENT INVOLVING OUR INSURED VEHICLE SLK1989R AND SLT6918R ON 28/07/2018 *LKK REF: CC4/LCR18013898/Kpb3

Dear all,

PS: kindly advise me on liability on case. Thanks

Thank You & Best Regards,
Jacelyn Loh

Hsiao Tong (LKKAUTO)

From: BHAS - Chan Yun Shi <yunshi.chan@bhauto.com.sg>
Sent: Tuesday, 29 January 2019 12:11 PM
To: Hsiao Tong (LKKAUTO); BHAS - Jacelyn Loh
Cc: BHAS - Moo Wen Zheng; BHAS - Bernard Kee; Admin A
Subject: accept offer - ACCIDENT INVOLVING OUR INSURED VEHICLE SLK1989R AND SLT6918R ON 28/07/2018 *LKK REF: CC4/LCR18013898/Kpb3

Dear Hsiao Tong ,

We accept below offer global sum @ \$2120.00 all in.

Appreciate you can assist to proceed DV for us.

Thank you.

Best Regards,

Yun Shi

BH AUTO SERVICES PTE LTD

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singapore: 575636

(T) +65-6559 8944 / 8942 (F) +65-6515 3144 / +65-6269 2404

Email: yunshi.chan@bhauto.com.sg

Website: <http://www.bhauto.com.sg>

From: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Sent: Tuesday, January 29, 2019 10:41 AM
To: BHAS - Jacelyn Loh <jacelyn.loh@bhauto.com.sg>
Cc: BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>; BHAS - Bernard Kee <bernard.kee@bhauto.com.sg>; BHAS - Chan Yun Shi <yunshi.chan@bhauto.com.sg>; Admin A <admin-a@lkkauto.com>
Subject: RE: CHECKING OF LIABILITY - ACCIDENT INVOLVING OUR INSURED VEHICLE SLK1989R AND SLT6918R ON 28/07/2018 *LKK REF: CC4/LCR18013898/Kpb3

Without Prejudice

Dear Sirs/Mdm,

We are of the opinion that this is a case of conflicting versions. There is no concrete evidence (ie: Video footage) yet to support either party's version. Enclosed herewith in this email is a copy of our insured's accident report for your perusal.

Strictly without admission of liability whatever, but with a view towards a resolutions of your client's claim in the above matter without resort to litigation, we propose settlement at a global sum of **\$2,120.00(all-in)**.

Please confirm acceptance.

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Wednesday, 8 August 2018 11:51 AM
To: 'Eileen, May Hwee Yap'
Subject: ACCIDENT INVOLVING SLK 1989R(AIG) & SLT 6918R ON 28/07/2018

Your Ref: **SLK 1989R**
Our Ref: CC4/LCR18013898/Kpb3

Dear Sir/Madam,

ACCIDENT INVOLVING SLK 1989R(AIG) & SLT 6918R ON 28/07/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from SLT 6918R against your insurance policy.

Both parties involved have given conflict of version. We are of the view that the case would be settled at equal liability.

If you have evidence/information to prove that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by **19/08/2018**, after we shall proceed with negotiation with Third Party claimant on the without prejudice basis and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please call us if you have further queries.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

AUTHORISATION

Name of owner of mv/vehicle: Hand Gregory Lewis

Address: -

NRIC No: F5599076W

RE ACCIDENT ON 28/07/18 ALONG Scott Rd Towards Newton (A) Newton Circus

INVOLVING SLT 6918R VS SLK 1989R

In consideration of **BH AUTO SERVICES PTE LTD** ("the Workshop") repairing my/our vehicle no SLT 6918R at my/our request. I/We the abovenamed owner of motor vehicle no SLT 6918R hereby authorise the Workshop to demand claim, negotiate, settle my/our claim for cost of repairs loss of use and all other expenses and damages arising out of the above accident.

I/We further authorise the Workshop to appoint solicitors to demand claim, negotiate, settle and/or commence legal proceedings in my/our name for the above purpose and at the sole discretion of the Workshop. All sums recovered therefrom shall belong to the Workshop absolutely and I/We further authorise the Workshop to give absolute discharge on my/our behalf and to sign all discharge vouchers and other documents in relation to the same on my/our behalf. I/We further agree to fully co-operate with the solicitors appointed by the Workshop on my/our behalf and attend all Court hearings that are necessary to prosecute the claims maintained by the Workshop.

I/We agree that in the event that the claim is rejected for whatsoever reason or the Workshop decides not to proceed with legal proceedings or for whatsoever reason the Workshop is unable to recover all of the repair costs or are only able to recover a portion of the same I/we hereby undertake to pay them the full repair costs and or any portion thereof that cannot be recovered and all expenses including legal costs that they may have incurred in pursuing the claim within 7 days from the date of the written notice for payment by them to my/our last known address.

I/We hereby declare that I/we will always remain and be liable to the Workshop for the cost of repair to my/our motor vehicle and expenses incurred on my/our behalf. In the event that Workshop has to issue any notice or commence legal proceedings against me/us to enforce this undertaking against me/us, I/we shall be liable for the Workshop's expenses and legal cost (including solicitor and client cost) on an indemnity basis.

I/We further authorise the Workshop to give to the other party/parties absolute discharge in respect of any liability and any sum, whether agreed or not made the Workshop or to the law firm appointed by the Workshop towards full settlement of my/our claim it shall be regarded as full and final discharge of the claim.

I/We further authorise the Workshop to settle the above mentioned claim in a manner that they deem fit and the Workshop is further authorised to receive payment further to settlement of my claim with payment cheque/s being made in favour of the Workshop.

Date this 29 (day) of 7 (month) 2018 (year)

Signed

Gregory L Hand

Owner of mv/vehicle: Gregory L Hand

HP: 93866073

Witnessed:

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **BH AUTO SERVICES PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$2,120.00** (Global Sum) for vehicle no. **SLT 6918R** that was damaged pursuant to the accident which occurred on **28/07/2018** (date) along **SCOTT RD TOWARDS NEWTON @ NEWTON CIRCUS** involving vehicle no/s **SLK 1989R**.

This is pursuant to the inspection conducted on **01/08/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **HAND GREGORY LEWIS** ("the third party claimant") of vehicle no. **SLT 6918R** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SLT 6918R** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 31 (day) of January (month) 2019 (year)


KSC

Signed by appointed surveyor

Signed by "the workshop" (with chop)

BH AUTO SERVICES PTE LTDBLK 1 SIN MING INDUSTRIAL ESTATE
SECTOR C #01-115 SINGAPORE 575636

Tel: 6743 3494

Fax: 6269 2404

CO. REG. NO. 201006106C

GST REG NO. 201006106C

TAX INVOICE**Final Repair Bill****Our Ref: SLT6918R****Date: 07/09/2018**M/s AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#07-16
Singapore 079120

BY EMAIL ONLY

Vehicle No : SLT6918R
Make/ Model : MAZDA RX
Year of Manufacture : 2008
Chassis No. : SE3P301657
Colour : WHITE
D.O.A : 28/07/2018

QTY	ITEM/PARTICULARS	AMOUNT (S\$)
-----	------------------	--------------

I. Repair Cost for Motor Vehicle No. **SLT6918R**
Type of repair: LUMP SUM :S\$ 3350.00

GST @ 7% : S\$ 234.50

GRAND TOTAL :S\$ 3584.50**Total : Singapore Dollars Three Thousand Five Hundred and Eighty - Four Dollars and Fifty Cents Only.**

Company's Stamp & Signature



BH AUTO SERVICES PTE LTD

BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-111/113/115/117
SINGAPORE 575636 TEL (65) 6559 8944 FAX (65) 6289 2404
CO. REG NO : 200917512K GST REG NO : 200917512K

VEHICLE RENTAL AGREEMENT

Owner: BH AUTO SERVICES PTE LTD ("the owner") Date: 1/8/2018
Hirer: Katherine Almazar Hand Tel / HP: 9386 6075
NRIC / Co. Reg No: F2052596R FAX: _____
Address: _____

Owner and Hirer have agreed to this Vehicle Rental Agreement for the motor vehicle described below and upon the Terms and Conditions contained on both sides of this document. Hirer acknowledges having read and understood all the Terms and Conditions and signifies acceptance upon signing.

Owner Vehicle No. <u>SLT 6918R</u>	
Vehicle Reg. No. <u>SLM3160R</u>	Rental:
Odometer:	
Date & Time Out: <u>1/8/2018 15:35pm</u>	Hirer's Signature: <u>Kathy Q. Hand</u>
Date & Time In: <u>05/08/18</u>	Hirer's Signature: _____

Third Party Claim

In respect of each third party insurance claim arising from the date of hire to date of return of the vehicle (both dates inclusive). Hirer unconditionally agrees to pay Owner S\$ 3000.00 comprising excess payable and compensation to Owner for impact of claim on future motor insurance premiums.


Own Vehicle Damage

Hirer is responsible for the first S\$ 3000.00 excess for collision or damage to first party (owner) and shall pay additional plus loss of earnings while damaged vehicle is under repair.

BH AUTO SERVICES PTE LTD



Authorised Signature



Hirer's Signature



明輝汽車服務私人有限公司
BH AUTO SERVICES PTE LTD

NO. 213, ARANJ ROAD, SINGAPORE 728465 TEL: (65) 6339 8844
FAX: (65) 6339 3144 C.O. REG. NO. 20081212N, GST REG. NO. 200817812N

Reference No.: CS04016

Invoice No.:

Customer Name: Hand Gregory Lewis

Date/ Time:

Address:

Mobile Number:

93866075

Car Make & Model:

MAZDA RX8

Car Plate No:

SL7G918D

SN	Services Provided	Brand	Qty	Unit Price	Amount
1	Towing Service				S\$
2	Battery				S\$
3	Tyres				S\$
4	Others: <u>Partial fee</u>	<u>SLM 260R</u>	<u>76</u>	<u>\$120.00</u>	<u>720.00</u>
Total Amount (inclusive of GST):					<u>S\$ 840.00</u>

Special Remarks

from 01/08/18 to 06/08/18

\$770.40

Service Done by:

Acknowledged by:

Received by:

Sales Person Name & Signature

Customer Name & Signature

Finance Department

> Back to OneMotoring



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 30 Jul 2018 / 12:12:31

Receipt Date/Time : 30 Jul 2018 / 12:12:31

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180730-000872

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
Result of Insurance Enquiry - SLK1989R				
As at 28 Jul 2018/21:10:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SLK1989R Enquiry Fee 20180730121112817800	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx0796	Credit Card: Visa/MasterCard		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK

Save as PDF

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jul 2018 Edit Reg		31 Jul 2018 00:00 Edit Adj Rpt	S\$3,350.00 Edit Estimates	S\$3,350.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: LCRF PTE LTD , Co. Reg. No.: 201624597K									
Main Claimant: HAND GREGORY LEWIS , ID: F5599076W									
Vehicle Reg. No.:	SLT6918R	Date of Loss:	28/07/2018 21:00 - :59 [115 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 2411522314SG	Policy/Cover Note No.:	0999994810 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLK1989R	Policy No. (Claimant):	GA289048/1						
		Excess:							
Repairer:	BH Auto Services Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117, 575636 Sin Ming - Tel: 6559 8944								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ng, Grace-TA] Tianaigrace.Ng@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 10/08/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLT6918R (2411522314SG)
[SLK1989R]
TP
HAND GREGORY LEWIS
Jul 28 2018 9:00PM
[LCRF PTE LTD]
BH Auto Services Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	{Draft}	Third Party Express Settlement – Payment Breakdown												1	Edit					
															1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
Assessment Reports															1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. {SG}													Thumbnail	Print				
1	01/08/18 11:00	Accident Statement From: SC – Reg. No: SUK1989R, Claimant: LCRF PTE LTD												1	Load HTM					
															3 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
Photos/Images															3 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	08/08/18 11:46	General View												1	Load JPG	<input checked="" type="checkbox"/>				
2	08/08/18 11:46	General View												1	Load JPG	<input checked="" type="checkbox"/>				
3	08/08/18 11:46	General View												1	Load JPG	<input checked="" type="checkbox"/>				
4	08/08/18 11:46	General View												1	Load JPG	<input checked="" type="checkbox"/>				
5	08/08/18 11:46	General View												1	Load JPG	<input checked="" type="checkbox"/>				
6	08/08/18 11:46	General View												1	Load JPG	<input checked="" type="checkbox"/>				
7	08/08/18 11:46	General View												1	Load JPG	<input checked="" type="checkbox"/>				
8	08/08/18 11:46	General View												1	Load JPG	<input checked="" type="checkbox"/>				
9	08/08/18 11:46	General View												1	Load JPG	<input checked="" type="checkbox"/>				
10	08/08/18 11:46	Odometer Reading												1	Load JPG	<input checked="" type="checkbox"/>				
11	08/08/18 11:46	Chassis Number												1	Load JPG	<input checked="" type="checkbox"/>				
12	08/08/18 11:46	General View												1	Load JPG	<input checked="" type="checkbox"/>				
13	08/08/18 11:46	General View												1	Load JPG	<input checked="" type="checkbox"/>				
14	08/08/18 11:46	General View												1	Load JPG	<input checked="" type="checkbox"/>				
															1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
Documentation															1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	31/07/18 14:54	TP GIA REPORT												1	Load PDF					
2	31/07/18 14:54	EMAIL FROM AIG DO 31072018												1	Load PDF					
3	03/08/18 09:24	TP ESTIMATE- MARKED												1	Load PDF					
4	01/02/19 14:21	WORKSHOP INVOICE												1	Load PDF					
5	01/02/19 14:21	AUTHORISATION TO ACT FORM												1	Load PDF					
6	01/02/19 14:21	Release Voucher												1	Load PDF					
7	01/02/19 14:21	RENTAL RECEIPT												1	Load PDF					
8	01/02/19 14:21	LTA SEARCH												1	Load PDF					
9	01/02/19 14:21	LETTER TO OI												1	Load PDF					

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLK1989R (Insd veh)	Model:	MAZDA RX-8 1.3 (A)
	SLT6918R (TP veh)		
Date of Accident:	28/07/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes		<input type="checkbox"/> No	
Repair Estimate	:	\$		10,286.34	
Final Repair Cost	:	\$		2,120.00	
Loss of Use	:	\$			days at \$0.00 per day
Rental (if any)	:	\$			6 days
LTA / GIA Search Fee	:	\$			
Others:	:	\$			
	:	\$			
Final Settlement Sum (Global Sum)	:	\$		2,120.00	

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 50 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	BH Auto Services Pte Ltd	:	\$ 2,120.00
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

01 Feb
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/LCR18013898/KPB3Q2

Date: 01/02/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994810
Claimant Vehicle No : SLT6918R **Insured Vehicle No :** SLK1989R
Date of Loss: 28/07/2018 **Nature of Claim:** TP **Claim No:** 2411522314SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLT6918R**
 Make & Model: MAZDA RX-8, 1.3 (A) Engine No: 13B544608
 Reg. Date: 12/12/2008 (Man. Year: 2008) Chassis No: SE3P301657
 Colour: White Odometer: 72585 km
 Engine Capacity: 1308 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
 Front Left Side: Yokohama 9 mm Rear Left Side: Yokohama 9 mm
 Front Right Side: Yokohama 9 mm Rear Right Side: Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,223.40	2,901.60	3,321.80	53.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,390.00	1,320.00	2,070.00	61.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,613.40	4,221.60	5,391.80	56.09
Approved Total (Overridden) (S\$)		3,350.00		
(S\$)	9,613.40	3,350.00	6,263.40	65.15
+ GST 7.00/7.00% (S\$)	672.94	234.50	438.44	65.15
Nett Amount (S\$)	10,286.34	3,584.50	6,701.84	65.15
+ Car Rental (6.0 x S\$100.00/day + 7.00% GST) (S\$)		642.00		
(S\$)		4,226.50		
Liabe Amount (50.00%) (S\$)		2,113.25		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,120.70		
Global Sum Settlement (S\$)		2,120.00		

INSPECTION

Date of Assignment: 31/07/2018
Date Inspected: 01/08/2018 Inspected At: BH Auto Services Pte Ltd (Sin Ming)
Blk 1 Sin Ming Industrial Estate Sector C,
#01/111/113/115/117
Singapore 575636
Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Bent	752.00 FL	*752.00 FL
2	1		*FRONT FENDER SHIELD FRONT SECTION LH	Serviceable	139.00 FL	*- FL
3	1		*FRONT FENDER SHIELD REAR SECTION LH	Distorted	159.00 FL	*159.00 FL
4	12		*FRONT FENDER SHIELD CLIPS	Necessary	48.00 FL	*48.00 FL
5	1		*FRONT FENDER LAMP LH	Serviceable	187.00 FL	*- FL
6	1		*FRONT WHEEL RIM LH	Dented	1,350.00 FL	*1,350.00 FL
7	1		*FRONT ABSORBER LH	Serviceable	420.00 FL	*- FL
8	1		*FRONT LOWER ARM LH	Serviceable	576.00 FL	*- FL
9	1		*FRONT KNUCKLE ARM LH	Serviceable	380.00 FL	*- FL
10	1		*FRONT KNUCKLE ARM BEARING LH	Not Necessary	672.00 FL	*- FL
11	1		*FRONT TIE ROD LH	Serviceable	125.00 FL	*- FL
12	1		*FRONT TIE ROD END LH	Serviceable	153.00 FL	*- FL
13	1		*FRONT DOOR LH	Bent	1,225.00 FL	*1,225.00 FL
14	1		*FRONT DOOR HINGE UPPER LH	Repair	43.00 FL	*- FL
15	1		*FRONT DOOR HINGE LOWER LH	Repair	43.00 FL	*- FL
16	1		*FRONT DOOR FRAME PILLAR STICKER LH	Necessary	93.00 FL	*93.00 FL
17	1		*FRONT DOOR WEATHERSTRIP LH	Serviceable	108.00 FL	*- FL
18	1		*ROCKER PANEL LH	Repair	950.00 FL	*- FL
19	1		*FRONT TYRE LH	Serviceable	285.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,708.00	3,627.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,484.60	725.40
Total Parts (\$\$)	6,223.40	2,901.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ANTI-RUST COATING	New	240.00	60.00
2	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS ,PANEL BEAT ,CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS	New	1,250.00	500.00
3	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITATES	New	1,250.00	600.00
4	PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING	New	60.00	20.00
5	REMOVE AND REINSTAL CUSHIONS ,SEATS ,BACKREST INNER TRIM GARNISH ,ROOF LINING AND OR UPHOLSTERY TO FACILITATE REPAIRS	New	150.00	0.00
6	DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM TO NEW DOOR /FACILITATE REPAIR	New	80.00	60.00
7	PROVIDE SKILL LABOUR TO CHECK AND RE-ADJUST WHEEL ALIGNMENT	New	80.00	60.00
8	PROVIDE SKILL LABOUR TO REMOVE AND REPLACE/REFIT FRONT LH UNDERCARRIAGE	New	200.00	0.00
9	PROVIDE SKILL LABOUR TO REMOVE AND REPLACE /BALANCING WHEEL RIM WITH TYRE	New	80.00	20.00
Gross Labour Cost (S\$)			3,390.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >