

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

FB511BA

FOOD PARADISE ENTERPRISE PTE LTD
7 MANDAI LINK
#06-25 MANDAI CONNECTION
S 728653

TPAXA
Vic

Date :03.09.2018
Vehicle no :GY 4604 S
Make/Model :MIT FB511
Accident date :19.03.2018

No	DESCRIPTION	Qty	Amount (\$S)
List Items			
1	Front RH corner panel <i>Dented</i>	1	\$ 554.4
2	Front grille <i>cracked</i>	1	\$ 624.8
3	Front RH side lamp <i>cracked</i>	1	\$ 627 <i>198</i>
4	Front RH door <i>Ryis</i>	1	\$ 1980 <i>+</i>
5	Front RH door inner rear ruber <i>new</i>	1	\$ 217.8 <i>+</i>
6	Front RH door pillar <i>Ryis</i>	1	\$ 1810.6 <i>+</i>
		25%	\$ 5814.6
		Less 20% Disc	\$ 1162.92
		Total	\$ 4651.68

Special Nett Items

- 1 Front RH door sticker

100

1

\$ 300 *100*

Total

\$ 300

Labour Cost

- 1 Remove, replace & repair consistent to the accident
2 Respray painting

600

\$ 900 *300*

\$ 1000 *300*

Total

\$ 1900

Grand Total

\$ 6851.68

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 1732.90

h/s: 1.3K

03 Days