

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0875/2018
DATE : 30-JUL-2018

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 63387288
FAX : 68804838/ 3382522
MS LINA EXT: 824

OWNER'S NAME : MOHAMAD KHAIRUL BIN MOHAMAD
ADDRESS : APT BLK 258A PUNGGOL FIELD
#13-13
S(821258)
TELEPHONE NO : 92365629

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1
VEHICLE NO : SMC5761J
MODEL CODE : SJ5EK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20YE26648
CHASSIS NO : JF1SJ5KC5JG111474
MILEAGE : 1 KM
DATE IN : 30/07/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : KUAN WEI LOONG**
ACCIDENT DATE : 24/07/2018

Print Date : 01/08/2018
Print Time : 13:12:12

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMC5761J

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST FBH4533L - AXA		
2	ZZ/001	CONDUCT TP CLAIM AXA LOCATION:PIE TUAS@LAMP POST 925 DATE:24/07/2018 TIME:1820HRS		
3	ZZ/002	REPAIR/REPLACE REAR BUMPER, REAR LEFT FENDER AND PANEL	2800.00	5601
4	ZZ/003	RESPRAY REAR BUMPER, REAR LHS FENDER AND PANEL	2100.00	X
5	ZZ/004	TRANSFER/BALANCE TYRE/RIM REAR LHS	50.00	X
6	ZZ/005	WHEEL ALIGNMENT	200.00	X
7	ZZ/006	REMOVE & REFIX CARPET, SEATS TO FACILITATE REPAIR	400.00	X
8	ZZ/007	REMOVE & INSTALL REAR LEFT QUARTER GLASS	180.00	X
9	ZZ/008	TO CONDUCT REAR LIGHTING TEST	50.00	301
10	ZZ/009	TO SUPPLY & INSTALL REVERSE SENSOR-2 EYES	300.00	X
11	ZZ/011	SUNDRIES	100.00	?
12	ZZ/10	TO SUPPLY & INSTALL REAR LEFT TINTED FILM	145.00	X
TOTAL LABOUR CHARGES			6325.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMC5761J

		DAMAGED PARTS & PRICES				
S/NO PARTS DESCRIPTION	PARTS NUMBER		NETT	LIST	S/NETT	S/LIST REMARKS
1 DISC WHEEL AL 17	28111SG130	SL	1500.00	X		
2 PNL SD OUT QTR RPLH	51439SG0119P	N	864.00	X		
3 BUMPER FACE REAR FORESTER IL	57704SG012	N	540.00	X		
4 BRKT CORNER R RH	57707SG060	SL	18.00	X		
5 BRKT CORNER R LH	57707SG070	SL	18.00	X		
6 BRKT SD R RH	(1) 57707SG080	N	14.40	X		
7 BRKT SD R LH	57707SG090	N	14.40	X		
8 BEAM COMPL R EU	57711SG0219P	N	288.00	X		
9 REFLEX AY LH	84281SC010	SL	20.40	X		
10 LENS & BODY COMPLJPL	84912SG111	CM	432.00			
11 FORESTER 2.0I-S KIT REAR UNDER SPOILER (TCS)	TCS-FJ8-RL-002	CM	828.00			
SUB TOTAL			4537.20	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			907.44	0.00	0.00	0.00
GRAND TOTAL			3629.76	0.00	0.00	0.00
OVERALL TOTAL			3629.76			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMC5761J

TOTAL LABOUR CHARGES	6325.00
TOTAL SPARE PARTS CHARGES	3629.76
GRAND TOTAL	9954.76 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:
SURVEYED DATE	:
AUTHORIZED DATE	:
EXCESS CLAUSE	: 0.00
LIABILITY	: 0.00
REMARKS	:

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

Not Notified
Heavy After Pain
1 day

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: