



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI  
MOTORS

### ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
JN TRANSPORTATION  APT B1k 662 JALAN DAMAI #04-135 SINGAPORE 410662 Contact No Mobile: 91183962 NEO	Cust No/Name	/Ms Mischa Leigh Pereira
	Reg No/Reg Date	SJX6966D / 01/07/201
	Date In/Mileage	/ 0
	Chassis No	JMYSRCY2AAU000796
	Engine No	4A910129334
	Make/Model	MIT/ LANCER EX 1.5 MIVEC 4AT ELE
	Colour/Trim	W03 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	30/07/2018/ 17:26	QUD	247 / DonBong	29067
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW ACCIDENT DAMAGED PARTS ON REAR BOOT LID, REAR BUMPER FACE, REPAIR REAR END PANEL				1375 1450 3520.00
E PNT88000	REMOVE AND INSTALL PARKING ASSIST				60 80.00
E PNT88000	REMOVE AND INSTALL REAR CABIN, SIDE TRIM AND OTHERS ATTACHMENT TO FACILITATE REPAIR				150. 180.00
E PNT98000	PAINT WORK SPRAY REAR END PANEL, REAR BOOT LID, REAR BUMPER AND AFFECTED PORTION				840 1680.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				✓ 200.00
M SUNDRY	SUPPLY PARKING SENSOR				AW 220.00
M SUNDRY	SUPPLY BODY SEALANT				? 120.00
M SUNDRY	SUPPLY C&C LOGO				WC 50.00
M SUNDRY	SUPPLY REAR BUMPER PLATE WITH FRAME				bt 50.00
M SUNDRY	SUNDRIES				20 50.00
M REINFORCEMENT, RR BUMPER		1.00	90.00	00.00	? 90.00
M PANEL, RR END		1.00	556.00	00.00	RY 556.00
M REINFORCEMENT, RR BUMPER		1.00	231.00	00.00	? 231.00
M BRKT, R/BMPR FACE SUPT, LH		1.00	17.00	00.00	? 17.00
M BRKT, R/BMPR FACE SUPT, RH		1.00	4.00	00.00	? 4.00
M FACE, RR BUMPER		1.00	852.00	00.00	de 852.00
P GROMMET, FR BUMPER		2.00	4.00	00.00	W 8.00
M PANEL, TRUNK LID		1.00	662.00	00.00	RY 662.00
M WEATHERSTRIP, TRUNK LID		1.00	182.00	00.00	X 182.00
Confirm & accepted by					
Authorized signatory and company stamp					

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

## ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
JN TRANSPORTATION	Cust No/Name	/Ms Mischa Leigh Pereira
APT B1k 662 JALAN DAMAI	Reg No/Reg Date	SJX6966D / 01/07/201
#04-135	Date In/Mileage	/ 0
SINGAPORE	Chassis No	JMYSRCY2AAU000796
410662	Engine No	4A910129334
Contact No Mobile: 91183962 NEO	Make/Model	MIT/ LANCER EX 1.5 MIVEC 4AT ELE
	Colour/Trim	W03 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00041	Cash	30/07/2018/ 17:26	QUD	247 / DonBong	29067		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	LATCH, TRUNK LID			1.00	74.00	00.00	X 74.00
M	MARK, THREE-DIA			1.00	51.00	00.00	net 51.00
M	MARK, LANCER			1.00	54.00	00.00	net 54.00
M	MARK, EX			1.00	40.00	00.00	net 40.00

# Estimate

SURVEYOR NAME: Tanpha 97495749

SURVEYOR SIGNATURE: Tanpha

DATE: 8/8/18 P 2:45 pm

REMARKS: Reming before print  
4-5 days  
surelbrando.com

Confirm & accepted by

	Nett	8,971.00
7% GST on	8971.00	627.97
	<b>Total Payable</b>	<b>9,598.97</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.