Meximon	Tauther	ASSIGNME		S*	
		_ of C	71	Date/Time: 31	1/18 8 4.55 pm
Estimated Co.			Bill to		
To Inspect Ve		sto 7536		Insured: SGX 6	
at Workshop of	7 - 0/2	Id Vich	eening telk Rd	Tel: 65137	148
Policy No:	DMPC8N1667	521701	Claim No:	SNM18D034260	02
Sum Insured.			Excess.		
Make of Veh	The last of the la			D.O.A. 1010F	8106 7
(Client's Record CA / REV Date/Time:	/ REP. / REV 24 HRS 5:33pm631 7 18	Person Contacted	Wee	Ollow 2018 H.O.D. Endorsement Vehicle (IN)OUT	
Date/Time	Action/Instruction (T Estimate		valled (11)	
10/180	SGX 6005 M-> 4-32 Confirm CRed \$ 3783.1	ed with h	Jee firms	ftg \$1989,20, 2	drys.

(08(11)53) REF:	CTI			
Simeyor: 1 mgm	ASSIGNMENT			S— ca—angues —av a d
* *		SLQ7356T	2017	Th.
From: Date:	Veh No:			()
Estimated Cost:		M.Cycle / Bus / Van / Lo	orry / Taxi / Prime move	
OD / TP /WS / TP RES / OD RES / EVA / INV / MV		Trailer or		1496
To Inspect Vehicle No:	Make:	Rhe S	C.C	
at Workshop m/s	Colour		A/C: Insured / St	
of	Sp.Reading	67783	T/Radio: Insured / St	Id / NI / NA
Insured:	Eng/No:		- 001 01	2 0 0 0
Policy No.	C/No:	2m 600	122 ASH 01	5 2909
Claims No.	Gen. Cond: 0	Good Fair / Poor / Burn	t	
Sum Insured: Excess:	Steering: Inc	rder / Jammed / Leaked	/ Burnt or	
(Client's Record)	Brake: Inc	order/ Jammed / Leaked	/ Burnt or	
Make of Veh:	Modi: Nil	/ S/Rim / STD A/Rim, o	N meaning -	
rz – <u>9</u> 8	Tyre Size:	F: 205/	66K14	
(Policy Condition)		'R: ^	_	
Remark: The veh had commenced its	N/S O/S BS / DUN / E	EXNOVA / GY / FS / LIZA	/ MIC / OHTSU / PIR / S	SUMI/
repair at the time of inspection.	TOYO / YO	KO or U	lest lake	
Bal. or Market Value:	Front		Rear	
IDAC Accident Rport: Consistent? : Yes or	No R/Bal.	mm	R/Bal.	mm
GIA / PR Seen: Consistent? : Yes or	A STATE OF THE STA	mm	L/Bal. 6	, nam
Est. Repairs: Yes o		V-W	D.O.I. 1/8/	18 0/63
Lat. repairs.		at Palay	as (7	
Lum Sum: % 3 Val.: Yes 0	100	nages : Frt / Rear / O/S	I N/S / U/C / Roofto	p or
CA / REV / REP. / 24 HRS	ehicle: IN / OUT	10g		
Date: Person Contacted:	The U/O	/ Chassis frame / Bo	dy Structure affected di	ue to collision.
Date / Time Action / Instruction				
			947	
RECEIVE	1 1 00T 2018			
	Y .			
			2014	
Date/Time, File Pass to? : Prell. Report	Days Of R	enair: >		
1. 1.04		No. of Trip:	Survey Fee:	
1) [[[D TV/W7] : Final Report Date/Time, File Return to?	Resurvey	no. or mp.	Transportation:	
Contract Contract Management and Contract	Add Fee: Site	e Insp (\$)S+RSSI	
2)		erview (\$) Photos	1 2
Report Format : WER TP		ch. Invs (\$) Others	B
Report Format : MER-1P Lump Sum / I.B.I: (\$ (989.20)	The state of the s	eekend (\$		
Equip dam 1.12.1. (e CO [-	<i></i>	v with the	TOTAL	220
			TO 18 (20 CA)	A CONTRACTOR OF THE PARTY OF TH



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

CHI	NA TAIDING INCLI	Affiliated to Federation Internation	Ref : CS/CTI1801392	Miles in the second sec	
CHII	NA TAIPING INSUI	VANCE (3) PIELID	Nei . Colo i i loci loci	zor i iquo	
	ISON ROAD #16-0 RINGLEAF TOWER	0 SINGAPORE 079909	Date: 31-07-2018		
			Code: CTI	35444-02-04000-00-00-00-00-00-00-00-00-00-00-00-	
1.		Policy Particulars	:- THIRD PARTY CLAI	IM	
	Insured Veh.	SGX 6005M	Veh. Inspected	SLQ 7536T	
	Policy No.	DMPCSN1667521701	Coverage (\$)	0.00	
	Claim No.	SNM18D03426C02	Excess (\$)	0.00	
	Assign From	MERIMEN (ELAINE CHEONG)	Assign Date	31/07/2018	
2.		Vehicle Parti	culars & Condition		
	Make & Model		c.c	0	
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No. Colour				
	Odometer	25	Steering		
	Brakes		Modification		
	General				
3.	161	Condit	ions of Tyres		
		Size	Make	Balance	
	R/H Front Tyre			mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre			mm	
	L/H Rear Tyre			mm	
4.		Descript	ion of Damages	AL EVENERA	
5.		Genera	al Information		
-	Accident Date	10/07/2018	Inspection Date	01/08/2018	
_	Survey held at	PEGASUS ENGINEERING & T			
	3,	51 DEFU LANE 10 SINGAPORE 539216			
5a.		A COLUMN TO PROPERTY FOR	Remarks	this is the late	
	A)THE INSPECTION	ON WAS CONDUCTED ON A"WI	THOUT PREJUDICE" BAS	SIS.	

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Sub	mitted	Ins Authred	Status		
Main	31 Jul 2018		31 Jul 2018 16:55 Assign					New Ass Cancel C	and the second	it
1	1ain	Ref	erence		Claim Details		Documen	ts		show All
CLAIM SU	BFOLDER DE	TAILS			SANT PROPERTY OF STREET	[Created	by insurer]	THE RESERVE		
Insured:	WONG FO	O WAH SPENCER	, ID: S700828	6A						
Main Claimant:	GRAB RE	NTALS 2 PTE LTD	Co. Reg. No.	: 20170134	5N					
Vehicle Reg. No.:	SLQ753	6Т			Date of Loss:	10/07/20	18 20:00 - :59			
Claim Type:	100-1-000	M18D03426C02			Policy/Cover Note No.:	DMPCSN1	.667521701 (Com	prehensive)		
Vehicle Reg. No. (Insured):	SGX6005	м			Policy No. (Claimant):	A29069774MKF				
					Excess:	S\$0.00				
Repairer:	Pegasus	Engineering & Tra	ding Pte Ltd (Kian Teck)	74 Kian Teck Ro	ad, 628800	Pioneer - Tel: 65	137751		
Handling Insurer:	The second second second second	ping Insurance (
Claimant's Insurer:		urance (Singapor								
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	[Final Rpt	due 10/0	8/2018]			
Driver/Custo dian (Insured):		O WAH SPENCER (4	8 / Male), NR	IC: S70082	86A					
Adj Asg. Remarks:	EST \$6176	.90, ASSIGN MARC	US CHUA AS S	E.						
ASSOCIAT	ED MAIL RE	CEIVED					17	View All C	ompose	Case Mai
There are no	mail for this	case.								
ALL ASSO	CIATED TAS	KS ⁼				View All	Search Tasks	Create New	Task	Complete
Due Date	Priority	Type Task 0	Froup Subj	ect Han	dler Assign	-	Completed On	_	ed On	Done
No results.				COSS PRIMER				61686	Cu On	white

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Wednesday, 10 October 2018 4:32 PM

To:

Pegasus Engineering

Cc:

Lionel Chua lionelchua@pegasusengrg.com.sg>; SUR

Subject:

RE: SLQ7536T TP-CHINA TAIPING (DOA-10/07/2018) Finalised on a Without

Prejudice basis

Dear Wee,

WITHOUT PREJUDISE

Confirm final fig \$1,989.20 before GST and 2 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto)

Sent: Wednesday, 5 September 2018 11:03 AM To: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Subject: FW: SLQ7536T TP-CHINA TAIPING (DOA-10/07/2018) Finalised on a Without Prejudice basis

CS/CTI18013926/T1qd3

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Pegasus Engineering <ar claims@pegasusengrg.com.sg>

Sent: Wednesday, 5 September, 2018 10:44 AM To: Taufikh (LKKAuto) < Taufikh@lkkauto.com >

Cc: Admin A <admin-a@lkkauto.com>; Lionel Chua lionelchua@pegasusengrg.com.sg>

lionelchua@pegasusengrg.com.sg>

Subject: Re: SLQ7536T TP-CHINA TAIPING (DOA-10/07/2018) Finalised on a Without Prejudice basis

Dear Taufikh,

Enclose a copy of the before paint photos for your reference.

Thank You

Best Regards,

Wee

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Company	
Owner ID:	1345N	
Vehicle Details		
Vehicle No.:	SLQ7536T	
Vehicle to be Exported:	Yes	
Intended De-registration Date:	11 Jul 2018	
Vehicle Make:	MAZDA	
Vehicle Model:	MAZDA3 SEDAN 1.5 AT EU6	
Primary Colour:	Blue	
Manufacturing Year:	2017	
Engine No.:	P520444562	
Chassis No.:	JM6BN22A8H0152909	
Maximum Power Output:	88.0 kW (118 bhp)	
Open Market Value:	\$14,761.00	
Original Registration Date:	21 Jul 2017	
First Registration Date:	21 Jul 2017	
Transfer Count:	0	
Actual ARF Paid: Intended PARF Rebate Details	\$9,761.00	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	20 Jul 2027	
PARF Rebate Amount:	\$7,320.00	
Intended COE Rebate Details		
COE Expiry Date:	20 Jul 2027	
COE Category:	A - Car up to 1600cc & 97kW (130bhp)	
COE Period(Years):	10	
QP Paid:	\$46,489.00	
COE Rebate Amount:	\$37,191.00	
Total Rebate Amount:	\$44,511.00	

The information contained herein is correct as at 11 Jul 2018

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT	
Date Of Report	11/07/2018 15:20	
Date Of Accident	10/07/2018 20:35	
Exact Location Of Accident	ALONG PIE/JURONG BEFORE CTE EXIT	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	

Vehicle Registration Number	SLQ7536T	
Insured/Policyholder		
Name Of Registered Owner	GRAB RENTALS 2 PTE LTD	

201701345N Co Reg No Email Address NOEMAIL

Mobile Phone No OFFICE-66550005 Alternative Phone No.

Vehicle Particulars MAZDA Manufacturer

MAZDA3 SEDAN 1.5 AT EU6 Model

Exact Purpose for which vehicle was being used at HIRE & REWARD time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

THIRD PARTY If No, Please state action to be taken PRIVATE HIRE Vehicle Category

YES

Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD. Name of Insurance Company

COMPREHENSIVE Type Of Coverage

Fleet Policy A29069774MKF Policy Number

Cover Note Number N.A

Driver

QUAH MING XUN Name of Driver S8815113E NRIC No 09/05/1988 Date Of Birth OUTDOOR Occupation 15/05/2013 Date Of Driving Pass

5 YEARS AND 1 MONTH Driving Experience

MALE Gender

(LOCAL) +65-90080704 Mobile Number

Fax Number Contact Number

EMail Address JAYNALD.QUAH@HOTMAIL.COM

HDB JURONG WEST, 662B JURONG WEST STREET 64 #10-314 Address

Postcode 642662

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

COLLISION - HEAD TO REAR Type Of Accident

CLEAR Weather Conditions DRY Road Surface

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

YES Was any body injured in the Accident?

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES NO

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

1

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

POLICE STATION NAME [OTHER]

JURONG WEST NPC

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT - T/20180711/2108 LODGED AT JURONG WEST NPC. ON THE 10/7/2018 AT ABOUT 2035HRS. I WAS DRIVING MY CAR ALONG PIE TOWARDS TUAS. I WAS ON THE FIRST LANE AND I NOTICED THAT THERE WAS ANOTHER BMW CAR IN FRONT OF ME, WHEN ALL OF A SUDDEN, THE BMW CAR JAM BRAKED WHICH CAUSE ME TO BRAKE TOO HOWEVER ANOTHER CAR THAT WAS FROM MY REAR COULDN'T STOP ON TIME. IT LED TO ITS FRONT BUMPER HITTING ONTO MY REAR CAUSING SOME IMPACT. AT THAT POINT OF TIME I WAS NOT PHYSICALLY INJURED BUT WAS JUST SHOCKED. AFTER A WHILE I THEN WENT OUT OF THE CAR TO EXCHANGE PARTICULARS. THE OTHER DRIVERS WERE ALSO FINE. THE NEXT DAY I FELT SOME PAIN ON MY NECK AND THE BACK OF MY BODY SO I DECIDED TO GO TO THE CLINIC. I WAS GIVEN THREE DAYS OF MC FOR MY PAIN. I WISH TO STATE THAT I HAVE AN IN CAR CAMERA.

Attachment(s)

Are accident photos available for attachment? YES Was there any video captured by Car Camera? YES Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGX6005M

TOYOTA LEXUS IS250 AUTO STD / BLK Vehicle Make/Model/Colour

NIL Details Of Properties

PRIVATE CAR Vehicle Category

SPENCER WONG FOO WAH Name of Driver

S7008286A NRIC/Passport Number Contact Number 81279283

Address Postcode Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

QUAH MING XUN

Approximate Age Injuries Sustain

Injured person in which vehicle?

SLQ7536T

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address Postcode



IMPORTANT NOTICE

- Pease report correctly the details of the accident to speed up the claims process.

 This Form must be completed by the Policyholder and/or the Authroised Driver.

 Information provided must be as truthful and accurate as possible. Any wiful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.

 The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.

 Any false reporting may be referred to the Police for investigation.

 The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.

 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

 Consent under the Personal Data Protection Act (PDPA)

 Lunderstand, asknowledge, agree and consent that

 (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/lare permitted to collect, use, diaclose and/or my insurer (collectively the Personal information') and diaclose and transfer such Personal information provided by me or possessed by my insurer (collectively the Personal Information') and diaclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the vehicle(s) involved in this accident shall be collectively referred to as the personal information of the personal information' and disclose and transfer such Personal Information' to all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the personal information, the foliation, the personal information' and disclose and transfer such Personal Information' provided by the Personal Information' an
- the claims:

 (i) investigating the accident ancion my claims;

 (iii) carrying out and/or dealing with my instructions or responding to any enquines by me;

 (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve decisions of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

 (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.


 (collectively the "Purposes")

 (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and (c) my Personal information may/can be disclosed by any of the Insurers and/or GiA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS REPORTING OFFICER MOHD FADZLY BIN ISMAIL

Policyholder's Signature / Date & Time Driver's Signature (if driver is not the policyholder) / Date & Time Witnessed by Reporting Centre

Sketch Plan



Common Statement Pg. 1

managed to stop in time, car SGX6005N	ar in front of me suddenly jammed brake. I If hit onto rear of my car SLQ7536T.
Refer as in video footage	
Taxi Voucher No.:	
100000000000000000000000000000000000000	
We declare that the above particulars & information provi	ded above are true in every aspect
DECLARATION We declare that the above particulars & information provious verified by AJAX MARS REPORTING OFFICER - MOHD FADZLY BIN ISMAIL	ded above are true in every aspect
We declare that the above particulars & information provi	ded above are true in every aspect
We declare that the above particulars & information provi	ded above are true in every aspect Registered Owner or Driver's Signature
We declare that the above particulars & information provi VERIFIED BY AJAX MARS REPORTING OFFICER - MOHD FADZLY BIN ISMAIL	



GST / ROC COMPANY NO: 201101753C

Quotation

From:

PEGASUS ENGINEERING & TRADING PTE LTD

74 KIAN TECK ROAD SINGAPORE 628800

Officer in Charge ; WEE TZE FAH

Email:

Customer:

GRAB RENTALS 2 PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960

Attn: : Tel:

Fax No.:

Quotation No.: QO18/07-1145	Quotation Date: 11/07/2018	Terms: 30 DAYS
Vehicle No. : SLQ7536T	Chassis No. : JM6BN22A8H0152909	Third Party Insurer : CHINA TAIPING
Model: MAZDA 3		Date of Accident: 10/07/2018

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER	1	1,075.0000	Je 1,075.00
2	REAR BUMPER REINFORCEMENT	1	538.0000	34 /538.00 U
3	REAR BUMPER REFLECTOR	2	51.0000	M x 102.00
4	REAR BUMPER SIDE RETAINER	2	92.0000	? 184.00 N
5	REAR BUMPER SIDE HOLDER	2	74.0000	× 148.00 ×
6	REAR BUMPER SIDE HOLDER RIVETS	4	6.0000	× 24.00 N
7	REAR BUMPER TOW COVER	2	18.0000	An/5/ 36.00/
8	REAR BUMPER CLIPS	10	5.0000	me / 50.00/
9	BOOTLID	1	958.0000	∫ [≺] 958.00
10	BOOTLID REFLECTOR	1	265.0000	₹ 265.00
11	BOOTLID LOCK	1	153.0000	★ 153.00
12	BOOTLID WEATHERSTRIP	1	130.0000	W 4 130.00
13	REAR END PANEL	1	506.0000	506.00
14	REAR END PANEL INNER TRIM	1	86.0000	86.00
15	REAR END PANEL INNER TRIM CLIPS	4	5.0000	× 20.00
16	REAR LUGGAGE FLOOR COMPARTMENT FOAM	1	166.0000	166.00
17	LESS 20% ON ITEM 1 - 16	1	-888.2000	-888.20
18	REAR BUMPER PARKING SENSOR	1	450.0000	260 450.00
19	TO RUST-PROOFING OF THE AFFECTED AREAS	1	100.0000	nh × 100.00
20	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	1	150.0000	∧h ⊀ 150.00
21	TO REINSTALL OF REAR BUMPER PARKING SENSOR	1	120.0000	}○ 120.00



GST / ROC COMPANY NO: 201101753C

Quotation

From:

PEGASUS ENGINEERING & TRADING PTE LTD

74 KIAN TECK ROAD SINGAPORE 628800

Officer in Charge: WEE TZE FAH

Tel: Email: Customer:

GRAB RENTALS 2 PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960

Attn::

Tel:

Fax No.:

Terms: 30 DAYS Quotation Date: 11/07/2018 Quotation No.: Q018/07-1145

Third Party Insurer: CHINA TAIPING Chassis No.: JM6BN22A8H0152909 Vehicle No.: SLQ7536T

Date of Accident: 10/07/2018 Model: MAZDA 3

marks: INSURED'S VEH NO: SGX6005M

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
22	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND	1	600.0000	B/F 0.00 20°600.00
23	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	800.0000	2 - 800.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub Total GST(7.00%) Total (SGD)

5,772.80

6,176.90

404.10

Please conduct the survey at Pegasus Engineering @ 74 Kian Teck Road Singapore 628800



GST / ROC COMPANY NO: 201101753C

Quotation

From:

PEGASUS ENGINEERING & TRADING PTE LTD

74 KIAN TECK ROAD SINGAPORE 628800

Officer in Charge : WEE TZE FAH

Tel: Email: Customer:

GRAB RENTALS 2 PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960

Attn::

Tel:

Fax No.:

 Quotation No. : QO18/07-1145
 Quotation Date : 11/07/2018
 Terms : 30 DAYS

 9hicle No. : SLQ7536T
 Chassis No. : JM6BN22A8H0152909
 Third Party Insurer : CHINA TAIPING

 Model : MAZDA 3
 Date of Accident : 10/07/2018

marks: INSURED'S VEH NO: SGX6005M

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER	1	1,075.0000	04 1,075.00
2	REAR BUMPER REINFORCEMENT	1	538.0000	? 538.00
3	- REAR BUMPER REFLECTOR	2	51,0000	★ 102.00
4	REAR BUMPER SIDE RETAINER	2	92.0000	7 184.00-
5	REAR BUMPER SIDE HOLDER	2	74.0000	× 148:00
6	REAR BUMPER SIDE HOLDER RIVETS	44	6:0000	×24:00→
7	REAR BUMPER TOW COVER	2	18.0000	M/3- 36.00
8	REAR BUMPER CLIPS	10	5.0000	me - 50.00
9	BOOTLID	1	958,0000	958.00
. 10	BOOTLID REFLECTOR-	1		
11	-BOOTLID LOCK	1	153,0000	—— ≯ —153:00·
) 12	- BOOTLID WEATHERSTRIP	1	130.0000	130.00
13	REAR END PANEL		506.0000	506.00
14	REAR END PANEL INNER TRIM			K-86.00
15	REAR END PANEL INNER TRIM CLIPS		5,0000	X20.00
16	REAR LUGGAGE FLOOR COMPARTMENT FOAM		166.0000	№ 166.00
17	LESS 20% ON ITEM 1 - 16	1	-888.2000	-888.20
18	REAR BUMPER PARKING SENSOR	1	450.0000	200 450.00
11.50	TO RUST-PROOFING OF THE AFFECTED AREAS	1	100.0000	
19	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND		150:0000	. K_150.00°
20	PERFORM WATER SEEPAGE TEST			
21	TO REINSTALL OF REAR BUMPER PARKING SENSOR	1	120.0000	go 120.00

C/F 0.00 Page 1 of 2



GST / ROC COMPANY NO: 201101753C

Quotation

_	w	-	м	-	١,
_	п	u	ш	18	

PEGASUS ENGINEERING & TRADING PTE LTD

74 KIAN TECK ROAD SINGAPORE 628800

Officer in Charge: WEE TZE FAH

Tel: Email: Customer:

GRAB RENTALS 2 PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960

Attn::

Tel:

Fax No.:

Quotation No.: QO18/07-1145	Quotation Date: 11/07/2018	Terms: 30 DAYS
shicle No. : SLQ7536T	Chassis No. : JM6BN22A8H0152909	Third Party Insurer : CHINA TAIPING
Model: MAZDA 3	1	Date of Accident: 10/07/2018

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
22	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY	1	600.0000	B/F 0.00 2 • 600.00
	PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME			0
23	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	800.0000	200.00

Parts	ə & 1,699.00	Taylin 9749 Trea
Less 20%.	(339.80)	Tanglin 9749 Tre9 1/8/10/2/650
	\$ 1,359.20	nessing before paint
SN	200.00	swellhout. En
Labour	430.00	
PBP	\$ 1,989.20	PBP \$ 1,989 -20
(101	1	1 1/4 \$ 11/10 1 . 2

Sub Total GST(7.00%) Total (SGD) 5,772.80 404.10 6,176.90

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI18013926/T1QD3N2

Date:

12/10/2018

REFERENCE

Vehicle No:

Date of Loss:

Handling Insurer:

China Taiping Insurance

(Singapore) Pte. Ltd.

Policy No:

DMPCSN1667521701

Claimant

SLQ7536T

10/07/2018

Insured Vehicle SGX6005M

No:

Nature of Claim:

TP

Claim No:

SNM18D03426C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLQ7536T

Make & Model:

MAZDA 3, 1.5 SEDAN EU6 (A)

Engine No:

P520444562

Reg. Date:

21/07/2017 (Man. Year: 2017)

Chassis No: Odometer:

JM6BN22A8H0152909 67783 km

Colour:

Blue 1496 cc

Engine Capacity: Market Value/New Car

N/A

Price:

Sum Insured (S\$):

General Condition:

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Yes Engine Modification:

Pre-accident Condition:

205/60R16

Front Tyre Size: Front Left Side:

West Lake 6 mm

205/60R16

Rear Tyre Size: Rear Left Side:

West Lake 6 mm

Front Right Side:

West Lake 6 mm

Rear Right Side:

West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Items	Repairer's 4,002.80 0.00	Adjuster's 1,559.20 0.00	Difference 2,443.60 0.00	Diff % 61.05
Labour Paintwork Labour	1,770.00 0.00	430.00 0.00	1,340.00 0.00	75.71
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,772.80	1,989.20	3,783.60	65.54
+ GST 7.00/7.00% (S\$)	404.10	139.24	264.86	65.54
Nett Amount (S\$)	6,176.90	2,128.44	4,048.46	65.54

INSPECTION

Date of Assignment:

31/07/2018

Date Inspected:

01/08/2018 Inspected At:

Pegasus Engineering & Trading Pte Ltd

(Kian Teck)

74 Kian Teck Road Singapore 628800

Estimated Period of Repair:

2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Oct 2018)

Parts: 143 MAZDA 3 1.5 SEDAN EU6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLQ7536T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Deformed	1,075.00 FL	*1,075.00 FL
2	1	*REAR BUMPER REINFORCEMENT	Bent	538.00 FL	*538.00 FL
3 4	2	*REAR BUMPER REFLECTOR *REAR BUMPER SIDE RETAINER	Not Necessary Not Necessary	102.00 FL 184.00 FL	
5	2	*REAR BUMPER SIDE HOLDER *REAR BUMPER SIDE HOLDER RIVETS	Not Necessary Not Necessary	148.00 FL 24.00 FL	
7	2	*REAR BUMPER TOW COVER *REAR BUMPER CLIPS	Missing Necessary	36.00 FL 50.00 FL	
9	1	*BOOTLID	Not Necessary	958.00 FL	*-FL
10	1	*BOOTLID REFLECTOR	Not Necessary	265.00 FL	*-FL
11	1	*BOOTLID LOCK	Not Necessary	153.00 FL	*-FL
12	1	*BOOTLID WEATHERSTRIP	Not Necessary	130.00 FL	*-FL
13 14	1	*REAR END PANEL *REAR END PANEL INNER TRIM	Not Necessary Not Necessary	506.00 FL 86.00 FL	*-FL *-FL
15	4	*REAR END PANEL INNER TRIM CLIPS	Not Necessary	20.00 FL	*-FL
16	1	*REAR LUGGAGE FLOOR COMPARTMENT FOAM	Not Necessary	166.00 FL	*-FL
17	1 anchise	*REAR BUMPER PARKING SENSOR part. S=SpcNett. L=ListItemDisc.	Not Working	450.00 FS	*200.00 FS
		6)	Sub Total (S\$)	4.891.00	1,899.00
		- List Item Discount on L Items 20			339.80
			Total Parts (S\$)	4,002.80	1,559.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recom	man	hah	l ah	OUR
Recom	men	aea	Lab	oui

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO RUST-PROOFING OF THE AFFECTED AREAS	New	100.00	-
2	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	150.00	
3	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	120.00	30.00
4	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION. REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	600.00	200.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	800.00	200.00
	Gross Labo	ur Cost (S\$)	1,770.00	430.00
	Report was unsubmitted dur	ing this print-out.		

< END OF ESTIMATES >