

INSURANCE

INS. CASE OWNER:

CC 3/III1801

h974, TI wbb

LKK

IDAC

Surveyor:

Taufik

DOE

ASSIGNMENT

Date / Time:

20/7/18

Registered in Merimen:

20/7/18

Pre-assign / CCU / FTE

SKL 8063E



Insured Vehicle No.:

Name of Insured:

LPL

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

20/7/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO. Driver Name / Age: 076 Kam Lhum

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

MLT15070840

Policy No.:

MLOA0015

Make / Model:

MERCEDES-

Place of Accident:

T-junction of upp Changi Rd
East of uppe Changi Link

OI GIA REPORT: YES / NO: TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SLC 94186



INSRS:

WSP:

Tel:

Liability:

RMKS:

Performance



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

URGENT

Date / Time		STAGE	DATE / PIC
20/7/18	SLC 94186 - X	Non-Reporting Itr (1st):	
20/7/18	SKL 8063E - Y	Non-Reporting Itr (2nd):	
18/8/18		Non-Reporting Itr (Final):	
18/8/18		Notification Itr (if non-pickup):	
		Call OI:	
		After call Itr to OI:	
		Documentation Check List: Handler Typist	
		Notification Itr (if non-pickup):	
		After call Itr to OI:	
		Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GIA:	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOI:	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time: 20-2-19	Confirm with: Caroline
Repair Cost:	RP \$532,460.85	(15 days) Reduction: %
FINAL SETTLEMENT	Date/Time: 10/7/19	Confirm with: Caroline
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.: 27
Repair Cost:	\$534,733.11	
Loss of Rental (LOR):	\$5 -	(days)
Loss of Use (LOU):	\$51,200.00	(560 x 20 days)
Loss of Income (LOI):	\$5 -	(5 x days)
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/>		[Tick only one]
GIA/LTA Search	\$57.45	
Medical:	\$5 -	
Disbursement:	\$5 -	(e.g. Tow/Independent)
Legal Cost	\$5 -	
Total:	\$535,940.56	Global Sum \$5:
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	\$535,940.56	Name 1: Performance Motors Ltd.
Payee 2: (Strike if N.A.)	\$5 -	Name 2:
Payee 3: (Strike if N.A.)	\$5 -	Name 3:

COPY SENT

 1) Claim status: Normal/Reject/Private Settle
 2) Report Format: G
 3) Survey fee: \$600.00

Surveyor:

Tanyan

REF:

III

W

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 990K.

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 15 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: Han

Veh No: SLC 95189 Yr Regn: 2016 May

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 116D cc 1496

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA1U720506724603

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. D.O.I. 1/8/18

Survey held at PML

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Refilling wheel
	P/p: +32,460.85
	CRed \$
	1SRd + 3 Sunday + 1PM + 1PPS = 20dy

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$) _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC3/III18013934/wb3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 31-07-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8063E	Veh. Inspected	SLC 9518G	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	31/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/07/2018	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kembangan Road
East Coast Centre
Singapore 438190
Tel. 63190888 (AfterSales)
Fax. 63449771

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64196601 (AfterSales)
64196624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 47872
Date Estimated : 30/07/2018
Prepared By : Han Kwan Yong

Page No. : 1 of 7

- ESTIMATE REPAIR FOR -

Chua Gek Choo
20 Lorong 7 Realty Park

Singapore 536778

- ACCOUNT - 238

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLC9518G	V724603	30/05/2016	116d	0

DESCRIPTION

To tow accident vehicle to PML workshop.

VALUE

195.00

To replace rear bumper & attachments, boot lid, tail panel, trunk floor panel including to pull & straighten both rear chassis, tail panel before cutting and to knock out dented area caused by the accident

photo of trunk floor panel & tail panel

7650 8,500.00

To respray rear bumper, boot lid, tail panel, rear right fender, rear left fender and boot compartment

4470 4,967.00

To carry out body cavity preservation.
(Per panel).

100 118.00

To carry out body cavity preservation.
(For cut panel).

4513 531.00

To replace front exhaust silencer including align exhaust system and conduct checks for leak.

photo 451? 531.00

To replace rear exhaust silencer including alignment system and conduct checks for leak.

451 531.00

To replace each diesel particulate filter including alignment and conduct checks for leak.

photo 564? 664.00

To replace engine mountings including re-alignment of engine block to body frame.

577? 679.00

To replace gearbox mountings including re-alignment of gearbox to cross member and propeller shaft system.

577? 679.00

To check steering geometry and conduct wheel alignment according to BMW specification (1X)

451? 531.00

To conduct chassis alignment measuring check using Car-O-Liner measuring system accordance with BMW

451? 531.00

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 19740155BW GST Reg. No M2-0020081-X



109, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kembangan Road
East Coast Centre
Singapore 438160
Tel. 63190688 (AfterSales)
Fax. 63649773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190828 (AfterSales)
63190833/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 47872
Date Estimated : 30/07/2018
Prepared By : Han Kwan Yong

Page No. : 2 of 7

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLC9518G	V724603	30/05/2016	116d	0

DESCRIPTION

VALUE

specification.

To mount accident vehicle on speed bench to facilitate re-alignment of body/chassis accordance with BMW specification.

5847 534 664.00

To remove and install rear windscreen glass to facilitate the replacement boot lid

487 574.00

To conduct water leak tests

63 75.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

230 271.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To remove and install wire harness, control units and battery at the rear section to facilitate panel replacement.

454Z 531.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

150 177.00

To supply rear emboss number plate.

66 83.00

Sundries. *me*

7 150.00

Total Labour 1: 21,159.00

DESCRIPTION

QTY

PRIC

VALUE

RUBBER MOUNTING

2

33.65

under 67.30

TAILPIPE END PIECE ALU LOOK

1

107.85

del 107.85

VibrAbsorber

1

95.95

un 95.95

V BAND CLAMP

1

41.80

bt 41.80

REAR RH SILENCER BRACKET

1

64.15

un 64.15

REAR LH SILENCER BRACKET

1

41.70

un 41.70

CLAMPING BUSH D=65.2MM

1

54.30

bt 54.30

FRONT PIPE

1

492.70

bt 492.70

EXCH DIESEL PARTICULATE FILTER (EU5

1

3,550.20

bt 3,550.20

MUFFLER CLAMP D=63.2MM

1

41.80

un 41.80

REAR SILENCER

1

864.80

bt 864.80

COLLAR SCREW

2

13.10

un 26.20

LH ENGINE MOUNT

1

198.55

un 198.55

RH ENGINE MOUNT

1

198.55

un 198.55

GEARBOX MOUNTING

2

39.75

un 79.50

LUGGAGE COMPARTMENT FLOOR RE

1

113.90

un 113.90

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401539W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/535 (Motorrad)
Fax. 64794601 (AfterSales)
64794624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 47872
Date Estimated : 30/07/2018
Prepared By : Han Kwan Yong

Page No. : 3 of 7

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLC9518G	V724603	30/05/2016	116d	0

DESCRIPTION

QTY

PRIC

VALUE

BOOTLID	1	1,108.45	bt 1,108.45
# TAIL END PANEL	1	497.45	bt 497.45
# LUGGAGE COMPARTMENT PAN	1	385.35	ht 385.35
REAR BUMPER CARRIER	1	385.25	bt 385.25
REAR BUMPER CENTRE GUIDE (M)	1	57.45	de 57.45
REAR BUMPER TOWING EYE COVER PRIMED	1	54.50	de 54.50
REAR BUMPER LH MOUNT	1	142.55	de 142.55
REAR BUMPER PANEL PRIMED	1	902.20	de 902.20
REAR PDC HOLDER SET	1	23.10	na 23.10
# TRUNK LID LOCK	1	155.70	na 155.70
# STRIKER TRUNK LID	1	55.75	na 55.75
EMBLEM BUTTON	1	103.40	na 103.40
# SUPPORTING RING	1	35.55	na 35.55
BUMP STOP	10	3.25	bt 32.50
HEAT INSULATOR REAR SILENCER	1	61.60	bt 61.60
PLAQUE 82MM	1	69.50	de 69.50
# TRUNK LID GASKET	1	66.95	na 66.95
(DG/SL) BMW AGM BATTERY (90 AH)	1	718.65	de 718.65
LH REFLECTOR	1	35.20	na 35.20
RH REFLECTOR	1	35.20	na 35.20
# REAR LH LIGHT IN THE SIDE PA	1	335.90	na 335.90
REAR RH LIGHT IN THE SIDE PANEL	1	335.90	na 335.90
REAR LH LIGHT IN THE TRUNK LID	1	278.65	na 278.65
REAR RH LIGHT IN THE TRUNK LID	1	278.65	na 278.65
THIRD STOPLAMP	1	169.90	na 169.90
NUMBER PLATE LIGHT LED	2	23.20	na 46.40
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	na 20.20
# PDC SENSOR MINERAL GRAU (B3	4	368.80	na 1,475.20
BLIND RIVET AVIBVLB	25	0.55	na 13.75
SCREW (SF PLUS M5X15)	12	0.55	na 6.60
(DG/SL) BODY ADHESIVE K5B (195ML)	1	281.55	na 281.55
PUNCH RIVET N5	10	0.55	na 5.50
(DG) CLEANER R1 (100ML)	2	23.85	na 47.70
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	na 263.10
(DG/SL) ADHESIVE SET K6	1	53.05	na 53.05
PUNCH RIVET N4	18	0.55	na 8.25
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	na 27.85
(S/L) SEAM SEAL 300ML	4	33.80	na 135.20

Total Parts : 14,748.90

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401539W GST Reg. No. M2-0020081-X



101, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

319, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 47872
Date Estimated : 30/07/2018
Prepared By : Han Kwan Yong

Page No. : 4 of 7

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLC9518G	V724603	30/05/2016	116d	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date&Time <u>1/8/18</u>	Excess S\$ _____
Surveyor's Name <u>Tan Jui</u>	Sign <u>Tan Jui</u>
Surveyor's Tel <u>87445247</u>	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____	
Surveyor's E-mail <u>Tan Jui E. Han Kwan</u>	
No. of Working Days Recommend <u>15 days</u>	

Labour 1	:	21,159.00
Parts	:	14,748.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	2,513.55
Grand Total	:	38,421.45

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 191401559N, GST Reg. No. M3-0020081-8



SUPPLEMENTARY

Estimate No. : b1 47872
Date Estimated : 30/07/2018
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Chua Gek Choo
20 Lorong 7 Realty Park

- ACCOUNT - 219
India Int'l Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

Singapore 536778

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLC9518G	V724603	30/05/2016	116d	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
# To remove and install rear suspension, rear axle and control system for inspection include replacement of damaged parts	2257.00		2,257.00	
# To replace battery positive cable and attachments, to perform high current tests and charge up battery	451.00		451.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# HOLDER CATALYTIC CONVERTER NEAR ENG *	64.15	1.00		64.15 <i>bf</i>
# REAR AXLE CARRIER *	1,728.25	1.00		1,728.25 <i>bf</i>
# LUGGAGE COMPARTMENT FLOOR REAR *	113.90	1.00		113.90 <i>bf</i>
# TRUNK TUB LH *	117.65	1.00		117.65 <i>bf</i>
# BATTERY CABLE (PLUS POLE) *	286.35	1.00		286.35 <i>bf</i>
# CONNECTOR *	3.65	1.00		3.65 <i>wh</i>
# GROMMET *	4.35	1.00		4.35 <i>wh</i>
# DEGASSING HOSE BATTERY *	15.60	1.00		15.60 <i>dy</i>
# REAR LH LIGHT IN THE SIDE PANEL * - <i>REPORT</i>	335.90	1.00		335.90 <i>one</i>

Total Labour : 2,708.00
Total Parts : 2,669.80
Total Labour & Parts : 5,377.80

Performance Motors Limited

A member of the Sincere Group
Co. Reg. No. 197401559W. GST Reg. No. M3-0020881-0



FINAL REPORT

Estimate No. : b1 47872
Date Estimated : 30/07/2018
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Chua Gek Choo
20 Lorong 7 Realty Park

- ACCOUNT - 219
India Int'l Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

Singapore 536778

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE	
SLC9518G	V724603	30/05/2016	116d	0	
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT		
To tow accident vehicle to PML workshop.	195.00		195.00		
To replace rear bumper and attachments, boot lid, tail end panel, LH trunk tub, rear luggage compartment floor, luggage compartment pan, rear LH light in side panel, rear LH light in trunk lid, third stoplamp include to pull and straighten on accident areas, to make good the rear RH/ LH fenders and knocking out dents caused by the accident	7650.00		7,650.00		
To respray rear bumper, boot lid, tail end panel, rear RH fender, rear LH fender and trunk floor panel	4470.00		4,470.00		
To carry out body cavity preservation. (Per panel).	100.00		100.00		
* To carry out body cavity preservation. (For cut panel).	451.00		451.00		
* To replace front exhaust silencer include alignment of exhaust system and conducting checks for leak	451.00		451.00		
To replace rear exhaust silencer include alignment of exhaust system and conducting checks for leak	451.00		451.00		
* To replace each diesel particulate filter include alignment of exhaust system and conducting checks for leak	564.00		564.00		
# To remove and install rear suspension, rear axle and control system for inspection include replacement of damaged parts	2257.00		2,257.00		
* To check steering geometry and conduct wheel alignment in accordance with BMW specifications (1x)	451.00		451.00		
* To mount accident vehicle on speed bench to facilitate re-alignment of body/chassis in accordance with BMW specifications	564.00		564.00		
To remove and install rear windscreen glass to facilitate	574.00		574.00		

Performance Motors Limited

A member of the Silver Clarity Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

repairs		
To conduct water leak tests.	75.00	75.00
To remove and install boot compartment carpet and garnish to facilitate repairs	230.00	230.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	150.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00	150.00
To supply rear emboss number plate.	83.00	83.00
# To replace battery positive cable and attachments, to perform high current tests and charge up battery	451.00	451.00
Sundries	150.00	150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# HOLDER CATALYTIC CONVERTER NEAR ENG *	64.15	1.00		64.15
TAILPIPE END PIECE ALU LOOK	107.85	1.00		107.85
V BAND CLAMP	41.80	1.00		41.80
CLAMPING BUSH D=65.2MM	54.30	1.00		54.30
FRONT PIPE	492.70	1.00		492.70
EXCH DIESEL PARTICULATE FILTER (EU5	3,550.20	1.00		3,550.20
REAR SILENCER	864.80	1.00		864.80
# REAR AXLE CARRIER *	1,728.25	1.00		1,728.25
# LUGGAGE COMPARTMENT FLOOR REAR *	113.90	1.00		113.90
# TRUNK TUB LH *	117.65	1.00		117.65
BOOTLID	1,108.45	1.00		1,108.45
LUGGAGE COMPARTMENT PAN	385.35	1.00		385.35
TAIL END PANEL	497.45	1.00		497.45
REAR BUMPER CARRIER	385.25	1.00		385.25
REAR BUMPER CENTRE GUIDE (M)	57.45	1.00		57.45
REAR BUMPER LH MOUNT	142.55	1.00		142.55
REAR BUMPER PANEL PRIMED	902.20	1.00		902.20
REAR PDC HOLDER SET	23.10	1.00		23.10
HEAT INSULATOR REAR SILENCER	61.60	1.00		61.60
# BATTERY CABLE (PLUS POLE) *	286.35	1.00		286.35
# CONNECTOR *	3.65	1.00		3.65
(DG/SL) BMW AGM BATTERY (90 AH)	718.65	1.00		718.65
# GROMMET *	4.35	1.00		4.35
# DEGASSING HOSE BATTERY *	15.60	1.00		15.60
LH REFLECTOR	35.20	1.00		35.20
# REAR LH LIGHT IN THE SIDE PANEL *	335.90	1.00		335.90
REAR LH LIGHT IN THE TRUNK LID -	278.65	1.00		278.65
REAR LH LIGHT IN THE TRUNK LID -	278.65	1.00		278.65
THIRD STOPLAMP	169.90	1.00		169.90
NUMBER PLATE LIGHT LED	23.20	1.00		23.20
BLIND RIVET AVIBVLB	0.55	60.00		33.00
(DG/SL) BODY ADHESIVE K5B (195ML)	281.55	1.00		281.55

Performance Motors Limited

A member of the Sima Darby Group
Co. Reg. No. 107401559W GST Reg. No. M3-0020091-0



FINAL REPORT

PUNCH RIVET N4	0.55	40.00	22.00
(DG/SL) ADHESIVE SET K6	53.05	1.00	53.05
(S/L) SEAM SEAL 300ML	33.80	1.00	33.80

SUPPLEMENTARY ITEMS

Total Labour :	19,467.00
Total Parts :	13,272.50
Total Labour & Parts :	32,739.50
Deduction for Excess :	0.00
Total Repair Costs less Excess:	32,739.50
GST @7%:	2,291.77
Grand Total :	35,031.27

32,460.85

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

repairs			
To conduct water leak tests.	75.00		75.00
To remove and install boot compartment carpet and garnish to facilitate repairs	230.00		230.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00		150.00
To supply rear emboss number plate.	83.00		83.00
# To replace battery positive cable and attachments, to perform high current tests and charge up battery	451.00	mc ✓	451.00
Sundries	150.00	✓	150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# HOLDER CATALYTIC CONVERTER NEAR ENG *	64.15	1.00		64.15 <i>bt ✓</i>
TAILPIPE END PIECE ALU LOOK	107.85	1.00		107.85
V BAND CLAMP	41.80	1.00		41.80
CLAMPING BUSH D=65.2MM	54.30	1.00		54.30
FRONT PIPE	492.70	1.00		492.70
EXCH DIESEL PARTICULATE FILTER (EU5	3,550.20	1.00		3,550.20
REAR SILENCER	864.80	1.00		864.80
# REAR AXLE CARRIER *	1,728.25	1.00		1,728.25 <i>bt ✓</i>
# LUGGAGE COMPARTMENT FLOOR REAR *	113.90	1.00		113.90 <i>bt ✓</i>
# TRUNK TUB LH *	117.65	1.00		117.65 <i>bt ✓</i>
BOOTLID	1,108.45	1.00		1,108.45
LUGGAGE COMPARTMENT PAN	385.35	1.00		385.35
TAIL END PANEL	497.45	1.00		497.45
REAR BUMPER CARRIER	385.25	1.00		385.25
REAR BUMPER CENTRE GUIDE (M)	57.45	1.00		57.45
REAR BUMPER LH MOUNT	142.55	1.00		142.55
REAR BUMPER PANEL PRIMED	902.20	1.00		902.20
REAR PDC HOLDER SET	23.10	1.00		23.10
HEAT INSULATOR REAR SILENCER	61.60	1.00		61.60
# BATTERY CABLE (PLUS POLE) *	286.35	1.00		286.35 <i>del's ✓</i>
# CONNECTOR *	3.65	1.00		3.65 <i>del's ✓</i>
(DG/SL) BMW AGM BATTERY (90 AH)	718.65	1.00		718.65
# GROMMET *	4.35	1.00		4.35
# DEGASSING HOSE BATTERY *	15.60	1.00		15.60
LH REFLECTOR	35.20	1.00		35.20
# REAR LH LIGHT IN THE SIDE PANEL *	335.90	1.00		335.90
REAR LH LIGHT IN THE TRUNK LID	278.65	1.00		278.65
REAR LH LIGHT IN THE TRUNK LID	278.65	1.00		278.65
THIRD STOPLAMP	169.90	1.00		169.90
NUMBER PLATE LIGHT LED	23.20	1.00		23.20
BLIND RIVET AVIBVLB	0.55	60.00		33.00
(DG/SL) BODY ADHESIVE K5B (195ML)	281.55	1.00		281.55

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 157401539W, GST Reg. No. M2-0020081-K



SUPPLEMENTARY

Estimate No. : b1 47872
Date Estimated : 30/07/2018
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Chua Gek Choo
20 Lorong 7 Realty Park

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

Singapore 536778

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SLC9518G	V724603	30/05/2016	116d	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
# To remove and install rear suspension, rear axle and control system for inspection include replacement of damaged parts	2257.00		2,257.00	
# To replace battery positive cable and attachments, to perform high current tests and charge up battery	451.00		451.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# HOLDER CATALYTIC CONVERTER NEAR ENG *	64.15	1.00		64.15
# REAR AXLE CARRIER *	1,728.25	1.00		1,728.25
# LUGGAGE COMPARTMENT FLOOR REAR *	113.90	1.00		113.90
# TRUNK TUB LH *	117.65	1.00		117.65
# BATTERY CABLE (PLUS POLE) *	286.35	1.00		286.35
# CONNECTOR *	3.65	1.00		3.65
# GROMMET *	4.35	1.00		4.35
# DEGASSING HOSE BATTERY *	15.60	1.00		15.60
# REAR LH LIGHT IN THE SIDE PANEL *	335.90	1.00		335.90

Total Labour : 2,708.00
Total Parts : 2,669.80
Total Labour & Parts : 5,377.80

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401539W, GST Reg. No. M2-0020051-X



FINAL REPORT

PUNCH RIVET N4	0.55	40.00	22.00
(DG/SL) ADHESIVE SET K6	53.05	1.00	53.05
(S/L) SEAM SEAL 300ML	33.80	1.00	33.80

SUPPLEMENTARY ITEMS

Total Labour :	19,467.00
Total Parts :	13,272.50
Total Labour & Parts :	32,739.50
Deduction for Excess :	0.00
Total Repair Costs less Excess:	32,739.50
GST @7%:	2,291.77
Grand Total :	35,031.27

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197611559W GST Reg. No. M2-0020081-X



115, Alexandra Road
Sime Darby Performance Centre
Singapore 159942
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

190, Tampong Arong Road
East Coast Centre
Singapore 436180
Tel. 63190888 (AfterSales)
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796831 (AfterSales)
64796424 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No.	: b1 47872	Page No. : 1 of 7
Date Estimated	: 30/07/2018	
Prepared By	: Han Kwan Yong	

- ESTIMATE REPAIR FOR - Chua Gek Choo 20 Lorong 7 Realty Park Singapore 536778	- ACCOUNT - 238 AXA Insurance Pte Ltd 8 Shenton Way #24-01 AXA Tower Singapore 068811
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLC9518G	V724603	30/05/2016	116d	0

DESCRIPTION	VALUE
To tow accident vehicle to PML workshop.	✓ 195.00
To replace rear bumper & attachments, boot lid, tail panel, trunk floor panel including to pull & straighten both rear chassis, tail panel before cutting and to knock out dented area caused by the accident <i>photo of trunk floor panel & tail panel</i>	✓ 7650 8,500.00
To respray rear bumper, boot lid, tail panel, rear right fender, rear left fender and boot compartment	✓ 4470 4,967.00
To carry out body cavity preservation. (Per panel).	✓ 100 118.00
To carry out body cavity preservation. (For cut panel).	✓ 4513 531.00
To replace front exhaust silencer including align exhaust system and conduct checks for leak.	✓ photo 451? 531.00
To replace rear exhaust silencer including alignment system and conduct checks for leak.	✓ 451 531.00
To replace each diesel particulate filter including alignment and conduct checks for leak.	✓ photo 564? 664.00
To replace engine mountings including re-alignment of engine block to body frame.	✓ 577? 679.00
To replace gearbox mountings including re-alignment of gearbox to cross member and propeller shaft system.	✓ 577? 679.00
To check steering geometry and conduct wheel alignment according to BMW specification (1X)	✓ 451? 531.00
To conduct chassis alignment measuring check using Car-O-Liner measuring system accordance with BMW	✓ 577? 531.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 19740189W GST Reg. No. M2-0020081-X

105, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64767770

249, Kembangan Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

111, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/330 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 47872 Page No. : 3 of 7
Date Estimated : 30/07/2018
Prepared By : Han Kwan Yong

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLC9518G	V724603	30/05/2016	116d	0

DESCRIPTION	QTY	PRIC	VALUE
BOOTLID	1	1,108.45	1,108.45
# TAIL END PANEL	1	497.45	497.45
# LUGGAGE COMPARTMENT PAN	1	385.35	385.35
REAR BUMPER CARRIER	1	385.25	385.25
REAR BUMPER CENTRE GUIDE (M)	1	57.45	57.45
REAR BUMPER TOWING EYE COVER PRIMED	1	54.50	54.50
REAR BUMPER LH MOUNT	1	142.55	142.55
REAR BUMPER PANEL PRIMED	1	902.20	902.20
REAR PDC HOLDER SET	1	23.10	23.10
# TRUNK LID LOCK	1	155.70	155.70
# STRIKER TRUNK LID	1	55.75	55.75
EMBLEM BUTTON	1	103.40	103.40
# SUPPORTING RING	1	35.55	35.55
BUMP STOP	10	3.25	32.50
HEAT INSULATOR REAR SILENCER	1	61.60	61.60
PLAQUE 82MM	1	69.50	69.50
# TRUNK LID GASKET	1	66.95	66.95
(DG/SL) BMW AGM BATTERY (90 AH)	1	718.65	718.65
LH REFLECTOR	1	35.20	35.20
RH REFLECTOR	1	35.20	35.20
# REAR LH LIGHT IN THE SIDE PA	1	335.90	335.90
REAR RH LIGHT IN THE SIDE PANEL	1	335.90	335.90
REAR LH LIGHT IN THE TRUNK LID	1	278.65	278.65
REAR RH LIGHT IN THE TRUNK LID	1	278.65	278.65
THIRD STOPLAMP	1	169.90	169.90
NUMBER PLATE LIGHT LED	2	23.20	46.40
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	20.20
# PDC SENSOR MINERAL GRAU (B3)	4	368.80	1,475.20
BLIND RIVET AVIBVLB	25	0.55	13.75
SCREW (SF PLUS M5X15)	12	0.55	6.60
(DG/SL) BODY ADHESIVE K5B (195ML)	1	281.55	281.55
PUNCH RIVET N5	10	0.55	5.50
(DG) CLEANER R1 (100ML)	2	23.85	47.70
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10
(DG/SL) ADHESIVE SET K6	1	53.05	53.05
PUNCH RIVET N4	15	0.55	8.25
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	27.85
(S/L) SEAM SEAL 300ML	4	33.80	135.20

Total Parts : 14,748.90



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438186
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/538 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X**E S T I M A T E**

Estimate No. : **b1 47872**
Date Estimated : **30/07/2018**
Prepared By : **Han Kwan Yong**

Page No. : **5 of 7**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLC9518G	V724603	30/05/2016	116d	0

Terms & Conditions of Service

- All requests for servicing, repairs, replacements or installations to the Vehicle (collectively, "Repairs") are subject to acceptance by Performance Motors Limited ("PML") and PML shall have the absolute discretion to reject or deny any request for the Repairs.
- The list of the Repairs or quantum of charges for the Repairs printed overleaf are estimates only and PML shall be entitled to carry out additional repairs or replacements ("Additional Works") if, in its absolute discretion, Additional Works are necessary provided that, where the cost of additional Works exceed S\$250, PML shall obtain the customer's prior consent (whether given orally or otherwise) before carrying out the additional Works.
- Subject to clause 2 above and save in the case of manifest error or gross negligence, in the event where PML's estimation of the Repairs recommended for the Vehicle differs from the Customer's own estimation of repairs needed, PML's estimate shall prevail.
- The Vehicle accepted by PML for the Repairs shall remain, at all times, at the Customer's own risk while the Vehicle undergoes the Repairs at PML's premises. PML's visual inspection and record of the physical condition of the Vehicle made prior to the commencement of the Repairs shall be binding and conclusive as between PML and the Customer. The Customer shall ensure that all valuables are removed from the Vehicle prior to delivering it to PML for the Repairs. PML shall not be liable, in any way, for theft, fire, accident, loss of or damage to the Vehicle, its contents or accessories whatsoever.
- The Vehicle may be driven on the road if and when PML, in its absolute discretion, decides that it is necessary for the purposes of carrying out tests in connection with the Repairs. Should any damage occur to the Vehicle in such an instance, PML's liability will be limited to the rectification of damage, free of charge.
- PML's entire liability whether, in respect of faulty workmanship or otherwise, shall be limited to the rectification of any faulty workmanship or other faults, free of charge, such faults being reasonably determined by PML to have been caused by PML in the course of the Repairs. The Customer shall, nevertheless, be responsible for all costs for the disassembly, diagnosis, inspection of the Vehicle etc., at PML's current labour charge-out rate, necessarily incurred for the purpose of determining the cause of the fault(s) if it is found that the fault(s) is or are not caused by PML.
- Except as provided in clause 6 above, PML makes no warranty (whether expressed or implied) in respect of the Repairs and shall not, to the fullest extent permitted by law, be liable under any circumstances for special, consequential or incidental damages including but not limited to the loss of use of or depreciation in value of the Vehicle.
- Unless otherwise agreed by PML in writing, the Customer shall pay the costs of the Repairs owing to PML, in cash, upon the completion of the Repairs and before the Customer collects the Vehicle. In the event any credit is granted by PML at its absolute discretion, and the Customer fails to make payment of the costs of the Repairs (or any part thereof) by the agreed payment date, interest shall be imposed on the sum remaining unpaid at the rate of 1% per month (or part thereof) from the due date of payment until the date all payments are actually received by PML. PML reserves the right, at any time, to suspend or withdraw any credit facility granted to the Customer without assigning any reason whatsoever.
- The Customer shall collect the Vehicle within 48 hours from the date PML notifies the Customer, (whether orally or otherwise), that the Vehicle is ready for collection. In the event that the Customer fails to collect the Vehicle within 48 hours, the Customer shall, in addition to the costs of the Repairs owing to PML, pay all storage charges, at a rate to be determined by PML provided always that the Customer shall not, under any circumstances, hold PML liable for any loss of or damage to the Vehicle, its contents or accessories or for any deterioration in the quality of or damage to the Vehicle arising from such storage. In the event that the Customer fails to collect the Vehicle for more than 14 days, PML shall be entitled, at its absolute discretion, to dispose of the Vehicle & deduct, from the proceeds of disposal, PML's costs in connection with the disposal as well as all other monies owing to PML.
- If PML does not receive any notification of faulty workmanship from the Customer within 7 days from the date the Customer collects the Vehicle from PML, the Customer shall be deemed to have accepted the Repairs as satisfactory.
- If the Vehicle is sent to PML for the Repairs by any person other than the Customer, PML shall be entitled, without need to make any inquiry, to treat such third party as acting for and on the Customer's behalf. PML shall be entitled to rely on this ostensible authority to carry out the repairs in compliance with such third party's instructions and the Customer shall not hold PML liable for any loss or damage suffered by the Customer as a result and shall pay for the costs of the Repairs owing to PML and further indemnify PML against all claims, losses, expenses, damages suffered or incurred by PML arising from PML's reliance on such authority and/or compliance with such instructions.
- PML may, in its absolute discretion and upon the Customer's request, provide a driver to deliver the Vehicle from the Customer to PML's premises or vice versa provided always that the driver shall, during the time of such conveyance of the Vehicle, be deemed to be the servant of the Customer and not that of PML's and the Customer shall not hold PML liable for any accident, loss of or damage to the Vehicle or its contents or accessories while the same is under the custody of the driver.
- These Terms & Conditions of Service including all annexes and attachments hereto contains the entire agreement between PML and the Customer with respect to the Services described in the Repair Order and supersedes all previous agreements and understandings between PML and the Customer relating to the subject matter herein. No amendments or changes to these Terms & Conditions of Service shall be effective unless made in writing and signed by authorized representatives of both PML and the Customer.
- If any term or provision of these Terms & Conditions of Service shall be held to be invalid, illegal or unenforceable, the remaining terms and provisions of these Terms & Conditions of Service not affected by such invalidity, illegality or unenforceability shall remain in force and effect.



103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kangkong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X**E S T I M A T E**

Estimate No. : **b1 47872**
Date Estimated : **30/07/2018**
Prepared By : **Han Kwan Yong**

Page No. : **6 of 7**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLC9518G	V724603	30/05/2016	116d	0

15. A person not party to these Terms & Conditions of Service shall have no right under any legislation for the enforcement of contractual terms by a third party (whether in force now or to be enacted in the future and as the same may be modified, adapted or supplemented from time to time) to enforce any term in these Terms & Conditions of Service.
16. The laws of the Republic of Singapore shall govern the validity and interpretation of these Terms & Conditions of Service and the Parties submit to the exclusive jurisdiction of the Courts of the Republic of Singapore.
17. The Sime Darby Motors Group companies in Singapore are committed to ensuring that your personal data is protected. The purpose of this document is to explain how we collect information about you, the procedures that we have in place to safeguard your privacy and how you can instruct us if you prefer to limit the use of that information.
- 17.1 The Vendor shall collect and use the Customer's personal data for any of the following purposes, including but not limited to:
- (a) the registration of the Vehicle with the relevant transportation authorities, including but not limited to Land Transport Authority;
 - (b) sharing of the Customer's personal data with the Vendor's principal, its related corporations and contractors, whether within Singapore or overseas, and/or insurance companies, so as to provide the necessary warranties and/or extended warranties for the Vehicle to the Customer;
 - (c) sharing of the Customer's personal data with financial institutions and motor vehicle insurers, on the Customer's behalf, in order for the Customer to obtain financing for the purchase of the Vehicle and the motor insurance on the Vehicle and when necessary, to obtain the loan amounts outstanding from financial institutions, on the Customer's behalf so as to assist the Customer in effecting the Vehicle loan redemptions;
 - (d) servicing of Vehicle and to update the Vendor's after-sales service records. The relevant personal data shall be used by the Vendor, its appointed after-sales service dealers, agents and sub-contractors and/or the Vendor's principal and/or its related corporations whether within or outside Singapore to provide the relevant after-sales service and/or to repair the Vehicle and to communicate with the Customer on any matter relating to the provision of the services in general including to notify the Customer by any means, including by short message services ("SMS") of the next/ subsequent date/mileage for routine service for the Vehicle;
 - (e) administrative, research and analysis purposes to enable it to monitor and improve the services it provides; and
 - (f) organizing events for the Customer, to inform the Customer of such events by any means (including through SMS, multi-media services ("MMS"), phone call, fax, magazines, or brochures) any new products, promotions or services provided by the Vendor in Singapore.
- 17.2 The Vendor shall also disclose the Customer's personal data:
- (a) to its service providers, for example, providers of web hosting or maintenance services, for the purpose of supplying itself with the inter connected servers and/or web site links with the relevant authorities;
 - (b) to its customer service agencies whether within or outside Singapore for administrative, research and analysis purposes to enable it to monitor and improve the services it provides;
 - (c) to the Vendor's service providers and/or the Vendor's principal, its related corporations and contractors whether within or outside Singapore for the purpose of organizing events for the Customer, to inform the Customer of and send to the Customer by any means (including through SMS, MMS, phone call, fax, magazine or brochures) any new products or promotions or services that are provided by the Vendor and/or the Vendor's principal whether within or outside Singapore;
 - (d) to the Vendor's business partners for the purpose of carrying out product promotions;
 - (e) to the Vendor's stakeholders and the Vendor's principal and its/their related corporations and contractors for the purpose of carrying out audits;
 - (f) to the Vendor's principal and/or the Vendor's stakeholders and their respective related corporations and contractors whether within or outside Singapore for the purposes of carrying out audits; and
 - (g) to the Vendor's principal and its related corporations whether located within or outside Singapore for the purpose of responding to any of the Customer's enquiries.
- 17.3 The Vendor shall retain the Customer's personal data either for the period of the business relationship or, for the requisite retention periods as stipulated in any contractual arrangements or under any applicable law, whichever is later.
- 17.4 If the Vendor amends any provision in this clause 17, it will notify the Customer via e-mail and may place notices on the Vendor's web site. The Vendor's email to the Customer shall require the Customer's consent to its change of use of the Customer's personal data. Continued use of the Vendor's services shall signify the Customer's agreement to any such changes.
- 17.5 The personal data the Customer provides may be transferred to the Vendor's principal within or outside Singapore for surveys and research purposes conducted with the objective of enhancing the Customer's satisfaction.
- 17.6 The Customer shall have a right to request a copy of the personal data the Vendor holds about the Customer and information about the ways in which the Customer's personal data has been or may have been used or disclosed within a year before the date the Customer's request. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or:
- (a) put his request in writing and indicate whether he would like to have a copy of his personal data or he wishes to have information about the ways in which his personal data is used or disclosed during the past year or both;
 - (b) include proof of his identity and address (e.g. a copy of the Customer's driving licence and a recent credit card bill); and
 - (c) specify the personal data he wants access to, including any account or reference numbers where applicable.

The Vendor shall reply to the Customer as soon as reasonably possible upon its receipt of the Customer's request.

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Karpong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190889 (AfterSales)
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 47872**
Date Estimated : **30/07/2018**
Prepared By : **Han Kwan Yong**

Page No. : 7 of 7

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLC9518G	V724603	30/05/2016	116d	0

- 17.7 The Customer shall pay an amount to access his personal data in the manner stated in Clause 17.6(a) above.
- 17.8 The Customer shall have the right to correct any inaccuracies in his personal data free of charge. If the Customer wishes to exercise this right, the Customer shall:
- (a) put his request in writing;
 - (b) provide the Vendor with enough information to identify himself (e.g. the Customer's account number, username, registration details); and
 - (c) specify the information that is incorrect and what it should be replaced with.
- The Vendor shall reply to the Customer as soon as practicable upon its receipt of the Customer's request.
- 17.9 The Customer's access or correction request will not be granted as of right; the Vendor's ability to accede to the Customer's access or correction request is subjected to the prohibitions and exceptions set out or which may be set out in the Singapore Personal Data Protection Act ("PDPA") and its accompanying regulations.
- 17.10 The Customer shall have the right to ask the Vendor to stop collecting, using or disclosing his personal data for any of the abovementioned purposes set out in Clauses 17.1 and 17.2. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or:
- (a) put his request in writing by way of an email sent to the Vendor;
 - (b) provide the Vendor with his name, NRIC number, mobile number, email and Vehicle registration number to identify the Customer; and
 - (c) if the Customer's objection is not to direct marketing in general, but to direct marketing by a particular channel (e.g. voice call, SMS, MMS, fax, mailers or email), the Customer has to specify the channel he is withdrawing his consent to.
- 17.11 In the event that the Customer withdraws consent to the collection, use or disclosure of his personal data such that it materially affects this Agreement and it renders the Vendor unable to, or such that it becomes difficult for the Vendor to perform or properly perform or discharge its obligations under this Agreement, at law, under the warranty undertakings, or its role as a responsible dealer of BMW vehicles, the Vendor may at its discretion, be entitled to terminate this Agreement with the Customer.
- 17.12 The obtaining the Customer's consent for the collection, use or disclosure of his personal data under this clause 17 is subject to the exceptions set out or which may be set out in the PDPA.
- 17.13 The Customer shall address all communications pertaining to this Clause 17 to:

The Data Protection Officer
Performance Motors Limited

Address:
Sime Darby Performance Centre
303 Alexandra Road
Singapore 159941

Email address:
dataprotection@pml.com.sg

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8219E
Vehicle Details	
Vehicle No.:	SLC9518G
Vehicle to be Exported:	No
Intended De-registration Date:	02 Aug 2018
Vehicle Make:	B.M.W.
Vehicle Model:	116D 5DR HATCHBACK DSC LED
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	34969567B37D15A
Chassis No.:	WBA1V72050V724603
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$23,904.00
Original Registration Date:	30 May 2016
First Registration Date:	30 May 2016
Transfer Count:	0
Actual ARF Paid:	\$10,466.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 May 2026
PARF Rebate Amount:	\$7,849.00
Intended COE Rebate Details	
COE Expiry Date:	29 May 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,889.00
COE Rebate Amount:	\$37,461.00
Total Rebate Amount:	\$45,310.00

The information contained herein is correct as at 02 Aug 2018

OK

Print Received Message

This mail is associated with :

*SLC9518G (MCT18070840)
[SHC8063E]
TP
CHUA GEK CHOO
Jul 28 2018 2:00PM
[-]
Performance Motors Limited

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 03/07/2019 16:45 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$35940.56) - SLC9518G - Claim Handler: Sundari Nagarajan

Approved:35940.56:

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Wednesday, 10 July 2019 7:51 AM
To: 'PBSP'
Cc: Admin A
Subject: RE: LOD REMINDER - SLC9518G & SHC8063E ON 28/07/2018

Without Prejudice

Dear Sirs/Mdm,

We refer to your below email.

We confirm settlement at \$35,940.56(all-in).

We will proceed to close file and submit all the docs to Ill asap.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Tuesday, 9 July 2019 5:46 PM
To: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Subject: Re: LOD REMINDER - SLC9518G & SHC8063E ON 28/07/2018

Dear HT

Urgent reminder for payment. Submitted to India already for payment?

Thank you.

Regards,
Caroline

C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Sent: Tuesday, 18 June 2019 5:14:13 PM
To: PBSP; Hsiao Tong (LKKAUTO)
Subject: RE: LOD REMINDER - SLC9518G & SHC8063E ON 28/07/2018

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Caroline,

We refer to the email below.

The current case handler for this case is Hsiao Tong.

Hi HT,

FYNA.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: asherSng@lkkauto.com | fax: 6741-4108

81k 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | 3(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Monday, 10 June 2019 6:35 PM
To: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Subject: Re: LOD REMINDER - SLC9518G & SHC8063E ON 28/07/2018

Dear Asher

Any update?

Thank you.

Regards,

Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Sent: Saturday, 20 April 2019 12:33:47 PM
To: PBSP
Subject: Re: LOD REMINDER - SLC9518G & SHC8063E ON 28/07/2018

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Hi Caroline,

We refer to the email below.

We are still seeking approval from our principal.

Shall revert to you once our principal approved.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: asher.sng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pmi-pbsp@simedarby.com.sg>
Sent: Thursday, April 18, 2019 6:28:21 PM
To: Asher Sng (LKKAUTO)
Subject: LOD REMINDER - SLC9518G & SHC8063E ON 28/07/2018

LOD REMINDER

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."



India Int'l Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711
Attention: Motor Claims

"Without Prejudice"

Your Ref :
Our Ref :
Date :
Subject :

27 February 2019

ACCIDENT INVOLVING VEHICLES SLC9518G & SHC8063E ON 28.07.2018

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:-

Cost of repair	: S\$ 34733.11
Loss of use	: S\$ 1200.00 (S\$60.00 x 20 days)
LTA search fee	: S\$ 7.45
Total	: S\$ 35940.56

A copy of each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair bill & LTA search slip
3. Copy of Police Report & Certificate of Insurance
4. Copy of Identification Card & Driving License
5. Copy of Letter of Authorisation & Discharge Voucher

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to pml-pbsp@sime-darby.com.sg.

Yours sincerely

Teng Wai Khan
Customer Service Manager, Body & Paint

Performance Motors
Limited
1800-Call-BMW
(1800-2255-2699)

www.pml.com.sg

303 Alexandra Road
Sime Darby
Performance Centre
Singapore 159941
Tel Sales 6319 0100
Tel Aftersales:
6319 0111
Fax 6474 7770

315 Alexandra Road
#01-01
Sime Darby
Business Centre
Singapore 159944
Tel Sales 6319 0511
Tel Aftersales:
6319 0527
Fax 6479 6624

280
Kampong Arang Rd
East Coast Centre
Singapore 438180
Tel Aftersales:
6319 0888
Fax 6344 1332

Registered office
305 Alexandra Road
#02-01
Vantage
Automotive Centre
Singapore 159942

Co. Reg. No:
197401559W

Performance Motors Limited

A member of the Sime Darby Group



LETTER OF AUTHORISATION

ACCIDENT INVOLVING SLC9518G & OHC8063E ON 28/07/18.

I, Mdm Chua Gek Choo owner of Vehicle Registration No. SLC9518G hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all documents whatsoever in relation to this matter and to accept and receive any payment due to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement amount in respect of such claim shall constitute the full discharge of my claim in respect of such loss and damage.

Signed by:

X

Name : CHUA GEK CHOO (Date)

NRIC No.: S0208219E

In the presence of:

Name :

NRIC No.:

HAN KWAN YONG
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

(Date) 30/07/18

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: FACT 18071840
Claimant Ref: SLC95186

We/I, Performance Motors Limited ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 34735.11 (repair cost), S\$ 126.46 (loss of use/rental), S\$ 7.45 (search fee), vehicle no. SLC95186 that was damaged pursuant to the accident which occurred on 28-7-18 (date) at Junction of Upper Changi Rd East & Link (location) involving vehicle no. SAC8015 (insured vehicle). This is pursuant to the inspection conducted on 1-8-18 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Chun Gek Choo ("the third party claimant") of vehicle no. SLC95186 to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLC95186 (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 35948.6 to Performance Motors Limited

Dated this 10 day of July 20 19

CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

NRIC:

Address:

Nationality:

Occupation:

HAN KWAN YONG
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 152941

WITNESS:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:



Signed by appointed Surveyor

LKK Auto Consultants Pte Ltd

199607198R

51 Ubi Ave 1 #01-25

Paya Ubi Industrial Park (C) 401985

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020001-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

200, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/510 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



SERVICE TAX INVOICE

Repair Order No. : B1 1288368

Date IN : 01/08/2018

Cust. Svc. Advisor: Han Kwan Yong

Page No. : 1 of 3

Invoice Number : 2069797 / WSB

Invoice Date : 26/02/2019

Payment Terms : 30 Days From Invoice

Invoice By : Toh Jing Xuan

- CUSTOMER INFORMATION -

Mdm Chua Gek Choo
20 Lorong 7 Realty Park

Singapore 536778

- INVOICE TO - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.
SLC9518G

CHASSIS NO.
V724603

REGN. DATE
30/05/2016

MODEL
116D

MILEAGE
43000

--- LABOUR 1 ---

To tow accident vehicle to PML workshop.

NETT

195.00

0.00

7,650.00

To replace rear bumper and attachments, bootlid, tail end panel, left trunk tub, rear luggage compartment floor, luggage compartment pan, rear left light in

side panel, rear left light in trunk lid, third stoplamp including to pull and straighten on accident areas, to make good the both rear fenders and knock out dented area caused by the accident.

4,470.00

To respray rear bumper, bootlid, tail end panel, both rear fenders and trunk floor panel.

100.00

To carry out body cavity preservation.

451.00

(Per panel).

To carry out body cavity preservation.

451.00

(For cut panel).

To replace front exhaust silencer including alignment of exhaust systems and conduct checks for leak.

451.00

To replace rear exhaust silencer including alignment of exhaust system and conduct checks for leak.

564.00

To replace each diesel particulate filter including alignment of exhaust system and conduct checks for leak.

2,257.00

To remove and install rear suspension, rear axle and control system for inspection including replacements of damaged parts.

451.00

To check steering geometry and conduct wheel alignment in accordance with BMW specifications.

564.00

To mount accident vehicle on speed bench to facilitate re-alignment of body/chassis in accordance with BMW specifications.

574.00

To remove and install rear windscreen glass to facilitate repairs.

75.00

To conduct water leak tests.

230.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

150.00

To check electrical wiring systems and lightings at the rear section for proper function.

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. W2-002081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/030 (Motorrad)
Fax. 64796801 (AfterSales)
64796624 (Motorrad)



SERVICE TAX INVOICE

Repair Order No. : **B1 1288368**Date IN : **01/08/2018**Cust. Svc. Advisor: **Han Kwan Yong**Page No. : **2 of 3**Invoice Number : **2069797 / WSB**Invoice Date : **26/02/2019**Payment Terms : **30 Days From Invoice**Invoice By : **Toh Jing Xuan**

To remove old PDC assembly, replace damaged parts and
reconnect to new bumper including conduct checks for
proper function.

150.00

To replace battery positive cables and attachments, to
perform high current tests and charge up battery.

451.00

Sundries.

150.00

0.00

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

DATE OF ACCIDENT : 28.07.2018. 3RD PARTY CAR : SHC8063E.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO ON
01.08.2018 AT 3PM. AUTHORISED REPAIR BY MS VIVIAN LAU
FROM LKK AUTO ON 01.08.2018 VIA EMAIL.

PROPOSE LOSS OF USE = \$60x20. THE AMOUNT IS SUBJECTED

0.00

TO INSURANCE COMPANY CONFIRMATION.

0.00

LTA SEARCH FEE = \$7.45.

0.00

VEHICLE WAS ALSO SURVEYED BY OD SURVEYOR MR SAM CHAN
FROM

AXA INSURANCE ON 01.08.2018 AT 10:30AM.

Total Labour 1: **19,384.00**

	Qty	Retail Price	NETT
----- P A R T S -----			
BOOTLID	1	1,108.45	1,108.45
TAIL END PANEL	1	497.45	497.45
REAR BUMPER CARRIER	1	385.25	385.25
LH REFLECTOR	1	35.20	35.20
REAR LH LIGHT IN THE TRUNK LID	1	278.65	278.65
LUGGAGE COMPARTMENT FLOOR REAR	1	113.90	113.90
LUGGAGE COMPARTMENT PAN	1	385.35	385.35
TRUNK TUB LH	1	117.65	117.65
REAR BUMPER PANEL PRIMED	1	902.20	902.20
REAR LH LIGHT IN THE SIDE PANEL	1	335.90	335.90
NUMBER PLATE LIGHT LED	1	23.20	23.20
BLIND RIVET AVIBVLB	60	0.55	33.00
PUNCH RIVET N4	40	0.55	22.00
(DG/SL) BODY ADHESIVE K5B (195ML)	1	281.55	281.55
(S/L) SEAM SEAL 300ML	1	33.80	33.80
(DG/SL) BMW AGM BATTERY (90 AH)	1	718.65	718.65
CLAMPING BUSH D=65.2MM	1	54.30	54.30
FRONT PIPE	1	492.70	492.70
REAR SILENCER	1	864.80	864.80
TAILPIPE END PIECE ALU LOOK	1	107.85	107.85
EXCH DIESEL PARTICULATE FILTER (EU5	1	3,550.20	3,550.20
V BAND CLAMP	1	41.80	41.80
THIRD STOPLAMP	1	169.90	169.90

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020001-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159943
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63483773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190531/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : **B1 1288368**Date IN : **01/08/2018**Cust. Svc. Advisor: **Han Kwan Yong**Page No. : **3 of 3**Invoice Number : **2069797 / WSB**Invoice Date : **26/02/2019**Payment Terms : **30 Days From Invoice**Invoice By : **Toh Jing Xuan**

(DG/SL) ADHESIVE SET K6	1	53.05	53.05
REAR PDC HOLDER SET	1	23.10	23.10
REAR BUMPER CENTRE GUIDE (M)	1	57.45	57.45
REAR BUMPER LH MOUNT	1	142.55	142.55
HOLDER CATALYTIC CONVERTER NEAR ENG	1	64.15	64.15
REAR AXLE CARRIER	1	1,728.25	1,728.25
BATTERY CABLE (PLUS POLE)	1	286.35	286.35
HEAT INSULATOR REAR SILENCER	1	61.60	61.60
CONNECTOR	1	3.65	3.65
GROMMET	1	4.35	4.35
DEGASSING HOSE BATTERY	1	15.60	15.60
Total Parts :			12,993.85

- - - - LABOUR 2 - - - -

To supply rear silver emboss lettering black base number
plate with bracket.

NETT

83.00

Total Labour 2: **83.00**

Labour Charges : **19,317.00**
Parts Charges : **12,993.85**
Lubricant/Misc : **150.00**

Total Labour & Parts Charges : **S\$ 32,460.85**
Less Insurance Excess : **S\$ 0.00**
Invoice Total Amount Exclude GST : **S\$ 32,460.85**
GST @ 7% : **S\$ 2,272.26**
Invoice Total Amount Include GST : **S\$ 34,733.11**

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 34,733.11**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.





Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 31 Jul 2018 / 15:01:17

Receipt Date/Time : 31 Jul 2018 / 15:01:17

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180731-001336

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
Result of Insurance Enquiry - SHC8063E				
As at 28 Jul 2018/14:00:00				
Insurance Co: INDIA INT'L INS PTE LTD				
1	Insurance Enquiry - SHC8063E Enquiry Fee 20180731150001487750	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
		xxxxxxxxxxxx2157	Credit Card Visa/MasterCard	7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement




































CLAIM SUBFOLDER TRACKING

















































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Aug 2018 Edit Reg		01 Aug 2018 00:00 Edit Adj Rpt	\$532,460.85 Edit Estimates	\$532,460.85 View Rpt		Pending for Survey Report Cancel Case












































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: -								
Main Claimant:	CHUA GEK CHOO , ID: S0208219E								
Vehicle Reg. No.:	SLC9518G	Date of Loss:	28/07/2018 14:00 - :59 [25 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18070840	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHC8063E	Policy No. (Claimant):	VPA/P1781253						
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagara - 6347 6071]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 10/08/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (03/07/2019): Alert - Adj Mandate Approved (\$535940.56) - SLC9518G - Claim Handler: Sundari Na... III_SG (01/08/2018): Alert - Adj Mandate Approved (\$50.00) - SLC9518G - Claim Handler: Sundari Nagara... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLC9518G (MCT18070840)
[SHC8063E]
TP
CHUA GEK CHOO
Jul 28 2018 2:00PM
[COMFORT TRANSPORTATION PTE LTD]
Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Photos/Images									3 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print		
1	21/02/19 15:47	Chassis Number							 Load JPG	<input checked="" type="checkbox"/>		
2	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
3	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
4	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
5	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
6	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
7	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
8	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
9	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
10	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
11	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
12	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
13	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
14	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
15	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
16	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
17	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
18	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
19	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
20	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
21	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
22	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
23	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
24	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
25	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
26	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
27	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
28	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
29	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
30	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
31	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
32	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
33	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
34	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
35	21/02/19 15:47	General View							 Load JPG	<input checked="" type="checkbox"/>		
36	21/02/19 15:47	General View							Load JPG	<input checked="" type="checkbox"/>		
37	21/02/19 15:47	General View							Load JPG	<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	21/02/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
39	21/02/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
40	21/02/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
41	21/02/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
42	21/02/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
43	21/02/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
44	21/02/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
45	21/02/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
46	21/02/19 15:47	General View	 Load JPG	<input checked="" type="checkbox"/>
47	21/02/19 15:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	21/02/19 15:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	21/02/19 15:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	21/02/19 15:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	21/02/19 15:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	21/02/19 15:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	21/02/19 15:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	21/02/19 15:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	21/02/19 15:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	21/02/19 15:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	21/02/19 15:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	21/02/19 15:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	21/02/19 15:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	21/02/19 15:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	21/02/19 15:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	21/02/19 15:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	21/02/19 15:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	21/02/19 15:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	21/02/19 15:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	21/02/19 15:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	21/02/19 15:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	21/02/19 15:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	21/02/19 15:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	21/02/19 15:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	21/02/19 15:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	21/02/19 15:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	21/02/19 15:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	21/02/19 15:47	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	21/02/19 15:48	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/07/18 18:26	TP ESTIMATE	 Load PDF	
2	31/07/18 18:26	TP GIA REPORT	 Load PDF	
3	03/08/18 09:12	TP ESTIMATE- MARKED	 Load PDF	
4	04/06/19 13:23	WORKSHOP INVOICE	 Load PDF	
5	04/06/19 13:23	LOD	 Load PDF	
6	18/06/19 17:34	LTA SEARCH FEE	 Load PDF	
7	11/07/19 13:36	DISCHARGE VOUCHER	 Load PDF	
8	11/07/19 13:37	AUTHORISATION TO ACT FORM	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	01/08/18 08:44	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III18013934/T1PB3Q2

Date: 11/07/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No: MCOM0015
Claimant Vehicle No : SLC9518G	Insured Vehicle No : SHC8063E
Date of Loss: 28/07/2018	Nature of Claim: TP Claim No: MCT18070840

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC9518G		
Make & Model:	BMW 116I, 1.6 ABS D/AIRBAG 2WD 5DR HID DSC (A)	Engine No:	34969567B37D15A
Reg. Date:	30/05/2016 (Man. Year: 2016)	Chassis No:	WBA1V72050V724603
Colour:	Grey	Odometer:	0 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,684.70	13,226.85	4,457.85	25.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	23,634.00	19,234.00	4,400.00	18.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	41,318.70	32,460.85	8,857.85	21.44
+ GST 7.00/7.00% (S\$)	2,892.31	2,272.26	620.05	21.44
Nett Amount (S\$)	44,211.01	34,733.11	9,477.90	21.44
+ Loss of Use (20.0 x S\$60.00/day) (S\$)		1,200.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		35,940.56		

INSPECTION

Date of Assignment:	01/08/2018	
Date Inspected:	01/08/2018 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	15.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jun 2019)
Parts:	144	BMW 116I 1.6 ABS D/AIRBAG 2WD 5DR HID DSC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC9518G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR EMBOSS NUMBER PLATE	Bent	83.00 FS	*83.00 FS
2	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
3	2		*RUBBER MOUNTING	Not Necessary	67.30 FS	*- FS
4	1		*TAILPIPE END PIECE ALU LOCK	Dented	107.85 FS	*107.85 FS
5	1		*VIBRABSORBER	Not Necessary	95.95 FS	*- FS
6	1		*V BAND CLAMP	Bent	41.80 FS	*41.80 FS
7	1		*REAR RH SILENCER BRACKET	Not Necessary	64.15 FS	*- FS
8	1		*REAR LH SILENCER BRACKET	Not Necessary	41.70 FS	*- FS
9	1		*CLAMPING BUSH D=65.2MM	Bent	54.30 FS	*54.30 FS
10	1		*FRONT PIPE	Bent	492.70 FS	*492.70 FS
11	1		*EXCH DIESEL PARTICULATE FILTER (EU5)	Bent	3,550.20 FS	*3,550.20 FS
12	1		*MUFFLER CLAMP D=63.2MM	Not Necessary	41.80 FS	*- FS
13	1		*REAR SILENCER	Bent	864.80 FS	*864.80 FS
14	2		*COLLAR SCREW	Not Necessary	26.20 FS	*- FS
15	1		*LH ENGINE MOUNT	Not Necessary	198.55 FS	*- FS
16	1		*RH ENGINE MOUNT	Not Necessary	198.55 FS	*- FS
17	2		*GEARBOX MOUNTING	Not Necessary	79.50 FS	*- FS
18	1		*LUGGAGE COMPARTMENT FLOOR RE	Not Necessary	113.90 FS	*- FS
19	1		*BOOTLID	Bent	1,108.45 FS	*1,108.45 FS
20	1		*TAIL END PANEL	Bent	497.45 FS	*497.45 FS
21	1		*LUGGAGE COMPARTMENT PAN	Bent	385.35 FS	*385.35 FS
22	1		*REAR BUMPER CARRIER	Bent	385.25 FS	*385.25 FS
23	1		*REAR BUMPER CENTRE GUIDE (M)	Deformed	57.45 FS	*57.45 FS
24	1		*REAR BUMPER TOWING EYE COVER PRIMED	Not Necessary	54.50 FS	*- FS
25	1		*REAR BUMPER LH MOUNT	Deformed	142.55 FS	*142.55 FS
26	1		*REAR BUMPER PANEL PRIMED	Deformed	902.20 FS	*902.20 FS
27	1		*SET REAR PDC HOLDER	Necessary	23.10 FS	*23.10 FS
28	1		*TRUNK LID LOCK	Not Necessary	155.70 FS	*- FS
29	1		*STRIKER TRUNK LID	Not Necessary	55.75 FS	*- FS
30	1		*EMBLEM BUTTON	Not Necessary	103.40 FS	*- FS
31	1		*SUPPORTING RING	Not Necessary	35.55 FS	*- FS
32	10		*BUMP STOP	Not Necessary	32.50 FS	*- FS
33	1		*HEAT INSULATOR REAR SILENCER	Bent	61.60 FS	*61.60 FS
34	1		*PLAQUE 82MM	Not Necessary	69.50 FS	*- FS
35	1		*TRUNK LID GASKET	Not Necessary	66.95 FS	*- FS
36	1		*(DG/SL) BMW AGM BATTERY (90 AH)	Deformed	718.65 FS	*718.65 FS
37	1		*LH REFLECTOR	Cut	35.20 FS	*35.20 FS
38	1		*RH REFLECTOR	Not Necessary	35.20 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*REAR LH LIGHT IN THE SIDE PA	Cracked	335.90 FS	*335.90 FS
40	1		*REAR RH LIGHT IN THE SIDE PANEL	Not Necessary	335.90 FS	*- FS
41	1		*REAR LH LIGHT IN THE TRUNK LID	Cracked	278.65 FS	*278.65 FS
42	1		*REAR RH LIGHT IN THE TRUNK LID	Not Necessary	278.65 FS	*- FS
43	1		*THIRD STOPLAMP	Necessary	169.90 FS	*169.90 FS
44	2		*NUMBER PLATE LIGHT LED	Cracked (1 PCS ONLY)	46.40 FS	*23.20 FS
45	4		*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	20.20 FS	*- FS
46	4		*PDC SENSOR MINERAL GRAU (B3)	Not Necessary	1,475.20 FS	*- FS
47	1		*BLIND RIVET AVIBVLB (30 PCS)	Necessary	33.00 FS	*33.00 FS
48	12		*SCREW (SF PLUS M5X15)	Not Necessary	6.60 FS	*- FS
49	1		*(DG/SL) BODY ADHESIVE K5B (195ML)	Necessary	281.55 FS	*281.55 FS
50	10		*PUNCH RIVET N5	Not Necessary	5.50 FS	*- FS
51	2		*(DG) CLEANER R1 (100ML)	Not Necessary	47.70 FS	*- FS
52	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Not Necessary	263.10 FS	*- FS
53	1		*(DG/SL) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS
54	1		*PUNCH RIVET N4 (40 PCS)	Necessary	22.00 FS	*22.00 FS
55	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Not Necessary	27.85 FS	*- FS
56	4		*(S/L) SEAM SEAL 300ML	Necessary (1 PCS ONLY)	135.20 FS	*33.80 FS
57	1		*HOLDER CATALYTIC CONVERTER NEAR ENG	Bent	64.15 FS	*64.15 FS
58	1		*REAR AXLE CARRIER	Bent	1,728.25 FS	*1,728.25 FS
59	1		*LUGGAGE COMPARTMENT FLOOR REAR	Bent	113.90 FS	*113.90 FS
60	1		*TRUNK TUB LH	Bent	117.65 FS	*117.65 FS
61	1		*BATTERY CABLE (PLUS POLE)	Distorted	286.35 FS	*286.35 FS
62	1		*CONNECTOR	Necessary	3.65 FS	*3.65 FS
63	1		*GROMMET	Necessary	4.35 FS	*4.35 FS
64	1		*DEGASSING HOSE BATTERY	Distorted	15.60 FS	*15.60 FS
65	1		*REAR LH LIGHT IN THE SIDE PANEL	Repeated	335.90 FS	*- FS
Total Parts (\$\$)					17,684.70	13,226.85

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND INSTALL REAR SUSPENSION ,REAR AXLE AND CONTROL SYSTEM FOR INSPECTION INCLUDE REPLACEMENT OF DAMAGED PARTS	New	2,257.00	2,257.00
2	TO REPLACE BATTERY POSITIVE CABLE AND ATTACHMENTS ,TO PERFORM HIGH CURRENT AND CHARGE UP BATTERY	New	451.00	451.00
3	TO TOW ACCIDENT VEHICLE TO PML WORKSHOP	New	195.00	195.00
4	TO REPLACE REAR BUMPER & ATTACHMENTS ,BOOT LID ,TAIL PANEL,TRUNK FLOOR PANEL INCLUDING TO PULL & STRAIGHTEN BOTH REAR CHASSIS ,TAIL PANEL BEFORE CUT TING AND TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT	New	8,500.00	7,650.00
5	TO RESPRAY REAR BUMPER,BOOT LID ,TAIL PANEL, REAR RIGHT FENDER ,REAR LEFT FENDER AND BOOT COMPARTMENT	New	4,967.00	4,470.00
6	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
7	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL)	New	531.00	451.00
8	TO REPLACE FRONT EXHAUST SILENCER INCLUDING ALIGN EXHAUST SYSTEM AND CONDUCT CHECKS FOR LEAK	New	531.00	451.00
9	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK	New	531.00	451.00
10	TO REPLACE EACH DIESEL PARTICULATE FILTER INCLUDING ALIGNMENT AND CONDUCT CHECKS FOR LEAK	New	664.00	564.00
11	TO REPLACE ENGINE MOUNTINGS INCLUDING RE-ALIGNMENT OF ENGINE BLOCK TO BODY FRAME	New	679.00	0.00
12	TO REPLACE GEARBOX MOUNTINGS INCLUDING RE-ALIGNMENT OF GEARBOX TO CROSS MEMBER AND PROPELLER SHAFT SYSTEM	New	679.00	0.00
13	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION	New	531.00	451.00
14	TO CONDUCT CHASSIS ALIGNMENT MEASURING CHECK USING CAR-O-LINER MEASURING SYSTEM ACCORDANCE WITH BMW SPECIFICATION	New	531.00	0.00
15	TO MOUNT ACCIDENT VEHICLE ON SPEED BENCH TO FACILITATE RE-ALIGNMENT OF BODY/CHASSIS ACCORDANCE WITH BMW SPECIFICATION	New	664.00	564.00
16	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPLACEMENT BOOT LID	New	574.00	574.00
17	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
18	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	230.00
19	TO CHECK ELECTRICAL WIRING SYSTEMS AD LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
20	TO REMOVE AND INSTALL WIRE HARNESS ,CONTROL UNITS AND BATTERY AT THE REAR SECTION TO FACILITATE PANEL REPLACEMENT	New	531.00	0.00
21		New	177.00	150.00

Report was unsubmitted during this print-out.

