

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0869/2018/KS
Date : 31-Jul-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : SLZ 6299 L

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : M/S PREMIUM AUTOMOBILES PTD LTD
Address : 55 UBI ROAD 1
Singapore 408699
Telephone : HP +65 87770600
Type of Claim : Third Party Claim
Policy No. : 100834113
Vehicle No : **SLV 2463 B**
Model Code : Audi A4 SEDAN 2.0 TFSI
Model / Year : Dec-17
Engine No : CVK 049196
Chassis No : WAUZZZF42JA063198
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 27-Jul-18
Place of Accident : CHERAS HIGHWAY

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLV 2463 B.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor.	S/N \$ 360.00 ✓	
2	To dismantle and renew rear bumper. Re-organise front crash management components. Reinstall parts removed.	\$ 900.00 500	
3	To respray front bumper.	\$ 800.00 550	
4	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>2,252.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLV 2463 B.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>deformed</i>	\$ 1,907.00	✓
2	FIXING PARTS FOR BUMPER	\$ 63.00	X
3	REAR BUMPER SECURING PLATE	\$ 56.00	X
4	REAR BUMPER SECURING STRIP	\$ 191.00	X
5	REAR BUMPER SPOILER	\$ 216.00	X
6	REAR LIGHT REFLECTOR LH / RH	2 \$ 70.00	X
7	REAR BUMPER CARRIER	\$ 786.00	X
8	UPPER GUIDE SECTION LH / RH	2 \$ 38.00	X
9	LOWER GUIDE SECTION LH / RH	\$ 75.00	X
10	REAR PARKING AID SENSOR <i>1 piece damaged</i>	\$ 421.00 210.50	
11	REAR PARKING AID SENSOR SEAL ?	\$ 14.00	?
12	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS		\$ 4,137.00	
TOTAL LABOUR CHARGES		\$ 2,252.00	
GRAND TOTAL		\$ 6,389.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Lim*
Surveyed Date : *03/08/18*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 03 Days*

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant