



Auto Insure Pte. Ltd.

Blk 3, 391A Woodlands Road
Yew Tee Industrial Estate
Singapore (677964)
E: claims@autoinsure.com.sg
W: www.autoinsure.com.sg
T: 6368 2788 F: 6368 0081
GST No.: 201437380M

AUTOMOBILE ASSESSMENT REPORT

Page No.1

Our Ref: SIT5612C
Your Ref: 34550MID

Date: 28-Jun-18

BY EMAIL ONLY
(claims@autoinsure.com.sg)

ATTENTION: MOTOR CLAIMS DEPT

Assessed Vehicle No : SIT5612C
Car Make and Model : NISSAN LATIO 1.5A
Date of Accident : 22-Jun-18
Date of Assessment : 28-Jun-18


We have carried out a physical assessment of SIT5612C at our workshop Auto Insure Pte Ltd sustained damages to the REAR LH portion of the vehicle.

4. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had sustained damages to the REAR LH portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL



Estimated Amount : P/P
Adjusted Amount : \$ 15,200.00
Est. Repair Days : 10

** Considering that our vehicle is less than 6 months old.
We will not agree to any repair of parts, only replacement will be done. **

Pursuant to your instruction, we have **NOT AUTHORIZED** repair.
The assessment was conducted on a "**WITHOUT PREJUDICE**" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.
No liability or responsibility whatsoever shall be held by
AUTO INSURE PTE. LTD. For any reliance on this report by any third party.

Our Ref: SJT5612C

Your Ref: 34550MID

S/NO	QTY	SPECIAL NOTE ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	1 SET	REAR BUMPER CLIPS ✓ NEL		\$ 50.00 30
2	1	REAR END PANEL SEALANT ✓ NEL		\$ 80.00 50
3	1	REAR WINDSCREEN RUBBER MOULDING ✓ NEL		\$ 180.00 100
4	1 SET	REAR FLOOR PANEL SOUND INSULATOR X		\$ 120.00
5	2	REAR TOWING CAP X		\$ 120.00
6	1	WINDSCREEN SEALANT ✓ NEL		\$ 80.00 50
SUB TOTAL				\$ 640.00
TOTAL PARTS COST				\$ 9,297.11

Our Ref: SJT5612C

Your Ref: 34550MID

S/NO	DESCRIPTION	EST. BY WORKSHOP
LABOUR & PAINTWORK		
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	\$ 2,000.00 1200
2	TOWING CHARGE	\$ 80.00 60
	TO CONDUCT HEADLAMP FOCUS	\$ -
3	TO REMOVE/REFIX A/C CONDENSOR & REFILL AIRCON GAS	\$ -
	TO CONDUCT WHEEL ALIGNMENT	\$ 100.00 50
	LABOR FOR UNDERCARRIDGE	\$ 250.00 200
4	TO REMOVE/INSTALL REAR WINDSCREEN	\$ 250.00 200
	TO REMOVE /INSTALL DOOR MECHANISIM,PANEL AND MIRROR	\$ 250.00 200
5	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR	\$ 200.00 100
6	TO REMOVE / REFIX WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	\$ 80.00 50
7	TO REMOVE / INSTALL REAR REVERSE SENSOR	\$ 150.00 X
8	TO REMOVE / REFIX UPHOSTERY, GARNISH AND ATTACHMENT PARTS	\$ -
9	TO REMOVE / REFIX REAR LUGGAGE COMPARTMENT	\$ -
10	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	\$ 1,800.00 1000
11	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	\$ 150.00 100
12	TO VACUUM, WAXING & CLEAN	\$ 100.00 X
13	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS	\$ 100.00 50
TOTAL BEFORE GST		\$ 14,207.11
GST 7%		\$ 994.50
TOTAL (PARTS & LABOUR):		\$ 15,201.61

Adjustments / Recommendations

Our estimator have thoroughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a sum of \$15,200.00 for direct settlement with the third party insurance.

Yours Faithfully,

Jason Heng
Claims Director

Sathya Sai

2/7/2018

- Lump Sum Repair
- Question mark item photo
- Photo after paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sathya Sai @ lkkauto.com

8 days

Our Ref: SIT5612C
Your Ref: 34550MID

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
<u>PARTS REPLACEMENT - LIST ITEMS</u>				
1	1	REAR BUMPER ✓cut		\$ 1,126.00
2	1	REAR BUMPER SIDE RETAINER ✓crk		\$ 48.20
3	1	REAR FENDER INNER SHIELD LH ✓Deform		\$ 279.20
4	1	REAR REINFORCEMENT ?		\$ 589.90
5	1	REAR DOOR LH ✓crk		\$ 1,185.00
6	1	REAR DOOR HANDLE LH ✓cut		\$ 189.50
7	1	REAR DOOR LH LOWER HINGE x		\$ 72.00
8	1	REAR DOOR LH UPPER HINGE x		\$ 72.00
9	1	REAR FENDER LH ✓crk		\$ 528.00
10	1	REAR FENDER TAIL LAMP LH ✓ms		\$ 785.00
11	1	REAR TAIL LAMP PANEL LH ✓DT		\$ 445.00
12	1	WHEEL ARCH PANEL LH ?		\$ 1,064.00
13	1	ROCKER PANEL x		\$ 890.00
14	1	REAR DOOR WINDOW MECHANISM LH ?		\$ 770.00
15	1	REAR DOOR RH INNER LOCK ?		\$ 278.00
16	1	REAR DOOR RH INNER TRIM BOARD ?		\$ 322.50
17	1	REAR DOOR WEATHER STRIP ?		\$ 180.00
18	1	REAR DOOR WINDOW MOULDING ?		\$ 229.00
19	1	BOOT R		\$ 865.00
20	1	BOOT TOP GARNISH x		\$ 349.00
21	1	RIM x		\$ 500.00
22	1	REAR LOWER ARM LH		\$ 368.00
23	1	REAR KNUCKLE ARM LH		\$ 472.00
24	1	REAR ABSORBER LH		\$ 478.00
25	1	REAR WHEEL BEARING LH		\$ 282.00
			SUB TOTAL	\$ 12,367.30
			LESS 30%	\$ 3,710.19
			TOTAL AMOUNT	\$ 8,657.11