



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: FY 18/19/0021  
Our Ref: CC2/MIDA18013941/Kpq2

**HQ-Transport Command**

Kranji Camp 3  
151 Chua Chu Kang Way  
Singapore 688248

**Attn : CPT MERLIN/ IWO RAVEEN**

Dear Sir,

**ACCIDENT INVOLVING MID 34092 & SMA 470S ON 28/07/2018**

We refer to the above matter.

We have completed settlement with M/s MBM Wheelpower Pte Ltd acting for third party (DV enclosed).

Third party vehicle was insured with M/s Liberty Insurance Pte Ltd and policy coverage under comprehensive with excess \$1,200.00. TCA is not applicable as the excess is more than \$1,000.00.

We have completed the claims activities and shall close our file.

Our note of charges is enclosed for your necessary action.

Summary: -

	Date of submission:	Remarks:
Professional Service Fee		Completed.
Disbursement Fee		DV from Civilian enclosed.
TCA	NIL	TCA is not applicable.

Yours faithfully

Chew Hsiao Tong  
Claims Section  
DID: 6742 3197  
Fax: 6741 4108  
E-mail: chewht@lkkauto.com

WITHOUT PREJUDICE to:  
(a) Insurers' Subrogated Claim and/or  
(b) Any Personal Injury Claims  
[Note: This Notice supersedes any  
Inconsistencies found in this  
Discharge Voucher]

## DISCHARGE VOUCHER AND INDEMNITY


I / We, the undersigned BENAZIR BINTE MOHAMED SHARIFF DO HEREBY AGREE to accept the offer by the Government of the Republic of Singapore (hereinafter referred to as the "Government") for the sum of SGD THREE THOUSAND SEVEN HUNDRED FIFTY THREE AND CENTS FORTY ONLY (S\$3,753.40) in full and final settlement of all claims (Excluding Injury Claim) howsoever arising out of or in connection with the damages caused to my vehicle no. SMA 470S, in an accident involving Govt, vehicle no. MID 34092 on 28/07/2018.

I hereby authorize you to make payment in favour of MBM WHEELPOWER PTE LTD.

I agree that the payment is made without any admission of liability on the part of the Government or any agent or servant of the Government, I declare that I have no further claim whatsoever against the Government or any agent or servant of the Government in respect of the abovementioned incident and hereby give the Government a full and final discharge in respect of any liability or liabilities (Excluding Injury Claim) which may arise out of the aforesaid accident.

I also declare that I am the person entitled to receive the above compensation and hereby undertake to indemnify the Government against any claim made or which may be made by any person in connection with this matter.

Date: 6.4.2019.

Signature of Claimant (with company stamp if applicable): 

Name of Claimant: Benazir Binte Mohamed Shariff

If the Claimant is a Company or Firm, Name and Designation  
Of the person signing on behalf of the Company or Firm.

Signature of Witness: 

Name and Designation of Witness: Kon Yin Siew

**Hsiao Tong (LKKAuto)**

To: yinsiew.kon@mbmwheelpower.com.sg  
Cc: stephanie.lin@mbmwheelpower.com.sg  
Subject: RE: LOD - Accident involving SMA470S and MID34092 along Inside Khatib Camp 23  
SA Carpark on 28/07/2018

**WITHOUT PREJUDICE**

Dear Sirs,

**ACCIDENT INVOLVING MID 34092 & SMA 470S ON 28/07/2018**

We refer to the above matter.

Strictly without admission of liability and for quick and amicable settlement, our principal MINDEF is prepared to settle your client's claim as follows :-

1. Cost of Repair (w/GST)	\$ 3,253.40
2. Loss of Rental (5days x \$100.00)	\$ 500.00
<b>Total</b>	<b>\$ 3,753.40</b>

Please confirm acceptance.

Dear CPT Merlin/ 1WO Raveen (FY18/19/0021)

- The accident occurred when our SAF driver hit onto third party parked vehicle. As such, SAF is fully at fault.
- We have adjusted claim amount as above;
- For your approval please.

Best Regards,  
Chew Hsiao Tong  
LKK Auto Consultants Pte Ltd  
14 Nov 2018

Best Regards,

Hsiao Tong, Chew | Case Handler  
LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

14/11  
51842144E  
1WO RAVEENDRAN  
TA INVESTIGATION WO  
HQ TRANSPORT

**APPROVED**



**mbm wheelpower**  
DARE TO BE

**To:** Ministry of Defence  
HQ-Transport Command Kranji Camp 3  
151 Choa Chu Kang Way  
Singapore 688248

TEL: 6760 8828

**Attn:** Motor Claims Dept

**Tax Invoice:** 42768

**Date:** 25/10/2018

**Vehicle No.:** SMA470S

**Make / Model:** Honda Freed

**Chassis No.:** GB71060146

**Engine No.:** LEB5591739

**Year of Make:** 2018

**Accident Date:** 28/7/2018

S/N	DESCRIPTION	Amount S\$
1	COSTS OF REPAIR - PART BY PART	\$ 3,040.56

Total :	\$	3,040.56
7% GST:	\$	212.84
<b>Amount Due S\$</b>	<b>\$</b>	<b>3,253.40</b>

For & on behalf  
MBM WHEELPOWER PTE LTD



Prepared by: Yin Siew

MBM Wheelpower Pte Ltd  
160 Sin Ming Drive #06-02  
Sin Ming Autocity Singapore 575722  
Customer Service Hotline 6262 8888  
[www.mbmwheelpower.com.sg](http://www.mbmwheelpower.com.sg)  
Company Registration Number: 200204110W  
GST Registration Number: M90368446L



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

**FACSIMILE**

To : Liberty Insurance Pte Ltd  
Attention : Claims Dept - TCA Recovery Section  
Fax no : 6224 1047

ENTERED 22 JAN 2019  
By fax.

Your ref : SMA470S  
Our ref : CC2/MIDA18013941/Kpq2  
Date : 19/01/2019

No of pages : 1

**TREASURY COLLISION AGREEMENT - ACCIDENT INVOLVING  
MID 34092 & SMA 470S ON 28 JULY 2018**

We understand that vehicle SMA 470S was insured with Liberty Insurance Pte Ltd at the time of accident.

We would be grateful if you could let us have the following information (please fill in the blanks and fax reply to 6741 4108):

1. Scope of your cover - Comprehensive ( ☒ ) Third Party ( ☐ )  
Third Party Injuries ( ☐ )
2. Excess under your policy: S\$ 1200.00
3. Cost of repair to your insured's vehicle (if applicable): N.A.

Yours faithfully

*Chew*

Chew Hsiao Tong  
Claims Section  
DID: 6742 3197  
Fax: 6741 4108  
E-mail: [chewht@lkkauto.com](mailto:chewht@lkkauto.com)



Dear Sirs / Mdm,

P/s see the above  
information as requested

Thanks

LIBERTY CLAIMS DEPARTMENT  
LIBERTY INSURANCE PTE  
51 CLAB STREET  
#03-00 LIBERTY HOUSE  
SINGAPORE 069428  
TEL: 6742 3197




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MINISTRY OF DEFENCE		Ref : CC2/MIDA18013941/Kpq2		
HQ TRANSPORT COMMAND KRANJI CAMP 3 151 CHOA CHU KANG WAYSINGAPORE 688248		Date : 23-01-2019		
		Code : MIDA		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	MID 34092	Veh. Inspected	SMA 470S	
Policy No.		Coverage (\$)	0.00	
Claim No.	FY18/19/0021	Excess (\$)	0.00	
Assign From		Assign Date	18/09/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA FREED (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	GB71060146	Colour	METALLIC GREY	
Odometer	5443	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	YOKOHAMA	9 mm	
L/H Front Tyre	185/65 R15	YOKOHAMA	9 mm	
R/H Rear Tyre	185/65 R15	YOKOHAMA	9 mm	
L/H Rear Tyre	185/65 R15	YOKOHAMA	9 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	28/07/2018	Inspection Date	18/09/2018	
Survey held at	MBM WHEELPOWER PTE LTD 176 SIN MING DRIVE #01-15 SIN MING AUTOCARE SINGAPORE 575721			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 470S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	TAIL GATE GLASS MOULDING	NECESSARY	85.00	85.00
1	TAIL GATE	BENT	1,500.00	1,193.20
1	TAIL GATE WEATHERSTRIP	SERVICEABLE	150.00	-
1	TAILGATE HINGE LH	NOT NECESSARY	180.00	-
1	TAILGATE HINGE RH	NOT NECESSARY	180.00	-
1	TAILGATE HINGE COVER LH	SERVICEABLE	95.00	-
1	TAILGATE HINGE COVER RH	SERVICEABLE	95.00	-
1	TAILGATE HYDRAULIC ARM LH	SERVICEABLE	620.00	-
1	TAILGATE HYDRAULIC ARM RH	SERVICEABLE	620.00	-
1	TAIL GATE HANDLE	DENTED	170.00	170.00
1	TAIL GATE REAR -VIEW CAMERA	SERVICEABLE	890.00	-
1	TAIL GATE LOCK	NOT NECESSARY	150.00	-
1	TAIL GATE LOCK COVER	SERVICEABLE	65.00	-
1	TAIL GATE STRIKER	TO REPAIR SEE LABOUR	60.00	-
1	TAILGATE INNER TRIM BOARD	NOT NECESSARY	485.00	-
10	TAILGATE INNER TRIM CLIPS	NECESSARY	60.00	60.00
1	TAIL GATE HONDA LOGO	NECESSARY	70.00	70.00
1	TAIL GATE 'FREED' EMBLEM	NECESSARY	65.00	65.00
1	TAIL GATE 'HYBRID' EMBLEM	NECESSARY	80.00	80.00
1	TAIL GATE CHROME MOULDING	DENTED	280.00	280.00
1	TAIL GATE LAMP LH	SERVICEABLE	600.00	-
1	TAIL GATE LAMP RH	SERVICEABLE	600.00	-
1	TAIL GATE SENSOR LH	SERVICEABLE	1,100.00	-
1	TAIL GATE SENSOR RH	SERVICEABLE	1,100.00	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,220.00	-
10	REAR BUMPER CLIPS	NECESSARY	60.00	60.00
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	75.00	-
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	75.00	-
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	90.00	-

Report Ref No. CC2/MIDA18013941/Kpq2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	90.00	-
2	REAR BUMPER REVERSE SENSORS	SERVICEABLE	500.00	-
2	REAR BUMPER REVERSE SENSOR SPACER RINGS	SERVICEABLE	30.00	-
1	END PANEL	TO REPAIR SEE LABOUR	750.00	-
1	END PANEL TOP GARNISH	SERVICEABLE	165.00	-
10	END PANEL TOP GARNISH CLIPS	NOT NECESSARY	60.00	-
	LESS 10% DISCOUNT		-1,241.50	-
	LESS 20% DISCOUNT		-	-412.64
			11,173.50	1,650.56
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	BODY SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	SET NUMBER PLATE WITH HOLDER (SN)	SERVICEABLE	60.00	-
1	G-GUARD COATING FOR TAILGATE & REAR BUMPER (SN)	NECESSARY	500.00	250.00
			720.00	290.00
	<b><u>LABOUR</u></b>			
	TO SPRAY PAINT ON THE AFFECTED AREAS.		1,000.00	500.00
	TO REMOVE ,REFIT & REPAIR AFFECTED DAMAGED PARTS.INCLUDING TO KNOCK -OUT,WELD & STRAIGHTEN ON THE AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF TAIL GATE STRIKER,REAR BUMPER AND END PANEL.		1,200.00	400.00
	TO DISMANTLE & TRANSFER TAILGATE FITTINGS & MECHANISM TO NEW SHELL.		120.00	60.00
	TO REMOVE & REFIT REAR WINDSCREEN.		150.00	120.00
	TO REMOVE & REPLACE BUMPER SENSORS .	NOT NECESSARY	80.00	-
	TO CHECK & RECONNECT ALL NECESSARY WIRING.		120.00	20.00
-			-	-
-			-	-
-			-	-
-			-	-
-			-	-



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
-			-	-
			2,670.00	1,100.00
GRAND TOTAL			14,563.50	3,040.56
RECOMMENDED COST OF REPAIRS				3,040.56

Report Ref No. CC2/MIDA18013941/Kpq2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SMA 470S

### INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SMA 470S

### RE-INSPECTION

