

ASS. REC. BY:

REF: CS / IAS 18013951 / D4652

Special Instruction:

SUBJECT:

ASSIGNMENT (Office)

From (Person): Jason Chua of Insight Adjusters Date/Time: 31/07/2018 3:39pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: EL 101U Insured: Forklift

at Workshop m/s Teamwork Tel: 6844 2475

of 53 Ubi Ave 1 #01-24

Policy No: Claim No: [IA2018-37642]

Sum Insured: Excess:

Make of Veh: D.O.A.  
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp' H.O.D. Endorsement:

Date/Time: 31/07/2018 4:28pm Person Contacted: Darren Vehicle: IN/OUT

Date/Time	Action/Instruction ( ✓ ) Estimate
	EL 101U - X
	Forklift - X
21-3	3:36pm Revert via preli aduse.

09/11/19  
Average

REF:

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: EL 101U Yr Regn: Nov 2016

Type: M.C / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz C200 C.C. 1991

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 42901 T/Radio: Insured / Std / NI / NA

Eng/No: 27492030621691

C/No: WDD2050422R174154

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/35 R 19

R: — — —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Pirelli

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 25/07/2018

D.O.I. 31/07/2018

Survey held at Teamwork Page Ubi

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or.

Front o/s

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Check Temping Parklight.

11/03/19 Jumper 2/5 167001 - with 6 days of repair (red: 18722) 53%

RECEIVED 13 MAR 2019

Date/Time, File Pass to?  : Preli. Report

1) BB Tupist  : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee:  : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

Report Format: TP

Lump Sum / I.B.I. (\$) 16700/-

Survey Fee:

Transportation:

S + RR SI

Photos 680

Others 888

TOTAL 14/19

545
50
50
120
80
845

25x15=375  
375+170=545

## Catherine Chong (LKK Auto)

---

**From:** Bryan Ang (LKKAuto) <bryanang@lkkauto.com>  
**Sent:** Tuesday, 31 July, 2018 3:43 PM  
**To:** Jason Chua; assignments  
**Cc:** Ryan Chia; Celine Fong (LKKAuto)  
**Subject:** RE: [IA2018-37642] Theng Liang Lee Services Pte Ltd

Dear Jason

Contents of your email is noted. Will carry out the needful and revert with our preliminary advice soon.

Dear Assignment Team

Please assign surveyor to survey the claimant's vehicle, details can be found in the email below.

Please forward a copy of our service request form for endorsement before surveying the vehicle.

Best Regards,

**Bryan Ang**

**LKK Auto Consultants Pte Ltd**

phone: 6256-3561 | email: [bryanang@lkkauto.com](mailto:bryanang@lkkauto.com) | fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Jason Chua [<mailto:jasonchua@insightadjusters.com>]

**Sent:** Tuesday, 31 July 2018 3:39 PM

**To:** Bryan Ang (LKKAuto) <bryanang@lkkauto.com>

**Cc:** Ryan Chia <[ryan.chia@sg.cntaiping.com](mailto:ryan.chia@sg.cntaiping.com)>

**Subject:** [IA2018-37642] Theng Liang Lee Services Pte Ltd

Dear Mr Bryan,

We are the Loss Adjusters appointed by China Taiping Insurance (Singapore) Pte Ltd to look into a Public Liability matter.

This incident involves impact damage to the Third Party's vehicle by our Insured's forklift.

Below are the brief details of the incident:-

➤ Third Party's vehicle

- Model : Mercedes Benz C200
- Brand : As above
- Registration no: EL101U
- Remarks : Impact damage to the front of the vehicle by a forklift.

We require your assistance to conduct a damage assessment on a "Without Prejudice" basis. This damage assessment is on an urgent basis and we appreciate if you can carry it out ASAP.

Enclosed are the details of the workshop and their contact person for your easy reference:

Contact person : Darren Ng

Contact no : 6844 2475 (O)

Name of workshop : Teamwork Garage Pte Ltd, 53 Ubi Avenue 1 #01-24 Paya Ubi Industrial Park, Singapore 408934.

We understand from the Third Party's workshop that the estimated repair cost is in the region of S\$20,000.00 to S\$30,000.00.

Enclosed are the photographs taken during the incident, along with the accident report for your perusal.

Please do not hesitate to contact me should you have any further enquires. Thank you.

Best regards,

Jason Chua

E-Mail : [jasonchua@insightadjusters.com](mailto:jasonchua@insightadjusters.com)

**Insight Adjusters and Surveyors Pte Ltd**

133 Cecil Street, #14-02

Keck Seng Tower

Singapore 069535

(65) 6223 2008 • Fax : (65) 6226 2356

<http://www.insightadjusters.com>

- ASIA Regional Office for vrs adjusters
- Loss Adjuster of the Year, Asia Insurance Industry Award
- A Singapore Top 500 SME
- CESAM Average Agents, AIMU Correspondents

\*CONFIDENTIAL NOTE: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law.

If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited.

If you have received this message in error, please immediately notify the sender and delete the mail.

Thank you.



Auto  
Consultants  
Pte Ltd

51 UBI AVE I, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: [IA2018-37642]

Date: 2/8/2018

Our Ref: CS/IAS18013951/Dtb

**Insight Adjusters Pte Ltd**

Dear Sirs/Mdm

**PRELIMINARY ADVICE OF VEHICLE NO. EL 101U**


We thank you for the instruction on 31/7/2017.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 31/7/2017 at the premises of M/s Teamwork and have the following to report:-

Workshop Estimate Amount	: S\$	<u>32,183.40</u>
Revised Estimate Amount	: S\$	<u>21,648.10</u>
"Check" Items Amount	: S\$	<u>-</u>
Market Value	: S\$	<u>-</u>
LTA Reimbursement Value	: S\$	<u>-</u>
Nett Value	: S\$	<u>-</u>

**Description of Damage:**

The vehicle sustained damages due to Front o/s portion



**Comments/ Present Status:**

Damages Consistent.

Estimated normal period of repairs 6 days

Yours faithfully

Rasul

Automotive Assessor

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	25/07/2018 15:55
Date Of Accident	25/07/2018 05:35
Exact Location Of Accident	PASIR PANJANG WHOLESALE CENTRE CP
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	EL101U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KATHERINE TAY KAI YIN
NRIC No	S7334368B
Email Address	KATHERINE@TOMHOUSE.COM.SG
Mobile Phone No	(LOCAL) +65-96196101
Alternative Phone No	OFFICE-96196101

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C200
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTPVO1O6640CHAN
Cover Note Number	

### Driver

Name of Driver	CHAN KHENG KIAT
NRIC No	S7005236I
Date Of Birth	30/01/1970
Occupation	INDOOR
Date Of Driving Pass	29/08/1994
Driving Experience	23 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90100101
Fax Number	
Contact Number	
EMail Address	KATHERINE@TOMHOUSE.COM.SG

Address 16A SOUTH BUOANA VISTA RD S118148  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured SPOUSE  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? YES  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

REFER TO ATTACHED REPORT

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number F16KNF  
 Vehicle Make/Model/Colour FORKLIFT  
 Details Of Properties  
 Vehicle Category MOBILE EQUIPMENT  
 Name of Driver NA  
 NRIC/Passport Number  
 Contact Number NA  
 Address NA  
 NA  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name CHAN KHENG KIAT

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

UNKNOWN

EL101U

YES

NO

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

*[Handwritten Signature]*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Handwritten Signature]*


SUBMIT FOR *[Signature]* (SON)  
25/07/18 1541

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



Accident Sketch Plan Pg. 1

SKETCH PLAN



A: E11014  
B: F16KNF

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was inside Pasir Panjang Wholesale Centre Carpark stationary waiting to reverse into the lot. Suddenly a forklift coming from the opposite direction and hit onto the front right portion of my vehicle. It was a one way road and the forklift is driving in the wrong direction of the traffic.


DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



FOR *John (son)* 25/07/18 1541

> [Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4368B
Vehicle Details	
Vehicle No.:	EL101U
Vehicle to be Exported:	No
Intended De-registration Date:	03 Aug 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C200 A
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	27492030621691
Chassis No.:	WDD2050422R174154
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$40,601.00
Original Registration Date:	17 Nov 2016
First Registration Date:	17 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$43,842.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Nov 2026
PARF Rebate Amount:	\$32,881.00
Intended COE Rebate Details	
COE Expiry Date:	16 Nov 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,410.00
COE Rebate Amount:	\$46,741.00
<b>Total Rebate Amount:</b>	<b>\$79,622.00</b>

The information contained herein is correct as at 03 Aug 2018

OK

MV 1501C



Teamwork Garage Pte Ltd  
 53 Ubi Avenue 1 #01-23/24 Spore 408934  
 Paya Ubi Industrial Park  
 Tel : 6844 2475  
 E-mail : claims@teamworkgarage.com  
 Register number : 201015366H

CHINA TAIPING INSURANCE (SINGAPORE)  
 3 ANSON ROAD  
 SPRINGLEAF TOWER SINGAPORE  
 #16-00 SINGAPORE 079909

Vehicle number	EL101U
Make / Model	MERCEDES/C200
Chassis number	WDD2050422R174154
Accident date	25/7/2018
Reference	1807-28

3RD PARTY CLAIM ESTIMATION

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	BONNET <i>Dented</i>	2020.00 ✓
1	BONNET DAMPER <i>HW</i>	100.00 X
1	FRONT BUMPER <i>broken</i>	1720.00 ✓
1	FRONT BUMPER REINFORCEMENT <i>Wt</i>	415.00 ✓
2	FRONT BUMPER REINFORCEMENT BRACKET <i>o/s wt H/S HW</i>	<del>200.00</del> 400.00 ✓
1	FRONT BUMPER INNER GUIDE <i>broken</i>	70.00 ✓
1	TOW HOOK COVER <i>cut</i>	45.00 ✓
1	FRONT BUMPER LOWER GRILLE <i>mainly crack</i>	280.00 ✓
1	RADIATOR <i>HW</i>	1140.00 X
1	AIRCON CONDENSER <i>HW</i>	960.00 X
1	FRONT RH HEADLAMP MODULE <i>broken</i>	550.00 ✓
1	FRONT RH INTELLIGENT HEADLAMP <i>broken</i>	3150.00 ✓
1	FRONT LH INTELLIGENT HEADLAMP <i>HW</i>	3150.00 X
1	FRONT LH HEADLAMP BALLAST <i>Done</i>	545.00 ✓
1	FRONT GRILLE <i>Crack</i>	650.00 ✓
1	FRONT GRILLE BRABUS LOGO <i>HW</i>	140.00 ✓
4	FRONT SENSOR <i>Done the bracket</i>	295.00 ✓
1	FRONT RH FEDNER <i>Dented</i>	890.00 ✓
1	FRONT RH FENDER INNER SHIELD <i>horn</i>	240.00 ✓
1	FRONT RH SHOCK ABSORBER <i>distorted</i>	749.00 ✓
1	FRONT RH WHEEL BEARING <i>Done</i>	530.00 ✓
1	FRONT RH KNUCKLE ARM <i>distorted</i>	1220.00 ✓
1	FRONT RH LOWER ARM <i>distorted</i>	<del>330.00</del> 600.00 ✓
1	FRONT RH LINKAGE <i>HW</i>	100.00 X
1	FRONT RH ANTI ROLL BAR <i>HW</i>	567.00 X
		20526.00
	Less 10 %	2052.60
	Subtotal	18473.40
	Balance C/F	18473.40

14039.00  
 12635.10

PARTS REPLACEMENT - SPECIAL NETT ITEMS

Balance B/F

18473.40

1	AFTERMKT FRONT BUMPER SPLITTER LOWER LIP <i>broken</i>	1600	<del>2000.00</del>	✓
1	AFTERMKT CARNARDS <i>broken</i>		900.00	✓
1	FRONT AIR VENT CARBON FIBER <i>broken</i>	600.00	<del>1000.00</del>	✓
1	INTERCOOLER <i>HH</i>		2500.00	X
1 SET	FRONT BUMPER CLIP <i>HCC</i>		60.00	✓
1	CARPLATE FRAME <i>HH</i>		80.00	X
1	CAR NUMBER PLATE <i>HH</i>		80.00	X
1	CAR STICKER LINE <i>HCC</i>		250.00	✓
1 SET	FRONT FENDER INNER SHIELD CLIP <i>HCC</i>		80.00	✓
1	RIM <i>cut</i>	1000.00	<del>1800.00</del>	✓
1	TOP UP AIRCON GAS <i>HH</i>		120.00	X
1	TOP UP COOLANT <i>HH</i>	4490.00	90.00	X
1	BRAKE FLUID <i>HH</i>		50.00	X

Subtotal 9010.00

Balance C/F 27483.40

LABOUR AND MISCELLANEOUS CHARGES

Balance B/F

27483.40

1	CHECK FRONT WIRING AND LIGHTNING SYSTEM		150.00	30%/-
2	DIAGNOIS CHECK AND CLEAR FAULT CODE		500.00	150%/-
3	REMOVE AND RENEW FRONT SENSOR		200.00	40%/-
4	CHECK FRONT WHEEL ALIGNMENT		200.00	60%/-
5	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS		300.00	180%/-
6	PANEL BEATING ON AFFECTED AREAS	2500.00	1400.00	1000%/-
7	SPRAY PAINTING ON AFFECTED AREAS		1800.00	1000%/-
8	APPLY ANTI RUST ON AFFECTED AREAS		150.00	40%/-

Subtotal 32183.40

Grand total 32183.40

35422.23

31/07/2018 @ 1800h

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*HH Andrew*  
*2/3mm 6 days*  
*Ryan*  
*LKK Auto*

19605.10  
57pp 1274.49  

---

20899.59  
1/5 16700/-

*Check part prices*



TeamWork Garage Pte Ltd  
 53 Ubi Avenue 1 #01-23/24 Spore 408934  
 Paya Ubi Industrial Park  
 Tel : 6844 2475  
 E-mail : claims@teamworkgarage.com  
 ROC: 201015366H  
 3PT ESTIMATION

CHINA TAIPING INSURANCE

Vehicle number	EL101U
Make / Model	MERCEDES C200
Chassis number	WDD2050422R174154
Accident Date	25-07-18
Reference	1807-28

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT ENGINE UNDER COVER <i>torn</i>	123.50 ✓
1	VOLTAGE CONVERTOR <i>mainly broken</i>	285.00 ✓
1	HEADLAMP CONTROL UNIT <i>Down repeated</i>	570.00 X
1	FRONT BUMPER GRILLE RH <i>deformed</i>	483.00 ✓
1	FRONT BUMPER INNER SPONGE <i>torn</i>	99.60 ✓
1	FRONT NUMBER PLATE GARNISH <i>HL</i>	81.60 X
1	FRONT RH LOWER ARM <i>repeated</i>	330.00 X
1	FRONT BRAKE DISC MOTOR <i>HL</i>	198.00 X
1	FRONT CRASH SENSOR <i>HL</i>	438.00 X
1	FRONT REINFORCEMENT RIGHT SUPPORT <i>for RH</i>	140.00 X
4	FRONT SENSOR <i>Down 2 pc</i>	425.00 850.00 ✓
		3598.70
	Less 10% Subtotal	359.87
		3238.83

1416.10

1274.49

02/08/2018

2 KKK Auto



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INSIGHT ADJUSTERS AND SURVEYORS PL		Ref : CS/IAS18013951/Dtbs2	
133 CECIL STREET #14-02 KECK SENG TOWER SINGAPORE 069535		Date : 13-03-2019	
Code : IAS			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FORKLIFT	Veh. Inspected	EL 101U
Policy No.		Coverage (\$)	0.00
Claim No.	IA2018-37642	Excess (\$)	0.00
Assign From	JASON CHUA	Assign Date	31/07/2018
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ C200	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WDD2050422R174154	Colour	WHITE
Odometer	42901	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/35R19	PIRELLI	5 mm
L/H Front Tyre	235/35R19	PIRELLI	5 mm
R/H Rear Tyre	235/35R19	PIRELLI	5 mm
L/H Rear Tyre	235/35R19	PIRELLI	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	25/07/2018	Inspection Date	31/07/2018
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. EL 101U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BONNET	DENTED	2,020.00	2,020.00
1	BONNET DAMPER	NOT NECESSARY	100.00	-
1	FRONT BUMPER	BROKEN	1,720.00	1,720.00
1	FRONT BUMPER REINFORCEMENT	BENT	415.00	415.00
2	FRONT BUMPER REINFORCEMENT BRACKET	O/S BENT / N/S NOT NECESSARY	400.00	200.00
1	FRONT BUMPER INNER GUIDE	BROKEN	70.00	70.00
1	TOW HOOK COVER	CUT	45.00	45.00
1	FRONT BUMPER LOWER GRILLE	MTG CRACKED	280.00	280.00
1	RADIATOR	NOT NECESSARY	1,140.00	-
1	AIRCON CONDENSER	NOT NECESSARY	960.00	-
1	FRONT RH HEADLAMP MODULE	BROKEN	550.00	550.00
1	FRONT RH INTELLIGENT HEADLAMP	BROKEN	3,150.00	3,150.00
1	FRONT LH INTELLIGENT HEADLAMP	NOT NECESSARY	3,150.00	-
1	FRONT LH HEADLAMP BALLAST	DAMAGED	545.00	545.00
1	FRONT GRILLE	CRACKED	650.00	650.00
1	FRONT GRILLE BRABUS LOGO	NECESSARY	140.00	140.00
4	FRONT SENSOR	BRACKET NECESSARY	295.00	295.00
1	FRONT RH FENDER	DENTED	890.00	890.00
1	FRONT RH FENDER INNER SHIELD	TORN	240.00	240.00
1	FRONT RH SHOCK ABSORBER	DISTORTED	749.00	749.00
1	FRONT RH WHEEL BEARING	DAMAGED	530.00	530.00
1	FRONT RH KNUCKLE ARM	DISTORTED	1,220.00	1,220.00
1	FRONT RH LOWER ARM	DISTORTED	600.00	330.00
1	FRONT RH LINKAGE	NOT NECESSARY	100.00	-
1	FRONT RH ANTI ROLL BAR	NOT NECESSARY	567.00	-
1	FRONT ENGINE UNDER COVER	TORN	123.50	123.50
1	VOLTAGE CONVERTOR	MTG BROKEN	285.00	285.00
1	HEADLAMP CONTROL UNIT	REPEATED	570.00	-
1	FRONT BUMPER GRILLE RH	DEFORMED	483.00	483.00
1	FRONT BUMPER INNER SPONGE	TORN	99.60	99.60
1	FRONT NUMBER PLATE GARNISH	NOT NECESSARY	81.60	-
1	FRONT RH LOWER ARM	REPEATED	330.00	-

Report Ref No. CS/IAS18013951/Dtbs2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BRAKE DISC MOTOR	NOT NECESSARY	198.00	-
1	FRONT CRASH SENSOR	NOT NECESSARY	438.00	-
1	FRONT REINFORCEMENT RIGHT SUPPORT	NOT NECESSARY	140.00	-
4	FRONT SENSOR	DAMAGED 2PCS	850.00	425.00
	LESS 10% DISCOUNT		-2,412.47	-1,545.51
			21,712.23	13,909.59
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	AFTERMKT FRONT BUMPER SPLITTER LOWER LIP (SN)	BROKEN	2,000.00	1,600.00
1	AFTERMKT CANARDS (SN)	BROKEN	900.00	900.00
1	FRONT AIR VENT CARBON FIBER (SN)	BROKEN	1,000.00	600.00
1	INTERCOOLER (SN)	NOT NECESSARY	2,500.00	-
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	60.00	60.00
1	CARPLATE FRAME (SN)	NOT NECESSARY	80.00	-
1	CAR NUMBER PLATE (SN)	NOT NECESSARY	80.00	-
1	CAR STICKER LINE (SN)	NECESSARY	250.00	250.00
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NECESSARY	80.00	80.00
1	RIM (SN)	CUT	1,800.00	1,000.00
1	TOP UP AIRCON GAS (SN)	NOT NECESSARY	120.00	-
1	TOP UP COOLANT (SN)	NOT NECESSARY	90.00	-
1	BRAKE FLUID (SN)	NOT NECESSARY	50.00	-
			9,010.00	4,490.00
	<b><u>LABOUR</u></b>			
	CHECK FRONT WIRING AND LIGHTING SYSTEM.		150.00	30.00
	DIAGNOIS CHECK AND CLEAR FAULT CODE.		500.00	150.00
	REMOVE AND RENEW FRONT SENSOR.		200.00	40.00
	CHECK FRONT WHEEL ALIGNMENT.		200.00	60.00
	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS.		300.00	180.00
	PANEL BEATING ON AFFECTED AREAS.		1,400.00	1,000.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,800.00	1,000.00
	APPLY ANTI RUST ON AFFECTED AREAS.		150.00	40.00
			4,700.00	2,500.00
<b>GRAND TOTAL</b>			<b>35,422.23</b>	<b>20,899.59</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>16,700.00</b>

Report Ref No. CS/IAS18013951/Dtbs2



Report Ref No. CS/IAS18013951/Dtbs2

**ANG BRYAN TANI**

Automotive Assessor / Investigator

**ADRIAN LING WAI PING**

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**