

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5105M

AAD1807-239

*Not Authorized
Lump \$640*

Vehicle No.:	SHC 5105M
Chassis No.:	VF1ABL15AUC276173
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	25.7.2018
Third Party Insurer :	III

	PART		LIST
1	DOOR PANEL REAR RH	\$	R 2,844.66
1	DOOR GUIDE REAR RH	\$	Sm 176.82
1	DOOR HINGE UPPER RH	\$	R 274.50
1	DOOR HINGE LOWER RH	\$	R 300.55
1	DOOR CHECK REAR LH/RH L70Y	\$	Sm 203.06
1	DOOR LOCK REAR RH	\$	R 908.75
1	DOOR HANDLE OUTER REAR RH	\$	Sm 126.49
1	DOOR HANDLE CAP REAR RH	\$	Sm 35.52
1	DOOR HANDLE SEAL REAR RH	\$	Sm 7.89
1	DOOR HANDLE COVER REAR RH	\$	Sm 13.22
1	DOOR HANDLE MODULE REAR RH	\$	Sm 133.60
1	DOOR REGULATOR REAR RH	\$	Sm 1,135.10
1	DOOR REGULATOR MOTOR REAR RH	\$	Sm 893.75
1	DOOR REGULATOR NUT REAR L70Y	\$	Sm 12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	Sm 6.31
1	DOOR FINISHER REAR RH	\$	Sm 423.10
1	DOOR MOULDING REAR RH	\$	Sm 176.82
1	DOOR MOULDING CLIP L70Y	\$	Sm 5.92
1	DOOR MOULDING SCREW L70Y	\$	Sm 6.91
1	DOOR CASING REAR RH	\$	Sm 1,509.06
1	DOOR WATER SHIELD REAR RH	\$	Sm 30.39
1	DOOR CASING CLIP	\$	Sm 12.63
1	DOOR CASING LIGHT L70Y	\$	Sm 48.74
1	DOOR FINISHER INNER REAR RH	\$	Sm 323.44
1	DOOR FINISHER BRACKET INNER REAR RH	\$	R 46.97
1	DOOR FINISHER BRACKET INNER REAR RH	\$	R 20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	R 20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	R 20.33
1	DOOR GRAB HANDLE REAR RH	\$	Sm 210.96

X

Trans-cab Auto Services Pte Ltd

AAD1807-239

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5105M

1	DOOR BLIND REAR RH	\$	Sm 741.80
1	DOOR WHEATHSTRIP REAR RH	\$	~ 410.66
1	DOOR SEAL REAR RH	\$	~ 162.02
1	DOOR GLASS RUNNER SEAL REAR RH	\$	~ 229.31
1	DOOR WAIST SEAL OUTER REAR RH	\$	~ 334.69
1	DOOR WAIST SEAL INNER REAR RH	\$	~ 115.64
1	FENDER PANEL REAR RH	\$	R 3,299.13
1	FENDER PANEL INNER TRIM REAR	\$	Sm 671.45
1	WHEELARCH REAR RH	\$	~ 543.47
1	DOOR MIRROR ASSY RH	\$	~ 1,483.40
1	ROCKER PANEL INNER GARNISH RH	\$	~ 466.51
1	ROCKER PANEL INNER RH	\$	R 1,024.79
1	ROCKER PANEL CENTER RH	\$	R 990.25
1	BUMPER COVER REAR	\$	Sm 1,108.46
1	BUMPER LOWER REAR	\$	na 768.84
1	BUMPER BRACKET CTR REAR	\$	na 113.47
1	BUMEPR BRACKET SIDE RH REAR	\$	na 135.97
1	BUMEPR RETAINER RH REAR	\$	na 44.99

X

	\$	22,573.43
10%	\$	2,257.34
	\$	20,316.08

Special Nett

2	FRAME FULL SUPPORT PANEL NUT	\$	na 20.00
2	FRAME FULL SUPPORT PANEL STUD	\$	~ 30.00
1SET	WHEELARCH CLIP FRT LH	\$	~ 30.50
1	REAR DOOR STICKER '6555-3333'	\$	~ 80.00
1	DOOR CHECK BOLT	\$	~ 22.69
1	DOOR GUIDE SCREW	\$	~ 10.85
1	DOOR HINGE BOLT	\$	~ 10.85
1	DOOR HINGE NUT RH	\$	~ 14.60
1	DOOR CHECK BOLT	\$	~ 22.69
1	DOOR CHECK NUT	\$	~ 3.75
1	DOOR LOCK SCREW L70Y	\$	~ 6.12
1	DOOR CATCH SCREW L70Y	\$	~ 10.06

X

Trans-cab Auto Services Pte Ltd

AAD1807-239

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5105M**TOTAL \$ 262.13****TOTAL PARTS \$ 20,578.21****LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	<i>2001</i>
Putty and spray painting of the affected portion.	\$	4,200.00	<i>4401</i>
To rust-proofing of the affected areas.	\$	<i>na</i> 170.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>↪</i> 380.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>↪</i> 220.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>↪</i> 170.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	<i>↪</i> 170.00	<i>X</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>↪</i> 380.00	<i>X</i>
To transfer of front door fittings, attachment and perform water seepage test.	\$	<i>↪</i> 380.00	<i>X</i>
To dismantle advertisement sticker	\$	<i>↪</i> 170.00	<i>X</i>
Towing Fees.	\$	<i>↪</i> 120.00	<i>X</i>
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<i>↪</i> 380.00	<i>X</i>

Trans-cab Auto Services Pte Ltd

AAD1807-239

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5105M

Labour charge to mount and dismount vehicle on jig
bench, to facilitate repair. \$ *nn* 380.00 *X*

TOTAL \$ 11,620.00

Over All Total \$ 32,198.21

LUMP SUM (REPAIR DAY)

15 DAYS

2 days

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: