

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

31-Jul-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1479 E

1 pc	Rear bumper ✓	\$	811.11
1 pc	Rear bumper o/s side bracket ✕	\$	52.20
1 pc	Rear bumper o/s reflector @ \$107.50 ✕	\$	107.50
1 pc	Rear o/s rim @ \$246.00 ✓	\$	246.00
			\$ 1,216.81
Less 20%			\$ 243.36
			\$ 973.45

S/NETT

1 set	Rear bumper clips ✓	\$	48.00
1 pc	rear o/s fender sticker ✓	\$	60.00

Sundry	\$	50.00 20
To dismantle and refit reverse sensor and test system	\$	80.00 30
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 50
To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the rear o/s fender of the same, etc.	\$	700.00 400
To putty and spray painting on the rear bumper, rear o/s fender,	\$	400.00 360
To apply rustproofing on the repaired and replaced panels	\$	150.00 ✕
Total		\$ 2,641.45

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvi (AKK)
31/7/18 1000h
3 Days
PIP
Before PIP

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: