

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

India International Insurance Pte Ltd

64 Cecil Street

#04-05 IOB Building

Singapore 049711

ATTN: MOTOR CLAIM DEPARTMENT

Tel : 63476100 Fax : 62244174

*Not Authorized
Resony 1-B1
B4 painting*

ACCIDENT REPAIR ON : SFC1122M

MODEL : TOYOTA HARRIER

POLICY NO : ZSU600050151

CHASSIS NO : ZSU600050151

MANUFACTURING YEAR : 2015

DATE / TIME OF ACCIDENT: 30/07/2018 Time: 1440Hrs ALONG PUNGGOL ROAD

THIRD PARTY VEHICLE NO : SHC8682T

Date: 01/07/2018

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
		S\$		S\$
1 Tailgate	1	2200.00	R	2,200.00 X
2 Tailgate Weatherstrip	1	442.00	Sm	442.00 X
3 Rear Bumper	1	1415.00	Bur	1,415.00 ✓
4 Rear Bumper Side Retainer LH	1	85.00	Sm	85.00 X
5 Rear Bumper Side Retainer RH	1	85.00	Sm	85.00 X
6 Rear Bumper Corner Bracket LH	1			-
7 Rear Bumper Corner Bracket RH	1			-
8 Rear Bumper Lower Garnish	1	455.00	Roll out	455.00 ✓
9 Rear Bumper Reflector LH	1	58.00	Sm	58.00 X
10 Rear Bumper Reflector RH	1	58.00	Sm	58.00 X
11 Rear Bumper Sponge	1	125.00		125.00 ?
12 Rear End Panel	1	581.00		581.00 ?
13 Rear Fender LH	1	981.00	R	981.00 X
14 Rear Fender Shield LH	1	107.00	Sm	107.00 X
Sub-Total:				6,592.00
Less Discount 25%				1,648.00
Total Parts:				4,944.00

Special Nett Items

1 Anti-rust coating	3	80.00	Sm	240.00 X
2 Rear Bumper Clips	10	5.50	Sm	55.00 ✓
3 Rear Fender Shield Clips	4	5.90	Sm	23.60 X
4 Rear Bumper Sensor Set	1	250.00		250.00 ?
Total Parts:				318.60

Labour Charges For Rear and Side Portion

1 Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.				1,200.00 ?
2 Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities			4401	1,200.00
3 Provide skill labour to disconnect and check electrical wiring				30.00 15%
4 Remove and refit rear end panel lining and garnish to facilitate repair				100.00 ?
5 Remove and replace bumper sensors				100.00 50%

Total Labour:

Total Parts & Labour:

GST 7%

Grand Total:

2,630.00

7,892.60

552.48

8,445.08

Estimate Repair Duration

8 Days

2-4 days

ACCIDENT VEHICLE OF : SFC1122M

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Survey attended by:

Name : Kenneth
Company : LKK
Date : 8/8/18
Time : 11:30 am
Contact No: 9691 0683
Email : _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: