

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

CHEN BENHUA

Not Notarized
C/Ling & ?
Resurvey After Repair 31-07-2018

5 days

REPAIR ESTIMATE FOR MERCEDES-BENZ - SKC 6677 L

List items			
1 pc. Front bumper	Bu	\$ 1,347.00	✓
2 pcs. Front bumper fog lamp cover	als my cm	170.00	disin lt
2 pcs. Front bumper tow cover	sn	134.00	x
1 set. Front bumper lower side chrome moulding	nu	182.00	✓
1 pc. Front bumper lower grille	cm	105.00	✓
1 pc. Front bumper number plate garnish	cm	149.00	✓
2 pcs. Front bumper side retainer	sn	156.00	x
1 pc. Front bumper inner foam	cm	125.00	✓
1 pc. Front bumper inner reinforcement	bu	758.00	✓
1 pc. Front bumper inner parts	cm	196.00	✓
1 set. Front grille complete	Dis/Pr	862.00	✓
2 pcs. Headlamp	my cm	2,598.00	✓
1 pc. Front bonnet	bu	2,223.10	✓
1 pc. Front bonnet outer rubber seal	sn	28.00	x
1 pc. Front bonnet top lock catch	n	34.00	x
1 pc. Front bonnet lower lock	n	136.00	x
1 pc. Front top panel	n	164.00	x
1 pc. Front top panel top cover	cm	143.00	✓
1 set. Front top panel top cover clips	nu	50.00	✓
1 pc. Front oil cooler	bu	874.00	✓
1 pc. Air con condenser	At/Pr	1,501.00	✓
1 pc. Radiator	sn	1,483.00	x
		13,418.10	
	Less 10%	1,341.81	
		\$ 12,076.29	\$ 12,076.29

Special Nett Items	
1 pc. Front number plate	nu 100.00 SN

Labour		
1. Labour charges for remove/refit, panel beating, cutting/welding and replacement of damages.	900.00	500
2. To putty and spray Spray Paintings charges.	1,000.00	600
3. To check wirings & lightings.	50.00	20
4. To remove, refit Air con condenser, radiator and refill gas.	150.00	100
5. To remove, refit oil cooler.	60.00	30

LKK Auto Consultants hence notify the Repairer of the following:	
• To resurvey before/after spray painting	\$ 14,336.29
• To display damaged part(s) during resurvey	
• Parts prices are subject to confirmation	
• Third party survey is on a "Without Prejudice" basis	
• No illegal modification(s) is allowed	
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	
Acknowledged by Repairer	
Signature:	
Date:	