

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0872/2018/KS
Date	:	31-Jul-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : SKN 4500 T

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Premium Automobiles Ptd Ltd
Address	:	55 Ubi road 1 Singapore 408699
Telephone	:	(HP) +65 68365223
Type of Claim	:	Third Pary Claim
Policy No.	:	100859740
Vehicle No	:	SLZ 6299 L
Model Code	:	Audi A4 SEDAN 2.0
Model / Year	:	May-18
Engine No	:	CVK 058544
Chassis No	:	WAUZZZF45JA144728
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	27-Jul-18
Place of Accident	:	Cheras Higway

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLZ 6299 L.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy and front parking aid.	S/N \$ 480.00	✓
2	To dismantle front bumper and renew radiator grille. Re-organise front crash management components. Reinstall all parts removed.	\$ 900.00	500
3	To respray front bumper.	\$ 800.00	550
TOTAL LABOUR CHARGES - FRONT		: \$ <u>2,180.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLZ 6299 L.

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
1	FRONT BUMPER LOWER CENTER GRILLE <i>new</i>	\$ 171.00	X
2	RADIATOR GRILLE <i>cracked</i>	\$ 1,155.00	✓
3	FRONT PARKING AID SENSOR <i>new</i>	\$ 211.00	✓
4	FRONT PARKING AID SENSOR SEAL	\$ 14.00	✓
5	SUNDRIES	\$ 300.00	✓
6	FRONT NO PLATE <i> Bent</i>	S/N \$ 25.00	✓
TOTAL SPARE PARTS CHARGES - FRONT		: \$ 1,876.00	
TOTAL LABOUR CHARGES - FRONT		: \$ 2,180.00	
GRAND TOTAL - FRONT		: <u>\$ 4,056.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLZ 6299 L.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function.	S/N \$ 360.00	/
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 900.00	500
3	To respray rear bumper.	\$ 800.00	550
4	To carry out diagnostic check.	S/N \$ 384.00	192.
TOTAL LABOUR CHARGES - REAR		: \$ <u>2,444.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLZ 6299 L.

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
1	REAR BUMPER <i>rehand</i>	\$ 1,907.00	✓
2	REAR BUMPER FIXING PARTS	\$ 63.00	✗
3	SECURING PLATE	\$ 56.00	✓
4	SECURING STRIP	\$ 191.00	✗
5	REAR BUMPER SPOILER	\$ 216.00	✗
6	REAR BUMPER REFLECTOR LH / RH	2 \$ 70.00	✗
7	REAR BUMPER CARRIER	\$ 786.00	✗
8	UPPER GUIDE SECTION LH / RH	2 \$ 75.00	✗
9	LOWER GUIDE SECTION LH / RH	2 \$ 38.00	✗
10	REAR PARKING AID SENSOR	\$ 421.00	✗
11	REAR PARKING AID SEAL	\$ 14.00	✗
12	SUNDRIES	\$ 300.00	✗
TOTAL SPARE PARTS - REAR		\$ 4,137.00	
TOTAL LABOUR CHARGES - REAR		\$ 2,444.00	
GRAND TOTAL - REAR		\$ 6,581.00	
GRAND TOTAL - FRONT/REAR		\$ 10,637.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 03/08/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 05 Days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant