

INSURANCE

INS. CASE OWNER:

JUSTIN

CCP / EQ11801

3976, E 163/1

LKK:

IDAC:

Surveyor:

frankth

DOI:

ASSIGNMENT

1/8/18

Date / Time:

1/8/18

Registered in Merimen:

1/8/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

YN 5875P

Name of Insured:

SEARSEA INTERNATIONAL P/L

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

10/7/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

BRUNN BIN MOHO SM

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

UMUPLA17-004654

Policy No.:

Make / Model:

MITSUBISHI

Place of Accident:

THAI IF INTERNATIONAL KOD
SOM VEE RD

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

YN 5875P

GBC 7757P

YP 4295



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

BH Auto
TP



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

6/8/18

LHT

8/8/18

Called OI company, spoken to PIC
Ms Hsu. Confirm accident. She need
to check with OIB total veh involved

10/10/18

email: Confirm 3 veh in

9/11/18

File pass to SHM per find

RECEIVED 08 NOV 2018

STAGE

DATE / PIC

Non-Reporting 1st (1st):

Non-Reporting 1st (2nd):

Non-Reporting 1st (Final):

Notification 1st (if non-pickup):

Call OI:

After call 1st to OI:

Documentation Check List: Handler Typist

Notification 1st (if non-pickup):

After call 1st to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

7/8/18

Sent By:

Poll

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

days) Reduction:

%

Confirm by:

Email

Call

FINAL SETTLEMENT

Date/Time:

9/11/18

Confirm with:

Jacelyn

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. 28 (3cc 01/1457)

If NO or B 28, Ass. Lia: 100%

Repair Cost:

W/hp

SS

4654.50

Loss of Rental (LOR):

SS

days)

Loss of Use (LOU):

SS

900.00

(S 90 x 10

days)

Loss of Income (LOI):

SS

(S x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

2-W

Medical:

SS

Disbursement:

SS

(e.g. Tow/Independent)

Legal Cost

SS

Total:

SS

5556.50

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

5556.50

Name 1:

BH Auto Services Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$400.00

COPY SENT

011/18

and

REF: EQL

ASSIGNMENT

From: Date: 02082018

Estimated Cost:

OD / ☒ P / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GBC 7757P

at Workshop no: BH Auto

of Blk 1 Sin Ming Ind Est #01-115

Insured

Policy No

Claims No

Sum Insured


Excess

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



B/L or Market Value

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repair: 10 days Res: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle IN / OUT

Veh No: GBC 7757P Regn: 10 13

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Dyna 2982

Colour: White A/C Insured / Std / NI / NA

Sp. Reading: 156750 T/Paro: Insured / Std / NI / NA

Eng/No:

C/No: JTRA+354P0K 202617

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orMod: ☒ M / S/Rim / STD A/Rim orTyre Size: F: 195 R15 x 8
R: 155 R 12 x 8 (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 9 mm R/Bal: 77 mm

L/Bal: 9 mm L/Bal: 77 mm

D.O.A: 30/7/18 D.O.I: 2/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

& M

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

3/8 File per to MUTE

18/10 L1 Reg B43501 Carlin

(Rel B 4343.59 / sum)

Date/Time File Per to

☐ : Prel. Report☐ : Final Report

N

Date/Time File Return to

S

Report Format

Lump Sum / L.B.U.S

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Insurance:

1. 3-P %

1. P/B

1. Other

Add Fee: ☐ Site Insp. \$☐ Interview \$☐ Tests/Tools \$☐ Workshop \$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQI18013976/Kpb3

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 01-08-2018



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	YN 5875P	Veh. Inspected	GBC 7757P
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	01/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	30/07/2018	Inspection Date	02/08/2018
Survey held at	BH AUTO SERVICES PTE LTD BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/EQI18013976/Kpb3

Date: 03.08.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

GBC7757P

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 02.08.2018 at the premises of M/s BH Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	8,693.59
Revised Estimate Amount	: S\$	5,473.61
"Check" Items Amount	: S\$	1,138.28
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Front & Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 10 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

EQ Insurance Company Ltd

22 Gemmill Lane

Singapore 069257

Tel: 6223 9433 Fax: 6223 4190

ATTN: MOTOR CLAIM DEPARTMENT

*Not Notified
1/1 Sep 87
Resurvey After Paint*

DEAR SIR / MADAM :

ACCIDENT REPAIR ON: GBC7757P

MODEL : TOYOTA DYNA

POLICY NO : 8-V0010954-MVA-R003

CHASSIS NO : JTFAT35Y90K202617

YEAR OF MANUFACTURE : 2013

DATE / TIME OF ACCIDENT: 30/07/2018 Time: 1105Hrs at INTERNATIONAL ROAD.

THIRD PARTY VEHICLE NO: YN5875P

Date: 01/08/2018

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
		S\$		S\$
1 Front wiper panel moulding	1	358.50	Ad/br	358.50 ✓
2 Front panel assy	1	1,019.30	Ry	1,019.30 ✓
3 Front panel lettering "DYNA"	1	64.40	Re	64.40 ✓
4 Front side panel LH	1	292.20	R	292.20 x
5 Front side panel RH	1	292.20	R	292.20 x
6 Front grille	1	470.50	CM	470.50 ✓
7 Front grille emblem	1	74.60	Re	74.60 ✓
8 Front grille clips	8	4.21	Re	33.68 ✓
9 Headlamp LH	1	620.80	Re	620.80 x
10 Headlamp RH	1	620.80	Re	620.80 x
11 Headlamp protector LH	1	27.20	Re	27.20 x
12 Headlamp protector RH	1	27.20	Re	27.20 x
13 Headlamp bracket LH	1	5.70	Re	5.70 x
14 Headlamp bracket RH	1	5.70	Re	5.70 x
15 Front bumper	1	396.00	Re	396.00 ✓
16 Front bumper bracket LH	1			
17 Front bumper bracket RH	1			
18 Cabin front mounting LH	1			
19 Cabin front mounting RH	1			
20 Rear gate assembly	1	1,267.30	Re	1,267.30 ✓
21 Rear gate lettering "DYNA"	1	27.20	Re	27.20 ✓
22 Rear lamp assy LH	1	242.70	Re	242.70 x
23 Rear lamp assy RH	1	242.70	Re	242.70 x
24 Spare tyre hanger assembly	1	276.10	R	276.10 x

Sub-Total: 6,364.78

Less: 25% discount - 1,591.20

Total Parts after 25% discount: 4,773.59

Special Nett Items

1 Anti-rust coating	2	80.00	60l	160.00
2 Front number plate	1	50.00	Re	50.00 25% Re
3 Sticker "70KM"	1	50.00	Re	50.00 15% Re

4 Company advertisement sticker

1

350.00

20012
350.00

610.00

Total Parts: 5,383.59

Labour Charges For Front & Rear Portion

- 1 Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.
- 2 Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities
- 3 Provide skill labour to disconnect and check electrical wiring
- 4 Provide skill labour to remove and reinstall dashboard and related parts

1100
1,500.00

1000
1,500.00

60.00

250.00 ✓

Total Labour:

3,310.00

Total Parts & Labour:

8,693.59

GST 7%

608.55

Grand Total:

9,302.14

Estimate Repair Duration

12 days

ACCIDENT VEHICLE OF : GBC7757P

Page : 2 of 2

10 days

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: WEN ZHENG

Survey attended by:

Name : Kenneth

Company : LKIC

Date : 2/8/18

Time : 1.45pm

Contact No : 96910663

Email :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

EQ Insurance Company Ltd
22 Gemmill Lane
Singapore 069257
Tel: 6223 9433 Fax: 6223 4190
ATTN: MOTOR CLAIM DEPARTMENT

Not Authorised
11 Sep @ 4350h
Resurvey After Paint

DEAR SIR / MADAM :

ACCIDENT REPAIR ON: GBC7757P
MODEL : TOYOTA DYNA
POLICY NO : 8-V0010954-MVA-R003
CHASSIS NO : JTFAT35Y90K202617
YEAR OF MANUFACTURE : 2013
DATE / TIME OF ACCIDENT: 30/07/2018 Time: 1105Hrs at INTERNATIONAL ROAD.
THIRD PARTY VEHICLE NO: YN5875P

Date: 01/08/2018
Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts		Quantity	Unit Price	Condition	Amount
S/N			SS		SS
1	Front wiper panel moulding	1	358.50		<i>Ad/hw</i> 358.50 ✓
2	Front panel assy	1	1,019.30		<i>Ad</i> 1,019.30 ✓
3	Front panel lettering "DYNA"	1	64.40		<i>Ad</i> 64.40 ✓
4	Front side panel LH	1	292.20		<i>R</i> 292.20 X
5	Front side panel RH	1	292.20		<i>R</i> 292.20 X
6	Front grille	1	470.50		<i>cm</i> 470.50 ✓
7	Front grille emblem	1	74.60		<i>Ad</i> 74.60 ✓
8	Front grille clips	8	4.21		<i>Ad</i> 33.68 ✓
9	Headlamp LH	1	620.80		<i>Ad</i> 620.80 X
10	Headlamp RH	1	620.80		<i>Ad</i> 620.80 X
11	Headlamp protector LH	1	27.20		<i>Ad</i> 27.20 X
12	Headlamp protector RH	1	27.20		<i>Ad</i> 27.20 X
13	Headlamp bracket LH	1	5.70		<i>Ad</i> 5.70 X
14	Headlamp bracket RH	1	5.70		<i>Ad</i> 5.70 X
15	Front bumper	1	396.00		<i>Ad</i> 396.00 ✓
16	Front bumper bracket LH	1			
17	Front bumper bracket RH	1			
18	Cabin front mounting LH	1			
19	Cabin front mounting RH	1			
20	Rear gate assembly	1	1,267.30		<i>Ad</i> 1,267.30 ✓
21	Rear gate lettering "DYNA"	1	27.20		<i>Ad</i> 27.20 ✓
22	Rear lamp assy LH	1	242.70		<i>Ad</i> 242.70 X
23	Rear lamp assy RH	1	242.70		<i>Ad</i> 242.70 X
24	Spare tyre hanger assembly	1	276.10		<i>R</i> 276.10 X
					Sub-Total: 6,364.78
					Less: 25% discount - 1,591.20
					Total Parts after 25% discount: 4,773.59

\$ 3711.48 - 25%
= \$ 2783.61

Special Nett Items

1	Anti-rust coating	2	80.00
2	Front number plate	1	50.00
3	Sticker "70KM"	1	50.00

601
Ad 160.00
Ad 50.00 *25%*
Ad 50.00 *15%*

4 Company advertisement sticker

1

350.00

20012
350.00

\$ 300

610.00

Total Parts: 5,383.59

Labour Charges For Front & Rear Portion

- 1 Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.
- 2 Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities
- 3 Provide skill labour to disconnect and check electrical wiring
- 4 Provide skill labour to remove and reinstall dashboard and related parts

1100
1,500.00

1000
1,500.00

400
60.00

250.00 ✓

Total Labour:

\$ 2390

Total Parts & Labour:

3,310.00

GST 7%

8,693.59

Grand Total:

608.55

9,302.14

Estimate Repair Duration

12 days

ACCIDENT VEHICLE OF : GBC7757P

Page : 2 of 2

10 days

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: WEN ZHENG

Survey attended by:

Name :

Kenneth

Company :

CKIC

Date :

21/8/18

Time :

1.45pm

Contact No :

96910663

Email :

Part: \$ 3711.48 - 25% = 2783.61

S/N: \$ 300.00

Labour: \$ 2390.00

Total: \$ 5473.61 - 20%

= \$ 4378.88

4350

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 0682G

Vehicle Details

Vehicle No.: GBC7757P

Vehicle to be Exported: No

Intended De-registration Date: 31 Jul 2018

Vehicle Make: TOYOTA

Vehicle Model: DYNA 150 MANUAL

Primary Colour: White

Manufacturing Year: 2013

Engine No.: 1KD2337532

Chassis No.: JTFAT35Y90K202617

Maximum Power Output: -

Open Market Value: \$24,970.00

Original Registration Date: 31 Oct 2013

First Registration Date: 31 Oct 2013

Transfer Count: 0

Actual ARF Paid: \$1,249.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Oct 2023

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$76,001.00

COE Rebate Amount: \$39,880.00

Total Rebate Amount: \$39,880.00

The information contained herein is correct as at 31 Jul 2018

OK



FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad | Advertiser Login | Ways of Selling

New 5 Years Coe Renewal Toyota Estima 2.4A

 \$5800 Downpayment Monthly From \$938 Onwards. Lowest 3.68%PA @ GV Cars Financing

Star Ad

HIN LUNG AUTO
Ho Bee Group

One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars

30 years of car sale

Browse by Category [Save Search](#) [Print](#) Sort by Date Posted 20 results/page

4 vehicles **Search** toyota dyna 150 [Advanced Search](#) [Search](#) [View All](#)

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection toyota dyna 150 Any Any 2013 Any Any Any Available



☐ Toyota Dyna 150 \$45,800 \$9,070 /yr 19-Aug-2013 2,982 cc - Truck Available

Fuel Type: Diesel

Price Slashed Worth Buy In Market As You Can't Find This Type Of 2 Sliding Doors Box In SG With Fully Catering Standard Fixed In! Driven By Careful Lady Yet Maintain Like Brand New Condition, New Pam...

Victory Automotives Pte Ltd

Posted: 20-Jun-2018 Tags: 2013 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota



☐ Toyota Dyna 150 \$44,800 \$8,960 /yr 31-Jul-2013 2,982 cc - Truck Available

Fuel Type: Diesel

High Trade In, High Loan With Lowest Interest Rate In Town. Call Our Friendly Salesperson Now To Ask For Test Drive Before It's Gone.

OK2 Pte Ltd

Posted: 30-Jun-2018 Tags: 2013 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota



☐ Toyota Dyna 150 \$36,000 \$8,030 /yr 24-Jan-2013 2,982 cc - Truck Available

Fuel Type: Diesel

New Paintwork! Most Reliable Commercial Vehicle In Market! Excellent Engine And Perfect Gearbox! Problem-Free Vehicle And Can Definitely Serve Your Company Well! Viewing At Toh Guan, Do Call To Arrang...

Posted: 19-Jun-2018 Tags: 2013 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota



☐ Toyota Dyna 150 \$40,000 \$8,460 /yr 23-Apr-2013 2,982 cc - Truck Available

Fuel Type: Diesel

Most Reliable Commercial Vehicle. Only 1 Owner, Full Canopy For Security And Plentiful Storage Space, Well Maintained, Fuel Economical.

Posted: 18-Jun-2018 Tags: 2013 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

[Save Search](#)

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classified for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, in CDE cars & OPC cars. You can also hire from a car website. Look up car loans, low mileage cars, car finance, carpark rates & car insurance. Find how used toyota dyna 150, toyota dyna 150 Singapore, used toyota dyna 150 Singapore, used toyota dyna 150, used vehicles Singapore or even buy used toyota dyna 150 Singapore. We have links to dealers comprising parallel importers, authorized car dealers, and used car dealers in our site. Find how car price fall, how car lease and how car promotions. Visit our partner sites for job openings for Singapore jobs, real estate agencies for sale, travel, car performance parts, car discounts, laptop discounts, commercial vehicle leasing & CDE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and users on sgCarMart that are believed to be reliable, but the insurance can be given that this information is accurate, complete or correct. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com



[About Us](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.

Compare



Catherine Chong (LKK Auto)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Wednesday, 1 August, 2018 9:30 AM
To: Justin Wong
Cc: Catherine Chong (LKK Auto); 'Team A (admin-a@lkkauto.com)'
Subject: RE: pre repair inspection (OUR VEHICLE - GBC7757P / YOUR VEHICLE - YN5875P)
Attachments: SAS2448200.pdf; SKM_C224e18073118510_0001.jpg

Justin

For your necessary action.
Thank you.

Regards,

Janet Tan
Senior Executive | Claims

*01082018 @ 1020am
Jacelyn veh not in.*



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: BHAS - Jacelyn Loh [mailto:jacelyn.loh@bhauto.com.sg]
Sent: Tuesday, July 31, 2018 6:50 PM
To: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>; 'Team A (admin-a@lkkauto.com)' <admin-a@lkkauto.com>; Elaine Cheong <elaine.cheong@eqinsurance.com.sg>; Janet Tan <janet.tan@eqinsurance.com.sg>
Cc: BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>; BHAS - Anthony Lau <anthony.lau@bhauto.com.sg>; BHAS - Bernard Kee <bernard.kee@bhauto.com.sg>
Subject: pre repair inspection (OUR VEHICLE - GBC7757P / YOUR VEHICLE - YN5875P)

To: the officer in charge

Dear sir, mdm,

I would like to arrange surveyor on of the above mentioned accident vehicle.

Ps- vehicle currently not in our workshop.

Appreciate awaiting for your favourable reply asap. Please kindly assist.

Greatly appreciate it. Thank you and have a nice day.

Thank You & Best Regards,

Jacelyn Loh

 **BH AUTO SERVICES PTE LTD**

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singapore: 575636

(T) +65-6559 8944 / 8940 (F) +65-6515 3144 / +65-6269 2404

Email: jacelyn.loh@bhauto.com.sg

Website: <http://www.bhauto.com.sg>

Shu Pei (LKKAuto)

From: Justin Wong <justin.wong@eqinsurance.com.sg>
Sent: Friday, 3 August 2018 3:26 PM
To: Shu Pei (LKKAuto)
Subject: RE: pre repair inspection (OUR VEHICLE - GBC7757P / YOUR VEHICLE - YN5875P)
Attachments: OI GIA - YN5875P.PDF

Dear Shu Pei,

Please find our insured's GIA report and process with D/S.

Regards,
Justin Wong
Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: Friday, August 3, 2018 11:30 AM
To: Justin Wong <justin.wong@eqinsurance.com.sg>
Subject: FW: pre repair inspection (OUR VEHICLE - GBC7757P / YOUR VEHICLE - YN5875P)

WITHOUT PREJUDICE

Dear Justin

We refer to the above matter.

This is a TP direct settlement case.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Wednesday, 1 August 2018 10:22 AM

To: 'Janet Tan' <janet.tan@eqinsurance.com.sg>; 'Justin Wong' <justin.wong@eqinsurance.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; assignments <assignments@lkkauto.com>

Subject: RE: pre repair inspection (OUR VEHICLE - GBC7757P / YOUR VEHICLE - YN5875P)

Dear Janet,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janet Tan [<mailto:janet.tan@eqinsurance.com.sg>]

Sent: Wednesday, 1 August, 2018 9:30 AM

To: Justin Wong <justin.wong@eqinsurance.com.sg>

Cc: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>; 'Team A (admin-a@lkkauto.com)' <admin-a@lkkauto.com>

Subject: RE: pre repair inspection (OUR VEHICLE - GBC7757P / YOUR VEHICLE - YN5875P)

Justin

For your necessary action.

Thank you.

Regards,

Janet Tan

Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190

www.eqinsurance.com.sg

A Member of CityState

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: BHAS - Jacelyn Loh [<mailto:jacelyn.loh@bhauto.com.sg>]

Sent: Tuesday, July 31, 2018 6:50 PM

To: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>; 'Team A (admin-a@lkkauto.com)' <admin-a@lkkauto.com>; Elaine Cheong <elaine.cheong@eqinsurance.com.sg>; Janet Tan <janet.tan@eqinsurance.com.sg>

Cc: BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>; BHAS - Anthony Lau <anthony.lau@bhauto.com.sg>; BHAS - Bernard Kee <bernard.kee@bhauto.com.sg>

Subject: pre repair inspection (OUR VEHICLE - GBC7757P / YOUR VEHICLE - YN5875P)

To: the officer in charge

Dear sir, mdm,

I would like to arrange surveyor on of the above mentioned accident vehicle.

Ps- vehicle currently not in our workshop.

Appreciate awaiting for your favourable reply asap. Please kindly assist.

Greatly appreciate it. Thank you and have a nice day.

Thank You & Best Regards,

Jacelyn Loh

 **BH AUTO SERVICES PTE LTD**

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singapore: 575636

(T) +65-6559 8944 / 8940 (F) +65-6515 3144 / +65-6269 2404

Email: jacelyn.loh@bhauto.com.sg

Website: <http://www.bhauto.com.sg>

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Thursday, 8 November 2018 12:33 PM
To: 'BHAS - Jacelyn Loh'
Cc: BHAS - Moo Wen Zheng; BHAS - Bernard Kee; BHAS - Ngai Kar Kit; Admin A; Vic (LKKAuto)
Subject: RE: Your Ref: GBC 7757P *Our Ref: CC4/EQ18013976/Kpb3 [ACCIDENT INVOLVING YN 5875P(EQ) / GBC 7757P/ ON 30/07/2018]

Without Prejudice

Hi,

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 4,654.50
2. Loss of Use (10days x \$90.00)	\$ 900.00
3. LTA/ GIA search fee	\$ 2.00
TOTAL	<u>\$ 5,556.50</u>

Please confirm acceptance.

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: BHAS - Jacelyn Loh <jacelyn.loh@bhauto.com.sg>
Sent: Wednesday, 31 October 2018 10:55 AM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>
Cc: BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>; BHAS - Bernard Kee <bernard.kee@bhauto.com.sg>; BHAS - Ngai Kar Kit <karkit.ngai@bhauto.com.sg>
Subject: RE: Your Ref: GBC 7757P *Our Ref: CC4/EQ18013976/Kpb3 [ACCIDENT INVOLVING YN 5875P(EQ) / GBC 7757P/ ON 30/07/2018]

Dear Sir / Madam,

Hsiao Tong (LKKAUTO)

From: BHAS - Jacelyn Loh <jacelyn.loh@bhauto.com.sg>
Sent: Thursday, 8 November 2018 2:45 PM
To: Hsiao Tong (LKKAUTO)
Cc: BHAS - Moo Wen Zheng; BHAS - Bernard Kee; BHAS - Ngai Kar Kit; Admin A; Vic (LKKAUTO)
Subject: RE: Your Ref: GBC 7757P *Our Ref: CC4/EQI18013976/Kpb3 [ACCIDENT INVOLVING YN 5875P(EQ) / GBC 7757P/ ON 30/07/2018]

Dear all,

Thank you for your offer, we shall accept below offer **\$ 5,556.50**

Kindly assist to forward us with your Discharge voucher.

Thank You & Best Regards,

Jacelyn Loh

 **BH AUTO SERVICES PTE LTD**

Address: Blk 1, Sector C, Sin Ming Industrial Estate

#01-111/113/115/117 Singapre:575636

(T) +65-6559 8944 /8940 (F) +65-6515 3144 / +65-6269 2404

Email: jacelyn.loh@bhauto.com.sg

Website: <http://www.bhauto.com.sg>

From: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Sent: Thursday, 8 November 2018 12:33 PM
To: BHAS - Jacelyn Loh <jacelyn.loh@bhauto.com.sg>
Cc: BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>; BHAS - Bernard Kee <bernard.kee@bhauto.com.sg>; BHAS - Ngai Kar Kit <karkit.ngai@bhauto.com.sg>; Admin A <admin-a@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>
Subject: RE: Your Ref: GBC 7757P *Our Ref: CC4/EQI18013976/Kpb3 [ACCIDENT INVOLVING YN 5875P(EQ) / GBC 7757P/ ON 30/07/2018]

Without Prejudice

Hi,

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 4,654.50
2. Loss of Use (10days x \$90.00)	\$ 900.00
3. LTA/ GIA search fee	\$ 2.00
TOTAL	\$ 5,556.50

Please confirm acceptance.

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

BH AUTO SERVICES PTE LTD

BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636

Tel: 6559 8944 Fax: 6269 2404

CO. REG. NO. 200917512K

GST REG NO. 200917512K

PLEASE QUOTE OUR FILE REFERENCE WHEN REPLYING

Your Reference: YN5875P

Our Reference: GBC7757P

Date: 31/10/2018

M/s EQ Insurance Company Limited
5 Maxwell Road
#17-00 Tower Block
MND Complex Singapore 069110

BY POST & EMAIL

Attention: Claims Department

CLAIMANT: BENG MUI MARINE ELECTRICAL PTE LTD

PROPERTY DAMAGED CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 30/07/2018 ALONG INTERNATIONAL RD INVOLVING VEHICLE NO GBC7757P & YN5875P.

We act for **BENG MUI MARINE ELECTRICAL PTE LTD** who was the owner of motor vehicle no. **GBC7757P**.

We are instructed by the above named to claim damages against you/your insured in connection with a road traffic accident on 30/07/2018 involving our client's vehicle registration number GBC7757P and vehicle registration number YN5875P, driven by you/your insured at the material time.

We are instructed that the accident was caused by you/your insured's negligent driving and /or management of your/you insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

1	Cost of Repair (Included 7% GST)	\$ 4654.50
2	Loss of Use (\$150.00 x 10days)	\$ 1500.00
3	LTA Search Fee	\$ 2.00
	Total :	\$ 6156.50

We enclose a copy of each of the following documents for your consideration:-

- (a) GIA/ Police report lodged by driver of;
- (b) Final Repair Bill
- (c) Rental Invoice / Loss Of Use
- (d) LTA Search Fee Invoice
- (e) Letter Of Authorization

Kindly revert to our client's claim within the next 7 days.

Yours faithfully,

Jacelyn Loh
(O): 6559 8944 (F): 6269 2404
Email: Jacelyn.loh@bhauto.com.sg





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/EQI18013976/Kpb3

10 AUG 2018

SEA2SEA INTERNATIONAL PTE LTD

17D TUAS ROAD

SINGAPORE 637817

ATTN: THE MANAGEMENT

Dear Sir/Madam,

ACCIDENT INVOLVING YN 5875P/ GBC 7757P/ OTHERS ON 30/07/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, EQ Insurance Company Ltd to deal with the third party claim against your policy.

We have received a claim from GBC 7757P against your insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal EQ INSURANCE COMPANY LIMITED.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG

Case Handler

DID: 6742 3197

FAX: 6741 4108

EMAIL: chewht@lkkauto.com

c.c. *EQ INSURANCE COMPANY LIMITED*
(Motor Claims Dept)

AUTHORISATION**Name of owner of m/vehicle: BENG HUI MARINE ELECTRICAL PTE LTD****Address: NIL****NRIC / ROC No: 199900682G****RE: ACCIDENT ON: 30/07/2018 & INTERNATIONAL RD****INVOLVING: GBC7757P & YN5875P**

In consideration of **BH AUTO SERVICES PTE LTD** ("the Workshop") repairing my/our vehicle no. **GBC7757P** at my/our request, I/We the abovenamed owner of motor vehicle no. **GBC7757P** hereby authorise the Workshop to demand claim, negotiate, settle my/our claim for cost of repairs loss of use and all other expenses and damages arising out of the above accident.

I/We further authorise the Workshop to appoint solicitors to demand, claim, negotiate, settle and/or commence legal proceedings in my/our name for the above purpose and at the sole discretion of the Workshop. All sums recovered therefrom shall belong to the Workshop absolutely and I/We further authorise the Workshop to give absolute discharge on my/our behalf and to sign all discharge vouchers and other documents in relation to the same on my/our behalf. I/We further agree to fully co-operate with the solicitors appointed by the Workshop on my/our behalf and attend all Court hearings that are necessary to prosecute the claims maintained by the Workshop.

I/We agree that in the event that the claim is rejected for whatsoever reason or the Workshop decides not to proceed with legal proceedings or for whatsoever reason the Workshop is unable to recover all of the repair costs or are only able to recover a portion of the same I/we hereby undertake to pay them the full repair costs and or any portion thereof that cannot be recovered and all expenses including legal costs that they may have incurred in pursuing the claim within 7 days from the date of the written notice for payment by them to my/our last known address.

I/We hereby declare that I/we will always remain and be liable to the Workshop for the cost of repair to my/our motor vehicle and expenses incurred on my/our behalf. In the event that Workshop has to issue any notice or commence legal proceedings against me/us to enforce this undertaking against me/us, I/we shall be liable for the Workshop's expenses and legal cost(including solicitor and client cost) on an indemnity basis.

I/We further authorise the Workshop to give to the other party/parties absolute discharge in respect of any liability and any sum, whether agreed or not made the Workshop or to the law firm appointed by the Workshop towards full settlement of my/our claim it shall be regarded as full and final discharge of the claim.

I/We further authorise the Workshop to settle the above mentioned claim in a manner that they deem fit and the Workshop is further authorised to receive payment further to settlement of my claim with payment cheque/s being made in favour of the Workshop.

Date this 30 (day) of 07 (month) 2018(year)

NAME: BENG HUI MARINE ELECTRICAL PTE LTD**PHONE: 94563760**

BH AUTO SERVICES PTE LTD

BLK 1 SIN MING INDUSTRIAL ESTATE
SECTOR C #01-115 SINGAPORE 575636

Tel: 6743 3494

Fax: 6269 2404

CO. REG. NO. 201006106C

GST REG NO. 201006106C

TAX INVOICE

Final Repair Bill

Our Ref: GBC7757P

Date: 31/10/2018

M/s EQ Insurance Company Limited
5 Maxwell Road
#17-00 Tower Block
MND Complex Singapore 069110

BY POST & EMAIL

Vehicle No : GBC7757P
Make/ Model : TOYOTA DYNA
Year of Manufacture : 2013
Chassis No. : JTFAT35Y90K202617
Colour : WHITE
D.O.A : 30/07/2018

QTY	ITEM/PARTICULARS	AMOUNT (S\$)
-----	------------------	--------------

1. Repair Cost for Motor Vehicle No. **GBC7757P**
Type of repair: LUMP SUM :S\$ 4350.00

GST @ 7% : S\$ 304.50

GRAND TOTAL :S\$ 4654.50

**Total : Singapore Dollars Four Thousand Six Hundred and Fifty - Four Dollars
Fifty Cents Only.**

Company's Stamp & Signature



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-117395

Date of Request: 31/07/2018

Your Ref No: Online Purchase

BH Auto Services Pte Ltd
Blk 1 Sin Ming Industrial Estate Sector C
#01/111/113/115/117
Singapore 575636

Dear Sir/Madam,

Enquiry Date 31/07/2018
Enquiry By Jacelyn Loh Cai Ling
TP Vehicle No. YN5875P
Accident Date 30/07/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
YN5875P	EQ Insurance Company Ltd	28/08/2017-27/08/2018	6223 9433

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

Hsiao Tong (LKKAUTO)

From: gaojie <gao.jie@sea2sea.com.sg>
Sent: Friday, 10 August 2018 10:01 AM
To: Hsiao Tong (LKKAUTO)
Subject: RE: ACCIDENT INVOLVING YN 5875P(EQ) / GBC 7757P/ ON 30/07/2018
Attachments: GIA REPORT - YN5875P.PDF; Police report.pdf; 0c023062-3055-494d-b8fe-9086aa154405.jpg; 1f1e8b8b-d31b-4d01-b525-e3b3bde5460f.jpg; 2c766924-e1df-4b00-98d1-30d67d16394a.jpg; 32f72bc8-d054-4bf2-b14b-64f693906ef7.jpg; 174d210c-e4f1-4cc9-bbfb-65ff7f41a2dd.jpg; c2a787df-39e1-4519-80e8-a4c58d96d348.jpg; dac00bcf-4661-461d-9b2b-7a1ab53b4d5e.jpg; e981cde9-e56a-4a08-adc0-5652a0d90dc8.jpg

Dear Chew:

We have check with our driver Mr Zailan. He said that it is a total 3 vehicles involved accident, we have report to EQ insurance on date 31th July 18. Please find GIA report , police report & some photos for your reference, thank you

Have a nice day.

Thank you.

Best Regards
Gao Jie (Ms)
HR & Admin Executive



Sea2Sea International Pte Ltd
17D, Tuas Road, Singapore 637817
Tel : 6299 1377 (Ext. 101) Fax : 6294 8156
Website : www.sea2sea.com.sg

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Wednesday, 8 August, 2018 2:29 PM
To: gao.jie@sea2sea.com.sg
Subject: ACCIDENT INVOLVING YN 5875P(EQ) / GBC 7757P/ ON 30/07/2018

Your Ref: **YN 5875P**
Our Ref: CC4/EQ118013976/Kpb3

M/s SEA2SEA International Pte Ltd

Dear Ms Gao,

ACCIDENT INVOLVING YN 5875P(EQ) / GBC 7757P/ ON 30/07/2018

We refer to the above accident where we are acting for EQ Insurance Company Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from GBC 7757P against your insurance policy.

Based on the accident report of GBC 7757P, it is a total 3 vehicles chain collision. However our driver, Mr Zailan reported that only 2 vehicles involved in the accident. Kindly assist to confirm with Mr Zailan total vehicles involved in the accident.

Your full co-operation in the handling of the claim is required and kindly submit the following **if not provided at EQ's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

We look forward your early reply.

Please call us if you have any queries.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 20/11/2018

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	YN 5875P (Insd Veh)	Your Ref. No. : DMCPHQ17-004654
	GBC 7757P (TP Veh)	Our Ref. No. : CC4/EQ118013976/Kpb3q2
Date of Accident	30/7/2018	

Liability	100%	
Final Repair Cost	: \$ 4,654.50	
Loss of Use	: \$ 900.00	10 days
Rental (If any)	: \$	days
Others:	: \$ 2.00	
	: \$	
	5,556.50	
Final Settlement Sum	: \$ 5,556.50	
Remarks	:	

Payment Instruction: Payee's Breakdown		
1)	BH AUTO SERVICES PTE LTD	: \$ 5,556.50
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC4/EQ18013976/Kpb3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 20-11-2018	
		Code : EQ1	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)			
	Insured Veh. YN 5875P	Veh. Inspected	GBC 7757P
	Policy No. DMCPHQ17-004654	Coverage (\$)	0.00
	Claim No.	Excess (\$)	0.00
	Assign From JUSTIN	Assign Date	01/08/2018
2. Vehicle Particulars & Condition			
	Make & Model TOYOTA DYNA	c.c	2982
	Engine No. HIDDEN	Year of Reg.	2013
	Chassis No. JTFAT35Y90K202617	Colour	WHITE
	Odometer 156750	Steering	IN ORDER
	Brakes IN ORDER	Modification	NIL
	General GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
	R/H Front Tyre 195 R15X8	YOKOHAMA	9 mm
	L/H Front Tyre 195 R15X8	YOKOHAMA	9 mm
	R/H Rear Tyre 155 R12X8 (D)	YOKOHAMA	7/7 mm
	L/H Rear Tyre 155 R12X8 (D)	YOKOHAMA	7/7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
	Accident Date 30/07/2018	Inspection Date	02/08/2018
	Survey held at BH AUTO SERVICES PTE LTD BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 7757P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT WIPER PANEL MOULDING	DENTED / CUT	358.50	358.50
1	FRONT PANEL ASSY	BENT	1,019.30	1,019.30
1	FRONT PANEL LETTERING 'DYNA'	NECESSARY	64.40	64.40
1	FRONT SIDE PANEL LH	TO REPAIR SEE LABOUR	292.20	-
1	FRONT SIDE PANEL RH	TO REPAIR SEE LABOUR	292.20	-
1	FRONT GRILLE	CRACKED	470.50	470.50
1	FRONT GRILLE EMBLEM	NECESSARY	74.60	74.60
8	FRONT GRILLE CLIPS @\$4.21	NECESSARY	33.68	33.68
1	HEADLAMP LH	SERVICEABLE	620.80	-
1	HEADLAMP RH	SERVICEABLE	620.80	-
1	HEADLAMP PROTECTOR LH	SERVICEABLE	27.20	-
1	HEADLAMP PROTECTOR RH	SERVICEABLE	27.20	-
1	HEADLAMP BRACKET LH	SERVICEABLE	5.70	-
1	HEADLAMP BRACKET RH	SERVICEABLE	5.70	-
1	FRONT BUMPER	BENT	396.00	396.00
1	FRONT BUMPER BRACKET LH (NPA)	NOT NECESSARY	-	-
1	FRONT BUMPER BRACKET RH (NPA)	NOT NECESSARY	-	-
1	CABIN FRONT MOULDING LH (NPA)	NOT NECESSARY	-	-
1	CABIN FRONT MOULDING RH (NPA)	NOT NECESSARY	-	-
1	REAR GATE ASSEMBLY	BENT	1,267.30	1,267.30
1	REAR GATE LETTERING 'DYNA'	NECESSARY	27.20	27.20
1	REAR LAMP ASSY LH	SERVICEABLE	242.70	-
1	REAR LAMP ASSY RH	SERVICEABLE	242.70	-
1	SPARE TYRE HANGER ASSEMBLY	TO REPAIR SEE LABOUR	276.10	-
	LESS 25% DISCOUNT		-1,591.20	-927.87
			4,773.58	2,783.61
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	BENT	50.00	25.00

Report Ref No. CC4/EQ18013976/Kpb3q2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	STICKER '70KM' (SN)	NECESSARY	50.00	15.00
1	COMPANY ADVERTISEMENT STICKER (SN)	NECESSARY	350.00	200.00
			450.00	240.00
	LABOUR			
	ANTI-RUST COATING.		160.00	60.00
	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS ,PANEL BEAT ,CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS,INCLUSIVE OF THE REPAIR OF FRONT SIDE PANEL LH ,FRONT SIDE PANEL RH AND SPARE TYRE HANGER ASSEMBLY .		1,500.00	1,100.00
	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITATES.		1,500.00	1,000.00
	PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING.		60.00	40.00
	PROVIDE SKILL LABOUR TO REMOVE AND REINSTALL DASHBOARD AND RELATED PARTS.		250.00	250.00
			3,470.00	2,450.00
GRAND TOTAL			8,693.58	5,473.61
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,350.00

Report Ref No. CC4/EQ118013976/Kpb3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.