

ASS. REC. BY:

REF: CS/FCI 18013986/Ktd3n2

Special Instruction:

Surveyor:

aws

Kenneth

ASSIGNMENT (Office)

From (Person):

Mary chua

of

FCI

Date/Time:

1/8/18 @ 2:30pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB 7840R

Insured:

SHC 2890Z

at Workshop in/

Trans-cab

Tel:

6287 6666

of

No. 2 AMK 84-63

Policy No:

Claim No:

D18005811 MFST

Sum Insured:

Excess:

Make of Veh:

D.O.A. 27/07/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

2:32pm @ 1/8/18

Person Contacted:

Ghien Yee

Vehicle

IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

SHB 7840R - CC3 / AIG / 2019776 / Gpb3w2

DOA: 14/03/2011

SHC 2890Z - CS/FCI / 702/656 / Agbn2

DOA: 9/11/2017

ASS. REC. BY:

REF:

1021

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

Trans Cob

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHB 7840R

Yr Regn:

10, 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Chevrolet Epica

c.c.

1.991

Colour:

White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

742945

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KL1LA6RTBB 103409

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F: Giti

185/65R13

Ling R: Long

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

8

mm

L/Bal.

6

mm

L/Bal.

8

mm

D.O.A.

27/7/18

D.O.I.

6/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

7/8

File pass to Catherine

1/18 8/18501 (Red. 18967.43; 91%)

RECEIVED 20 AUG 2018

Date/Time, File Pass to?



: Prell. Report

1) 2018 Typist



: Final Report

Date/Time, File Return to?

Days Of Repair:

2

Resurvey No. of Trip:

-

10x15=150

Survey Fee:

170+150

Transportation:

50

S - RS - SI

Fixtures

14

Others

TOTAL

384

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

18501



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |                |                           |                                                                                     |
|-------------------------------------------------------------------|----------------|---------------------------|-------------------------------------------------------------------------------------|
| FIRST CAPITAL INSURANCE LTD                                       |                | Ref : CS/FCI18013986/Ktd3 |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877             |                | Date : 01-08-2018         |  |
|                                                                   |                | Code : FCI2               |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                 |                |                           |                                                                                     |
| Insured Veh.                                                      | SHC 2890Z      | Veh. Inspected            | SHB 7840R                                                                           |
| Policy No.                                                        |                | Coverage (\$)             | 0.00                                                                                |
| Claim No.                                                         | D18005811MFSH  | Excess (\$)               | 0.00                                                                                |
| Assign From                                                       | CWS (MAY CHUA) | Assign Date               | 01/08/2018                                                                          |
| <b>2. Vehicle Particulars &amp; Condition</b>                     |                |                           |                                                                                     |
| Make & Model                                                      | c.c            |                           |                                                                                     |
| Engine No.                                                        | Year of Reg.   |                           |                                                                                     |
| Chassis No.                                                       | Colour         |                           |                                                                                     |
| Odometer                                                          | Steering       |                           |                                                                                     |
| Brakes                                                            | Modification   |                           |                                                                                     |
| General                                                           |                |                           |                                                                                     |
| <b>3. Conditions of Tyres</b>                                     |                |                           |                                                                                     |
|                                                                   | Size           | Make                      | Balance                                                                             |
| R/H Front Tyre                                                    |                |                           | mm                                                                                  |
| L/H Front Tyre                                                    |                |                           | mm                                                                                  |
| R/H Rear Tyre                                                     |                |                           | mm                                                                                  |
| L/H Rear Tyre                                                     |                |                           | mm                                                                                  |
| <b>4. Description of Damages</b>                                  |                |                           |                                                                                     |
|                                                                   |                |                           |                                                                                     |
| <b>5. General Information</b>                                     |                |                           |                                                                                     |
| Accident Date                                                     | 27/07/2018     | Inspection Date           |                                                                                     |
| Survey held at                                                    |                |                           |                                                                                     |
| <b>5a. Remarks</b>                                                |                |                           |                                                                                     |
|                                                                   |                |                           |                                                                                     |



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005811MFSH

Date: 15/8/2018

Our Ref: CS/FCI18013986/Ktd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHB 7840R

Please be informed that we had conducted the inspection of the abovementioned vehicle  
6/8/2018 at the premises of M/s Trans - Cab and have the following to report: -

|                          |                         |
|--------------------------|-------------------------|
| Workshop Estimate Amount | : S\$ <u>20,817.43</u>  |
| Revised Estimate Amount  | : S\$ <u>1,850.00</u>   |
| "Check" Items Amount     | : S\$ <u>0.00</u>       |
| LTA Reimbursement Value  | : S\$ <u>          </u> |
| Nett Value               | : S\$ <u>          </u> |

Description of Damage:

The vehicle sustained damages at the rear portion.



**Comments/ Present Status:**

Damages Consistent.

Yours faithfully

Kenneth

Automotive Assessor

**MOTOR SURVEY ASSIGNMENT**

|                    |                                                             |                               |
|--------------------|-------------------------------------------------------------|-------------------------------|
| Date               | 01-08-2018                                                  | Our Ref No. D18005811MFSH     |
| Accident Date      | 27-07-2018                                                  | Claim Type. Third Party       |
| Insured Vehicle    | SHC2890Z                                                    | Third Party Vehicle. SHB7840R |
| Survey Location    | NO. 2 ANG MO KIO STREET 63                                  |                               |
| Contact Person.    | GHIEEN YEE LOONG                                            |                               |
| Contact No.        | 62876666/ 0                                                 | Fax No. 62571330              |
| Survey Type        | WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED: |                               |
| Appointed Surveyor | LKK AUTO CONSULTANTS PTE LTD                                |                               |
| Contact Person     | NA                                                          | Fax No. 68416315              |
| Contact Number.    | NA                                                          |                               |

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

|                   |                                 |                         |
|-------------------|---------------------------------|-------------------------|
| Cc : Workshop     | TRANS-CAB AUTO SERVICES PTE LTD | Attention. NIL          |
| Cc : TP Solicitor | NA                              | TP Solicitor Fax No. NA |
| Officer Incharge  | MAY CHUA                        |                         |

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242915)



PRI Documents



Close



## PRI Header Details

|                   |                                                                      |                                   |                                                                                                                     |                      |              |
|-------------------|----------------------------------------------------------------------|-----------------------------------|---------------------------------------------------------------------------------------------------------------------|----------------------|--------------|
| Claim No          | D18005811MFSH                                                        | Policy No                         | D-18088936MFSH                                                                                                      | Claimant S.No & Name | 1 & TRANS-C/ |
| Workshop Name     | TRANS-CAB AUTO SERVICES PTE LTD<br>(Contact Person : GHIE YEE LOONG) | Survey Location & Contact Details | NO. 2 ANG MO KIO STREET 63<br>Mobile: 0 , Phone: 62876666 , Fax: 62571330<br>EmailId: GHIEYEE.LOONG@TRANSCAB.COM.SG |                      |              |
| Our Surveyor      | LKK AUTO CONSULTANTS PTE LTD                                         | Instructions To Surveyor          | WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM                                                                       |                      |              |
| Insured Name      | COMFORT TRANSPORTATION PTE LTD                                       | Insured Vehicle No                | SHC2890Z                                                                                                            | TP Vehicle No        | SHB7840R     |
| PRI Recieved Date | 01-08-2018 04:11:05 PM                                               | Surveyor Appointed Date           | 01-08-2018 02:29:45 PM                                                                                              | Surveyor Accept Date |              |

## Survey Report Upload

|                             |  |                      |            |                         |                                            |
|-----------------------------|--|----------------------|------------|-------------------------|--------------------------------------------|
| Surveyor Inspection Date *: |  | Surveyor Report Date | 01-08-2018 | Upload Survey Report *: | <input type="button" value="Choose File"/> |
|-----------------------------|--|----------------------|------------|-------------------------|--------------------------------------------|

## Vehicle Particulars

|           |                      |                |                       |         |                      |
|-----------|----------------------|----------------|-----------------------|---------|----------------------|
| Make      | Please Select Make ▾ | Model          | Please Select Model ▾ | Year    | Select Year ▾        |
| Chasis No | <input type="text"/> | Engine No      | <input type="text"/>  | Mileage | <input type="text"/> |
| Color     | <input type="text"/> | Cubic Capacity | <input type="text"/>  |         |                      |

## Multiple Documents Upload

|                                                          |        |
|----------------------------------------------------------|--------|
| <input type="button" value="Upload Multiple Documents"/> |        |
| File Name                                                | Action |

## Surveyor Job Remarks

|         |                      |                                     |
|---------|----------------------|-------------------------------------|
| Remarks | <input type="text"/> | <input type="button" value="Save"/> |
|---------|----------------------|-------------------------------------|

## Denise Tay (LKKAUTO)

---

**From:** Denise Tay (LKKAUTO)  
**Sent:** Wednesday, 15 August 2018 12:07 PM  
**To:** Admin-D (LKKAUTO); 'Claim Workflow System'; assignments  
**Cc:** MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18005811MFSH/1  
**Attachments:** PRELI ADVISED SHB 7840R.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHB 7840R**

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Wednesday, 1 August 2018 3:02 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18005811MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Wednesday, 1 August 2018 2:30 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [MAYCHUA@MSFIRSTCAPITAL.COM.SG](mailto:MAYCHUA@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18005811MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,  
Admin Team  
Claim Workflow System  
Motor Claims Department

7/30/2018

PARF/COE Rebate Enquiry

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

|                |         |
|----------------|---------|
| Owner ID Type: | Company |
| Owner ID:      | 3878K   |

**Vehicle Details**

|                                |                                        |
|--------------------------------|----------------------------------------|
| Vehicle No.:                   | SHB7840R                               |
| Vehicle to be Exported:        | Yes                                    |
| Intended De-registration Date: | 30 Jul 2018                            |
| Vehicle Make:                  | CHEVROLET                              |
| Vehicle Model:                 | EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO |
| Primary Colour:                | Red                                    |
| Manufacturing Year:            | 2011                                   |
| Engine No.:                    | Z20S1456241K                           |
| Chassis No.:                   | KL1LA69RJBB103409                      |
| Maximum Power Output:          | 110.0 kW (147 bhp)                     |
| Open Market Value:             | \$13,981.00                            |
| Original Registration Date:    | 31 Oct 2012                            |
| First Registration Date:       | 31 Oct 2012                            |
| Transfer Count:                | 0                                      |
| Actual ARF Paid:               | \$13,981.00                            |

**Intended PARF Rebate Details**

|                               |             |
|-------------------------------|-------------|
| PARF Eligibility:             | Yes         |
| PARF Eligibility Expiry Date: | 30 Oct 2020 |
| PARF Rebate Amount:           | \$9,786.00  |

**Intended COE Rebate Details**

|                             |                          |
|-----------------------------|--------------------------|
| COE Expiry Date:            | 30 Oct 2020              |
| COE Category:               | A - Car (1600cc & below) |
| COE Period(Years):          | 8                        |
| PQP Paid:                   | \$53,263.00              |
| COE Rebate Amount:          | \$14,980.00              |
| <b>Total Rebate Amount:</b> | <b>\$24,766.00</b>       |

**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 30 Jul 2018

OK



**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 7840R****AAD1807-259***Not Authored  
L/Sing 8/8501*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

**SHB 7840R** ✓

KL1LA69RJBB103409

CHEVROLET

EPICA 2.0

27.7.2018

**FCIL****PART****LIST**

|    |   |                                     |    |                         |
|----|---|-------------------------------------|----|-------------------------|
| 1  | 1 | Rear Bumper                         | \$ | <i>Br/nd</i> 1,202.00 — |
| 2  | 1 | Rear Bumper Beam                    | \$ | <i>R</i> 239.94 X       |
| 3  | 1 | Rear Bumper Centre Absorber         | \$ | <i>Sm</i> 260.00 X      |
| 4  | 1 | Rear Bumper Side Retainer RH        | \$ | <i>Dir</i> 68.76 ✓      |
| 5  | 1 | Rear Bumper Side Retainer LH        | \$ | <i>Sm</i> 68.76         |
| 6  | 1 | Rear Bumper Reflectors RH           | \$ | <i>Sm</i> 119.74        |
| 7  | 1 | Rear Bumper Reflectors LH           | \$ | <i>Sm</i> 119.74        |
| 8  | 1 | Rear Bumper Tow Hook Cover          | \$ | <i>Sm</i> 93.00         |
| 9  | 1 | Rear End Panel Outer                | \$ | <i>R</i> 623.76         |
| 10 | 1 | Rear End Panel Inner Trim           | \$ | <i>Sm</i> 263.84        |
| 11 | 1 | Rear Luggage Floor Panel            | \$ | <i>R</i> 973.00 X       |
| 12 | 1 | Rear Luggage Floor Panel Insulator  | \$ | <i>Sm</i> 63.50         |
| 13 | 1 | Rear Luggage Floor Panel Trim Board | \$ | <i>Sm</i> 378.00        |
| 14 | 1 | Bootlid                             | \$ | <i>R</i> 973.00         |
| 15 | 1 | Bootlid inner trim board            | \$ | <i>Sm</i> 400.00        |
| 16 | 1 | Bootlid Weatherstrip                | \$ | <i>Sm</i> 344.28        |
| 17 | 1 | Bootlid Lock - Top                  | \$ | <i>R</i> 466.56         |
| 18 | 1 | Bootlid 'CHEVROLET' Badge           | \$ | <i>R</i> 120.62 —       |
| 19 | 1 | Bootlid Logo                        | \$ | <i>R</i> 138.84 —       |
| 20 | 1 | Bootlid 'EPICA LT' Badge            | \$ | <i>R</i> 119.84 —       |
| 21 | 1 | Bootlid Reflector Centre            | \$ | <i>Sm</i> 217.97        |
| 22 | 1 | Bootlid Reflector RH                | \$ | <i>Sm</i> 128.40        |
| 23 | 1 | Bootlid Reflector LH                | \$ | <i>Sm</i> 128.40        |
| 24 | 1 | Rear Tail Lamp RH                   | \$ | <i>Sm</i> 479.30 X      |
| 25 | 1 | Rear Tail Lamp LH                   | \$ | <i>Sm</i> 479.30        |
| 26 | 1 | Rear Exhaust Box (Muffler A-EXH,RR) | \$ | <i>R</i> 1,110.00       |
| 27 | 1 | Rear Fender RH                      | \$ | <i>R</i> 1,145.00       |
| 28 | 1 | Rear Fender Inner Trim RH           | \$ | <i>Sm</i> 418.44        |
| 29 | 1 | Rear Fender LH                      | \$ | <i>R</i> 1,145.00       |

**Trans-cab Auto Services Pte Ltd**

AAD1807-259

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7840R

|    |   |                           |    |                           |
|----|---|---------------------------|----|---------------------------|
| 30 | 1 | Rear Fender Inner Trim LH | \$ | <i>sn</i> 418.44 <i>X</i> |
|----|---|---------------------------|----|---------------------------|

|              |           |                  |
|--------------|-----------|------------------|
| <b>TOTAL</b> | <b>\$</b> | <b>12,707.43</b> |
| <b>10%</b>   | <b>\$</b> | <b>1,270.74</b>  |
|              | <b>\$</b> | <b>11,436.69</b> |

**Specical Nett**

|    |      |                                   |    |                           |
|----|------|-----------------------------------|----|---------------------------|
| 1  | 1Set | Bootlid inner trim board Clip     | \$ | <i>nn</i> 40.00 <i>X</i>  |
| 2  | 1Set | Rear Bumper Parking Sensor        | \$ | <i>sn</i> 300.00 <i>X</i> |
| 3  | 1Set | Rear Bumper Fastener Clip         | \$ | <i>nn</i> 44.00 ✓         |
| 4  | 1Set | Rear Fender Inner Trim Clip LH    | \$ | <i>nn</i> 30.00           |
| 5  | 1Set | Rear Bumper End Dust Cover Clip   | \$ | <i>nn</i> 30.00           |
| 6  | 1    | Rear Exhaust Mounting             | \$ | <i>sn</i> 300.00          |
| 7  | 2    | Rear Windscreen Sealant           | \$ | <i>nn</i> 80.00           |
| 8  | 1    | Rear Windscreen Inner Sponge Seal | \$ | <i>nn</i> 100.00          |
| 9  | 1    | Spare Tyre                        | \$ | <i>sn</i> 180.00          |
| 10 | 1    | Spare Wheel Rim                   | \$ | <i>sn</i> 126.74          |

|              |           |                 |
|--------------|-----------|-----------------|
| <b>TOTAL</b> | <b>\$</b> | <b>1,230.74</b> |
|--------------|-----------|-----------------|

|                    |           |                  |
|--------------------|-----------|------------------|
| <b>TOTAL PARTS</b> | <b>\$</b> | <b>12,667.43</b> |
|--------------------|-----------|------------------|

Panel Beating, Knocking And Straightening The  
Necessary Portion, Remove And Renewal Of  
Parts, Adjust And Realign The Same

|    |          |             |
|----|----------|-------------|
| \$ | 3,500.00 | <i>300l</i> |
|----|----------|-------------|

To Check Electrical Lighting Concerned.

|    |        |            |
|----|--------|------------|
| \$ | 170.00 | <i>10l</i> |
|----|--------|------------|

To Rust-Proofing Of The Affected Areas.

|    |                  |          |
|----|------------------|----------|
| \$ | <i>nn</i> 170.00 | <i>X</i> |
|----|------------------|----------|

Putty And Spray Painting Of The Affected  
Portion.

|    |          |             |
|----|----------|-------------|
| \$ | 3,200.00 | <i>400l</i> |
|----|----------|-------------|

To reinstall rear bumper parking sensor.

|    |        |            |
|----|--------|------------|
| \$ | 170.00 | <i>60l</i> |
|----|--------|------------|

**Trans-cab Auto Services Pte Ltd****AAD1807-259**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 7840R**To transfer of end panel fittings and conduct  
water seepage test.\$ *na* 170.00 XTo transfer of boot fittings and conduct water  
seepage test.\$ *na* 170.00 XTo remove and refit interior fittings, trimings,  
garnish, fittings and other, to enable repair.\$ *na* 380.00 XTo check steering geometry and computer  
wheel alignment\$ *na* 220.00 X

---

\$ **8,150.00**

---

**TOTAL \$ 20,817.43**

---

**Repair Days (LUMP SUM)***10 Days**2 days***LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                      |                                                                              |                       |                             |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|-----------------------|-----------------------------|-------------------------------------------------------------------------------------|
| FIRST CAPITAL INSURANCE LTD                                                                                                                                                            |                                                                              |                       | Ref : CS/FCI18013986/Ktd3n2 |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                                                                  |                                                                              |                       | Date : 27-08-2018           |  |
|                                                                                                                                                                                        |                                                                              |                       | Code : FCI2                 |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                                                                      |                                                                              |                       |                             |                                                                                     |
| Insured Veh.                                                                                                                                                                           | SHC 2890Z                                                                    | Veh. Inspected        | SHB 7840R                   |                                                                                     |
| Policy No.                                                                                                                                                                             | D-18088936MFSH                                                               | Coverage (\$)         | 0.00                        |                                                                                     |
| Claim No.                                                                                                                                                                              | D18005811MFSH                                                                | Excess (\$)           | 0.00                        |                                                                                     |
| Assign From                                                                                                                                                                            | MAY CHUA                                                                     | Assign Date           | 01/08/2018                  |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                          |                                                                              |                       |                             |                                                                                     |
| Make & Model                                                                                                                                                                           | CHEVROLET EPICA (A)                                                          | c.c                   | 1991                        |                                                                                     |
| Engine No.                                                                                                                                                                             | HIDDEN                                                                       | Year of Reg.          | 2012                        |                                                                                     |
| Chassis No.                                                                                                                                                                            | KL1LA69RJBB103409                                                            | Colour                | WHITE / RED                 |                                                                                     |
| Odometer                                                                                                                                                                               | 742945                                                                       | Steering              | IN ORDER                    |                                                                                     |
| Brakes                                                                                                                                                                                 | IN ORDER                                                                     | Modification          | NIL                         |                                                                                     |
| General                                                                                                                                                                                | GOOD                                                                         |                       |                             |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                                                                          |                                                                              |                       |                             |                                                                                     |
|                                                                                                                                                                                        | Size                                                                         | Make                  | Balance                     |                                                                                     |
| R/H Front Tyre                                                                                                                                                                         | 195/65 R15                                                                   | GITI                  | 6 mm                        |                                                                                     |
| L/H Front Tyre                                                                                                                                                                         | 195/65 R15                                                                   | GITI                  | 6 mm                        |                                                                                     |
| R/H Rear Tyre                                                                                                                                                                          | 195/65 R15                                                                   | LING LONG             | 8 mm                        |                                                                                     |
| L/H Rear Tyre                                                                                                                                                                          | 195/65 R15                                                                   | LING LONG             | 8 mm                        |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                                                                       |                                                                              |                       |                             |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.                                                                                                             |                                                                              |                       |                             |                                                                                     |
| <b>5. General Information</b>                                                                                                                                                          |                                                                              |                       |                             |                                                                                     |
| Accident Date                                                                                                                                                                          | 27/07/2018                                                                   | Inspection Date       | 06/08/2018                  |                                                                                     |
| Survey held at                                                                                                                                                                         | TRANS-CAB AUTO SERVICES PTE LTD<br>NO.2 ANG MO KIO ST 63<br>SINGAPORE 569111 |                       |                             |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                                                                     |                                                                              |                       |                             |                                                                                     |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                              |                       |                             |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                                                                     |                                                                              |                       |                             |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                    |                                                                              | <b>2 Working Days</b> |                             |                                                                                     |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 7840R

| Qty | Description of Parts                | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-------------------------------------|----------------------|---------------------------|-------------------|
|     | <b>REPLACEMENT OF PARTS</b>         |                      |                           |                   |
| 1   | REAR BUMPER                         | BUCKLED / DENTED     | 1,202.00                  | 1,202.00          |
| 1   | REAR BUMPER BEAM                    | TO REPAIR SEE LABOUR | 239.94                    | -                 |
| 1   | REAR BUMPER CENTRE ABSORBER         | SERVICEABLE          | 260.00                    | -                 |
| 1   | REAR BUMPER SIDE RETAINER RH        | DISTORTED            | 68.76                     | 68.76             |
| 1   | REAR BUMPER SIDE RETAINER LH        | SERVICEABLE          | 68.76                     | -                 |
| 1   | REAR BUMPER REFLECTORS RH           | SERVICEABLE          | 119.74                    | -                 |
| 1   | REAR BUMPER REFLECTORS LH           | SERVICEABLE          | 119.74                    | -                 |
| 1   | REAR BUMPER TOW HOOK COVER          | SERVICEABLE          | 93.00                     | -                 |
| 1   | REAR END PANEL OUTER                | TO REPAIR SEE LABOUR | 623.76                    | -                 |
| 1   | REAR END PANEL INNER TRIM           | SERVICEABLE          | 263.84                    | -                 |
| 1   | REAR LUGGAGE FLOOR PANEL            | TO REPAIR SEE LABOUR | 973.00                    | -                 |
| 1   | REAR LUGGAGE FLOOR PANEL INSULATOR  | SERVICEABLE          | 63.50                     | -                 |
| 1   | REAR LUGGAGE FLOOR PANEL TRIM BOARD | SERVICEABLE          | 378.00                    | -                 |
| 1   | BOOTLID                             | TO REPAIR SEE LABOUR | 973.00                    | -                 |
| 1   | BOOTLID INNER TRIM BOARD            | SERVICEABLE          | 400.00                    | -                 |
| 1   | BOOTLID WEATHERSTRIP                | SERVICEABLE          | 344.28                    | -                 |
| 1   | BOOTLID LOCK-TOP                    | TO REPAIR SEE LABOUR | 466.56                    | -                 |
| 1   | BOOTLID "CHEVROLET" BADGE           | NECESSARY            | 120.62                    | 120.62            |
| 1   | BOOTLID LOGO                        | NECESSARY            | 138.84                    | 138.84            |
| 1   | BOOTLID "EPICA LT" BADGE            | NECESSARY            | 119.84                    | 119.84            |
| 1   | BOOTLID REFLECTOR CENTRE            | SERVICEABLE          | 217.97                    | -                 |
| 1   | BOOTLID REFLECTOR RH                | SERVICEABLE          | 128.40                    | -                 |
| 1   | BOOTLID REFLECTOR LH                | SERVICEABLE          | 128.40                    | -                 |
| 1   | REAR TAIL LAMP RH                   | SERVICEABLE          | 479.30                    | -                 |
| 1   | REAR TAIL LAMP LH                   | SERVICEABLE          | 479.30                    | -                 |
| 1   | REAR EXHAUST BOX (MUFFLER A-EXH,RR) | TO REPAIR SEE LABOUR | 1,110.00                  | -                 |

Report Ref No. CS/FCI18013986/Ktd3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts                                                                                                                                                                                                                                                                                             | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|---------------------------|-------------------|
| 1   | REAR FENDER RH                                                                                                                                                                                                                                                                                                   | TO REPAIR SEE LABOUR | 1,145.00                  | -                 |
| 1   | REAR FENDER INNER TRIM RH                                                                                                                                                                                                                                                                                        | SERVICEABLE          | 418.44                    | -                 |
| 1   | REAR FENDER LH                                                                                                                                                                                                                                                                                                   | TO REPAIR SEE LABOUR | 1,145.00                  | -                 |
| 1   | REAR FENDER INNER TRIM LH                                                                                                                                                                                                                                                                                        | SERVICEABLE          | 418.44                    | -                 |
|     | LESS 10% DISCOUNT                                                                                                                                                                                                                                                                                                |                      | -1,270.74                 | -165.01           |
|     |                                                                                                                                                                                                                                                                                                                  |                      | 11,436.69                 | 1,485.05          |
|     | <b>SPECIAL NETT ITEMS</b>                                                                                                                                                                                                                                                                                        |                      |                           |                   |
| 1   | SET BOOTLID INNER TRIM BOARD CLIP (SN)                                                                                                                                                                                                                                                                           | NOT NECESSARY        | 40.00                     | -                 |
| 1   | SET REAR BUMPER PARKING SENSOR (SN)                                                                                                                                                                                                                                                                              | SERVICEABLE          | 300.00                    | -                 |
| 1   | SET REAR BUMPER FASTENER CLIP (SN)                                                                                                                                                                                                                                                                               | NECESSARY            | 44.00                     | 44.00             |
| 1   | SET REAR FENDER INNER TRIM CLIP LH (SN)                                                                                                                                                                                                                                                                          | NOT NECESSARY        | 30.00                     | -                 |
| 1   | SET REAR BUMPER END DUST COVER CLIP (SN)                                                                                                                                                                                                                                                                         | NOT NECESSARY        | 30.00                     | -                 |
| 1   | REAR EXHAUST MOUNTING (SN)                                                                                                                                                                                                                                                                                       | SERVICEABLE          | 300.00                    | -                 |
| 2   | REAR WINDSCREEN SEALANT (SN)                                                                                                                                                                                                                                                                                     | NOT NECESSARY        | 80.00                     | -                 |
| 1   | REAR WINDSCREEN INNER SPONGE SEAL (SN)                                                                                                                                                                                                                                                                           | NOT NECESSARY        | 100.00                    | -                 |
| 1   | SPARE TYRE (SN)                                                                                                                                                                                                                                                                                                  | SERVICEABLE          | 180.00                    | -                 |
| 1   | SPARE WHEEL RIM (SN)                                                                                                                                                                                                                                                                                             | SERVICEABLE          | 126.74                    | -                 |
|     |                                                                                                                                                                                                                                                                                                                  |                      | 1,230.74                  | 44.00             |
|     | <b>LABOUR</b>                                                                                                                                                                                                                                                                                                    |                      |                           |                   |
|     | PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF REAR BUMPER BEAM,REAR END PANEL OUTER,REAR LUGGAGE FLOOR PANEL,BOOTLID,BOOTLID LOCK-TOP,REAR EXHAUST BOX (MUFFLER A-EXH,RR),REAR FENDER RH AND REAR FENDER LH. |                      | 3,500.00                  | 300.00            |
|     | TO CHECK ELECTRICAL LIGHTING CONCERNED.                                                                                                                                                                                                                                                                          |                      | 170.00                    | 10.00             |
|     | TO RUST-PROOFING OF THE AFFECTED AREAS.                                                                                                                                                                                                                                                                          | NOT NECESSARY        | 170.00                    | -                 |
|     | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.                                                                                                                                                                                                                                                                |                      | 3,200.00                  | 400.00            |
|     | TO REINSTALL REAR BUMPER PARKING SENSOR.                                                                                                                                                                                                                                                                         |                      | 170.00                    | 60.00             |
|     | TO TRANSFER OF END PANEL FITTINGS AND CONDUCT WATER SEEPAGE TEST.                                                                                                                                                                                                                                                | NOT NECESSARY        | 170.00                    | -                 |

Report Ref No. CS/FCI18013986/Ktd3n2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty | Description of Parts                                                                            | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
|     | TO TRANSFER OF BOOT FITTINGS AND CONDUCT WATER SEEPAGE TEST.                                    | NOT NECESSARY | 170.00                    | -                 |
|     | TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR. | NOT NECESSARY | 380.00                    | -                 |
|     | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.                                        | NOT NECESSARY | 220.00                    | -                 |
|     |                                                                                                 |               | 8,150.00                  | 770.00            |
|     | GRAND TOTAL                                                                                     |               | 20,817.43                 | 2,299.05          |
|     | RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)                            |               |                           | 1,850.00          |

Report Ref No. CS/FCI18013986/Ktd3n2

**KONG SENG CHEONG**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.