

INSURANCE

INS. CASE OWNER:

CC 4/111801 3987, N y63

LKK:
IDAC:

Surveyor:

NRZ

DOE:

ASSIGNMENT

Date / Time:

1/8/18

Registered in Merimen:

1/8/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHD 65310

Name of Insured:

LPZ

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

20/3/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: TMM MH 181

Driver Tel No.:

(V/LAYE / NO)

Claim No.:

MCT18011878

Policy No.:

M0000015

Make / Model:

MUNIMORI

Place of Accident:

WIDEFOKO RD

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

54 31456



INSRS:

WSP:

Tel:

Liability:

RMKS:

world
Auto



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

6/8/18
jon

54 31456-X SHD65310-X

10 CHANGING LANE

FOR MANDATE. LOD IN

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call Of:

After call ltr to OI:

NA

Documentation Check List: Handler Typist

Notification ltr (if non-pickup):

X

After call ltr to OI:

X

Authorisation To Act:

X

Release Voucher:

X

Final Repair Bill:

X

Car Rental Invoice:

X

Towing Invoice:

X

LTA / GIA:

X

Medical Bill:

X

PIR:

X

Mandate/Reject Instruction:

X

LOD:

X

Payment Breakdown Form:

X

Post-Repair Photos:

X

Others:

X

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email:

Call:

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email:

Call:

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

11

Repair Cost:

GST

SS

5,963.11

Loss of Rental (LOR):

SS

300

(\$ 66 x 5 days)

Loss of Use (LOU):

SS

300

(\$ 66 x 5 days)

Loss of Income (LOI):

SS

—

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search:

SS

—

Medical:

SS

—

Disbursement:

SS

—

(e.g. Tow/ Independent)

Legal Cost:

SS

—

Total:

SS

6,263.11

Global Sum SS:

6,250

FINAL PAYMENT

Date/Time:

Confirm with:

Email:

Call:

Payee 1:

SS

6,250.00

Name 1:

WORLD AUTO PRE LTD

Payee 2: (Strike if N.A.)

SS

X

Name 2:

X

Payee 3: (Strike if N.A.)

SS

X

Name 3:

X

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL			Ref : CC4/III18013987/jb3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Date : 01-08-2018	
			Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6531D		Veh. Inspected	SLT 3945G
Policy No.			Coverage (\$)	0.00
Claim No.			Excess (\$)	0.00
Assign From			Assign Date	01/08/2018
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
Accident Date	30/07/2018		Inspection Date	
Survey held at	WORLD AUTO PTE LTD 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG SINGAPORE 577200			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department
 Contact : 6223 8122

Estimate : ES000263

Date : 01/08/2018
 Vehicle Num. : SLT 3946G(LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# : JTDKB3F450356242
 Accident Date : 30/07/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|--------------|------|--------------------------------------|--|--|
| LIST ITEMS : | | | | |
| 1. | 1 | REAR BUMPER | | |
| 2. | 1 | REAR BUMPER RETAINER | | |
| 3. | 1 | REAR FENDER RH | | |
| 4. | 1 | SIDE SKIRT RH | | |
| 5. | 1 | REAR DOOR - RH | | |
| 6. | 1/RH | REAR DOOR WEATHERSTRIP | | |
| 7. | 1 | REAR DOOR POWER WINDOW REGULATOR RH | | |
| 8. | 1 | FRONT DOOR - RH | | |
| 9. | 1 | FRONT DOOR WEATHERSTRIP | | |
| 10. | 1/RH | FRONT DOOR INNER TRIM BOARD | | |
| 11. | 1 | FRONT DOOR POWER WINDOW REGULATOR RH | | |
| 12. | 1 | FRONT DOOR LOCK RH | | |

List Total S\$:
 25.00% Discount S\$:

- | | | | | |
|----------------------|-----------|------------------|--|--|
| SPECIAL NETT ITEMS : | | | | |
| 1. | 1 | REAR BUMPER CLIP | | |
| 2. | REAR RRH | WHEEL CAP | | |
| 3. | REAR R RH | TYRE | | |
| 4. | 1 | SIDE SKIRT CLIPS | | |

Special Nett Total S\$:

LABOUR :
 TRANSFER DOOR MECHANISM (X2 DOORS)

550.00	X2	
120.00	XSVL	
950.00	X2	DT
550.00	X2	CRK
1,450.00	X2	DT
310.00	XSVL	
380.00	X2	DT
1,450.00	X2	DT
310.00	XSVL	
730.00	X2	DT
380.00	X2	DT
350.00	X2	DT
4,100		
7,530.00		
1,882.50		
3,075		
5,647.50		
40.00	X2	NN
188.00	X2	NN
210.00	X2	NN
40.00	X2	NN
228		
478.00		
380.00		120

CONTINUE / ...

WORLD AUTO PTE LTD

47 .Jalan Pemimpin #01-02/03
 Haicyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department
 Contact : 6223 8122

Estimate : ES000263

Date : 01/08/2018
 Vehicle Num. : SLT 3945G(LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 30/07/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	REAR BUMPER	550.00	XR
2.	1	REAR BUMPER RETAINER	120.00	X SVC
3.	1	REAR FENDER RH	950.00	DT
4.	1	SIDE SKIRT RH	550.00	DT
5.	1	REAR DOOR - RH	1,450.00	DT
6.	1/RH	REAR DOOR WEATHERSTRIP	310.00	X SVC
7.	1	REAR DOOR POWER WINDOW REGULATOR RH	380.00	?
8.	1	FRONT DOOR - RH	1,450.00	DT
9.	1	FRONT DOOR WEATHERSTRIP	310.00	X SVC
10.	1/RH	FRONT DOOR INNER TRIM BOARD	730.00	DT
11.	1	FRONT DOOR POWER WINDOW REGULATOR RH	380.00	?
12.	1	FRONT DOOR LOCK RH	350.00	?
List TotalS\$:			7,530.00	
25.00% Discount S\$:			1,882.50	
			5,647.50	

SPECIAL NETT ITEMS :				
1.	1	REAR BUMPER CLIP	40.00	?
2.	REAR RRH	WHEEL CAP	188.00	SCR
3.	REAR R RH	TYRE	210.00	X N N
4.	1	SIDE SKIRT CLIPS	40.00	?
Special Nett Total S\$:			478.00	
LABOUR :				
TRANSFER DOOR MECHANISM (X2 DOORS)			360.00	120

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department
 Contact : 6223 8122

Estimate : ES000263

Date : 01/08/2018
 Vehicle Num. : SLT 3945G(LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 30/07/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

REMOVE REAR UPHOLSTERY IN ORDER TO FACILITATE REPAIRS
 AND REFIT BACK SAME

280.00 150

LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO
 REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN
 PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.

1,500.00 1000

PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/ OUTER)

1,400.00 1000

3,540.00

Labour Total S\$:

Repairer to be notify
 of the following:
 * To survey & estimate painting
 * To be signed & dated during resurvey
 * To be signed & dated for confirmation
 * The survey is to be "Without Prejudice" basis
 * No modification(s) is allowed
 * Surveys must be resurveyed and
 approved from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

NA2 LKX

6/8/18 1200

PIP

5 DAYS

BEFORE PAINT PHOTO

E. & O.E.**Total S\$: 9,665.50**

=====

for WORLD AUTO PTE LTD

Print Received Message

This mail is associated with :

***SLT3945G (MCT18070898)**
[SHD6531D]

TP

LCRF PTE LTD

Jul 30 2018 5:00PM

[COMFORT TRANSPORTATION PTE LTD]

World Auto Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 05/03/2019 15:47 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$6263.11) - SLT3945G - Claim Handler: Zuhaidah Bte Samsuri

Approved:6263.11.



WORLD AUTO PTE LTD

47 JALAN PEMIMPIN #01-02/03

HALCYON 2

SINGAPORE 577200

07/01/2019

Your Ref :

Our Ref : TP/2154/2018

LKF

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL ST #04/ #05 IOB BLDG

SINGAPORE 049711

Attn : Motor Claim Dept – Third Party

Dear Sirs,

ACCIDENT INVOLVING VEH.NO. SLT3945G / SHD6531D ON 30/07/2018

Reference is made to the aforesaid matter (on behalf of our client M/S LCRF)

Enclosed herewith are the following documents for your information and necessary actions only :-

a) Our Final Repair Bill

Please assist in our claims of :

Final Bill	\$ 5573.00 (already finalised)
GST 7%	\$ 390.11
Loss of Use (\$60 x 5 days)	\$ 300.00
Amount	<u>\$ 6263.11</u>

Kindly let us have your reply and payment as soon as possible.

Thank you for your kind attention and much appreciated assistance.

Yours faithfully,

LETTER OF AUTHORISATION

In the matter of the following accident:-

DATE OF ACCIDENT : 30/07/2018

CLIENT'S VEHICLE NO : SLT3945G

PLACE OF ACCIDENT : BIDEFORD ROAD

THIRD PARTY VEHICLE NO : SHD6531D

I/We, LCRF PTE LTD

ADDRESS: 29 PAYA LEBAR ROAD, PAYA LEBAR OFFICE CENTRE

UEN/NRIC/FIN NO : 201624597K

Tel. (O) _____ (H) _____ (MOBILE) _____

I/We hereby authorize and appoint World Auto Pte Ltd to act for me/us in respect of the above matter up to the final conclusion of the said matter.

I/We hereby authorize and appoint World Auto Pte Ltd to act for me/us for the purpose of negotiating and enter into settlement with the tortfeasor, their insurers or solicitors appointed by the tortfeasor/insurers without the need to commence action.

I/We hereby authorize World Auto Pte Ltd to receive on my/our behalf all settlement sums and disbursements including loss of use/rental to pay to yourselves all costs you may at any time receive in connection with the above mention matter.

DATED THIS 31ST DAY OF JULY YEAR 2018.



Name: LCRF PTE LTD

UEN No: 201624597K

Wk - Joy here

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MCT18070898
Claimant Ref: SLT 3945G

We/I, WORLD AUTO PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 6,250.00 (GLOBAL SUM) (repair cost), S\$ - (loss of use/rental), S\$ - (search fee), vehicle no SLT 3945G that was damaged pursuant to the accident which occurred on 30.07.2018 (date) at BIDEFORD ROAD (location) involving vehicle no SHD 6531D (insured vehicle). This is pursuant to the inspection conducted on 06/08/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner LCRF PTE LTD ("the third party claimant") of vehicle no SLT 3945G to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLT 3945G (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 6,250.00 to WORLD AUTO PTE LTD

Dated this 13 day of March 20 19

CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

Guadine Hong

NRIC:

S2002848

Address:

18 Jalan Pemimpin
#01-02, Singapore 527000

Nationality:

Singaporean

Occupation:

Admin Executive

WITNESS:

Signature:

Signed by appointed Surveyor

Name:

LKK AUTO CONSULTANTS PTE LTD

NRIC:

199607198R

Address:

51 UBI AVENUE 1 #01-25

PAYA UBI INDUSTRIAL PARK (S) 408933

Nationality:

Occupation:



WORLD AUTO PTE LTD
 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG
 S'PORE 577200
 Tel No. : 64513933 Fax No. : 64557576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL STREET #04 / #05 IOB BUILDING
 S'PORE 049711

Attention : Motor Claim Department
 Contact : 63476100 63476139-LALITA Fax No. : 62244174

Tax Invoice : F189076

Date : 07/01/2019
 Vehicle Num. : SLT 3945G
 Make/Model : TOYOTA PRIUS, 1.8 HYBRID
 Chassis/Eng# :
 Accident Date : 30/07/2018
 Claim No. : TP/2154/2018
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		LIST ITEMS :		
		REAR FENDER RH		850.00
1.	1	SIDE SKIRT RH		550.00
2.	1	REAR DOOR RH		1,350.00
3.	1	FRONT DOOR RH		1,350.00
4.	1			
		List Total S\$:		4,100.00
		25.00% Discount S\$:		1,025.00
				3,075.00
		SPECIAL NETT ITEMS :		
		REAR WHEEL CAP RH		188.00
1.	1	SIDE SKIRT CLIPS		40.00
2.	1			
		Special Nett Total S\$:		228.00
		LABOUR :		
		TRANSFER DOOR MECHANISM (x2 DOORS)		120.00
		REMOVE & INSTALL REAR UPHOLSTERY FOR REPAIRS		150.00
		REMOVE ACCIDENT DAMAGED PARTS FOR REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL		1,000.00
		PUTTY & SPRAY PAINTING ON ALL AFFECTED AREAS		1,000.00
		Labour Total S\$:		2,270.00

Total S\$: 5,573.00
 GST 7% S\$: 390.11
 Amount Due S\$: 5,963.11
 =====


 WORLD AUTO PTE LTD

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Aug 2018 Edit Reg		01 Aug 2018 00:00 Edit Adj Rpt	S\$5,573.00 Edit Estimates	S\$5,573.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD. Co. Reg. No.: -								
Main Claimant:	LCRF PTE LTD. Co. Reg. No.: 201624597K								
Vehicle Reg. No.:	SLT3945G	Date of Loss:	30/07/2018 17:00 - :59 [9 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18070898	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHD6531D	Policy No. (Claimant):	999995046						
		Excess:							
Repairer:	World Auto Pte Ltd (HQ) 47 Jin Pemimpin, #01-02/03 Halcyon 2, 577200 Bishan - Tel: 6451 3933								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 13/08/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (05/03/2019): Alert - Adj Mandate Approved (S\$6263.11) - SLT3945G - Claim Handler: Zuhaidah Bt... - III_SG (13/08/2018): Alert - Adj Mandate Approved (S\$0.00) - SLT3945G - Claim Handler: Zuhaidah Bte S...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLT3945G (MCT18070898)
[SHD6531D]
TP
LCRF PTE LTD
Jul 30 2018 5:00PM
[COMFORT TRANSPORTATION PTE LTD]
World Auto Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/08/18 10:04	General View		Load JPG	☒
2	07/08/18 10:04	General View		Load JPG	☒
3	07/08/18 10:04	General View		Load JPG	☒
4	07/08/18 10:04	General View		Load JPG	☒
5	07/08/18 10:04	General View		Load JPG	☒
6	07/08/18 10:04	General View		Load JPG	☒
7	07/08/18 10:04	General View		Load JPG	☒
8	07/08/18 10:04	General View		Load JPG	☒
9	07/08/18 10:04	General View		Load JPG	☒
10	07/08/18 10:04	General View		Load JPG	☒
11	07/08/18 10:04	General View		Load JPG	☒
12	07/08/18 10:04	General View		Load JPG	☒
13	07/08/18 10:04	General View		Load JPG	☒
14	07/08/18 10:04	General View		Load JPG	☒
15	07/08/18 10:04	General View		Load JPG	☒
16	07/08/18 10:04	General View		Load JPG	☒
17	07/08/18 10:04	General View		Load JPG	☒
18	07/08/18 10:04	General View		Load JPG	☒
19	07/08/18 10:04	General View		Load JPG	☒
20	07/08/18 10:04	General View		Load JPG	☒
21	07/08/18 10:04	General View		Load JPG	☒
22	26/12/18 16:39	Dismantled Parts		Load JPG	☒
23	26/12/18 16:39	Dismantled Parts		Load JPG	☒
24	26/12/18 16:39	Dismantled Parts		Load JPG	☒
25	26/12/18 16:39	Dismantled Parts		Load JPG	☒
26	26/12/18 16:39	Dismantled Parts		Load JPG	☒
27	26/12/18 16:39	Dismantled Parts		Load JPG	☒
28	26/12/18 16:39	Dismantled Parts		Load JPG	☒
29	26/12/18 16:39	Dismantled Parts		Load JPG	☒
30	26/12/18 16:39	Dismantled Parts		Load JPG	☒
31	26/12/18 16:40	Replacement Part Photo		Load JPG	☒
32	26/12/18 16:40	Replacement Part Photo		Load JPG	☒
33	26/12/18 16:40	Replacement Part Photo		Load JPG	☒
34	26/12/18 16:40	Replacement Part Photo		Load JPG	☒
35	26/12/18 16:40	Replacement Part Photo		Load JPG	☒
36	26/12/18 16:40	Replacement Part Photo		Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/08/18 16:01	TP GIA REPORT	 Load PDF	
2	01/08/18 16:01	EMAIL FROM III DD 01082018	 Load PDF	
3	13/08/18 18:45	TP ESTIMATE- MARKED	 Load PDF	
4	18/02/19 11:15	WORKSHOP INVOICE	 Load PDF	
5	18/02/19 11:15	LOD	 Load PDF	
6	01/04/19 16:23	DISCHARGE VOUCHER	 Load PDF	
7	01/04/19 16:23	AUTHORISATION TO ACT FORM	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	02/08/18 08:52	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18013987/NJB3Q2

Date: 01/04/2019

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SLT3945G	Insured Vehicle No :	SHD6531D
Date of Loss:	30/07/2018	Nature of Claim:	TP
		Claim No:	MCT18070898

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT3945G	Engine No:	HIDDEN
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU503562442
Reg. Date:	27/10/2017 (Man. Year: 2017)	Odometer:	59895 km
Colour:	White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,125.50	3,303.00	2,822.50	46.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,540.00	2,270.00	1,270.00	35.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,665.50	5,573.00	4,092.50	42.34
+ GST 7.00/7.00% (S\$)	676.59	390.11	286.48	42.34
Nett Amount (S\$)	10,342.09	5,963.11	4,378.98	42.34
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
	Nett Liability (S\$)	6,263.11		
	Global Sum Settlement (S\$)	6,250.00		

INSPECTION

Date of Assignment:	01/08/2018	
Date Inspected:	06/08/2018	Inspected At:
		World Auto Pte Ltd (HQ)
		47 Jln Pemimpin, #01-02/03 Halcyon 2
		Singapore 577200
Estimated Period of Repair:	5.0 days	

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Feb 2019)
Parts: 144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT3945G)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	550.00 FL	*- FL
2	1		*REAR BUMPER RETAINER	Serviceable	120.00 FL	*- FL
3	1		*REAR FENDER RH	Dented	950.00 FL	*850.00 FL
4	1		*SIDE SKIRT RH	Cracked	550.00 FL	*550.00 FL
5	1		*REAR DOOR -RH	Dented	1,450.00 FL	*1,350.00 FL
6	1		*RH REAR DOOR WEATHERSTRIP	Serviceable	310.00 FL	*- FL
7	1		*REAR DOOR POWER WINDOW REGULATOR RH	Serviceable	380.00 FL	*- FL
8	1		*FRONT DOOR -RH	Dented	1,450.00 FL	*1,350.00 FL
9	1		*FRONT DOOR WEATHERSTRIP	Serviceable	310.00 FL	*- FL
10	1		*RH FRONT DOOR INNER TRIM BOARD	Serviceable	730.00 FL	*- FL
11	1		*FRONT DOOR POWER WINDOW REGULATOR RH	Serviceable	380.00 FL	*- FL
12	1		*FRONT DOOR LOCK RH	Serviceable	350.00 FL	*- FL
13	1		*REAR BUMPER CLIP	Not Necessary	40.00 FS	*- FS
14	1		*REAR RRH WHEEL CAP	Scratched	188.00 FS	*188.00 FS
15	1		*REAR RRH TYRE	Not Necessary	210.00 FS	*- FS
16	1		*SIDE SKIRT CLIPS	Necessary	40.00 FS	*40.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc

Sub Total (\$\$)	8,008.00	4,328.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,882.50	1,025.00
Total Parts (\$\$)	6,125.50	3,303.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TRANSFER DOOR MECHANISM (X2 DOORS)	New	360.00	120.00
2	REMOVE REAR UPHOLSTERY IN ORDER TO FACILITATE REPAIRS AND REFIT BACK SAME	New	280.00	150.00
3	LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT ,CUT /WELD ,STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS	New	1,500.00	1,000.00
4	PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)	New	1,400.00	1,000.00
Gross Labour Cost (S\$)			3,540.00	2,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >