

ASS. REC. BY:

REF: CS/MSG18013990/KVD3/m2

Special Instructions:

Survivor
merimen

Kenneth

ASSIGNMENT (Office)

From (Person):

jurmire lok

of

MSIG

Date/Time:

1/8/18 @ 10.25am

Estimated Cost:

Bill to:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGG 7289 T

Insured:

82K94D

at Workshop m/s

Cheng Hoe Motor

Tel:

67556142

of

81K 1019 # 01-374/382 Yishun Ind. Park A

Policy No:

A2904 986 2 MCY

Claim No:

565953

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/07/2018

CA / REV / REP. / REV 24 HRS

'up)

H.O.D. Endorsement:

Date/Time:

11:30am @ 1/8/18

Person Contacted:

June

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SGG 7289 T-X

SLK 94D-X

3/8/18

Send preli revised via merimen

12/9

C/Ln 812001 Carbinet Effect (Red 835.70, 4170)

ASS. REC. BY:

REF:

MSG-1

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGG 7289T Yr Regn: 05, 06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy with c.c. 1794Colour: M. Grey A/C: Insured / Std / NI / NASp. Reading: 168393 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZNE10 . 0302804Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / SRim / STD A/Rim or

Tyre Size: F: 215/50R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 28/7/18 D.O.I. 1/8/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Acc

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

3/8 File pass to Catherine

RECEIVED 1-2 SEP 2010

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1)

Date/Time, File Return to?

2) 12/9 - typist

Days Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

150

10

160

Report Format :

merimen

Lump Sum / I.B.I. (\$

1200/-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18013990/Kvd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 01-08-2018	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLK 94D	Veh. Inspected	SGG 7289T	
Policy No.	A29049862MCY	Coverage (\$)	0.00	
Claim No.	565953	Excess (\$)	0.00	
Assign From	MERIMEN (JASMINE LOK)	Assign Date	01/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/07/2018	Inspection Date	01/08/2018	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 03 Aug 2018

Preliminary Advice

Insured Vehicle No	: SLK94D		
TP Vehicle No	: SGG7289T	Accident Date	: 28/07/2018
Make	: TOYOTA WISH	Assignment Date	: 01/08/2018
Date of Inspection	: 01/08/2018	Est. Duration of Repair	: 3.00
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,035.70
Revised Amount	:S\$	1,525.70
Check Items (Estimated)	:S\$	200.00
Total	:S\$	1,725.70

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jul 2018		01 Aug 2018 10:25 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HSUEN CHOW PTE LTD, Co. Reg. No.: 199607541N		
Main Claimant:	MOHAMAD SALEH BIN KASSIM, ID: S68215388		
Vehicle Reg. No.:	SGG7289T	Date of Loss:	28/07/2018 13:00 - :59 [146 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 565953	Policy/Cover Note No.:	A29049862MCY (Comprehensive) Coverage: 16/12/2017 - 15/12/2018
Vehicle Reg. No. (Insured):	SLK94D	Policy No. (Claimant):	
		Excess:	S\$800.00
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwel - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 02/08/2018]		
Driver/Custodian (Insured):	POUR BENG QUEY (), NRIC: S0174320A, Tel: +6597564682		
Adj Asg. Remarks:	Third Party Pre-Repair Survey. TP nominated LKK (Mr Kenneth Kong) to be SJE, pls assist to arrange. Liability : Clear Contact : Ms June @ 6755 6142		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1538B
Vehicle Details	
Vehicle No.:	SGG7289T
Vehicle to be Exported:	No
Intended De-registration Date:	01 Aug 2018
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 A
Primary Colour:	Grey
Manufacturing Year:	2006
Engine No.:	1ZZ2549631
Chassis No.:	ZNE100302804
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$22,081.00
Original Registration Date:	22 May 2006
First Registration Date:	22 May 2006
Transfer Count:	2
Actual ARF Paid:	\$24,290.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 May 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$23,024.00
COE Rebate Amount:	\$12,910.00
Total Rebate Amount:	\$12,910.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 01 Aug 2018

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SGG7289T

TP/MSIG

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/YS

Claim Type: Third Party

Accident Date: 28/07/2018

TP Veh Reg No: SLK94D

Estimate No: ES1890881/YISHUN

Date: 01 Aug 2018

Policy No: 18-MV003900-R02

Veh Reg No: SGG7289T

Make/Model: TOYOTA WISH 1.8 A

Chassis No: ZNE100302804

Engine No: 1ZZ2549631

Reg. Date: 22/05/2006

Estimate Repair Cost to Vehicle No :SGG7289T

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	530.50	1 PC	530.50	
2 REAR BUMPER LH SIDE RETAINER	23.50	1 PC	23.50	
3 REAR BUMPER CLIPS	3.50	6 PCS	21.00	
4 LH TAILLAMP	472.60	1 PC	472.60	
			1,047.60	
		Less 25%	261.90	785.70
Special Net				
5 REVERSE SENSOR	200.00	1 SET	200.00	
			200.00	200.00
Labour				
6 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMP, TO KNOCK & REPAIR REAR LH FENDER, REAR PANEL & REALIGN THE SAME	400.00	1 LA	400.00	
7 PUTTY & RESPRAY ON REAR BUMPER, REAR LH FENDER & REAR PANEL	650.00	1 LA	650.00	
			1,050.00	1,050.00
			Total	S\$ 2,035.70
			Add GST @ 7%	142.50
			Total Amount Payable	S\$ 2,178.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18013990/KVD3N2

Date: 13/09/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29049862MCY
Claimant Vehicle No :	SGG7289T	Insured Vehicle No :	SLK94D
Date of Loss:	28/07/2018	Nature of Claim:	TP
		Claim No:	565953

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGG7289T	Engine No:	1ZZ2549631
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	ZNE100302804
Reg. Date:	22/05/2006 (Man. Year: 2006)	Odometer:	168393 km
Colour:	Metallic Grey		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50ZR17	Rear Tyre Size:	215/50ZR17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	985.70	785.70	200.00	20.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,050.00	740.00	310.00	29.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,035.70	1,525.70	510.00	25.05
Approved Total (Overridden) (S\$)		1,200.00		
(S\$)	2,035.70	1,200.00	835.70	41.05
+ GST 7.00/7.00% (S\$)	142.50	84.00	58.50	41.05
Nett Amount (S\$)	2,178.20	1,284.00	894.20	41.05

INSPECTION

Date of Assignment: 01/08/2018

Date Inspected: 01/08/2018 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial
Park A
Singapore 768761

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 Sep 2018)
Parts: M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGG7289T)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	530.50 FL	*530.50 FL
2	1		*REAR BUMPER LH SIDE RETAINER	Distorted	23.50 FL	*23.50 FL
3	6		*REAR BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
4	1		*LH TAILLAMP	Broken	472.60 FL	*472.60 FL
5	1		*SET REVERSE SENSOR	Serviceable	200.00 FS	*- FS
					Sub Total (\$\$)	1,247.60 1,047.60
					- List Item Discount on L Items 25.00/25.00% (\$\$)	261.90 261.90
					Total Parts (\$\$)	985.70 785.70

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIX REAR BUMPER ASSY, TAILLAMP, TO KNOCK & REPAIR REAR LH FENDER, REAR PANEL & REALIGN THE SAME	New	400.00	300.00
2	PUTTY & RESPRAY ON REAR BUMPER, REAR LH FENDER & REAR PANEL	New	650.00	440.00
Gross Labour Cost (S\$)			1,050.00	740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >