

2/20/2018

ASS. REC. BY:

REF: CS/CT#18013994/T190302

Special Instruction:

Surveyor
men

Taubert

ASSIGNMENT (Office)

From (Person):

Irene Ky

of

CTI

Date/Time: 1/6/18 @ 11:00am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLB 5682R

Insured:

YN177D

at Workshop m/s

Eng Ah Lee

Tel:

6268 6183

of

31k3 Pioneer Rd north #01-18

Policy No:

DMCVSN 3031051802

Claim No:

SNM18D03728C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/07/2018

CA / REV / REP. / REV 24 HRS

lup

03083018 @ 1pm - 5pm

H.O.D. Endorsement:

Date/Time:

11:47am @ 1/6/18

Person Contacted:

jenice

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLB 5682R - X
	YN177D
12/1/18 @ 10:05am	confirmed with Sharon from Ky @ 3337-38, 4 days.
	CPed @ 119.65, 30/10

(05/11/13) wsf

*ASS. REC. BY:

Tayfuk

REF: CTI

ASSIGNMENT

From:

Date: 3/8/18

Estimated Cost:

OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SIB 5632R

at Workshop m/s

of SIK 3, Pioneer Rd North # 01-18

Insured:

Policy No.:

Claims No.:

Sum Insured:

Excess:

(Client's Record) 1pm - 5pm

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bail. or Market Value:

976K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS ^{up}

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLB 5632R Yr Regn: 2007, Dec.

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Estima c.c 2362

Colour:

Grey A/C: Insured / Std / NI / NA

Sp. Reading:

136890 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ACR 507048801

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 245/45R18

R: ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Wanabe

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

3/8/18 @ 230

Survey held at

Sng Ah Tee.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Df n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 23 JAN 2019



22/1/2019

Date/Time, File Pass to?

☐

Preli. Report

11/22/18 Tayfuk

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

220

Transportation:

S + RS SI

Photos

Others

TOTAL

220

Report Format:

WEB T

Lump Sum / I.B.I. (\$

3387.38



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18013994/T1qd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 01-08-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YN 177D	Veh. Inspected	SLB 5632R
Policy No.	DMCVSN3031051802	Coverage (\$)	0.00
Claim No.	SNM18D03728C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	01/08/2018
2. Vehicle Particulars & Condition			
Make & Model	c.c		0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	27/07/2018	Inspection Date	03/08/2018
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Aug 2018 Sendback Est	01 Aug 2018 10:58 \$53,096.43	01 Aug 2018 11:22 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	N/A, Co. Reg. No.: N/A		
Main Claimant:	BONG KHONG LEE, ID: S82802951		
Vehicle Reg. No.:	SLB5632R	Date of Loss:	27/07/2018 12:00 - :59 [127 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D03728C02	Policy/Cover Note No.:	DMCVSN3031051802
Vehicle Reg. No. (Insured):	YN177D	Policy No. (Claimant):	DMPCSN3097541700
		Excess:	S\$0.00
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/08/2018]		
Adj Asg. Remarks:	EST \$3313.18, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 22 January 2019 10:05 AM
To: 'Sharon Sng'; Taufikh (LKKAUTO)
Cc: SUR
Subject: RE: SLB5632K - FINALISE & BEFORE PAINT (2)

Dear Sharon,

WITHOUT PREJUDICE

Confirm final fig \$3,387.38 before GST and 4 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sharon Sng <sharon@sngahtee.com>
Sent: Friday, 14 December 2018 4:08 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Subject: SLB5632K - FINALISE & BEFORE PAINT (2)

Best Regards

Sharon Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



-Please note that all offer/acceptance is made without prejudice.-

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 0295I

Vehicle Details

Vehicle No.: SLB5632R
Vehicle to be Exported: No
Intended De-registration Date: 11 Aug 2018
Vehicle Make: TOYOTA
Vehicle Model: ESTIMA 2.4 A
Primary Colour: Blue
Manufacturing Year: 2007
Engine No.: 2AZF023281
Chassis No.: ACR507048801
Maximum Power Output: 125.0 kW (167 bhp)
Open Market Value: \$26,796.00
Original Registration Date: 21 Dec 2007
First Registration Date: 21 Dec 2007
Transfer Count: 3
Actual ARF Paid: \$29,476.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 20 Dec 2027
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
PQP Paid: \$51,850.00
COE Rebate Amount: \$48,518.00
Total Rebate Amount: \$48,518.00

The information contained herein is correct as at 30 Jul 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/07/2018 14:41
Date Of Accident	27/07/2018 12:25
Exact Location Of Accident	ALONG TUAS SOUTH BLVD TOWARDS TUAS SOUTH AVE 14
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB5632R
Insured/Policyholder	
Name Of Registered Owner	BONG KHONG LEE
NRIC No	S82802951
Email Address	FATTNEWS@GMAIL.COM
Mobile Phone No	(LOCAL) +65-94247873
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	TOYOTA
Model	ESTIMA-2.4 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3097541700
Cover Note Number	

Driver

Name of Driver	BONG KHONG LEE
NRIC No	S82802951
Date Of Birth	14/07/1982
Occupation	INDOOR
Date Of Driving Pass	24/11/2007
Driving Experience	10 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94247873
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	FATTNEWS@GMAIL.COM

Address	BLK 657B JURONG WEST ST 65 #16-652
Postcode	642657
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 27/07/2018 AT ABOUT 1225 HRS. WHILE I WAS TRAVELLING ALONG TUAS SOUTH BLVD TOWARDS TUAS SOUTH AVE 14, WHEN MY VEHICLE PASS THROUGH VEHICLE B AND REACH THE TRAFFIC JUNCTION. VEHICLE B SUDDENLY CUT INTO MY LANE AND HIT ONTO MY VEHICLE CAUSING MY VEHICLE LEFT PORTION DAMAGED. THAT ALL.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN177D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A **14 DAYS TIMEFRAME** FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

SKETCH PLAN

A-SLB5632R
B-YN1770

↑ ↑ ↑ ↑
Tuas South Blvd

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to circumstances

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

☐ Claim own policy
☒ Claim third party
☐ Claim OD / TP at other works hop
☐ For record purpose
Policy No. AMP CSV 3097 S4701
Insurer Chin 9 Veh. No. SLB5632R

**SNG AH TEE MOTOR &
PANEL SERVICE PTE LTD
3 PIONEER ROAD NORTH
#01-18
SINGAPORE 628457**

Claim Reference:
Assessment Number: DS000534
Version: SNGAHTEE/1
Date Calculated: 01/08/2018 03:47

Full Report - V1
Registration: SLB5632K
Printed: 01/08/2018 10:47

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	SNG AH TEE	Date of Incident:	27/07/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	-	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:	True	Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer: TOYOTA
Model: Estima
Sub Model: BASE MODEL
Model Sheet Number: YM2 01
Registration: SLB5632K
Registration Month:
Registration Year:
VIN Number:
Odometer: Not Known
Colour:
Engine Number:
Fuel Level: %

Model Specs

FROM 08/2007 RR AIR CONDITIONING
XENON HEADLAMPS 2.4 LTR 117/125 KW
TWO COAT METALLIC PREPARE OFF VEHICLE

Tanjiluh 17495749
NP
3/8/18 @ 230 pm
To check 4/s on p/p
To viewing before or after paint
04 days

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on
	Inspection:
Brakes Pedal Travel:	Date of Inspection: 01/08/2018
Place of Inspection:	
Pre-Accident Damage:	

Tyres Condition:
Tread Depth LHF:
Tread Depth LHR:
Damage Areas:

Tread Depth LHF:
Tread Depth LHR:
Direction of Impact:

LKK Auto Consultants hence notify the Repairer of the following:
RHF: resurvey before/after spray painting
RHR: display damaged part(s) during resurvey
Prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000534



Version: SNGAHTEE/1

Date Calculated: 01/08/2018 03:47

Full Report - V1

Registration: SLB5632K

Printed: 01/08/2018 10:47



Addresses

Cost Summary

Total Labour	\$819.00
Total Paint/Material	\$177.43
Total Parts	\$2,100.00
Excess:	TBA
Grand Total Exc GST:	\$3,096.43
7 % GST:	\$216.75
Grand Total Inc GST:	\$3,313.18

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
Price/Dent = \$0.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
NO NUMBER	ADJUST HEADLAMPS	2.0	8.40
B100 ZAX	R + R LEFT FRONT WING (FRT BUMPER AND L/HEADLAMP ASSY REMOVED)	4.0	16.80
B110) ZAX	RENEW LEFT FRONT WING (REMOVED)	2.0	8.40
B010) ZAX	R + R FRONT BUMPER NOT INCLUDED: RADIATOR GRILLE R + R	5.0	21.00
NO NUMBER	R + R FRONT BUMPER ATTACHED PARTS	2.0	8.40
B010) ZAX	R + R FRONT BUMPER REINFORCEMENT	2.0	8.40
B030 ZAX	R + R RADIATOR GRILLE	2.0	8.40
B040) ZAX	R + R LEFT HEADLAMP (BUMPER REMOVED)	1.0	4.20
B040) ZAX	DOES NOT INCLUDE: ADJUST HEADLAMP R + R HEADLAMPS	1.0	4.20
B040) ZAX	R + R XENON HEADLAMP (ADD/WORK)	1.0	4.20
B085) ZAX	R + R SCUTTLE PANEL GRILLE	4.0	16.80
B210 ZAX	INCLUDES: R + R BOTH WIPER ARMS RENEW LEFT FRONT DOOR INCLUDES: R + R AND ALIGN LEFT FRONT DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	29.0	121.80
670201) ZAX	RENEW L/F UPPER DOOR HINGE	11.0	46.20
670201) ZAX	RENEW L/F LOWER DOOR HINGE	11.0	46.20
0283	REPAIR FRONT BUMPER	5.0*	21.00
1019	REPAIR L/F UPPER END PANEL	5.0*	21.00
1169	REPAIR L/UPPER WHEELHOUSE	5.0*	21.00
1551	CHECK L/F WINDOW MOTOR	5.0*	21.00

LABOUR COST

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000534

Version: SNGAHTTE/1

Date Calculated: 01/08/2018 03:47

Full Report - V1

Registration: SLB5632K

Printed: 01/08/2018 10:47

Total Work Units	97.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	9.7HRS	\$407.40
Paint Labour	9.8HRS	\$411.60
Total Labour	19.5HRS	\$819.00

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$42.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
741	L/F WING NEW PART PAINTING	10.0	
1481	LEFT FRONT DOOR NEW PART PAINTING	18.0	
1735	L/DOOR MIRROR COVER NEW PART PAINT K1R	4.0	
2219	L/F SILL MOULDING NEW PART PAINT K1R	3.0	
283	FRONT BUMPER REPAIR PAINT PLASTIC	16.0	
1019	L/F UPPER END PANEL SURFACE PAINT	4.0	
1169	L/UPPER WHEELHOUSE SURFACE PAINT	4.0	
1565	L/F DOOR OUT HANDLE SURFACE PAINT PLAST.	3.0	
1567	L/DOOR LOCK PROTECT SURFACE PAINT PLAST.	3.0	
LABOUR COST - PAINT			
TIME(PAINT)		65.0	
Preparation Main Work Plastic		8.0	
Preparation Main Work Metal		25.0	
Preparation Work Multi Layer Paint		0.0	
Total Work Units (10WU/HR)		98.0	
Total Paintwork Labour		9.8HRS	\$411.60
MATERIAL COST - PAINT			Cost Price
New Part Painting			\$74.30
New Part Painting - Plastic K1R			\$5.41
Material-Constant Main Work Metal			\$28.60
Surface-/Blend Paint			\$3.48
Surface Paint Plastic			\$1.10
Repair Painting Plastic			\$51.84
Material-Const Main Work Plastic			\$12.70
Total Excluding Pearlescent Uplift			\$177.43
Pearlescent Uplift @ 0.0%			\$0.00
Total Paint Material Cost			\$177.43

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
319	1	L/F OUT BUMPER BRKT	52116 28060		0% 35.00* x 171
350	1	FRT BUMPER CLAMP KIT	USE SINGLE PARTS		0% ? 25.00* x 171
561	1	LEFT HEADLAMP ASSY	81150 28D60		1050 0% one 500.00*
707	1	L/SIDE REPEATER LAMP	81740 52031		0% 45.00*
741	1	L/F WING	53812 28080		0% 180 175.00*
789	1	L/F WING CLAMP KIT	USE SINGLE PARTS		0% one 25.00* x 171
841	1	L/F WHEELHOUSE COVER	53806 28030		0% 90 x 95.00* de
1481	1	LEFT FRONT DOOR	67002 28210		0% 550.00*
1487	1	L/UPPER DOOR HINGE	68720 12151		0% 35.00*
1495	1	L/LOWER DOOR HINGE	68740 33021		0% 35.00*

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000534

Version: SNGAHTEE/1

Date Calculated: 01/08/2018 03:47

Full Report - V1

Registration: SLB5632K

Printed: 01/08/2018 10:47

1505	1	L/F DOOR CHECK	68610 28060	0%	60.00*	X
1735	1	L/DOOR MIRROR COVER	87945 28060A1	0%	350.00*	
2219	1	L/F SILL MOULDING	76914 28070	0%	70.00*	X
f: OEM Parts			Sub Total		\$2,000.00	
g: Original			Mark Up From Cost	(0 %)	\$0.00	
h: Secondhand			Sundry Parts	(Fixed)	\$100.00	
p: Parallel			Total Parts		\$2,100.00	
x: Exchange						
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER						
Total Extras					\$0.00	

Final Calculation

Total Parts	\$2,100.00
Labour	
Total Panel/Mechanical	\$407.40
Total Paintwork	\$411.60
Total Labour	\$819.00
Total Paint/Material Costs	\$177.43
Grand Total Excludes GST	\$3,096.43
GST @ 7 %	\$216.75
Grand Total Includes GST	\$3,313.18

Assessment Notes

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
N/A

Singapore

Claimant Insurer: China Taiping Insurance (Singapore) Pte. Ltd.**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	27/07/2018
Vehicle Reg. No.:	SLB5632R	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	BONG KHONG LEE		
Make/Model:	TOYOTA ESTIMA, 2.4 (A)	Vehicle Reg. Date:	21/12/2007
Vehicle Colour:	BLUE		
Engine No:	2AZF023281	Chassis No:	ACR507048801
Odometer:	5 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Description of Accident/Loss	ON 27/07/2018 AT ABOUT 1225 HRS. WHILE I WAS TRAVELLING ALONG TUAS SOUTH BLVD TOWARDS TUAS SOUTH AVE 14. WHEN MY VEHICLE PASS THROUGH VEHICLE B AND REACH THE TRAFFIC JUNCTION. VEHICLE B SUDDENLY CUT INTO MY LANE AND HIT ONTO MY VEHICLE CAUSING MY VEHICLE LEFT PORTION DAMAGED. THAT ALL.		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

COST OF CLAIMS	Amount
Parts	2,100.00
Miscellaneous Items	0.00
Labour	996.43
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,096.43
+ GST 7.00% (S\$)	216.75
Nett Amount (S\$)	3,313.18

This claim is handled by: JANICE CHANG SIEW YIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

3/26/43

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 01 Aug 2018)**Parts:** M1-MPV TOYOTA ESTIMA 2.4 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Sng Ah Tee Motor & Panel Service Pte Ltd/SLB5632R/01/08/2018 10:58**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*FRT BUMPER CLAMP KIT	0.00	0.00	*25.00 F ^{FR}
2	1	NA	*L/DOOR MIRROR COVER	0.00	0.00	40 *350.00 F ^{CAF}
3	1	NA	*L/F DOOR CHECK	0.00	0.00	*60.00 F ^{FR}
4	1	NA	*L/F OUT BUMPER BRKT	0.00	0.00	*35.00 F ^{FR}
5	1	NA	*L/F SILL MOULDING	0.00	0.00	*70.00 F ^{FR}
6	1	NA	*L/F WHEELHOUSE COVER	0.00	0.00	90 *95.00 F ^{de}
7	1	NA	*L/F WING	0.00	0.00	180 *175.00 F ^{FR}
8	1	NA	*L/F WING CLAMP KIT	0.00	0.00	*25.00 F ^{FR}
9	1	NA	*L/LOWER DOOR HINGE	0.00	0.00	*35.00 F ^{XR}
10	1	NA	*L/SIDE REPEATER LAMP	0.00	0.00	*45.00 F ^{FR}
11	1	NA	*L/UPPER DOOR HINGE	0.00	0.00	*35.00 F ^{XR}
12	1	NA	*LEFT FRONT DOOR	0.00	0.00	*550.00 F ^{FR}
13	1	NA	*LEFT HEADLAMP ASSY	0.00	0.00	1080 *500.00 F ^{CAF}
14	1	NA	*SUNDRY PARTS	0	0.00	*100.00 FS ^{FR}

F=Franchise part. S=SpcNett.

Total Parts (S\$)**2,100.00**

Sng Ah Tee Motor & Panel Service Pte Ltd/SLB5632R/01/08/2018 10:58. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Total Paint Labour	New	411.60
2	Total Paint Materials	New	177.43
3	Total Panel/Mechanical Labour	New	348.60
Gross Labour Cost (S\$)			996.43

Sng Ah Tee Motor & Panel Service Pte Ltd/SLB5632R/01/08/2018 10:58. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg;darren@sngahtee.com;janice@sngahtee.com

(SUPPLEMENTARY)**TP INSURER:** China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
N/A

Singapore

Claimant Insurer: China Taiping Insurance (Singapore) Pte. Ltd.**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	DMCVSN3031051802	Date of Loss:	27/07/2018
Vehicle Reg. No.:	SLB5632R	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	BONG KHONG LEE		
Make/Model:	TOYOTA ESTIMA, 2.4 (A)	Vehicle Reg. Date:	21/12/2007
Vehicle Colour:	BLUE		
Engine No:	2AZF023281	Chassis No:	ACR507048801
Odometer:	5 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Description of Accident/Loss	ON 27/07/2018 AT ABOUT 1225 HRS. WHILE I WAS TRAVELLING ALONG TUAS SOUTH BLVD TOWARDS TUAS SOUTH AVE 14.WHEN MY VEHICLE PASS THROUGH VEHICLE B AND REACH THE TRAFFIC JUNCTION . VEHICLE B SUDDENLY CUT INTO MY LANE AND HIT ONTO MY VEHICLE CAUSING MY VEHICLE LEFT PORTION DAMAGED. THAT ALL.		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

COST OF CLAIMS	Amount
Parts	410.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	410.00
+ GST 7.00% (S\$)	28.70
Nett Amount (S\$)	438.70
+ Previous Estimates (S\$)	3,313.18
Claim Total (S\$)	3,751.88

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 14 Dec 2018)**Parts:** M1-MPV TOYOTA ESTIMA 2.4 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Sng Ah Tee Motor & Panel Service Pte Ltd/SLB5632R/14/12/2018 16:25**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*L/F UPP DOOR STRIPE	0.00	0.00	*35.00 F <i>Free</i>
2	1		*L/F DOOR REAR STRIPE	0.00	0.00	*40.00 F <i>Free</i>
3	1		*L/DOOR MIRROR	0.00	0.00	*310.00 F <i>dis</i>
4	1		*WIPER GARNISH SIDE	0.00	0.00	*25.00 F <i>dis</i>
Total Parts (S\$)						410.00

F=Franchise part.

Sng Ah Tee Motor & Panel Service Pte Ltd/SLB5632R/14/12/2018 16:25. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Sng Ah Tee Motor & Panel Service Pte Ltd/SLB5632R/14/12/2018 16:25. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

**SNG AH TEE MOTOR &
PANEL SERVICE PTE LTD
3 PIONEER ROAD NORTH
#01-18
SINGAPORE 628457**

Claim Reference:
Assessment Number: DS000534
Version: SNGAHTEE/2
Date Calculated: 18/08/2018 02:31

Full Report - V1
Registration: SLB5632K
Printed: 14/12/2018 15:48

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	DARREN SNG	Date of Incident:	27/07/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	-	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:	True	Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Estima
Sub Model:	BASE MODEL
Model Sheet Number:	YM2 01
Registration:	SLB5632K
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FROM 08/2007	RR AIR CONDITIONING
XENON HEADLAMPS	2.4 LTR 117/125 KW
TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition



Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	01/08/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:	Tread Depth RHR:	
Tread Depth LHR:	Direction of Impact:	
Damage Areas:		

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:
Assessment Number: DS000534
Version: SNGAHTEE/2
Date Calculated: 18/08/2018 02:31

Full Report - V1
Registration: SLB5632K
Printed: 14/12/2018 15:48



Addresses

Cost Summary

Total Labour	\$760.20
Total Paint/Material	\$177.18
Total Parts	\$2,450.00
Excess:	TBA
Grand Total Exc GST:	\$3,387.38
7 % GST:	\$237.12
Grand Total Inc GST:	\$3,624.50

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
Price/Dent = \$0.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
NO NUMBER	ADJUST HEADLAMPS	2.0	8.40
B100 ZAX	R + R LEFT FRONT WING (FRT BUMPER AND L/HEADLAMP ASSY REMOVED)	4.0	16.80
B110) ZAX	RENEW LEFT FRONT WING (REMOVED)	2.0	8.40
B010) ZAX	R + R FRONT BUMPER NOT INCLUDED: RADIATOR GRILLE R + R	5.0	21.00
B010) ZAX	R + R FRONT BUMPER REINFORCEMENT	2.0	8.40
B030 ZAX	R + R RADIATOR GRILLE	2.0	8.40
B040) ZAX	R + R LEFT HEADLAMP (BUMPER REMOVED)	1.0	4.20
	DOES NOT INCLUDE: ADJUST HEADLAMP		
B040) ZAX	R + R HEADLAMPS	1.0	4.20
B040) ZAX	R + R XENON HEADLAMP (ADD/WORK)	1.0	4.20
B085) ZAX	R + R SCUTTLE PANEL GRILLE INCLUDES: R + R BOTH WIPER ARMS	4.0	16.80
B210 ZAX	RENEW LEFT FRONT DOOR INCLUDES: R + R AND ALIGN LEFT FRONT DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	29.0	121.80
0283	REPAIR FRONT BUMPER	5.0*	21.00
1019	REPAIR L/F UPPER END PANEL	5.0*	21.00
1169	REPAIR L/UPPER WHEELHOUSE	5.0*	21.00
1487	REPAIR L/UPPER DOOR HINGE	5.0*	21.00
1495	REPAIR L/LOWER DOOR HINGE	5.0*	21.00
1551	CHECK L/F WINDOW MOTOR	5.0*	21.00

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:
Assessment Number: DS000534
Version: SNGAHTTE/2
Date Calculated: 18/08/2018 02:31

Full Report - V1
Registration: SLB5632K
Printed: 14/12/2018 15:48

LABOUR COST

Total Work Units	83.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	8.3HRS	\$348.60
Paint Labour	9.8HRS	\$411.60
Total Labour	18.1HRS	\$760.20

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$42.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
741	L/F WING NEW PART PAINTING	10.0	
1481	LEFT FRONT DOOR NEW PART PAINTING	18.0	
1735	L/DOOR MIRROR COVER NEW PART PAINT K1R	4.0	
283	FRONT BUMPER REPAIR PAINT PLASTIC	16.0	
1019	L/F UPPER END PANEL SURFACE PAINT	4.0	
1169	L/UPPER WHEELHOUSE SURFACE PAINT	4.0	
1565	L/F DOOR OUT HANDLE SURFACE PAINT PLAST.	3.0	
1567	L/DOOR LOCK PROTECT SURFACE PAINT PLAST.	3.0	
2219	L/F SILL MOULDING SURFACE PAINT PLAST.	3.0	

LABOUR COST - PAINT

TIME(PAINT)	65.0	
Preparation Main Work Plastic	8.0	
Preparation Main Work Metal	25.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	98.0	
Total Paintwork Labour	9.8HRS	\$411.60

MATERIAL COST - PAINT

New Part Painting	\$74.30
New Part Painting - Plastic K1R	\$4.43
Material-Constant Main Work Metal	\$28.60
Surface-/Blend Paint	\$3.48
Surface Paint Plastic	\$1.83
Repair Painting Plastic	\$51.84
Material-Const Main Work Plastic	\$12.70
Total Excluding Pearlescent Uplift	\$177.18
Pearlescent Uplift @ 0.0%	\$0.00
Total Paint Material Cost	\$177.18

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Price (\$)
561	1	LEFT HEADLAMP ASSY	81150 28D60	0%	1,080.00*
741	1	L/F WING	53812 28080	0%	180.00*
841	1	L/F WHEELHOUSE COVER	53806 28030	0%	90.00*
1481	1	LEFT FRONT DOOR	67002 28210	0%	550.00*
1647	1	L/F UPP DOOR STRIPE	75956 28030	0%	35.00* <i>new</i>
1655	1	L/F DOOR REAR STRIP	75958 28030	0%	40.00* <i>new</i>
1735	1	L/DOOR MIRROR COVER	87945 28060A1	0%	40.00*
1737	1	L/DOOR MIRROR	87940 28A21	0%	310.00* <i>dis</i>
1000	1	WIPER GARNISH SIDE	CVR (LH)	0%	25.00* <i>de</i>
f: OEM Parts			Sub Total		\$2,350.00

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD**Claim Reference:****Full Report - V1****Assessment Number: DS000534****Registration: SLB5632K****Version: SNGAHTEE/2****Printed: 14/12/2018 15:48****Date Calculated: 18/08/2018 02:31**

g: Original	Mark Up From Cost	(0 %)	\$0.00
h: Secondhand	Sundry Parts	(Fixed)	\$100.00
p: Parallel	Total Parts		\$2,450.00
x: Exchange			

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER**Total Extras \$0.00****Final Calculation**

Total Parts		\$2,450.00
Labour		
Total Panel/Mechanical	\$348.60	
Total Paintwork	\$411.60	
Total Labour		\$760.20
Total Paint/Material Costs		\$177.18
Grand Total Excludes GST		\$3,387.38
GST @ 7 %		\$237.12
Grand Total Includes GST		\$3,624.50

Assessment Notes



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 196307741M



Dept Direct: 6417 8791 / 8746 9636

Dept Direct: 6306 9610

Dept Direct: 6306 9611

Dept Direct: 6417 8792



Dept Direct: 6417 8794

Dept Direct: 6417 8786

Dept Direct: 6417 8796

Dept Direct: 6417 8792

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD
BLK 03 #01-18 PIONEER ROAD NOR
SPORE 628457
CHENG PAGER :94008212

TEL : 62686183 9624964 FAX : 62681429
ATTN : VIVIAN / SHARON / BERTHA/JANICE/ SAMANTHA

TAX INVOICE : AR201808-06925
DATE : 14/08/2018
CUSTOMER ID : SNG001
VEH REG. NO. : SLB5632K
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 767002-28210	PANEL SUB ASSY, FR DOOR LH	CC	1	550.00	550.00
ACR50 ESTIMA	#1451	CC12-C-04A			

SUB-TOTAL : 550.00
ADD GST 7.00 % 38.50

E. & O.E TOTAL AMOUNT SGD : 588.50

[P] 14/08/2018 4:13:30PM

[E] 14/08/2018 4:11:21PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: JASON

This is computer generated document.

No signature is required.



AR201808-06925

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450816 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6366 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9938



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD
BLK 03 #01-18 PIONEER ROAD NOR
SPORE 628457
CHENG PAGER :94008212

TEL : 62686183 9624964 FAX : 62681429
ATTN : VIVIAN / SHARON / BERTHA/JANICE/ SAMANTHA

TAX INVOICE : AR201808-07019
DATE : 14/08/2018
CUSTOMER ID : SNG001
VEH REG. NO. : SLB5632K
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ STOCKID	DESCRIPTION	StkLoo	QTY	U/PRICE	AMOUNT
1. T53812-28280 ACR50	FRT FENDER LH #741	PA PL2-B1-07A	1	180.00	180.00
2. T81106-28G20 ACR50/2016	HEAD LAMP LH #561	PA PL2-D1-040	1	1080.00	1,080.00

SUB-TOTAL : 1,260.00
ADD GST 7.00 % 88.20

E. & O.E TOTAL AMOUNT SGD : 1,348.20

14/08/2018 5:49:02PM

[E] 14/08/2018 5:46:33PM

is Sold are not refundable for Cash.

st Rate of 1.5% per month will be imposed on OverDue Account(s).

o Pte. Ltd.

utive: JASON

puter generated document.

is required.



* AR201808-07019 *

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0118201-3 CO. REG. NO.: 199307741M

WINDSHIELD GLASS
Dept Direct: 6417 3791 / 6745 8828



Dept Direct: 6302 9810

Dept Direct: 6302 9811

Dept Direct: 6417 9782



Dept Direct: 6417 8794

Dept Direct: 6417 9786

Dept Direct: 6417 9798

Dept Direct: 6417 9790

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD
BLK 03 #01-18 PIONEER ROAD NOR
S'PORE 628457
CHENG PAGER :94008212

TEL : 62686183 9624964 FAX : 62681429

ATTN : VIVIAN / SHARON / BERTHA/JANICE/ SAMANTHA

TAX INVOICE : AR201808-07611
DATE : 15/08/2018
CUSTOMER ID : SNG001
VEH REG. NO. : SLB5632K
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. T53806-28120 ACR50	FRT FENDER LINER LH #841	PA PL2-L1-08S	1	90.00	90.00

SUB-TOTAL : 90.00
ADD GST 7.00 % 6.30

E A O R TOTAL AMOUNT SGD : 96.30

[P] 15/08/2018 3:42:23PM

[E] 15/08/2018 3:40:26PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: JASON

This is computer generated document.
No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450818 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 9417 8791 / 6745 0838



Dept Direct: 6306 9610

Dept Direct: 6306 9611

Dept Direct: 9417 8792



Dept Direct: 9417 8794

Dept Direct: 9417 8795

Dept Direct: 9417 8796

Dept Direct: 9417 8797

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD
BLK 03 #01-18 PIONEER ROAD NOR
S'PORE 628457
CHENG PAGER: 94008212

TEL: 62686183 9624964 FAX: 62681429
ATTN: VIVIAN / SHARON / BERTHA / JANICE / SAMANTHA

TAX INVOICE : AR201808-08084
DATE : 16/08/2018
CUSTOMER ID : SNG001
VEH REG. NO. : SLB5632K
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SO STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
T53867-28050 ACR50	WIPER GARNISH S/SEAL LH #1000	PA PL2-K1-03H	1	25.00	25.00

SUB-TOTAL : 25.00
ADD GST 7.00 % 1.75

E. & O.E TOTAL AMOUNT SGD : 26.75

[P] 16/08/2018 1:12:55PM

[E] 16/08/2018 1:06:34PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: JASON

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450816 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729872
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 8791 / 6742 9828



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 8792



Dept Direct: 6417 8794

Dept Direct: 6417 8795

Dept Direct: 6417 8796

Dept Direct: 6417 8798

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD
BLK 03 #01-18 PIONEER ROAD NOR
S'PORE 628457
CHENG PAGER :94008212

TEL : 62686183 9624964 FAX : 62681429
ATTN : VIVIAN / SHARON / BERTHA/JANICE/ SAMANTHA

TAX INVOICE : AR201808-08308
DATE : 16/08/2018
CUSTOMER ID : SNG001
VEH REG. NO. : SLB5632K
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	T75956-28030	TAPE, BLACK OUT FR <i>11657</i>	U1	1	35.00	35.00
	ACR50 ESTIMA	<i>LF (FR RR)</i>	SUPPLIER			
2	T75958-28030	TAPE, BLACK OUT FR <i>11658</i>	U1	1	40.00	40.00
	ACR50 ESTIMA	<i>(top)</i>	SUPPLIER			

SUB-TOTAL : 75.00
ADD GST 7.00 % 5.25

E. & O.E TOTAL AMOUNT SGD : 80.25

[P] 16/08/2018 15:55:21

[E] 16/08/2018 3:54:45PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : HAO



This is computer generated document.
No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

BLK 03 #01-18 PIONEER ROAD NOR

S'PORE 628457

CHENG RAGER : 94008212

TEL : 62686183 9624964 FAX : 62681429

ATTN : VIVIAN / SHARON / BERTHA/JANICE/ SAMANTHA

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 0639



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9796

Dept Direct: 6417 9798

Dept Direct: 6417 9799

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea).
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201808-08441
DATE : 17/08/2018
CUSTOMER ID : SNG001
VEH REG. NO. : SLB5632K
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SO STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. T87940-28A21	SIDE MIRROR L.H	U1	1	310.00	310.00
ACR50-AERAS	#1737	SUPPLIER			

SUB-TOTAL 310.00
ADD GST 7.00 % 21.70

E. & O.E TOTAL AMOUNT SGD 331.70

[P] 17/08/2018 9:18:25AM

[E] 17/08/2018 9:08:36AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on Over Due Account(s).

JAE Auto Pte. Ltd.

Sales Executive JASON



*A R 2 0 1 8 0 8 - 0 8 4 4 1 *

Goods Received in Good Order

This is computer generated document.

No signature is required.

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD GLASS
Dept Direct: 8417 8761 / 8745 9638



Dept Direct: 8308 9810

Dept Direct: 8308 9811

Dept Direct: 8417 8762



Dept Direct: 8417 8794

Dept Direct: 8417 8795

Dept Direct: 8417 8796

Dept Direct: 8417 8797

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea).

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

BLK 03 #01-18 PIONEER ROAD NOR

SPORE 628457

CHENG PAGER :94008212

TEL : 62686183 9624964 FAX : 62681429

ATTN : VIVIAN / SHARON / BERTHA/JANICE/ SAMANTHA

TAX INVOICE : AR201808-08087

DATE : 16/08/2018

CUSTOMER ID : SNG001

VEH REG. NO. : SLB5632K

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	187945-28060-C0	SIDE MIRROR COVER LH	PA	1	40.00	40.00
	ACR50	11735.	PL2-J1-081			

SUB-TOTAL : 40.00
ADD GST 7.00 % 2.80

E & OE TOTAL AMOUNT SGD : 42.80

[P] 17/08/2018 9:09:31AM

[E] 16/08/2018 1:10:08PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: JASON

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Full Report - V1
Registration: SLB5632R
Printed: 28/12/2018 15:46

Claim Reference:
Assessment Number: DS000534
Version: SNGAHTTE/2
Date Calculated: 28/12/2018 07:46

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	27/07/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	-	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:	True	Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Estima
Sub Model:	BASE MODEL
Model Sheet Number:	YM2 01
Registration:	SLB5632R
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FROM 08/2007	RR AIR CONDITIONING
XENON HEADLAMPS	2.4 LTR 117/125 KW
TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	01/08/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	

Claim Reference:

Full Report - V1



Assessment Number: DS000534

Registration: SLB5632R

Version: SNGAHTTE/2

Printed: 28/12/2018 15:46

Date Calculated: 28/12/2018 07:46



Addresses

Cost Summary

Total Labour	\$760.20
Total Paint/Material	\$177.18
Total Parts	\$2,450.00
Excess:	TBA
Grand Total Exc GST:	\$3,387.38
7 % GST:	\$237.12
Grand Total Inc GST:	\$3,624.50

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
Price/Dent = \$0.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
NO NUMBER	ADJUST HEADLAMPS	2.0	8.40
B100 ZAX	R + R LEFT FRONT WING (FRT BUMPER AND L/HEADLAMP ASSY REMOVED)	4.0	16.80
B110) ZAX	RENEW LEFT FRONT WING (REMOVED)	2.0	8.40
B010) ZAX	R + R FRONT BUMPER	5.0	21.00
	NOT INCLUDED: RADIATOR GRILLE R + R		
B010) ZAX	R + R FRONT BUMPER REINFORCEMENT	2.0	8.40
B030 ZAX	R + R RADIATOR GRILLE	2.0	8.40
B040) ZAX	R + R LEFT HEADLAMP (BUMPER REMOVED)	1.0	4.20
	DOES NOT INCLUDE: ADJUST HEADLAMP		
B040) ZAX	R + R HEADLAMPS	1.0	4.20
B040) ZAX	R + R XENON HEADLAMP (ADD/WORK)	1.0	4.20
B085) ZAX	R + R SCUTTLE PANEL GRILLE	4.0	16.80
	INCLUDES: R + R BOTH WIPER ARMS		
B210 ZAX	RENEW LEFT FRONT DOOR	29.0	121.80
	INCLUDES: R + R AND ALIGN LEFT FRONT DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY		
0283	REPAIR FRONT BUMPER	5.0*	21.00
1019	REPAIR L/F UPPER END PANEL	5.0*	21.00
1169	REPAIR L/UPPER WHEELHOUSE	5.0*	21.00
1487	REPAIR L/UPPER DOOR HINGE	5.0*	21.00
1495	REPAIR L/LOWER DOOR HINGE	5.0*	21.00
1551	CHECK L/F WINDOW MOTOR	5.0*	21.00
LABOUR COST			
Total Work Units		83.0	

Claim Reference:

Full Report - V1

Assessment Number: DS000534

Registration: SLB5632R

Version: SNGAHTTE/2

Printed: 28/12/2018 15:46

Date Calculated: 28/12/2018 07:46

Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	8.3HRS	\$348.60
Paint Labour	9.8HRS	\$411.60
Total Labour	18.1HRS	\$760.20

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$42.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
741	L/F WING NEW PART PAINTING	10.0	
1481	LEFT FRONT DOOR NEW PART PAINTING	18.0	
1735	L/DOOR MIRROR COVER NEW PART PAINT K1R	4.0	
283	FRONT BUMPER REPAIR PAINT PLASTIC	16.0	
1019	L/F UPPER END PANEL SURFACE PAINT	4.0	
1169	L/UPPER WHEELHOUSE SURFACE PAINT	4.0	
1565	L/F DOOR OUT HANDLE SURFACE PAINT PLAST.	3.0	
1567	L/DOOR LOCK PROTECT SURFACE PAINT PLAST.	3.0	
2219	L/F SILL MOULDING SURFACE PAINT PLAST.	3.0	
LABOUR COST - PAINT			
TIME(PAINT)		65.0	
Preparation Main Work Plastic		8.0	
Preparation Main Work Metal		25.0	
Preparation Work Multi Layer Paint		0.0	
Total Work Units (10WU/HR)		98.0	
Total Paintwork Labour		9.8HRS	\$411.60
MATERIAL COST - PAINT			Cost Price
New Part Painting			\$74.30
New Part Painting - Plastic K1R			\$4.43
Material-Constant Main Work Metal			\$28.60
Surface-/Blend Paint			\$3.48
Surface Paint Plastic			\$1.83
Repair Painting Plastic			\$51.84
Material-Const Main Work Plastic			\$12.70
Total Excluding Pearlescent Uplift			\$177.18
Pearlescent Uplift @ 0.0%			\$0.00
Total Paint Material Cost			\$177.18

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Price (\$)
561	1	LEFT HEADLAMP ASSY	81150 28D60		0% 1,080.00*
741	1	L/F WING	53812 28080		0% 180.00*
841	1	L/F WHEELHOUSE COVER	53806 28030		0% 90.00*
1481	1	LEFT FRONT DOOR	67002 28210		0% 550.00*
1647	1	L/F UPP DOOR STRIPE	75956 28030		0% 35.00*
1655	1	L/F DOOR REAR STRIP	75958 28030		0% 40.00*
1735	1	L/DOOR MIRROR COVER	87945 28060A1		0% 40.00*
1737	1	L/DOOR MIRROR	87940 28A21		0% 310.00*
1000	1	WIPER GARNISH SIDE	CVR (LH)		0% 25.00*
f: OEM Parts		Sub Total			\$2,350.00
g: Original		Mark Up From Cost		(0 %)	\$0.00

Claim Reference:

Full Report - V1

Assessment Number: DS000534

Registration: SLB5632R

Version: SNGAHTTE/2

Printed: 28/12/2018 15:46

Date Calculated: 28/12/2018 07:46

h: Secondhand	Sundry Parts	(Fixed)	\$100.00
p: Parallel	Total Parts		\$2,450.00
x: Exchange			
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER			
	Total Extras		\$0.00

Final Calculation

Total Parts		\$2,450.00
Labour		
Total Panel/Mechanical	\$348.60	
Total Paintwork	\$411.60	
Total Labour		\$760.20
Total Paint/Material Costs		\$177.18
Grand Total Excludes GST		\$3,387.38
GST @ 7 %		\$237.12
Grand Total Includes GST		\$3,624.50

Assessment Notes

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Aug 2018 Sendback Est	01 Aug 2018 10:58 S\$3,096.43	01 Aug 2018 11:22 Edit Adj Rpt	S\$3,387.38 Edit Estimates	S\$3,387.38 View Rpt		Pending for Survey Report Cancel Case
Supp #1	14 Dec 2018 16:11	14 Dec 2018 16:25 S\$410.00	14 Dec 2018 16:25			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	N/A, Co. Reg. No.: N/A								
Main Claimant:	BONG KHONG LEE, ID: 582802951								
Vehicle Reg. No.:	SLB5632R	Date of Loss:	27/07/2018 12:00 - :59 [127 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D03728C02	Policy/Cover Note No.:	DMCVSN3031051802						
Vehicle Reg. No. (Insured):	YN177D	Policy No. (Claimant):	DMPCSN3097541700						
		Excess:	S\$0.00						
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 13/08/2018]								
Adj Asg. Remarks:	EST \$3313.18, CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED									
View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLB5632R (SNM18D03728C02)
[YN177D]

TP

BONG KHONG LEE

Jul 27 2018 12:00PM

[N/A]

Sng Ah Tee Motor & Panel Service Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
View
[View in Browser](#)

Assessment Reports

1 per page



No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	30/07/18 17:15	Accident Statement	Load HTM	
2	01/08/18 10:58	Repairer Estimates	Load HTM	
3	14/12/18 16:25	Repairer Estimates Suppl. #1	Load HTM	

Photos/Images

3 per page



No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	30/07/18 17:12	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
2	30/07/18 17:12	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
3	30/07/18 17:12	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
4	30/07/18 17:12	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
5	30/07/18 17:12	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
6	30/07/18 17:14	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
7	30/07/18 17:14	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
8	30/07/18 17:14	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
9	30/07/18 17:14	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/12/18 15:58	Odometer Reading	Load JPG	☒
2	28/12/18 15:58	Chassis Number	Load JPG	☒
3	28/12/18 15:58	General View	Load JPG	☒
4	28/12/18 15:58	General View	Load JPG	☒
5	28/12/18 15:58	General View	Load JPG	☒
6	28/12/18 15:58	General View	Load JPG	☒
7	28/12/18 15:58	General View	Load JPG	☒
8	28/12/18 15:58	General View	Load JPG	☒
9	28/12/18 15:58	General View	Load JPG	☒
10	28/12/18 15:58	General View	Load JPG	☒
11	28/12/18 15:58	General View	Load JPG	☒
12	28/12/18 15:58	General View	Load JPG	☒
13	28/12/18 15:58	General View	Load JPG	☒
14	28/12/18 15:58	General View	Load JPG	☒
15	28/12/18 15:58	General View	Load JPG	☒
16	28/12/18 15:58	General View	Load JPG	☒
17	28/12/18 15:58	General View	Load JPG	☒
18	28/12/18 15:58	General View	Load JPG	☒
19	28/12/18 15:58	General View	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
20	28/12/18 15:58	General View	 Load JPG	☒
21	28/12/18 15:58	General View	 Load JPG	☒
22	28/12/18 15:58	General View	 Load JPG	☒
23	28/12/18 15:58	General View	 Load JPG	☒
24	28/12/18 15:58	General View	 Load JPG	☒
25	28/12/18 15:58	Reinspection Photo	 Load JPG	☒
26	28/12/18 15:58	Reinspection Photo	 Load JPG	☒
27	28/12/18 15:58	Reinspection Photo	 Load JPG	☒
28	28/12/18 15:58	Reinspection Photo	 Load JPG	☒
29	28/12/18 15:58	Reinspection Photo	 Load JPG	☒
30	28/12/18 15:58	Reinspection Photo	 Load JPG	☒
31	28/12/18 15:58	Reinspection Photo	 Load JPG	☒
32	28/12/18 15:58	Reinspection Photo	 Load JPG	☒
33	28/12/18 15:58	Reinspection Photo	 Load JPG	☒
34	28/12/18 15:58	Reinspection Photo	 Load JPG	☒
35	28/12/18 15:58	Reinspection Photo	 Load JPG	☒
36	28/12/18 15:58	Reinspection Photo	 Load JPG	☒
37	28/12/18 15:58	Reinspection Photo	 Load JPG	☒
38	28/12/18 15:58	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	30/07/18 17:11	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	30/07/18 17:12	IC,CI,DL [Linked Accident Report Documents]	 Load TIF	
3	01/08/18 10:59	E-filed GIA report	 Load PDF	
4	01/08/18 10:59	IC,DL,CI	 Load TIF	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	01/08/18 11:18	OI GIA	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/01/19 10:12	Parts Invoice	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	30/07/18 17:15	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	30/07/18 17:12	Accident Photo	 Load JPG	☒
2	30/07/18 17:12	Accident Photo	 Load JPG	☒
3	30/07/18 17:12	Accident Photo	 Load JPG	☒
4	30/07/18 17:12	Accident Photo	 Load JPG	☒
5	30/07/18 17:12	Accident Photo	 Load JPG	☒
6	30/07/18 17:14	Accident Photo	 Load JPG	☒
7	30/07/18 17:14	Accident Photo	 Load JPG	☒
8	30/07/18 17:14	Accident Photo	 Load JPG	☒
9	30/07/18 17:14	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print

Assessment Reports			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	30/07/18 17:11	Sketch Plan	 Load TIF	
2	30/07/18 17:12	IC,CI,DL	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118013994/T1QD3E2

Date: 24/01/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3031051802
Claimant Vehicle No :	SLB5632R	Insured Vehicle No :	YN177D
Date of Loss:	27/07/2018	Nature of Claim:	TP
		Claim No:	SNM18D03728C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB5632R	Engine No:	2AZF023281
Make & Model:	TOYOTA ESTIMA, 2.4 (A)	Chassis No:	ACR507048801
Reg. Date:	21/12/2007 (Man. Year: 2007)	Odometer:	136890 km
Colour:	Grey		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,510.00	2,450.00	60.00	2.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	996.43	937.38	59.05	5.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,506.43	3,387.38	119.05	3.40
+ GST 7.00/7.00% (S\$)	245.45	237.12	8.33	3.39
Nett Amount (S\$)	3,751.88	3,624.50	127.38	3.40

INSPECTION

Date of Assignment:	01/08/2018 Present Location:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Date Inspected:	03/08/2018 Inspected At:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18 Singapore 628457
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Jan 2019)
Parts:	M1-MPV	TOYOTA ESTIMA 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB5632R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*FRT BUMPER CLAMP KIT	Not Necessary	25.00 F	*- F
2	1	NA	*L/DOOR MIRROR COVER	Cut	350.00 F	*40.00 F
3	1	NA	*L/F DOOR CHECK	Not Necessary	60.00 F	*- F
4	1	NA	*L/F OUT BUMPER BRKT	Not Necessary	35.00 F	*- F
5	1	NA	*L/F SILL MOULDING	Not Necessary	70.00 F	*- F
6	1	NA	*L/F WHEELHOUSE COVER	Deformed	95.00 F	*90.00 F
7	1	NA	*L/F WING	Bent	175.00 F	*180.00 F
8	1	NA	*L/F WING CLAMP KIT	Not Necessary	25.00 F	*- F
9	1	NA	*L/LOWER DOOR HINGE	Repair	35.00 F	*- F
10	1	NA	*L/SIDE REPEATER LAMP	Not Necessary	45.00 F	*- F
11	1	NA	*L/UPPER DOOR HINGE	Repair	35.00 F	*- F
12	1	NA	*LEFT FRONT DOOR	Bent	550.00 F	*550.00 F
13	1	NA	*LEFT HEADLAMP ASSY	Cracked	500.00 F	*1,080.00 F
14	1	NA	*SUNDRY PARTS	Necessary	100.00 FS	*100.00 FS
Supplementary #1						
15	1		*L/F UPP DOOR STRIPE	Necessary	35.00 F	*35.00 F
16	1		*L/F DOOR REAR STRIPE	Necessary	40.00 F	*40.00 F
17	1		*L/DOOR MIRROR	Distorted	310.00 F	*310.00 F
18	1		*WIPER GARNISH SIDE	Deformed	25.00 F	*25.00 F

F=Franchise part. S=SpcNett.

Total Parts (S\$)	2,510.00	2,450.00
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Total Paint Labour	New	411.60	411.60
2	Total Paint Materials	New	177.43	177.18
3	Total Panel/Mechanical Labour	New	407.40	348.60
Gross Labour Cost (\$\$)			996.43	937.38

Report was unsubmitted during this print-out.

< END OF ESTIMATES >