

ASS. REC. BY:

REF:

CS/C718013995/Kvd3n2

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Hucng Shing Yi

of

CPI

Date/Time:

01/08/2018 @ 11:14am

Estimated Cost:

Bill to:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFB 4818A

Insured:

GBD 7832A

at Workshop m/s

City Auto

Tel:

6453 1235

of

160 San Ming Drive #05-01

Policy No:

SNM18D03740C02

Claim No:

SNM18D03740C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/07/2018

CA / REV / REP. / REV 24 HRS

(up)

Date/Time:

11:55am @ 1/8/18

Person Contacted:

Vronica

H.O.D. Endorsement:

Vehicle ☒ IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SFB 4818A - X

GBD 7832A - X

20/9 L1 R1 @ 5450 Cn firm (Real 2911.68, 3490)

ASS. REC. BY:

REF: CTZ/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

2/8 File pass to Catherine

RECEIVED 21 SEP 2010

Veh No:

SPB 4818A

Yr Regn:

10, 06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Odyssey

c.c

2354

Colour:

M. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

318510

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHMRB185064201865

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Mod:

Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

30/7/18

D.O.I.

1/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

20/9- typist

Days Of Repair:

6

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fixes

Others

Report Format:

Lump Sum / I.B.I. (\$

Merimen

5450/-

TOTAL

220



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18013995/Kvd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 01-08-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBD 7832A	Veh. Inspected	SFB 4818A
Policy No.	DMCVSN1624741002	Coverage (\$)	0.00
Claim No.	SNM18D03740C02	Excess (\$)	0.00
Assign From	MERIMEN (HWANG SHIANG YI)	Assign Date	01/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	30/07/2018	Inspection Date	01/08/2018
Survey held at	160 SIN MING DRIVE # 05-01		
Repairer	CITY AUTO PTE LTD		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Jul 2018		01 Aug 2018 11:14 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	TRIPLE S SOLID SURFACE PTE LTD, Co. Reg. No.: -			
Main Claimant:	TAN CHEE HWEE			
Vehicle Reg. No.:	SFB4818A	Date of Loss:	30/07/2018 20:00 - :59	
Claim Type:	TP / SNM18D03740C02	Policy/Cover Note No.:	DMCVSN1624741002 (Comprehensive)	
Vehicle Reg. No. (Insured):	GBD7832A	Policy No. (Claimant):		
		Excess:	S\$0.00	
Repairer:	City Auto Pte Ltd (HQ) 160 Sin Ming Drive #05-01,, Sin Ming AutoCity,, 575722 Sin Ming - Tel: 6453 1235			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Hwang Shiang Yi - 63896541]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/08/2018]			
Adj Asg. Remarks:	NO EST, ASSIGN KENNETH KONG A SJE.			

ASSOCIATED MAIL RECEIVED
[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7575A
Vehicle Details	
Vehicle No.:	SFB4818A
Vehicle to be Exported:	No
Intended De-registration Date:	02 Aug 2018
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4A
Primary Colour:	Blue
Manufacturing Year:	2006
Engine No.:	K24A63001865
Chassis No.:	JHMRB18506C201865
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$28,753.00
Original Registration Date:	11 Oct 2006
First Registration Date:	11 Oct 2006
Transfer Count:	1
Actual ARF Paid:	\$31,629.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jun 2026
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$48,479.00
COE Rebate Amount:	\$38,352.00
Total Rebate Amount:	\$38,352.00

The information contained herein is correct as at 02 Aug 2018

OK



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201807-000536(00)

Date : 31/07/2018

Vehicle No. : SFB4818A

Make/Model : HONDA ODYSSEY 2.4A

Mileage (km) : 0

Chassis No. : JHMRB18506C201865

Accident Date : 30/07/2018 00:00:00

Claim No. :

Reference :

Policy No. :

TAN CHEE HWEE

Contact : 97836205

Fax No. :

*Not authorized
L1 Pump & ?
Assembly After Paint 6 days*

S/No	Particular	Quantity	Unit Price	Amount S\$
LIST ITEMS :				
1	Tailgate	1.0	1,257.90	1,257.90 ✓
2	Rear tailgate glass	1.0	1,103.50	1,103.50 ✓
3	Tailgate moulding	1.0	200.00	200.00 ✓
4	Tailgate logo	1.0	27.60	27.60 ✓
5	Tailgate emblem - Odyssey	1.0	32.50	32.50 ✓
6	Tailgate lock	1.0	109.40	109.40 ✓
7	Tailgate sticker	1.0	28.00	28.00 X
8	Tailgate damper	2.0	155.30	310.60 X
9	Tailgate hinge	2.0	39.30	78.60 X
10	Tailgate garnish (outer)	1.0	462.70	462.70 ✓
11	Tailgate weatherstrip	1.0	121.60	121.60
12	Number plate lamp	1.0	32.80	32.80 X
13	Rear bumper	1.0	756.30	756.30 ✓
14	Rear bumper retainer	2.0	18.00	36.00 ✓
15	Rear bumper bracket	2.0	18.00	36.00 ?
16	Rear Bumper chrome LH	1.0	55.00	55.00 ✓
17	Rear Bumper clips	8.0	3.80	30.40 ✓
18	Rear bumper towing cover	1.0	16.40	16.40 ✓
19	Rear taillamp	2.0	325.50	651.00 ✓
20	Rear end panel	2.0	445.70	891.40 ?
21	Rear end panel top garnish	1.0	216.40	216.40 ✓
22	Tailgate trimboard	1.0	182.40	182.40 ✓
23	Rear wiper arm	1.0	36.50	36.50 ✓
24	Rear wiper motor	1.0	275.30	275.30 ?
25	Rear wiper blade	1.0	41.30	41.30 ✓
List Total :				6,989.60
20% Discount S\$				1,397.92
				5,591.68
SPECIAL NET :				
1	Tailgate sealant	1.0	40.00	40.00 ✓
2	Reverse sensor	1.0	350.00	350.00 ✓
3	Number plate	1.0	25.00	25.00 ✓
4	Number plate garnish	1.0	35.00	35.00 X
SPECIAL NET Total S\$:				450.00

CONTINUE NEXT PAGE



CITY AUTO PTE LTD

One-Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

TAN CHEE HWEE

Contact : 97836205

Fax No. :

Estimate : QUOT201807-000536(00)

Date : 31/07/2018

Vehicle No. : SFB4818A

Make/Model : HONDA ODYSSEY 2.4A

Mileage (km) : 0

Chassis No. : JHMRB18506C201865

Accident Date : 30/07/2018 00:00:00

Claim No. :

Reference :

Policy No. :

S/No	Particular	Quantity	Unit Price	Amount S\$
LABOUR :				
	- To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	1.0	800.00	800.00
	- Spray painting on affected & replace parts	1.0	950.00	950.00
	- To install rear windscreen glass	1.0	150.00	150.00
	- To supply panel sealant tp seal off all weld sport seam and graps	1.0	90.00	90.00
	- To check and rewiring	1.0	60.00	60.00
	- To spray under coating	1.0	120.00	120.00
	- To remove and install rear trims and upholstery	1.0	90.00	90.00
	- To install rear parking sensor	1.0	60.00	60.00
LABOUR Total S\$:				2,320.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

E. & O.E.

Total S\$: 8,361.68

GST 7% S\$: 585.32

Amount Due S\$: 8,947.00


for CITY AUTO PTE LTD



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201807-000536(00)

TAN CHEE HWEE

Date : 31/07/2018

Vehicle No. : SFB4818A

Make/Model : HONDA ODYSSEY 2.4A

Mileage (km) : 0

Chassis No. : JHMRB18506C201865

Accident Date : 30/07/2018 00:00:00

Claim No. :

Reference :

Policy No. :

Contact : 97636205

Fax No. :

*Not Authorized
C1 Imp 8545d
Penny the Paint*

S/No	Particular	Quantity	Unit Price	Amount S\$
LIST ITEMS :				
1	Tailgate	1.0	1,257.90	1,257.90
2	Rear tailgate glass	1.0	1,103.50	1,103.50
3	Tailgate moulding	1.0	200.00	200.00
4	Tailgate logo	1.0	27.60	27.60
5	Tailgate emblem - Odyssey	1.0	32.50	32.50
6	Tailgate lock	1.0	109.40	109.40
7	Tailgate sticker	1.0	28.00	28.00
8	Tailgate damper	2.0	155.30	310.60
9	Tailgate hinge	2.0	39.30	78.60
10	Tailgate garnish (outer)	1.0	462.70	462.70
11	Tailgate weatherstrip	1.0	121.60	121.60
12	Number plate lamp	1.0	32.80	32.80
13	Rear bumper	1.0	756.30	756.30
14	Rear bumper retainer	2.0	18.00	36.00
15	Rear bumper bracket	2.0	18.00	36.00
16	Rear Bumper chrome LH	1.0	55.00	55.00
17	Rear Bumper clips	8.0	3.80	30.40
18	Rear bumper towing cover	1.0	16.40	16.40
19	Rear taillamp	2.0	325.50	651.00
20	Rear end panel	1.0	445.70	445.70
21	Rear end panel top garnish	1.0	216.40	216.40
22	Tailgate trimboard	1.0	182.40	182.40
23	Rear wiper arm	1.0	36.50	36.50
24	Rear wiper motor	1.0	275.30	275.30
25	Rear wiper blade	1.0	41.30	41.30
List Total :				6,989.60
20% Discount S\$				1,397.92
				5,591.68

SPECIAL NET :

1	Tailgate sealant	1.0	40.00	40.00
2	Reverse sensor	1.0	350.00	350.00
3	Number plate	1.0	25.00	25.00
4	Number plate garnish	1.0	35.00	35.00
SPECIAL NET Total S\$:				450.00

CONTINUE NEXT PAGE

Page 1 of 2



CITY AUTO PTE LTD

One-Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel 9823 0098

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920973-4

Estimate : QUOT201807-000536(00)

Date : 31/07/2018

Vehicle No. : SFB4818A

Make/Model : HONDA ODYSSEY 2.4A

Mileage (km) : 0

Chassis No. : JHMRB18506C201865

Accident Date : 30/07/2018 00:00:00

Claim No. :

Reference :

Policy No. :

TAN CHEE HWEE

Contact : 97836205

Fax No. :

S/No	Particular	Quantity	Unit Price	Amount S\$
	LABOUR :			600
	- To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	1.0	800.00	800.00
	- Spray painting on affected & replace parts	1.0	950.00	950.00
	- To install rear windscreen glass	1.0	150.00	150.00
	- To supply panel sealant tp seal off all weld sport seam and gaps	1.0	90.00	90.00
	- To check and rewiring	1.0	60.00	60.00
	- To spray under coating	1.0	120.00	120.00
	- To remove and install rear trims and upholstery	1.0	90.00	90.00
	- To install rear parking sensor	1.0	60.00	60.00
	LABOUR Total S\$:			1,690.00 2,320.00

P- \$ 6,061.40

-20%

\$ 4,849.12

SN \$ 265.00

L \$ 1,690.00

\$ 6,804.12

-20%

\$ 5,443.30

L/S- \$ 5,450.00

6Days.

E. & O.E.

Total S\$: 8,361.68

GST 7% S\$: 585.32

Amount Due S\$: 8,947.00

for CITY AUTO PTE LTD

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18013995/KVD3N2

Date: 24/09/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1624741002
Claimant Vehicle No :	SFB4818A	Insured Vehicle No :	GBD7832A
Date of Loss:	30/07/2018	Nature of Claim:	TP
		Claim No:	SNM18D03740C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFB4818A	Engine No:	K24A63001865
Make & Model:	HONDA ODYSSEY, 2.4 (A)	Chassis No:	JHMRB18506C201865
Reg. Date:	11/10/2006 (Man. Year: 2006)	Odometer:	318510 km
Colour:	Metallic Blue		
Engine Capacity:	2354 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,041.68	5,077.64	964.04	15.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	1,720.00	600.00	25.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,361.68	6,797.64	1,564.04	18.70
Approved Total (Overridden) (\$\$)		5,450.00		
(\$\$)	8,361.68	5,450.00	2,911.68	34.82
+ GST 7.00/7.00% (\$\$)	585.32	381.50	203.82	34.82
Nett Amount (\$\$)	8,947.00	5,831.50	3,115.50	34.82

INSPECTION

Date of Assignment:	01/08/2018	
Date Inspected:	01/08/2018 Inspected At:	City Auto Pte Ltd (HQ) 160 Sin Ming Drive #05-01., Sin Ming AutoCity, Singapore 575722

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Sep 2018)
Parts:	M1-MPV	HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFB4818A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,257.90 FL	*1,257.90 FL
2	1		*REAR TAILGATE GLASS	Shattered	1,103.50 FL	*1,103.50 FL
3	1		*TAILGATE MOULDING	Necessary	200.00 FL	*200.00 FL
4	1		*TAILGATE LOGO	Necessary	27.60 FL	*27.60 FL
5	1		*TAILGATE EMBLEM-ODYSSEY	Not Necessary	32.50 FL	*- FL
6	1		*TAILGATE LOCK	Dented	109.40 FL	*109.40 FL
7	1		*TAILGATE STICKER	Repair	28.00 FL	*- FL
8	2		*TAILGATE DAMPER	Serviceable	310.60 FL	*- FL
9	2		*TAILGATE HINGE	Repair	78.60 FL	*- FL
10	1		*TAILGATE GARNISH (OUTER)	Bent	462.70 FL	*462.70 FL
11	1		*NUMBER PLATE LAMP	Serviceable	32.80 FL	*- FL
12	1		*REAR BUMPER	Buckled	756.30 FL	*756.30 FL
13	2		*REAR BUMPER RETAINER	Distorted	36.00 FL	*36.00 FL
14	2		*REAR BUMPER BRACKET	Distorted	36.00 FL	*36.00 FL
15	1		*REAR BUMPER CHROME LH	Cracked	55.00 FL	*55.00 FL
16	8		*REAR BUMPER CLIPS	Necessary	30.40 FL	*30.40 FL
17	1		*REAR BUMPER TOWING COVER	Dented	16.40 FL	*16.40 FL
18	2		*REAR TAILLAMP	Cracked	651.00 FL	*651.00 FL
19	1		*REAR END PANEL	Bent (1 Pc only)	891.40 FL	*445.70 FL
			(2Pcs)			
20	1		*REAR END PANEL TOP GARNISH	Buckled	216.40 FL	*216.40 FL
21	1		*TAILGATE TRIMBOARD	Dented	182.40 FL	*182.40 FL
22	1		*REAR WIPER ARM	Broken	36.50 FL	*36.50 FL
23	1		*REAR WIPER MOTOR	Bent/Jammed	275.30 FL	*275.30 FL
24	1		*TAILGATE SEALANT	Necessary	40.00 FS	*40.00 FS
25	1		*REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS
26	1		*NUMBER PLATE	Dented	25.00 FS	*25.00 FS
27	1		*NUMBER PLATE GARNISH	Not Necessary	35.00 FS	*- FS
28	1		*TAILGATE WEATHERSTRIP (50%)	Distorted/Cut	97.28 FS	*60.80 FS
29	1		*REAR WIPER BLADE	Missing	41.30 FL	*41.30 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,415.28	6,265.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,373.60	1,187.96
Total Parts (\$\$)	6,041.68	5,077.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK JACKOUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ACCIDENT PARTS	New	800.00	600.00
2	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	950.00	750.00
3	TO INSTALL REAR WINDSCREEN GLASS	New	150.00	120.00
4	TO SUPPLY PANEL SEALANT TO SEAL OFF ALL WELD SPORT SEAM AND GRAPS	New	90.00	30.00
5	TO CHECK AND REWRING	New	60.00	20.00
6	TO SPRAY UNDER COATING	New	120.00	60.00
7	TO REMOVE AND INSTALL REAR TRIMS AND UPHOLSTARY	New	90.00	90.00
8	TO INSTALL REAR PARKING SENSOR	New	60.00	50.00
Gross Labour Cost (S\$)			2,320.00	1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >