

ASS. REC. BY

REF

CS/FCI/8014008/N/d312

Special Instruction:

Surveyor
CWS

Na2

ASSIGNMENT (Office)

From (Person):

Sarena Ler

of

FCI

Date/Time

31/7/18 @ 6:51pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLJ 6310X

Insured:

SH 9609T

at Workshop m/s

World Auto

Tel:

6362 1776

of

No. 1, Krunji Loop

Policy No:

Claim No:

D18 005785MFSTH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/07/2018

CA / REV / REP. / REV 24 HRS Cup

H.O.D. Endorsement:

Date/Time:

01/08/2018

Person Contacted:

Ainee

Vehicle

IN OUT

Date/Time

Action/Instruction (✓) Estimate

SLJ 6310 X - CCB / LCR / 7014487 / 8p43q2 DOA: 23/7/2017

SH 9609T - CS/FCI/6019942/R/ybm2 DOA: 14/10/16

6/8-

Revert via email preli advice.

Part by Part \$3001.20 (Red: 1166.27%)

Surveyor

082

REF:

FCI

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLJ 6310X Yr Regn: 19 DEC 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA SHUTTLE HYBRID cc 1,496

Colour: SILVER A/C: Insured Std / NI / NA

Sp. Reading: 122,417 T/Radio: Insured Std / NI / NA

Eng/No: _____

C/No: GP 71046160

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or PIRELLI (CF) GITI (CR)

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 28/7/18 D.O.I. 1/8/18

Survey held at WORLD AUTO

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FRONT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

FCI P/P

RECEIVED 15 OCT 2018

Date/Time, File Pass to?

☐ : Preli. Report

1) 15/10 Typist

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

) \$ + RS, \$

) Photos

) Others

)

TOTAL

Report Format :

Lump Sum / P.B.I. (\$) 3001.20

135

50

12

197



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18014008/Ntd3

36 ROBINSON ROAD
#16-01 CITY HOUSES SINGAPORE 068877

Date : 01-08-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 9609T	Veh. Inspected	SLJ 6310X
Policy No.		Coverage (\$)	0.00
Claim No.	D18007851MFSH	Excess (\$)	0.00
Assign From	CWS (SEREE LER)	Assign Date	01/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	28/07/2018	Inspection Date	01/08/2018
Survey held at	WORLD AUTO PTE LTD 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG SINGAPORE 577200		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007851MFSH

Date: 6/8/2018

Our Ref: CS/FCI18014008/Ntd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLJ 6310X

Please be informed that we had conducted the inspection of the abovementioned vehicle
1/8/2018 at the premises of M/s World Auto and have the following to report: -

Workshop Estimate Amount	: S\$ <u>4,167.20</u>
Revised Estimate Amount	: S\$ <u>2,951.20</u>
"Check" Items Amount	: S\$ <u>192.00</u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the
o/s front portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Naz

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	31-07-2018	Our Ref No.	D18005785MFSH
Accident Date	28-07-2018	Claim Type.	Third Party
Insured Vehicle	SH9609T	Third Party Vehicle.	SLJ6310X
Survey Location	NO.1, KRANJI LOOP		
Contact Person.	AINEE		
Contact No.	63621776/ 0	Fax No.	63631250
Survey Type	WITHOUT PREJUDICE: NO EST. PROVIDED		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WORLD AUTO PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	SERENE		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242886)



PRI Documents



Close



PRI Header Details

Claim No	D18005785MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & WORLD A LTD / WEE PO
Workshop Name	WORLD AUTO PTE LTD (Contact Person : AINEE)	Survey Location & Contact Details	NO.1, KRANJI LOOP Mobile: 0 , Phone: 63621776 , Fax: 63631250 EmailId: AINEE31@WORLD AUTO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: NO EST. PROVIDED		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH9609T	TP Vehicle No	SLJ6310X
PRI Recieved Date	31-07-2018 06:16:52 PM	Surveyor Appointed Date	31-07-2018 06:50:10 PM	Surveyor Accept Date	01-08-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	01-08-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 6 August 2018 5:14 PM
To: 'Claim Workflow System'
Cc: assignments; 'CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG'; 'Serene Ler'; SUR
Subject: RE: SURVEY ASSESSMENT - D18005785MFSH/1
Attachments: PRELI ADVISED SLJ 6310X.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLJ 6310X**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 6 August 2018 4:58 PM
To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Subject: FW: SURVEY ASSESSMENT - D18005785MFSH/1

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 31 July 2018 6:51 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005785MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.


Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

Sketch Plan #3



WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

FIRST CAPITAL INSSURANCE LIMITED

80 ROBINSON RD #09-02/03

068898

Attention : Motor Claim Department

Contact : 6222 2311 Fax No. : 6222 3547

Estimate : ES000258

Date : 31/07/2018

Vehicle Num. : SLJ 6310X (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 28/07/2018

Claim No. :

Reference :

Policy No. :

Reg Date

Dec 2016

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	FRONT FENDER - RH	550.00	DT
2.	1	FRONT FENDER HYBRID EMBLEM RH	89.00	NR
3.	1	FRONT FENDER UNDER DUST COVER - RH	250.00	BYC
4.	1	FRONT DOOR - RH	1,200.00	BT
5.	1	FRONT DOOR HINGE UPPER RH	120.00	2X SUL
6.	1	FRONT DOOR HINGE LOWER RH	120.00	2X SUL
7.	1	SIDE SKIRT RH	430.00	X R

List Total S\$:

2,759.00

20.00% Discount S\$:

551.80

2,207.20

SPECIAL NETT ITEMS :				
1.	1	FRONT FENDER UNDER DUST COVER CLIPS	40.00	ALL
2.	1	SIDE SKIRT CLIPS	40.00	REC

Special Nett Total S\$:

80.00

LABOUR :

TRANSFER DOOR MECHANISM

180.00 X 50

LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.

900.00 600

PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/ OUTER)

800.00 600

Labour Total S\$:

1,880.00

E. & O.E.

Total S\$: 4,167.20

=====

for WORLD AUTO PTE LTD

LKK Auto Consultants
the Repairer of the following
• To resurvey before/after spray paint
• To display damaged part(s) during survey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be approved
is subject to final approval from LKK Auto Consultants

Acknowledged by Repairer

Signature

NAZ LKK

1/8/18 1520

P/P

4 DAYS

BEFORE PAINT PHOTO



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18014008/Ntd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 19-10-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 9609T	Veh. Inspected	SLJ 6310X	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18005785MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	31/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE HYBRID	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	GP71046160	Colour	SILVER	
Odometer	122417	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	PIRELLI	5 mm	
L/H Front Tyre	185/60 R15	PIRELLI	5 mm	
R/H Rear Tyre	185/60 R15	GITI	5 mm	
L/H Rear Tyre	185/60 R15	GITI	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/07/2018	Inspection Date	01/08/2018	
Survey held at	WORLD AUTO PTE LTD 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG SINGAPORE 577200			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 6310X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER-RH	DENTED	550.00	550.00
1	FRONT FENDER HYBRID EMBLEM RH	NECESSARY	89.00	89.00
1	FRONT FENDER UNDER DUST COVER-RH	BUCKLED	250.00	250.00
1	FRONT DOOR-RH	BENT	1,200.00	1,200.00
1	FRONT DOOR HINGE UPPER RH	SERVICEABLE	120.00	-
1	FRONT DOOR HINGE LOWER RH	SERVICEABLE	120.00	-
1	SIDE SKIRT RH	TO REPAIR SEE LABOUR	430.00	-
	LESS 20% DISCOUNT		-551.80	-417.80
			2,207.20	1,671.20
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT FENDER UNDER DUST COVER CLIPS (SN)	NECESSARY	40.00	40.00
1	SIDE SKIRT CLIPS (SN)	NECESSARY	40.00	40.00
			80.00	80.00
	<u>LABOUR</u>			
	TRANSFER DOOR MECHANISM.		180.00	50.00
	LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT,CUT/WELD,STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.INCLUSIVE OF THE REPAIR OF SIDE SKIRT RH.		900.00	600.00
	PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER).		800.00	600.00
			1,880.00	1,250.00
	GRAND TOTAL		4,167.20	3,001.20
RECOMMENDED COST OF REPAIRS				3,001.20

Report Ref No. CS/FCI18014008/Ntd3n2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.