

ASS. REC. BY:

REF: CS/MSG18014017/Ktd342

Special Instruction:

Survivor
merimen

Kenneth

ASSIGNMENT (Office)

From (Person):

Elaine Ngu

of

MSG

Date/Time:

1/8/18 @ 3:04pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 902

Insured:

SAR 3850R

at Workshop m/s

Transcarb

Tel:

6287 6666

of

No. 2 Amk St 63

Policy No:

A29069232 QMX

Claim No:

565995

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/07/2018

CA / REV / REP. / REV 24 HRS

lup

2/8/2018

H.O.D. Endorsement:

Date/Time:

5:29pm @ 1/8/2018

Person Contacted:

Candy

Vehicle ☒ IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SHD 902 - NA / MSG18013766 / K1

DOA: 27/7/18

SAR 3850R - NA / MSG18013766 / K1

DOA: 27/7/18

3/8/18

Report via merimen

lump sum \$25,000 (Red: 102671.12, 80%)

REF: MSTH

Medimen

ASSIGNMENT

From Date: 02082018

Estimated Cost:

QD ☒ TP / WS / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No:

SHD 90Z

at Workshop no:

Trans Gab

of

No - 2 NMK St 63

Insured

Policy No:

Claims No:

Sum Insured

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

Arond 871k

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res: Yes or No

Lum Sum:

1-B, %

3 Val Yes or No

CA / REV / REP. / 24 HRS

Date

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 90Z 08 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude 1993

Colour:

M. White / Red

A/C Insured / Std / NI / NA

Sp Reading:

175395

T/Ratio Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABL15AUC 283229

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Giti

Front

Rear

R/Bal:

9

mm

R/Bal:

9

mm

L/Bal:

9

mm

L/Bal:

9

mm

D.O.A:

27/7/18

D.O.I:

2/8/18

Survey held at

Des. of Damages: Frt / Rear / Q/S / N/S / U/C / Rooftop or

& 1st

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

3/8 File new to note

RECEIVED 11 APR 2019

10/4/2019

Case/Time, File Pass to?

10/4 Typist

Case/Time, File Return to?

Q

Report Format

Lump Sum / L.B. / L.S.



Preli. Report

Final Report

Days Of Repair:

19

Resurvey No. of Trip:

1

Add Fee:



Site Trip \$

Interview \$

Field work \$

Workshop \$

Survey Fee

Transport

1 - 2 - 3 - 4

1 - 2 - 3 - 4

1 - 2 - 3 - 4

1 - 2 - 3 - 4

300

10

30



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18014017/td3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 01-08-2018	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGR 3850R	Veh. Inspected	SHD 90Z	
Policy No.	A29069232QMX	Coverage (\$)	0.00	
Claim No.	565995	Excess (\$)	0.00	
Assign From	MERIMEN (ELAINE NGU)	Assign Date	01/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	27/07/2018	Inspection Date		
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jul 2018		01 Aug 2018 15:04 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MOH SWEE PING, ID: S0185195J, Tel: +6590092612, Email: YIKANGMOH@GMAIL.COM		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHD90Z	Date of Loss:	27/07/2018 16:00 - :59 [22 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 565995	Policy/Cover Note No.:	A29069232QMX (TP, Fire & Theft) Coverage: 07/02/2018 - 06/02/2019
Vehicle Reg. No. (Insured):	SGR3850R	Policy No. (Claimant):	
		Excess:	
Repairer:	Trans-cab Auto Services Pte Ltd () No 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Imm.Advice due 02/08/2018]		
Driver/Custodian (Insured):	MOH SWEE PING (64 / Male), NRIC: S0185195J, Tel: +6590092612		
Adj Asg. Remarks:	URGENT! Car is in, survey by today. Please contact us ASAP if you are not able to attend this assignment. liability: 100% (chain collision) contact: Loong - 6213 0998		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Friday, 5 April 2019 1:49 PM
To: Denise Tay (LKKAUTO)
Subject: RE: SHD 90Z / TP - MSIG / DOA: 27/07/18 -- AAD1807-271
Attachments: AAD1807-271 - ESTIMATE MARKING.pdf

Hi Denise

We submit LOD amount for COR is \$ 25,000.00 (before GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Wednesday, 3 April, 2019 9:43 AM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Subject: SHD 90Z / TP - MSIG / DOA: 27/

Dear Wai Yin,

Update status, finalized.

Best Regards,
Denise Tay | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHD90Z
Vehicle to be Exported:	No
Intended De-registration Date:	03 Aug 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C003170
Chassis No.:	VF1ABL15AUC283229
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	31 Aug 2016
First Registration Date:	31 Aug 2016
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Aug 2024
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	
COE Expiry Date:	30 Aug 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$41,215.00
COE Rebate Amount:	\$31,285.00
Total Rebate Amount:	\$46,283.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 03 Aug 2018

OK

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 03 Aug 2018

Preliminary Advice

Insured Vehicle No	: SGR3850R	Accident Date	: 27/07/2018
TP Vehicle No	: SHD90Z	Assignment Date	: 01/08/2018
Make	: RENAULT LATITUDE	Est. Duration of Repair	: 19.00
Date of Inspection	: 02/08/2018		
Inspection At	: TRANS-CAB AUTO SERVICES PTE LTD NO 2 ANG MO KIO STREET 63 SINGAPORE 569111		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear, front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	127,671.12
Revised Amount	:S\$	31,226.04
Check Items (Estimated)	:S\$	0.00
Total	:S\$	31,226.04

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/07/2018 13:30
Date Of Accident	27/07/2018 17:00
Exact Location Of Accident	BRAS BASAH ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD90Z
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	KANG KHENG LONG
NRIC No	S1141698E
Date Of Birth	07/08/1955
Occupation	OUTDOOR
Date Of Driving Pass	21/03/1973
Driving Experience	45 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96613544
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	BLK 102A PUNGGOL FIELD #17-436
Postcode	821102
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	PUNGGOL N.P.C
Police Station Address	ROAD: 21A TEBING LANE , POSTCODE: 828837 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Please refer to police report

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE SIZE IS TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGR3850R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MOH SWEE PING
NRIC/Passport Number	S0185195J
Contact Number	90092612

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SJH881M

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

TAN KHEN BOON

NRIC/Passport Number

S7620648A

Contact Number

98236466

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

KANG KHENG LONG

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SHD90Z

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the internal cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

A= SHD902
B= SHR3850R
C= SJH811m
Bras Basah Road

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Good refer to Police Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
SRC/TIN No:



**SINGAPORE
POLICE FORCE**



T/20180728/2073

1 of 4

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 628837
Tel No: 1800-6049999

Report No. T/20180728/2073

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/07/2018 15:19		Vide Report No.:		Station Diary No.: 72	
Informant's Particulars					
Name of Informant: KANG KHENG LONG			Address: APT BLK 102A PUNGGOL FIELD #17-436 SINGAPORE 821102		
ID Type / ID No.: NRIC NO / S1141698E			Contact No.: Home/Office: Mobile: 96613544		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 62	Date of Birth: 07/08/1955	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 27/07/2018 17:00	Type of Location: Straight Road
Location: Along Road 1 BRAS BASAH ROAD ALONG BRAS BASAH ROAD BEFORE WATERLOO STREET				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 50 Km/h	
Traffic Flow: Dual Carriage Way		Traffic Control: Pedestrian Crossing	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SGR3850R	Car				Seriously Damaged	0
SHD90Z	Car				Seriously Damaged	1
SJH881M	Car				Seriously Damaged	0



**SINGAPORE
POLICE FORCE**



T/20180728/2073

2 of 4

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

Report No. T/20180728/2073

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	KANG KHENG LONG	ID No.	S1141698E
Related Vehicle	SHD90Z (Car)	Contact No.	96613544
Hospital/Clinic	TRINITY MEDICAL (PUNGGOL)	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	27/07/2018	Date Discharge	27/07/2018
No. of Days granted Medical Leave	05	Degree of Injury	Slight
Driver			
Name	TAN KHIEH BOON	ID No.	S7620648A
Related Vehicle	SJH881M (Car)	Contact No.	98236466
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	MOH SWEE PING	ID No.	S0185195J
Related Vehicle	NIL SGR3850R	Contact No.	90092612
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 27/07/2018 at around 1700hrs, I was driving my taxi bearing registration number SHD90Z along Bras Basah Road heading towards Victoria Street. I was travelling on the centre lane and noticed the vehicle in front of me bearing registration number SJH881M slowing down. I immediately slowed down my vehicle and subsequently felt and impact at the rear of my vehicle. The impact caused me to hit the rear of the vehicle in front of me. I then alighted from the vehicle and noticed that a vehicle bearing registration number SGR3850R had hit on the rear of my taxi. The impact also caused the vehicle's air bag to be deployed. I then exchanged particulars with the other drivers. The vehicle that rear ended me spoke something about the incident but I did not catch what he mentioned. I then decided to seek treatment at



**SINGAPORE
POLICE FORCE**



T/20180728/2073

3 of 4

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-8049999

Report No. T/20180728/2073

CONTINUATION OF REPORT

the clinic as I felt pain around my neck and shoulder joint area and was given 5 days of MC. My taxi suffered damages to the front bumper and rear bumper area.



**SINGAPORE
POLICE FORCE**



T/20180728/2073

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-8049999

4 of 4

Report No. T/20180728/2073

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Staff Sgt MUHAMMAD AQIB BIN MOHAMMAD AKHTAR	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 28/07/2018 15:19
Officer In Charge Of Case: TP / AEIT / SI DZUL HAIRIE BIN RAMLI Contact No.: 55476220	Classification Of Case:
Authentication Stamp NP168	

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD90Z
Vehicle to be Exported:	Yes
Intended De-registration Date:	30 Jul 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C003170
Chassis No.:	VF1ABL15AUC283229
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	31 Aug 2016
First Registration Date:	31 Aug 2016
Transfer Count:	0
Actual ARF Paid:	\$19,998.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Aug 2024
PARF Rebate Amount:	\$14,998.00

Intended COE Rebate Details

COE Expiry Date:	30 Aug 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$41,215.00
COE Rebate Amount:	\$31,340.00
Total Rebate Amount:	\$46,338.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 30 Jul 2018

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 90Z

AAD1807-271

*Not Authored
L/Sing &*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 90Z

VF1ABL15AUC283229

RENAULT

LATITUDE

27.7.2018

MSIG**PART****LIST**

1	1 BUMPER COVER REAR	\$	R ₁ 1,108.46	—
2	1 BUMPER LOWER REAR	\$	PRD17 768.84	—
3	1 BUMPER BRACKET CTR REAR	\$	CM 113.47	—
4	1 BUMPER BRACKET SIDE RH REAR	\$	SL 135.97	X
5	1 BUMPER RETAINER RH REAR	\$	SL 44.99	X
6	1 BUMPER REFLECTOR RH	\$	SL 43.61	X
7	1 BUMPER BRACKET SIDE LH REAR	\$	DI 135.97	—
8	1 BUMPER RETAINER LH REAR	\$	CM 44.99	—
9	1 BUMPER REFLECTOR LH	\$	BR 43.61	—
10	1 BUMPER BEAM REAR	\$	R ₁ 777.52	—
11	1 BUMPER BEAM BRACKET LH REAR	\$	R ₁ 225.95	—
12	1 BUMPER BEAM BRACKET RH REAR	\$	DI 225.95	—
13	1 BOOT REAR	\$	R ₁ 2,872.68	—
14	1 BOOT FINISHER	\$	SL 470.06	X
15	1 BOOT WHEATERSTRIP	\$	LM 323.05	—
16	1 BOOT REFLECTOR LAMP LH	\$	SL 493.35	✓
17	1 BOOT REFLECTOR LAMP RH	\$	SL 493.35	X
18	1 BOOT BADGE 'RENAULT'	\$	RM 225.36	—
19	1 BOOT BADGE	\$	RM 225.36	—
20	1 BOOT STRUT LH	\$	SL 276.08	} X
21	1 BOOT STRUT RH	\$	SL 276.08	
22	1 BOOT HINGE LH	\$	R 367.84	
23	1 BOOT HINGE RH	\$	R 367.84	
24	1 BOOT INNER TRIM	\$	SL 586.45	
25	1 BOOT SWITCH	\$	SL 168.13	
26	1 BOOT LOCK	\$	R 202.67	
27	1 BOOT LOCK CATCH	\$	R 74.40	}
28	2 LICENCE PLATE LAMP	\$	SL 50.52	
29	2 BOOT RUBBER PLUG	\$	SL 221.81	

Trans-cab Auto Services Pte Ltd**AAD1807-271**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 90Z

30	1 DOOR PANEL REAR LH	\$	R	2,844.66	X
31	1 FENDER PANEL INNER TRIM REAR LH	\$	Sn	671.45	X
32	1 FENDER PANEL REAR LH	\$	Bu	3,299.13	✓
33	1 WHEELARCH REAR LH	\$	Sn	543.47	X
34	1 FENDER PANEL INNER TRIM REAR RH	\$	Sn	671.45	X
35	1 FENDER PANEL REAR RH	\$	R	3,299.13	X
36	1 WHEELARCH REAR RH	\$	Sn	543.47	X
37	1 TAILLAMP RH	\$	Sn	552.55	X
38	1 TAILLAMP PANEL RH	\$	R	986.70	✓
39	1 TAILLAMP LH	\$	m31M	552.55	✓
40	1 TAILLAMP PANEL LH	\$	R	986.70	✓
41	1 OUTER PANEL REAR (End Panel)	\$	R	1,471.77	✓
42	1 OUTER PANEL REAR (End Panel)TRIM	\$	CM	404.56	✓
43	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	BT1Bu	2,189.88	✓
44	1 SPARE WHEEL PANEL TRIM	\$	Sn	612.21	X
45	1 EXHAUST REAR	\$	R	7,489.05	X
46	1 EXHAUST CAP REAR	\$	R	230.49	X
47	1 FUEL FLAP L70Y	\$	Sn	343.57	X
48	1 WHEEL HOUSING PANEL REAR LH	\$	R	4,682.09	X
49	1 CHASSIS PANEL REAR LH L70Y	\$	R	3,766.43	X
50	1 CHASSIS PANEL REAR RH L70Y	\$	R	3,766.43	X
51	1 BUMPER COVER FRT	\$	Bu	1,259.42	✓
52	1 BUMPER SPOILER FRT	\$	D.Y	181.75	✓
53	1 BUMPER ABSORBER FRT	\$	CM	394.68	✓
54	1 BUMPER RETAINER FRT LH	\$	Sn	151.41	X
55	1 BUMPER SUPPORT FRT	\$	Sn	123.88	X
56	1 BUMPER RETAINER FRT RH	\$	Sn	150.77	X
57	1 BUMPER SUPPORT FRT	\$	Sn	123.88	X
58	1 BUMPER UNDERTRAY FRT	\$	CM	472.83	✓
59	1 BUMPER GRILLE LOWER FRT	\$	Sn	266.80	X
60	1 BUMPER FOG LAMP GRILLE LH	\$	Sn	207.21	X
61	1 BUMPER FOG LAMP GRILLE RH	\$	Sn	207.21	X
62	1 BUMPER BEAM FRT	\$	R	914.08	✓
63	1 TOW COVER FRT	\$	Sn	28.61	X
64	1 RADIATOR GRILLE	\$	CM	1,707.78	✓
65	1 RADIATOR GRILLE BADGE 'RENAULT'	\$	Ad	225.36	✓
66	1 RADIATOR GRILLE FRAME	\$	CM	1,353.75	✓
67	1 FRAME FULL SUPPORT PANEL	\$	CM	615.90	✓
68	1 FRAME FULL SUPPORT BRACKET	\$	R	89.79	X

Trans-cab Auto Services Pte Ltd**AAD1807-271**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 90Z

69	1 FRONT BRACE PANEL	\$	R 177.22	✓
70	1 HORN	\$	Sm 314.17	X
71	1 HORN BRACKET	\$	R 40.45	X
72	1 HEADLAMP LH	\$	mgcm 1,184.43	—
73	1 HEADLAMP RH	\$	mg D. 1,184.43	—
74	1 HEADLAMP PANEL FRT LH	\$	R 152.15	}
75	1 HEADLAMP PANEL FRT RH	\$	R 152.15	
76	1 BONNET	\$	R 1,941.63	
77	1 BONNET INSULATOR	\$	Sm 405.73	
78	1 BONNET STRUT LH	\$	Sm 88.61	
79	1 BONNET STRUT RH	\$	Sm 88.61	
80	1 BONNET HINGE LH	\$	R 348.31	
81	1 BONNET HINGE RH	\$	R 348.31	
82	1 BONNET LOCK	\$	R 305.48	
83	1 BONNET CABLE	\$	Sm 119.19	
84	1 BONNET CABLE COVER	\$	Sm 161.03	
85	1 BONNET SEAL OUTER	\$	Sm 92.36	
86	1 BONNET SEAL INNER	\$	Sm 157.28	
87	1 FENDER PANEL FRT LH	\$	R 783.83	
88	1 WHEELARCH FRT LH	\$	Sm 278.84	
89	1 FENDER BRACKET LOWER LH	\$	R 15.79	
90	1 FENDER INSULATOR LH	\$	Sm 130.84	
91	1 FENDER INSULATOR RH	\$	Sm 130.84	
92	1 AIR CLEANER LOWER	\$	Sm 271.26	
93	1 AIR CLEANER HOSE	\$	Sm 76.14	
94	1 BASE BATTERY TRAY	\$	Sm 363.40	
95	1 AIR CLEANER BOX	\$	Sm 464.20	
96	1 TURBO DUCT	\$	Sm 1,027.80	
97	1 A/C HEATER VALVE	\$	Sm 484.50	
98	1 SUBFRAME OUTER FRT	\$	Sm 2,652.45	
99	1 SUBFRAME BRACKET OUTER LH	\$	Sm 92.36	
100	1 ENGINE UNDERTRAY	\$	Sm 564.98	
101	1 A/C CONDENSER	\$	R 2,020.37	✓
102	1 A/C CONDENSER GARNISH LH UPPER	\$	Sm 39.67	}
103	1 A/C CONDENSER GARNISH RH UPPER	\$	Sm 39.67	
104	1 A/C CONDENSER GARNISH LH	\$	Sm 58.81	
105	1 A/C CONDENSER GARNISH RH	\$	Sm 59.60	
106	1 A/C PIPE CONDENSER TO COMPRESSOR	\$	Sm 208.39	X

Trans-cab Auto Services Pte Ltd

AAD1807-271

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 90Z

107	1 A/C PIPE CONDENSER TO EXPENSION VALVE	\$	Sh 658.72	}
108	1 A/C PIPE COMPRESSOR	\$	Sh 334.29	
109	1 A/C PIPE	\$	Sh 658.72	
110	1 A/C COMRPRESSOR	\$	Sh 2,684.61	
111	1 AIR COOLER	\$	Sh 792.60	
112	1 AIR INTERCOOLER HOSE (LONG)	\$	Sh 1,014.13	
113	1 AIR INTERCOOLER HOSE (Short)	\$	Sh 375.14	
114	1 TRANSMISSION COOLER	\$	Sh 1,219.30	
115	1 TRANSMISSION COOLER PAD	\$	Sh 17.96	
116	1 RADIATOR	\$	Sh 1,202.20	
117	2 RADIATOR STUD UPPER	\$	Sh 14.41	
118	2 RADIATOR BUSH UPPER	\$	Sh 50.12	
119	2 RADIATOR MTG LOWER	\$	Sh 55.85	
120	1 RADAITOR FAN COWLING	\$	Sh 820.54	
121	1 RADIATOR FAN MOTOR LH	\$	Sh 967.36	
122	1 RADIATOR FAN MOTOR RH	\$	Sh 1,479.46	
123	1 RADIATOR TANK	\$	Sh 324.62	
124	1 RADIATOR HOSE UPPER	\$	Sh 240.56	
125	1 RADIATOR HOSE LOWER	\$	Sh 491.18	
126	1 RADIATOR TANK HOSE	\$	Sh 61.18	
127	1 AUTO COMPUTER	\$	Sh 5,032.17	} X
128	1 INJECTION COMPUTER	\$	Sh 4,706.30	
129	1 RHD HYDRAULIC POWER(ROCK&PINION)	\$	Sh 5,154.52	
130	1 STEERING PUMP ELECTRIC L70Y	\$	Sh 2,306.90	
131	1 STEERING PINION RACK L70Y	\$	Sh 4,413.11	

TOTAL	\$	111,848.45
10%	\$	11,184.84
	\$	100,663.60

Special Nett

1 1SET PARKING AID	\$	Short 700.00 600.00
2 1SET REAR BUMPER CLIP	\$	na 66.00 —
3 1SET BUMPER BRACKET CTR CLIP	\$	na 33.00 —
4 1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na 10.00 X
5 1SET BUMPR RETAINER RH CLIP RR	\$	na 20.00 X
6 1SET BUMPR BRACKET SIDE CLIP LH RR	\$	na 10.00 X

Trans-cab Auto Services Pte Ltd**AAD1807-271**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 90Z

7 1SET BUMPR RETAINER CLIP LH RR	\$	na	20.00	X
8 1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9 1SET BUMPER LOWER REAR CLIP	\$	na	66.00	X
10 1 EXHAUST MOUNTING REAR	\$	na	17.82	X
11 1SET BOOT FINISHER CLIP	\$	na	24.20	X
12 1 BOOT STICKER "Trans-cab"	\$	na	30.00	—
13 1 BOOT STICKER "6555-3333"	\$	na	30.00	—
14 1 BOOT INNER TRIM CLIP	\$	na	45.00	X
15 1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	X
16 1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	X
17 1 FENDER INNER TRIM CLIP LH	\$	na	28.00	X
18 1 FENDER INNER TRIM CLIP LH	\$	na	28.00	X
19 1 TAILLAMP CLIP RH	\$	na	5.00	X
20 1 TAILLAMP CLIP LH	\$	na	5.00	—
21 2 REAR WINDSCREEN SELANT	\$	na	80.00	405A
22 1 WINDSCREEN MOULDING	\$	na	100.00	—
23 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	305A
24 1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	na	385.00	X
25 1 SPARE TYRE	\$	na	330.00	X
26 1SET RADIATOR GRILLE FRAME CLIP	\$	na	52.00	—
27 1SET BUMPER CLIP FRT	\$	na	66.00	—
28 1 BUMPER BRACKET CLIP FRT LH	\$	na	12.00	} X
29 1 BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	
30 1 BUMPER BRACKET CLIP FRT RH	\$	na	12.00	
31 1 BUMPER SUPPORT CLIP FRT RH	\$	na	10.50	
32 1 TOW COVER FRT	\$	na	14.50	
33 1SET RADIATOR GRILLE SCREW	\$	na	16.00	
34 1SET BUMPER GRILLE LOWER CLIP	\$	na	69.00	
35 1SET FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	
36 2 FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	} 455A
37 2 FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	
38 1 Windscreen moulding	\$	na	100.00	
39 1SET Front licence plate with holder	\$	na	80.00	

TOTAL \$ 2,787.52**TOTAL PARTS \$ 103,451.12**

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 90Z**AAD1807-271****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	9,000.00	15401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	25001
To Rust-Proofing Of The Affected Areas.	\$	170.00	1201
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	170.00	} 801
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 1001
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	801
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	1201
To check steering geometry and computer wheel alignment	\$	220.00	601

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 90Z**AAD1807-271**

To transfer of rear door fittings, attachment and perform water seepage test.	\$	nn	380.00	X
Towing Fees.	\$		120.00	501
To apply paint protection system (PPS) maintain and enhancement	\$	nn	380.00	X
To rust-proofing of the affected areas.	\$	Agun	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
To check steering geometry and computer wheel alignment	\$	4	220.00	X
To transfer of tire, rim and on wheel balancing.	\$	4	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	401
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$		380.00	} 2501
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$		380.00	
To lift-up engine with gear box and refit.	\$	nn	440.00	X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	4	440.00	X
To remove and refit air bag system and reset.	\$	4	480.00	X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	4	380.00	X

Trans-cab Auto Services Pte Ltd**AAD1807-271**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 90Z

To vacuum, replace, refix and recharge air condenser	\$	380.00	100
To replace, refix and top up coolant for radiator	\$	170.00	50
To vacuum, replace, refix and recharge Air Intercooler	\$	~ 170.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	~ 170.00	X

TOTAL \$ 24,220.00**Over All Total \$ 127,671.12****(LUMP SUM)****Repair Days****30 DAYS****18 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jul 2018		01 Aug 2018 15:04 Edit Adj Rpt	S\$25,000.00 Edit Estimates	S\$25,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	MOH SWEE PING, ID: S0185195J, Tel: +6590092612, Email: YIKANGMOH@GMAIL.COM								
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K								
Vehicle Reg. No.:	SHD90Z	Date of Loss:	27/07/2018 16:00 - :59 [22 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 565995	Policy/Cover Note No.:	A29069232QMX (TP, Fire & Theft) Coverage: 07/02/2018 - 06/02/2019						
Vehicle Reg. No. (Insured):	SGR3850R	Policy No. (Claimant):							
		Excess:							
Repairer:	Trans-cab Auto Services Pte Ltd () No 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 31/08/2018]								
Driver/Custodian (Insured):	MOH SWEE PING (64 / Male) , NRIC: S0185195J, Tel: +6590092612 Email: YIKANGMOH@GMAIL.COM								
Adj Asg. Remarks:	URGENT! Car is in, survey by today. Please contact us ASAP if you are not able to attend this assignment. liability: 100% (chain collision) contact: Loong - 6213 0998								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHD90Z (565995)
[SGR3850R]
TP
TRANS-CAB SERVICES PTE LTD
Jul 27 2018 4:00PM
[MOH SWEE PING]
Trans-cab Auto Services Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page		☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail	Print	
1	31/07/18 15:25	Accident Statement From: SC - Reg. No: SGR3850R, Claimant: MOH SWEE PING							Load HTML		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	03/08/18 12:33	Adjuster Immediate Advice							Load HTML		
Photos/Images									3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	11/04/19 09:06	General View							Load JPG	☒	
2	11/04/19 09:06	General View							Load JPG	☒	
3	11/04/19 09:06	General View							Load JPG	☒	
4	11/04/19 09:06	General View							Load JPG	☒	
5	11/04/19 09:06	General View							Load JPG	☒	
6	11/04/19 09:06	General View							Load JPG	☒	
7	11/04/19 09:06	General View							Load JPG	☒	
8	11/04/19 09:06	General View							Load JPG	☒	
9	11/04/19 09:06	General View							Load JPG	☒	
10	11/04/19 09:06	General View							Load JPG	☒	
11	11/04/19 09:06	General View							Load JPG	☒	
12	11/04/19 09:06	General View							Load JPG	☒	
13	11/04/19 09:06	General View							Load JPG	☒	
14	11/04/19 09:06	General View							Load JPG	☒	
15	11/04/19 09:06	General View							Load JPG	☒	
16	11/04/19 09:06	General View							Load JPG	☒	
17	11/04/19 09:06	General View							Load JPG	☒	
18	11/04/19 09:06	General View							Load JPG	☒	
19	11/04/19 09:06	General View							Load JPG	☒	
20	11/04/19 09:06	General View							Load JPG	☒	
21	11/04/19 09:06	General View							Load JPG	☒	
22	11/04/19 09:06	General View							Load JPG	☒	
23	11/04/19 09:06	General View							Load JPG	☒	
24	11/04/19 09:06	General View							Load JPG	☒	
25	11/04/19 09:06	General View							Load JPG	☒	
26	11/04/19 09:06	General View							Load JPG	☒	
27	11/04/19 09:06	General View							Load JPG	☒	
28	11/04/19 09:06	General View							Load JPG	☒	
29	11/04/19 09:06	General View							Load JPG	☒	
30	11/04/19 09:06	General View							Load JPG	☒	
31	11/04/19 09:06	General View							Load JPG	☒	
32	11/04/19 09:06	General View							Load JPG		

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				☒
33	11/04/19 09:06	General View	Load JPG	☒
34	11/04/19 09:06	General View	Load JPG	☒
35	11/04/19 09:06	General View	Load JPG	☒
36	11/04/19 09:06	General View	Load JPG	☒
37	11/04/19 09:06	General View	Load JPG	☒
38	11/04/19 09:06	General View	Load JPG	☒
39	11/04/19 09:06	General View	Load JPG	☒
40	11/04/19 09:06	General View	Load JPG	☒
41	11/04/19 09:06	General View	Load JPG	☒
42	11/04/19 09:06	General View	Load JPG	☒
43	11/04/19 09:06	General View	Load JPG	☒
44	11/04/19 09:06	General View	Load JPG	☒
45	11/04/19 09:06	General View	Load JPG	☒
46	11/04/19 09:06	General View	Load JPG	☒
47	11/04/19 09:07	Reinspection Photo	Load JPG	☒
48	11/04/19 09:07	Reinspection Photo	Load JPG	☒
49	11/04/19 09:07	Reinspection Photo	Load JPG	☒
50	11/04/19 09:07	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	31/07/18 15:23	TP PRI Request - with estimate	Load PDF	
2	31/07/18 15:25	SHD90Z e-file report From: SC - Reg. No: SGR3850R, Claimant: MOH SWEE PING	Load PDF	
3	31/07/18 15:25	SJH881M e-file report From: SC - Reg. No: SGR3850R, Claimant: MOH SWEE PING	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18014017/KTD3E2

Date: 17/04/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29069232QMX

Claimant Vehicle No: SHD90Z

Insured Vehicle No: SGR3850R

Date of Loss: 27/07/2018

Nature of Claim: TP

Claim No: 565995

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD90Z

Make & Model: RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)

Engine No: M9R8839C003170

Reg. Date: 31/08/2016 (Man. Year: 2015)

Chassis No: VF1ABL15AUC283229

Colour: Metallic White/Red

Odometer: 175395 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Giti 9 mm

Rear Left Side: Giti 9 mm

Front Right Side: Giti 9 mm

Rear Right Side: Giti 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	103,451.13	26,016.02	77,435.11	74.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	24,220.00	5,210.00	19,010.00	78.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	127,671.13	31,226.02	96,445.11	75.54
Approved Total (Overridden) (S\$)		25,000.00		
(S\$)	127,671.13	25,000.00	102,671.13	80.42
+ GST 7.00/7.00% (S\$)	8,936.98	1,750.00	7,186.98	80.42
Nett Amount (S\$)	136,608.11	26,750.00	109,858.11	80.42

INSPECTION

Date of Assignment: 01/08/2018

Date Inspected: 02/08/2018 Inspected At:

Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 19.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Apr 2019)
Parts:	143	RENAULT LATITUDE 2.0 L DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD90Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Bent	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Bent / Distorted	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Cracked	113.47 FL	*113.47 FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Distorted	135.97 FL	*135.97 FL
8	1		*BUMPER RETAINER LH REAR	Cracked	44.99 FL	*44.99 FL
9	1		*BUMPER REFLECTOR LH	Broken	43.61 FL	*43.61 FL
10	1		*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Bent	225.95 FL	*225.95 FL
12	1		*BUMPER BEAM BRACKET RH REAR	Distorted	225.95 FL	*225.95 FL
13	1		*BOOT REAR	Bent	2,872.68 FL	*2,872.68 FL
14	1		*BOOT FINISHER	Serviceable	470.06 FL	*- FL
15	1		*BOOT WHEATHERSTRIP	Cut	323.05 FL	*323.05 FL
16	1		*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*- FL
17	1		*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*- FL
18	1		*BOOT BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
19	1		*BOOT BADGE	Necessary	225.36 FL	*225.36 FL
20	1		*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
21	1		*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
22	1		*BOOT HINGE LH	Repair	367.84 FL	*- FL
23	1		*BOOT HINGE RH	Repair	367.84 FL	*- FL
24	1		*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
25	1		*BOOT SWITCH	Serviceable	168.13 FL	*- FL
26	1		*BOOT LOCK	Repair	202.67 FL	*- FL
27	1		*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
28	2		*LICENCE PLATE LAMP	Serviceable	50.52 FL	*- FL
29	2		*BOOT RUBBER PLUG	Serviceable	221.81 FL	*- FL
30	1		*DOOR PANEL REAR LH	Repair	2,844.66 FL	*- FL
31	1		*FENDER PANEL INNER TRIM REAR LH	Serviceable	671.45 FL	*- FL
32	1		*FENDER PANEL REAR LH	Buckled	3,299.13 FL	*3,299.13 FL
33	1		*WHEELARCH REAR LH	Serviceable	543.47 FL	*- FL
34	1		*FENDER PANEL INNER TRIM REAR RH	Serviceable	671.45 FL	*- FL
35	1		*FENDER PANEL REAR RH	Repair	3,299.13 FL	*- FL
36	1		*WHEELARCH REAR RH	Serviceable	543.47 FL	*- FL
37	1		*TAILLAMP RH	Serviceable	552.55 FL	*- FL
38	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
39	1		*TAILLAMP LH	Mtg Cracked	552.55 FL	*552.55 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*TAILLAMP PANEL LH	Bent	986.70 FL	*986.70 FL
41	1		*OUTER PANEL REAR (END PANEL)	Bent	1,471.77 FL	*1,471.77 FL
42	1		*OUTER PANEL REAR (END PANEL) TRIM	Cracked	404.56 FL	*404.56 FL
43	1		*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Bent / Buckled	2,189.88 FL	*2,189.88 FL
44	1		*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*- FL
45	1		*EXHAUST REAR	Repair	7,489.05 FL	*- FL
46	1		*EXHAUST CAP REAR	Repair	230.49 FL	*- FL
47	1		*FUEL FLAP L70Y	Serviceable	343.57 FL	*- FL
48	1		*WHEEL HOUSING PANEL REAR LH	Repair	4,682.09 FL	*- FL
49	1		*CHASSIS PANEL REAR LH L70Y	Repair	3,766.43 FL	*- FL
50	1		*CHASSIS PANEL REAR RH L70Y	Repair	3,766.43 FL	*- FL
51	1		*BUMPER COVER FRT	Buckled	1,259.42 FL	*1,259.42 FL
52	1		*BUMPER SPOILER FRT	Distorted	181.75 FL	*181.75 FL
53	1		*BUMPER ABSORBER FRT	Cracked	394.68 FL	*394.68 FL
54	1		*BUMPER RETAINER FRT LH	Serviceable	151.41 FL	*- FL
55	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
56	1		*BUMPER RETAINER FRT RH	Serviceable	150.77 FL	*- FL
57	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
58	1		*BUMPER UNDERTRAY FRT	Cracked	472.83 FL	*472.83 FL
59	1		*BUMPER GRILLE LOWER FRT	Serviceable	266.80 FL	*- FL
60	1		*BUMPER FOG LAMP GRILLE LH	Serviceable	207.21 FL	*- FL
61	1		*BUMPER FOG LAMP GRILLE RH	Serviceable	207.21 FL	*- FL
62	1		*BUMPER BEAM FRT	Bent	914.08 FL	*914.08 FL
63	1		*TOW COVER FRT	Serviceable	28.61 FL	*- FL
64	1		*RADIATOR GRILLE	Cracked	1,707.78 FL	*1,707.78 FL
65	1		*RADIATOR GRILLE BADGE RENAULT	Dented	225.36 FL	*225.36 FL
66	1		*RADIATOR GRILLE FRAME	Cracked	1,353.75 FL	*1,353.75 FL
67	1		*FRAME FULL SUPPORT PANEL	Cracked	615.90 FL	*615.90 FL
68	1		*FRAME FULL SUPPORT BRACKET	Repair	89.79 FL	*- FL
69	1		*FRONT BRACE PANEL	Bent	177.22 FL	*177.22 FL
70	1		*HORN	Serviceable	314.17 FL	*- FL
71	1		*HORN BRACKET	Repair	40.45 FL	*- FL
72	1		*HEADLAMP LH	Mtg Cracked	1,184.43 FL	*1,184.43 FL
73	1		*HEADLAMP RH	Mtg Distorted	1,184.43 FL	*1,184.43 FL
74	1		*HEADLAMP PANEL FRT LH	Repair	152.15 FL	*- FL
75	1		*HEADLAMP PANEL FRT RH	Repair	152.15 FL	*- FL
76	1		*BONNET	Repair	1,941.63 FL	*- FL
77	1		*BONNET INSULATOR	Serviceable	405.73 FL	*- FL
78	1		*BONNET STRUT LH	Serviceable	88.61 FL	*- FL
79	1		*BONNET STRUT RH	Serviceable	88.61 FL	*- FL
80	1		*BONNET HINGE LH	Repair	348.31 FL	*- FL
81	1		*BONNET HINGE RH	Repair	348.31 FL	*- FL
82	1		*BONNET LOCK	Repair	305.48 FL	*- FL
83	1		*BONNET CABLE	Serviceable	119.19 FL	*- FL
84	1		*BONNET CABLE COVER	Serviceable	161.03 FL	*- FL
85	1		*BONNET SEAL OUTER	Serviceable	92.36 FL	*- FL
86	1		*BONNET SEAL INNER	Serviceable	157.28 FL	*- FL
87	1		*FENDER PANEL FRT LH	Repair	783.83 FL	*- FL
88	1		*WHEELARCH FRT LH	Serviceable	278.84 FL	*- FL
89	1		*FENDER BRACKET LOWER LH	Repair	15.79 FL	*- FL
90	1		*FENDER INSULATOR LH	Serviceable	130.84 FL	*- FL
91	1		*FENDER INSULATOR RH	Serviceable	130.84 FL	*- FL
92	1		*AIR CLEANER LOWER	Serviceable	271.26 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
93	1		*AIR CLEANER HOSE	Serviceable	76.16 FL	*- FL
94	1		*BASE BATTERY TRAY	Serviceable	363.40 FL	*- FL
95	1		*AIR CLEANER BOX	Serviceable	464.20 FL	*- FL
96	1		*TURBO DUCT	Serviceable	1,027.80 FL	*- FL
97	1		*A/C HEATER VALVE	Serviceable	484.50 FL	*- FL
98	1		*SUBFRAME OUTER FRT	Serviceable	2,652.45 FL	*- FL
99	1		*SUBFRAME BRACKET OUTER LH	Serviceable	92.36 FL	*- FL
100	1		*ENGINE UNDERTRAY	Serviceable	564.98 FL	*- FL
101	1		*A/C CONDENSER	Punctured	2,020.37 FL	*2,020.37 FL
102	1		*A/C CONDENSER GARNISH LH UPPER	Serviceable	39.67 FL	*- FL
103	1		*A/C CONDENSER GARNISH RH UPPER	Serviceable	39.67 FL	*- FL
104	1		*A/C CONDENSER GARNISH LH	Serviceable	58.81 FL	*- FL
105	1		*A/C CONDENSER GARNISH RH	Serviceable	59.60 FL	*- FL
106	1		*A/C PIPE CONDENSER TO COMPRESSOR	Serviceable	208.39 FL	*- FL
107	1		*A/C PIPE CONDENSER TO EXPENSION VALVE	Serviceable	658.72 FL	*- FL
108	1		*A/C PIPE COMPRESSOR	Serviceable	334.29 FL	*- FL
109	1		*A/C PIPE	Serviceable	658.72 FL	*- FL
110	1		*A/C COMPRESSOR	Serviceable	2,684.61 FL	*- FL
111	1		*AIR COOLER	Serviceable	792.60 FL	*- FL
112	1		*AIR INTERCOOLER HOSE (LONG)	Serviceable	1,014.13 FL	*- FL
113	1		*AIR INTERCOOLER HOSE (SHORT)	Serviceable	375.14 FL	*- FL
114	1		*TRANSMISSION COOLER	Serviceable	1,219.30 FL	*- FL
115	1		*TRANSMISSION COOLER PAD	Serviceable	17.96 FL	*- FL
116	1		*RADIATOR	Serviceable	1,202.20 FL	*- FL
117	2		*RADIATOR STUD UPPER	Serviceable	14.41 FL	*- FL
118	2		*RADIATOR BUSH UPPER	Serviceable	50.12 FL	*- FL
119	2		*RADIATOR MTG LOWER	Serviceable	55.85 FL	*- FL
120	1		*RADIATOR FAN COWLING	Serviceable	820.54 FL	*- FL
121	1		*RADIATOR FAN MOTOR LH	Serviceable	967.36 FL	*- FL
122	1		*RADIATOR FAN MOTOR RH	Serviceable	1,479.46 FL	*- FL
123	1		*RADIATOR TANK	Serviceable	324.62 FL	*- FL
124	1		*RADIATOR HOSE UPPER	Serviceable	240.56 FL	*- FL
125	1		*RADIATOR HOSE LOWER	Serviceable	491.18 FL	*- FL
126	1		*RADIATOR TANK HOSE	Serviceable	61.18 FL	*- FL
127	1		*AUTO COMPUTER	Serviceable	5,032.17 FL	*- FL
128	1		*INJECTION COMPUTER	Serviceable	4,706.30 FL	*- FL
129	1		*RHD HYDRAULIC POWER (ROCK&PINION)	Serviceable	5,154.52 FL	*- FL
130	1		*STEERING PUMP ELECTRIC L70Y	Serviceable	2,306.90 FL	*- FL
131	1		*STEERING PINION RACK L70Y	Serviceable	4,413.11 FL	*- FL
132	1		*SET PARKING AID	Shorted	700.00 FS	*600.00 FS
133	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
134	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
135	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
136	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
137	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
138	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
139	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
140	1		*SET BUMPER LOWER REAR CLIP	Not Necessary	66.00 FS	*- FS
141	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
142	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
143	1		*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
144	1		*BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS
145	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
146	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
147	1		*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*- FS
148	1		*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
149	1		*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
150	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*- FS
151	1		*TAILLAMP CLIP LH	Necessary	5.00 FS	*5.00 FS
152	2		*REAR WINDSCREEN SELANT	Necessary	80.00 FS	*40.00 FS
153	1		*WINDSCREEN MOULDING	Necessary	100.00 FS	*100.00 FS
154	1		*REAR WINDSCREEN INNER SPONGE SEAL	Necessary	100.00 FS	*30.00 FS
155	1		*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*- FS
156	1		*SPARE TYRE	Serviceable	330.00 FS	*- FS
157	1		*SET RADIATOR GRILLE FRAME CLIP	Necessary	52.00 FS	*52.00 FS
158	1		*SET BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
159	1		*BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	*- FS
160	1		*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	*- FS
161	1		*BUMPER BRACKET CLIP FRT RH	Not Necessary	12.00 FS	*- FS
162	1		*BUMPER SUPPORT CLIP FRT RH	Not Necessary	10.50 FS	*- FS
163	1		*TOW COVER FRT	Serviceable	14.50 FS	*- FS
164	1		*SET RADIATOR GRILLE SCREW	Not Necessary	16.00 FS	*- FS
165	1		*SET BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS
166	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
167	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS
168	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS
169	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
170	1		*SET FRONT LICENCE PLATE WITH HOLDER	Bent	80.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (S\$) 114,635.98 28,784.80
 - List Item Discount on L Items 10.00/10.00% (S\$) 11,184.85 2,768.78

Total Parts (S\$) 103,451.13 26,016.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	9,000.00	1,540.00
2	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	7,500.00	2,500.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	120.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE }	New	170.00	80.00
7	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE }	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST }	New	170.00	100.00
9	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST }	New	170.00	0.00
10	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	80.00
11	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
12	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	120.00
13	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
14	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
15	TOWING FEES	New	120.00	50.00
16	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT	New	380.00	0.00
17	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
18	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	0.00
19	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
20	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
21	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	40.00
22	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK }	New	380.00	250.00
23	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR }	New	380.00	0.00
24	TO LIFT-UP ENGINE WITH GEAR BOX AND REFIT	New	440.00	0.00
25	TO REMOVE AND RENEW POWER STEERING PUMP, OIL COOLER PIPE AND FINAL CHECKING AND TESTING	New	440.00	0.00
26	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET	New	480.00	0.00
27	TO DROP DIESEL TANK, PIPES, HOSES TO FACILITATE BODYWORK REPAIR, FINAL CHECKING AND TESTING	New	380.00	0.00

Report was unsubmitted during this print-out.

No	Particulars	Lab.Type	Repairer's	Amount
28	TO VACCUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER	New	380.00	100.00
29	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	50.00
30	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR INTERCOOLER	New	170.00	0.00
31	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (\$\$)			24,220.00	5,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >