7	ASS_REC.BY:		REF:	C8/AGU8		Special Instruction	Е
	From (Person):	Julie			AGIL	Date/Time:	01082018 511pm
	Estimated Cost			1	Bill to:		
	OD / WS			LINVIMVICS N 1155P		Insured:	SIB 2764L
	at Workshop m	/s	Pegus			Tel: 15K	7748
	Policy No:		4000	TION TECK NO.	Claim No:	(10001792	/AH
	Sum Insured:				Excess:	D.O.A.	S105700C
	(Client's Record) CA / REV / Date/Time:	REP. / R	EV 24 HRS AV 535pm Pr	() (P) erson Contacted:	082018 Alvin	H.O.D. Er Vehicle	dorsement:
	Date/Time	Action/Ins	struction (v) Estimate			
	NIII manada sanada	SIN III	35P - X			85	
		SIB J	164L - X				

Colon Colon	REF: MGL		72004
	77	SAGNMENT	
From. Estimated Cost	Date: 03081018	Veh No. SLN 115 Type M.Car / M.Cycle / Bus /	I Van / Lorry / Taxi / Prime Mover /
OD THIWS / TP RES / OD RI	ES / EVA / INV / MV	Truck / Trailer or	
To Inspect Vehicle No.	SLN 11559	Make Toyoth V	105 15E = 1496
at Workshop m/s	Pegasus	Colour GREY	A/C Insured / Std / NI / NA
74	Kran Teck Rd	Sp.Reading 88800	T/Radio: Insured / Std / NI / NA
nsured		Eng/No:	
Policy No.		C/No: M4F \$29	1F3302009826
Claims No.		Gen. Cond. Good / Pair Poo	or / Burnt
Sum Insured	Excess	Steering: Inorder/ Jammed /	/ Leaked / Burnt or
(Client's Record)		Brake: Norder / Jammed /	/ Leaked / Burnt or
Make of Veh		Modi: Nil / Rid / STD	
		Tyre Size: F:	195/50Ril
(Policy Condition)		R:	m
Remark: The veh had comme	nced its N/S O	BS/DUN/EXNOVA/GY/F	S / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of	inspection.	TOYO / YOKO or	was TUNKE
al, or Market Value:		Front	Rear
DAC Accident Rport:	Consistent?: Yes or No	R/Bal. 5 m	m R/Bal. 5 mm
SIA / PR Seen:	Consistent?: Yes or No	L/Bal. 5 m	im L/Bal. S min
Est Repairs: 4	days Res.: Yes or No	D.O.A. 20 07 18	02/08/18
Lum Sum:	% 3 Val. Yes or No	Survey held at	PEGASUS 1
CA / REV / REP. / 24	HRS		O/S / N/S / U/C / Rooftop or
	Vehicle: IN / 0	PART OF THE PART O	
Date: Person	Contacted.	The U/C / Chassis fram	ne / Body Structure affected due to collisio
	d P/P \$ 1,792 ,282.54 Red-	63 @ 4 days 75%)	with Resul.
R	ECEIVED 1 3 JUN 2	019	(1)67
Date/Time File Pass to 1	: Preli. Report : Final Report	Days Of Repair: Resurvey No. of Trip:	4 Survey Fee.
Date/Time File Return to?	. Final Report	meaniney not or mp.	Transportation
	Add	Fee: Site thap (\$	1 S+P5 Si
		To the second se	
	10	Interview. (\$) Fholis
Report Format :	8	Interview (\$ Tech invs (\$	250

Catherine Chong (LKK Auto)

From:

Julie Mangubat <julie.m@budgetdirect.com.sg>

Sent:

Wednesday, 1 August, 2018 5:11 PM

To:

SUR; 'assignments'

Cc:

Albert Hong

Subject:

FW: Third party survey - SLN1155P Your Insured: SJB2764L DOA: 20.07.2018 || Claim

ref: C10001792/AH

Attachments:

MSGR-MARS00000710-SLN1155P-GIA.PDF

Hi Team

Please accept TPPD survey and survey on a without prejudice basis.

TP workshop would like to request for Mohd Taufihk from LKK Auto Consultants Pte Ltd to survey their client's car.

Thank you,

-Julie

From: Pegasus Engineering <ar_claims@pegasusengrg.com.sg>

Sent: Tuesday, 31 July, 2018 5:35 PM
To: Claims <claims@budgetdirect.com.sg>

Subject: Third party survey - SLN1155P Your Insured: SJB2764L DOA: 20.07.2018

Your Ref: SJB2764L

Our Ref: SLN1155P

DOA: 20.07.2018

Without Prejudice

Dear All.

We refer to the above matter.

We enclose the following documents for your attention:-

- a. Copy of our client's SAS report and damaged photos;
- b. Copy of the estimated cost of repair. (sending soon)

Pursuant to paragraph 2.3 of Pre-Action Protocol for NIMA Cases, please let us have a list of 10 motor surveyors for our selection and

please let us know within 2 working days whether you would like to conduct a pre-repair survey of our client's vehicle. If we do not hear from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

In the event that you request for post repair inspection pursuant to paragraph 4.1 under the NIMA Protocol, you must compensate our client for the loss of use of his/her vehicle for the day that the inspection is conducted.

In addition, please confirm in writing whether you are agreeable to direct settle with us at 100% liability for this case.

Vehicle will be in our premises at 24/07/2018@11.00am, please arrange to survey our client's vehicle at 74 Kian Teck Road S628800.

Thank you

Regards,
Queenie Quay
Pegasus Engineering & Trading Pte Ltd
74 Kian Teck Road
Singapore
628800

Tel

6513 7748

Fax : 6251 3161

Email : ar claims@pegasusengrg.com.sg

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

Shirley Hiew (LKK Auto)

Cc: ar claims@pegasusengrg.com.sg

Subject: Fwd: Finalise For SLN1155P (DOA 20/07/2018)

From:	Vivian Tan <vivian.pegasusengrg@gmail.com> Wednesday, 12 June 2019 6:48 PM</vivian.pegasusengrg@gmail.com>
Sent:	Shirley Hiew (LKK Auto)
To:	Re: Finalise For SLN1155P (DOA 20/07/2018)
Subject:	Ne. Tillalise For Scivinssi (South Edigor)
Dear Shirley Hiew,	
We confirm final fig \$ 1,792 Thank you.	2.63 @ 4 days of repairs before GST.
Best Regards, Vivian Tan	
On Tue, 11 Jun 2019 at 12:0	5, Shirley Hiew (LKK Auto) < Shirley Hiew@lkkauto.com > wrote:
Dear Vivian,	
-	
Please re-confirm final fig \$	5 1,792.63 @ 4 days of repairs before GST.
112	
-	
Thank you.	
Best Regards,	
Shirley Hiew Case Handler	
LKK Auto Consultants Pte Ltd	
Phone: 6256-3561 email: Sur@lkk	auto.com fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi	Avenue 1, #02-25 S(408933)
2	
From: Vivian Tan [mailto:vivial Sent: Friday, 7 June 2019 8:50	an.pegasusengrg@gmail.com]
To: ShirleyHiew@lkkauto.com	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Company	
Owner ID: Vehicle Details	7200G	
Vehicle No.:	SLN1155P	
Vehicle to be Exported:	No	
Intended De-registration Date:	20 Jul 2018	
Vehicle Make:	TOYOTA	
Vehicle Model:	VIOS 1.5E CVT	
Primary Colour:	Silver	
Manufacturing Year:	2017	
Engine No.:	2NRX145383	
Chassis No.:	MHFB29F3302009826	
Maximum Power Output:	79.0 kW (105 bhp)	
Open Market Value:	\$12,946.00	
Original Registration Date:	24 Apr 2017	
First Registration Date:	24 Apr 2017	
Transfer Count:	0	
Actual ARF Paid: Intended PARF Rebate Details	\$7,946.00	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	23 Apr 2027	
PARF Rebate Amount: Intended COE Rebate Details	\$5,959.00	
COE Expiry Date:	23 Apr 2027	
COE Category:	A - Car up to 1600cc & 97kW (130bhp)	
COE Period(Years):	10	
QP Paid:	\$51,765.00	
COE Rebate Amount:	\$45,337.00	
Total Rebate Amount:	\$51,296.00	

The information contained herein is correct as at 20 Jul 2018

MBHH18093628 / Ajax Mars Pte Ltd - Bukit Merah ENTRY DATE & TIME: 20/07/2018 11:07 SUBMITTED BY: Ben Ng

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACC	200	IT C		-	- 1
ACC	DEN	41 O	нан	EWI	ENI

 Date Of Report
 20/07/2018 11:07

 Date Of Accident
 20/07/2018 07:40

Exact Location Of Accident AYE(TUAS) AROUND CLEMENTI AVE 2/CLEMENTI RD

Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLN1155P

Insured/Policyholder

Name Of Registered Owner GRAB RENTALS PTE LTD

Co Reg No 201617200G Email Address NOEMAIL

Mobile Phone No

Alternative Phone No OFFICE-66550005

Vehicle Particulars

Manufacturer TOYOTA

Model VIOS 1.5E CVT

Exact Purpose for which vehicle was being used at

time of accident

HIRE & REWARD

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE HIRE

Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy YES

Policy Number A29069766MKF

Cover Note Number

Driver

Name of Driver LIM HU CHARMANE

 NRIC No
 \$7016530I

 Date Of Birth
 18/05/1970

 Occupation
 OUTDOOR

 Date Of Driving Pass
 28/03/2001

Driving Experience 17 YEARS AND 3 MONTHS

Gender FEMALE

Mobile Number (LOCAL) +65-96650032

Fax Number

Contact Number

EMail Address NOEMAIL

Address

NA

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

2

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged? I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

2

Number of Passengers (Including Driver)

Passenger 1

NAME:

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I WAS DRIVING ALONG THE SAID LOCATION IN THE EXTREME RIGHT LANE. THE TRAFFIC WAS HEAVY AND THE ROAD WAS DAMP. THEREFORE, I HAD KEPT QUITE A DISTANCE BETWEEN THE VEHICLE IN FRONT FOR SAFETY REASONS. WHEN THE TRAFFIC AHEAD HAD CAME TO A STOP, I HAD ALSO MANAGE TO STOP ON TIME, SUDDENLY I FELT AN IMPACT FROM THE REAR OF MY VEHICLE. VEHICLE B HAD COLLIDED ONTO THE REAR PORTION OF MY VEHICLE NO INJURIES WERE INVOLVED AT THE TIME OF THE INCIDENT HOWEVER, MY PASSENGER WILL BE SEEING THE DOCTOR LATER ON DUE TO NECK PAIN.

Attachment(s)

Are accident photos available for attachment?

YES VES

Was there any video captured by Car Camera?

YES-RETRIEVING

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SJB2764L

Vehicle Make/Model/Colour

TOYOTA/ISIS 1.8LX A

Details Of Properties

Remarks/ Reasons:

Vehicle Category

PRIVATE CAR

Name of Driver

WOO KENG KHIEW

NRIC/Passport Number

S1177003G

Contact Number

96262922

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

PASSENGER 1

Approximate Age

Injuries Sustain

NECK PAIN

Injured person in which vehicle?

SLN1155P

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode



ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO: 201101753C

Quotation

From:

PEGASUS ENGINEERING & TRADING PTE LTD

74 KIAN TECK ROAD SINGAPORE 628800

Officer in Charge: QUAY SIEW TENG

Tel: Email: Customer:

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960

Tel:

Fax No.:

Quotation No.: QO18/08-1012	Quotation Date: 01/08/2018	Terms: 30 DAYS
Vehicle No. : SLN1155P	Chassis No.: MHFB29F3302009826	Third Party Insurer :
Model: VIOS	•	Date of Accident: 27/07/2018

ITEM	DESCRIPTION	Qty	UNIT PRICE AMOUNT (SGD)
1	REAR BUMPER	1	504.9000 № / 504.90
2	REAR BUMPER REFLECTORS	1	130.5000 × € m 130.50
3	REAR BUMPER SIDE RETAINERS	1	116.3000 🗡 116.30
4	REAR BUMOER SIDE HOLDERS	1	22.3000 🕰 🥏 22.30
5	REAR BUMPER YELLOW CLIPS	1	9.0000
6	REAR BUMPER REINFORCEMENT	1	323.0000 7. 323.00
7	REAR BUMPER CLIPS	1	4.3000/10 4.30
8	REAR BUMPER END SPLASHIELD COVER	1	89.8000 × m 89.80
9	LESS 25% (ITEM 1-8)	1	-300.0300 -300.03
10	REAR LICENSE PLATE	1	80.000 35 84 80.00
11	REAR BUMPER PARKING SENSOR	1	450.0000 7. 200-450.00 XM
12	TO REINSTALL OF REAR BUMPER PARKING SENSOR	1	120,000 60 120.00
13	TO RUST PROOFING OF THE AFFECTED AREAS	1	180.0000 ×19 180.00
14	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	1,600,0000 200 1,600.00
15	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	600 1,200,0000 2000 1,200.00

> LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Please conduct the survey at Pegasus Engineering @ 74 Kian Teck Road Singapore 628800 600 1,200,0000

Sub Total GST(7.00%) Total (SGD) 4.530.07 317.10 4,847.17

7075.17



ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO: 201101753C

Quotation

Customer:

GRAB RENTALS PTE LTD

18 SIN MING LANE

#01-08 MIDVIEW CITY SINGAPORE 573980

From:

PEGASUS ENGINEERING & TRADING PTE LTD

74 KIAN TECK ROAD SINGAPORE 628800

Officer in Charge: QUAY SIEW TENG

Tel: Email:

Tel: Fax No.:

Ouotation No. : QO18/08-1012	Quotation Date: 01/08/2018	Terms: 30 DAYS
vahlcle No. : SLN1155P	Chassis No.: MHFB29F3302009826	Third Party Insurer :
Model: VIOS		Date of Accident: 27/07/2018

ITEM	DESCRIPTION		Qty	UNIT PRICE	AMOUN	NT (SGD)
1	REAR BUMPER		1	504.9000	DE-	504.90
2	REAR BUMPER REFLECTORS		1	130.5000	X	130.50
3	REAR BUMPER SIDE RETAINERS		1	116.3000	×	116.30
4	REAR BUMOER SIDE HOLDERS	2	1	22,3000	m-	22.30
5	REAR BUMPER YELLOW CLIPS	W.	1	9.0000	ne-	9.00
6	BEAD DUMPED DEINFORGENENT	3-	1	323.0000	つれノ	323.00
7	REAR BUMPER CLIPS	0 /	1	4.3000		4.30
8	REAR BUMPER END SPLASHIELD COVER		1	89.8000	X	89.80
9	LESS 25% (ITEM 1-8)	1.0	1	-300.0300		-300.03
0	REAR LICENSE PLATE		1	80.0000	35 PH.	80.00
11	REAR BUMPER PARKING SENSOR		17	450.0000	7. 20	450.00
12	TO REINSTALL OF REAR BUMPER PARKING SENSOR		1/	120.0000	60	120.00
13	TO RUST PROOFING OF THE AFFECTED AREAS		17	180.0000	X	180.00
14	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECES PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME		1 11	1,600,0000	200	1,600.00
15	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	Bsu	1	1,200,0000	600	1,200.00
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and	# Soo	w)	12		
ease co	Acknowledged by Repairer Acknowledged by Repairer Signature: Signature: A A King Teck Read Singapore 628800	8/18/81	110	Sub Total GST(7.00%) Total (SGD)		4,530.07 317.10 4,847.17

Resy 6 4 paint To repair, Parel Beatery, enodough or Boothed & End pany - + # 450/= 250



ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO: 201101753C

Quotation

Customer:

Attn::

Tel:

GRAB RENTALS PTE LTD

18 SIN MING LANE

#01-08 MIDVIEW CITY

SINGAPORE 573960

From:

PEGASUS ENGINEERING & TRADING PTE LTD

74 KIAN TECK ROAD SINGAPORE 628800

Officer in Charge: QUAY SIEW TENG

Tel: Email:

Fax No.:

Quotation Date: 03/08/2018 Quotation No.: QO18/08-1038

Terms: 30 DAYS

ehicle No.: SLN1155P

Chassis No.: MHFB29F3302009826

Third Party Insurer: Date of Accident: 20/07/2018

Model: VIOS

Remarks: SUPPLEMENTARY ITEMS

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	REAR END PANEL & 22pm Report	1	694.7000	694.70
2	BOOTLID REPORT Report	1	1,662.4000	1,662.40
3	BOOTLID WEATHERSTRIP X MSVC	1	188.0000	188.00
4	REAR BUMPER REINFORCEMENT BRACE PANEL X no dans	fre 1		

P - # 788.63 N - # 1110.00 L - # 1110.00 PN - # 1923.63 P/1.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI18014029/R1sbn2

(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01

Date: 13-06-2019



	GAPORE SHOPPI 924	NG CENTRESINGAPORE	Date: 13-06-2019	11.111111111111111111111111111111111111
			Code: AGI	
1.		Policy Particul	ars :- THIRD PARTY CLA	JM
	Insured Veh.	SJB 2764L	Veh. Inspected	SLN 1155P
	Policy No.		Coverage (\$)	0.00
	Claim No.	C10001792/AH	Excess (\$)	0.00
	Assign From	JULIE	Assign Date	01/08/2018
2.		Vehicle P	articulars & Condition	
	Make & Model	TOYOTA VIOS 1.5E	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	MHFB29F3302009826	Colour	GREY
	Odometer	88800	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3.		Con	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	195/50 R16	WEST LAKE	5 mm
	L/H Front Tyre	195/50 R16	WEST LAKE	5 mm
	R/H Rear Tyre	195/50 R16	WEST LAKE	5 mm
	L/H Rear Tyre	195/50 R16	WEST LAKE	5 mm
1.		Descri	ption of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	REAR PORTION.	
	DAMAGES SEE D	ETAILS.		
5.		Gen	eral Information	
	Accident Date	20/07/2018	Inspection Date	02/08/2018
	Survey held at	74 KIAN TECK RD	•	
	Repairer	PEGASUS ENGINEERING 8	TRADING PTE LTD	
5a.			Remarks	
	A)THE INSPECTION	ON WAS CONDUCTED ON A" CE TO YOUR INSTRUCTIONS	WITHOUT PREJUDICE" BAS	SIS. SED REPAIRS
5b.			ate Days of Repair	ALL AIRO.
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	4 Working Day	/S



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 1155P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	504.90	504.90
1	REAR BUMPER REFLECTORS	NOT NECESSARY	130.50	
1	REAR BUMPER SIDE RETAINERS	NOT NECESSARY	116.30	
1	REAR BUMPER SIDE HOLDERS	NECESSARY	22.30	22.30
1	REAR BUMPER YELLOW CLIPS	NECESSARY	9.00	9.00
1	REAR BUMPER REINFORCEMENT	BENT	323.00	323.00
1	REAR BUMPER CLIPS	NECESSARY	4.30	4.30
1	REAR BUMPER END SPLASHIELD COVER	NOT NECESSARY	89.80	100
	LESS 25% DISCOUNT		-300.03	-215.87
			900.07	647.63
	SPECIAL NETT ITEMS			
1	REAR LICENSE PLATE (SN)	BENT	80.00	35.00
1	REAR BUMPER PARKING SENSOR (SN)	NOT NECESSARY	450.00	
1	REAR END PANEL (ADDITIONAL)(SN)	TO REPAIR SEE LABOUR	694.70	
1	BOOTLID (ADDITIONAL)(SN)	TO REPAIR SEE LABOUR	1,662.40	
1	REAR BUMPER REINFORCEMENT BRACE PANEL (NPA) (ADDITIONAL)(SN)	NO DAMAGED	-	
1	BOOTLID WEATHERSTRIP (ADDITIONAL)(SN)	SERVICEABLE	188.00	
			3,075.10	35.00
	LABOUR			
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.		120.00	60.00
	TO RUST PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	180.00	
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE O THE REPAIR OF REAR END PANEL AND BOOTLID.	F	1,600.00	450.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,200.00	600.00
	•		1.7	
	-		7.4	
	±0 1		1.5	
			3,100.00	1,110.00
	GRAND TOTAL		7,075.17	1,792.63

Report Ref No. CS/AGI18014029/R1sbn2



Page No.: 2 of 2

RECOMMENDED COST OF REPAIRS 1,792.63

Report Ref No. CS/AGI18014029/R1sbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.