

ASS. REC. BY:

REF:

CS/FCT18014181/R1vbn2

Special Instruction:

Survivor:

ASSIGNMENT (Office)

From (Person): CWS Lurena Jua

of FCI

Date/Time: 01082018 510 pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCL 2199Z

Insured:

SHA 9116R

at Workshop m/s

MONG

Tel:

6272 3892

9776 2311

of

Blk 1008 Bukit Merah Lane 3 #01-04

Ah Wei

Policy No:

Claim No:

D18005761MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

27072018

(Client's Record)

CA / REV / REP. / REV 24 HRS DS

02082018

H.O.D. Endorsement:

Date/Time: 01082018 539 pm

Person Contacted:

Nitha

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SCL 2199Z - X
	SHA 9116R - 08 / INCO9006868 / Yn
	DIA: 2708018
6/8/18	Email preli revised to FCI
7/9/18	@ 435pm Ah Wei will email finalised
13/9/18	LS \$ 7500 confirmed by email (Red 3034.50, 2990)

Pass

REF: TCI

1281F

COE XPIRY: Aug/2027


ASSIGNMENT

From: Date: 02082018
 Estimated Cost:
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle-No: SL 2199Z
 at Workshop m/s: MOVU
 of: BIK 1008 Bukit Merah Lane 3 #01-04
 Insured:
 Policy No:
 Claims No:
 Sum Insured: Excess:
 (Client's Record)
 Make of Veh:

62723892

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: days Res: Yes or No
 Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS '09'

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SL 2199Z Yr Regn: 2007 Jul
 Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: MERCEDES Benz SLK280 c.c. 2997
 Colour: BLUE A/C: Insured / Std / NI / NA
 Sp. Reading: 132828 T/Radio: Insured / Std / NI / NA

Eng/No: WDB1714542F161753
 C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 265/35R18
 R:

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm
L/Bal. 6 mm	L/Bal. 6 mm
D.O.A. 27/07/18	D.O.I. 02/08/18

Survey held at: MOVU (bm)

Des. of Damages: Frt / Rear / O/S / ☒ UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: Action / Instruction

Note: mv: \$ 85K (EST) LTA: \$ 46,094 NV: \$ 38,906

RECEIVED 14 SEP 2018

Date/Time, File Pass to? ☐ Preli. Report

☐ Final Report

Date/Time, File Return to?

149- typist

Report Format: CWS
 Lump Sum / I.B.I: \$ 7500/-

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Insp (\$)
☐ Weekend (\$)

Survey Fee

Transportation

\$ - R.C. - ST

Photo

Plan

TOTAL

170
50
50
86
356



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18005761MFSH
Our Ref: CS/FCI18014031/R1vb

Date :6/8/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SCL 2199Z


We thank you for your instruction on 1/8/2018

Please be informed that we had conducted the inspection of the above mentioned
2/8/2018 at the premises of M/s MOVA AUTOMOTIVE PTE LTD
and have the following to report:-

Workshop Estimate Amount	: S\$9,976.50
Revised Estimate Amount	: S\$8,473.50
"Check" Items Amount	: S\$351.00
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the
n/s body



Comments/Present Status:

Damages Consistent
Some of the parts pending for parts prices

Yours faithfully,

MOHAMMED RASUL
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	30-07-2018	Our Ref No. D18005761MFSH
Accident Date	27-07-2018	Claim Type. Third Party
Insured Vehicle	SHA9116R	Third Party Vehicle. SCL2199Z
Survey Location	BLOCK 1008 BUKIT MERAH LANE 3 #01-04/06/08	
Contact Person.	NITHA	
Contact No.	62723892/ 0	Fax No. 62708314
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MOVA AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 13 September 2018 4:32 PM
To: 'Tan Yoong Wei'; SUR
Subject: RE: FINALISE SCL2199Z

Dear Yoong Wei,

Noted with thanks.

Kindly send Final invoice and all supporting documents to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan Yoong Wei <tanyw@mova.com.sg>
Sent: Thursday, 13 September 2018 3:05 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: RE: FINALISE SCL2199Z

Ok we accept your offer \$7500 with 6 working days.

Best Regards,
Tan Yoong Wei
Estimator
Mova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

From: Veron Chen (LKKAUTO) [<mailto:veronchen@lkkauto.com>]
Sent: Thursday, 13 September 2018 11:40 AM
To: Tan Yoong Wei; Rasul (LKKAUTO)
Cc: SUR
Subject: RE: FINALISE SCL2199Z

Dear Yoong Wei,

WITHOUT PREJUDICE

Offer Lump Sum \$7500 @ 6 working days.

Labour remain at \$600.

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan Yoong Wei <tanyw@moval.com.sg>

Sent: Monday, 10 September 2018 4:57 PM

To: Rasul (LKKAuto) <Rasul@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: FINALISE SCL2199Z

Hi rasul,

Please advice whether we can finalise cost of repair \$7700 lumpsum with 6 working days ?

Thank you.

Best Regards,

Tan Yoong Wei

Estimator

Mova Automotive Pte Ltd

Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 6 August 2018 2:04 PM
To: 'Claim Workflow System'
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005761MFSH/1, SCL 2199Z
Attachments: SCL 2199Z PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SCL 2199Z
Date of survey: 2/8/2018
Number of days : 6 days

Some of the parts,pending for parts prices.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 1 August 2018 5:27 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005761MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 1 August 2018 5:10 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005761MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

1281F

Vehicle Details

Vehicle No.:

SCL2199Z

Vehicle to be Exported:

Yes

Intended De-registration Date:

28 Jul 2018

Vehicle Make:

MERCEDES BENZ

Vehicle Model:

SLK 280

Primary Colour:

Silver

Manufacturing Year:

2007

Engine No.:

27294230601760

Chassis No.:

WDB1714542F161753

Maximum Power Output:

170.0 kW (227 bhp)

Open Market Value:

\$56,019.00

Original Registration Date:

14 Aug 2007

First Registration Date:

14 Aug 2007

Transfer Count:

1

Actual ARF Paid:

\$61,621.00

Intended PARF Rebate Details

PARF Eligibility:

Forfeited

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

13 Aug 2027

COE Category:

B - Car (1601cc & above)

COE Period(Years):

10

PQP Paid:

\$50,972.00

COE Rebate Amount:

\$46,094.00

Total Rebate Amount:

\$46,094.00

The information contained herein is correct as at 28 Jul 2018

OK

85,000
46,094

38,906

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

31/07/2018

MS FIRST CAPITAL INSURANCE LIMITED
36 Robinson Road
#16-01 City House
Singapore 068877.

Page # :- 1

Veh # :- SCL2199Z

Veh Model :- MERCEDES BENZ

Estimate# :- CK417777

Claim # :-

ACC. Date :- 27/07/18

Terms :- C.O.D Days

Remarks :-

Attention :- XA026

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	FRONT FENDER LH	1	PC 945.00	945.00
2.	SIDE SKIRT LH	1	PC 915.00	915.00
3.	SIDE SKIRT CLIPS	15	PC 4.00	60.00
4.	FRONT DOOR LH	1	PC 3,665.00	3,665.00
5.	FRONT DOOR LOCK LH	1	PC 375.00	375.00
6.	FRONT DOOR CATCH LH	1	PC 305.00	305.00
7.	REAR WHEEL RIM LH 265/35/R18 (AMG)	1	PC 1,840.00	1,840.00
8.	FRONT DOOR STEP RUBBER LH	1	PC 290.00	290.00
9.	REAR WHEEL BEARING LH	1	PC 390.00	390.00
10.	FRONT WINDOW REGULATOR LH - CHECK	1	PC	
11.	FRONT POWER WINDOW MOTOR LH - CHECK	1	PC	
12.	FRONT DOOR WEATHERSTRIP LH - CHECK	1	PC	
13.	REAR WHEEL HUB LH - CHECK	1	PC	
14.	REAR ABSORBER LH - CHECK	1	PC	
15.	REAR ABSORBER MOUNTING LH - CHECK	1	PC	
16.	REAR LOWER ARM LH - CHECK	1	PC	
17.	REAR UPPER ARM LH - CHECK	1	PC	
18.	REAR BRAKE CALIBER LH - CHECK	1	PC	
19.	REAR DISC BRAKE LH - CHECK	1	PC	
20.	REAR AXLE SHAFT - CHECK	1	PC	
21.	REAR AXLE - CHECK	1	PC	
22.	REAR AXLE OIL - CHECK	1	PC	
23.	REAR FENDER LH - REPAIR	1	PC	

LIST TOTAL S\$

10% DISCOUNT S\$

8,785.00

-878.50

7,906.50

LABOUR :

TO REPAIR REAR FENDER LH & TO REALIGN
ACCIDENT AFFECTED AREAS. TO REMOVE & REPLACE
ALL ACCIDENT DAMAGED PARTS

TO SPRAY PAINT ON ACCIDENT DAMAGED PARTS

TO REMOVE FRONT DOOR LH MECHANISM, FRONT
POWER WINDOW & REGULATOR AND CHECK WIRING

TO CHECK REAR WHEEL ALIGNMENT

TO REMOVE REAR WHEEL RIM & CONDUCT BALANCING

TO RUST PROOF AFFECTED AREAS

LABOUR TOTAL S\$

600 950.00

700 850.00

60 80.00

60 80.00

50.00

60.00

2,070.00

Estimate

31/07/2018

MS FIRST CAPITAL INSURANCE LIMITED
36 Robinson Road
#16-01 City House
Singapore 068877.

Attention :- XA026

Page # :- 1 132188

Veh # :- SCL2199Z

Veh Model :- MERCEDES BENZ

Estimate# :- CK417777

Claim # :-

ACC. Date :- 27/07/18

Terms :- C.O.D Days

Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel : (65) 6272 3892
Fax : (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S	10,534.50
AMOUNT S\$	9,976.50
GST @ 7 %	698.36
AMOUNT DUE S\$	10,674.86

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068

6 days

4/8

02/08/18 @ 1245

Resy after repair

6/8/18

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1006,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

Tel: (65) 6272 3892
 Fax: (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

Estimate

31/07/2018

MS FIRST CAPITAL INSURANCE LIMITED
 36 Robinson Road
 #16-01 City House
 Singapore 068877.

Attention :- XA026

Page # :- 1

Veh # :- SCL2199Z

Veh Model :- MERCEDES BENZ

Estimate# :- CK417777

Claim # :-

ACC. Date :- 27/07/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	FRONT FENDER LH	1 PC	945.00	945.00
2.	SIDE SKIRT LH	1 PC	915.00	915.00
3.	SIDE SKIRT CLIPS	15 PC	4.00	60.00
4.	FRONT DOOR LH	1 PC	3,665.00	3,665.00
5.	FRONT DOOR LOCK LH	1 PC	375.00	375.00
6.	FRONT DOOR CATCH LH	1 PC	305.00	305.00
7.	REAR WHEEL RIM LH 265/35/R18 (AMG)	1 PC	1,840.00	1,840.00
8.	FRONT DOOR STEP RUBBER LH	1 PC	290.00	290.00
9.	REAR WHEEL BEARING LH	1 PC	390.00	390.00
10.	FRONT WINDOW REGULATOR LH - CHECK	1 PC		
11.	FRONT POWER WINDOW MOTOR LH - CHECK	1 PC		
12.	FRONT DOOR WEATHERSTRIP LH - CHECK	1 PC		
13.	REAR WHEEL HUB LH - CHECK	1 PC		
14.	REAR ABS ORDER LH - CHECK	1 PC		
15.	REAR ABS ORDER MOUNTING LH - CHECK	1 PC		
16.	REAR LOWER ARM LH - CHECK	1 PC		
17.	REAR UPPER ARM LH - CHECK	1 PC		
18.	REAR BRAKE CALIPER LH - CHECK	1 PC		
19.	REAR DISC BRAKE LH - CHECK	1 PC		
20.	REAR AXLE SHAFT - CHECK	1 PC		
21.	REAR AXLE CHECK	1 PC		
22.	REAR AXLE OIL - CHECK	1 PC		
23.	REAR FENDER LH - REPAIR	1 PC		
LIST TOTAL S\$				8,785.00
10% DISCOUNT S\$				-878.50
				7,906.50

LABOUR :

TO REPAIR REAR FENDER LH & TO REALIGN
 ACCIDENT AFFECTED AREAS. TO REMOVE & REPLACE
 ALL ACCIDENT DAMAGED PARTS

TO SPRAY PAINT ON ACCIDENT DAMAGED PARTS

TO REMOVE FRONT DOOR LH MECHANISM, FRONT
 POWER WINDOW & REGULATOR AND CHECK WIRING

TO CHECK REAR WHEEL ALIGNMENT

TO REMOVE REAR WHEEL RIM & CONDUCT BALANCING

TO RUST PROOF AFFECTED AREAS

LABOUR TOTAL S\$

Parts \$8725 - 10%
 \$ 7852.50

Labours \$1786

total 4/s \$ 7700 6 DAYS.

\$850
 600 950.00
 700 850.00
 60 80.00
 60 80.00
 50.00
 60.00
 2,070.00

Estimate

31/07/2018

MS FIRST CAPITAL INSURANCE LIMITED
36 Robinson Road
#16-01 City House
Singapore 068877.

Attention :- XA026

Page # :- 1 132188
Veh # :- SCL2199Z
Veh Model :- MERCEDES BENZ
Estimate# :- CK417777
Claim # :-
ACC. Date :- 27/07/18
Terms :- C.O.D Days
Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg
Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S	
AMOUNT S\$	9,976.50
GST @ 7 %	698.36
AMOUNT DUE S\$	10,674.86

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Farul
Hp 90010068

6 days
4/8
02/08/18 @ 1245

Resy after repair

Tyre Warehouse Pte. Ltd

BLK. 1002, Bukit Merah Lane 3
#01-89, Singapore 159719

Phone Number: 8828 7733 / 8866 7733 / 68163089
Fax Number:

Customer:	Date: 1/8/2018 12:05 PM
Company:	VIN
License NO: SCL 2199 Z	Technician:
Odometer:	Order NO:

VEHICLE ALIGNMENT REPORT

MERCEDES-BENZ, 171 SLK Steel Suspension / Standard, 04-09 (Customized)

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	—	10.48°	11.48°	—
		Right	—	10.48°	11.48°	—
	Camber	Left	-1.39°	-1.83°	-1.17°	-1.39°
		Right	-1.69°	-1.83°	-1.17°	-1.69°
	Toe	Left	0.39°	0.02°	0.19°	0.39°
		Right	-0.25°	0.02°	0.19°	-0.24°
Total		0.14°	0.03°	0.37°	0.15°	
Rear	Camber	Left	-2.00°	-1.74°	-1.02°	-2.00°
		Right	-1.41°	-1.74°	-1.02°	-1.41°
	Toe	Left	0.16°	0.22°	0.34°	0.15°
		Right	0.28°	0.22°	0.34°	0.28°
		Total	0.44°	0.43°	0.67°	0.43°
	Max Thrust Angle		0.06°	0.25°		0.06°
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		—	—	—	—
	Right		—	—	—	—
Included Angle	Left		—	—	—	—
	Right		—	—	—	—
Toe Out On Turns	Left		—	1.40°	2.40°	—
	Right		—	1.40°	2.40°	—
Max Turn Inside	Left		—	41.60°	41.60°	—
	Right		—	41.60°	41.60°	—
Toe Curve Change	Left		—	—	—	—
	Right		—	—	—	—
Setback	Front		-0.17"	—	—	-0.17"
	Rear		-0.25"	—	—	-0.25"
Track Width Diff.			-2.06"			-2.06"
Wheel Base Diff.			0.08"			0.08"
Front Ride Height	Left		—	0.04"	0.83"	—
	Right		—	0.04"	0.83"	—
Rear Ride Height	Left		—	0.28"	1.06"	—
	Right		—	0.28"	1.06"	—
Frame Angle						—

Tyre Warehouse Pte. Ltd

BLK. 1002, Bukit Merah Lane 3
#01-89, Singapore 159719

Phone Number: 8828 7733 / 8866 7733 / 68163089

Fax Number:

Customer:			Date: 7/8/2018 1:44 PM			
Company:			VIN			
License NO: SCL2199Z			Technician:			
Odometer:			Order NO:			
VEHICLE ALIGNMENT REPORT						
MERCEDES-BENZ, 171 SLK Europa Version / USA Version Normal, 04-05 (Customized)						
Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	—	10.48°	11.48°	—
		Right	—	10.48°	11.48°	—
	Camber	Left	-1.43°	-1.83°	-1.17°	-1.42°
		Right	-1.50°	-1.83°	-1.17°	-1.51°
	Toe	Left	0.23°	0.02°	0.19°	0.07°
		Right	-0.12°	0.02°	0.19°	0.07°
Total		0.11°	0.03°	0.37°	0.14°	
Rear	Camber	Left	-1.80°	-1.74°	-1.02°	-1.73°
		Right	-1.31°	-1.74°	-1.02°	-1.30°
	Toe	Left	0.08°	0.15°	0.40°	0.26°
		Right	0.24°	0.15°	0.40°	0.26°
		Total	0.32°	0.30°	0.80°	0.52°
	Max Thrust Angle		0.08°	0.25°		-0.00°
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left	—	—	—	—	—
	Right	—	—	—	—	—
Included Angle	Left	—	—	—	—	—
	Right	—	—	—	—	—
Toe Out On Turns	Left	—	1.40°	2.40°	—	—
	Right	—	1.40°	2.40°	—	—
Max Turn Inside	Left	—	—	—	—	—
	Right	—	—	—	—	—
Toe Curve Change	Left	—	—	—	—	—
	Right	—	—	—	—	—
Setback	Front	-0.18"	—	—	—	-0.18"
	Rear	-0.28"	—	—	—	-0.28"
Track Width Diff.			-2.04"			-2.04"
Wheel Base Diff.			0.10"			0.10"
Front Ride Height	Left	—	0.04"	0.83"	—	—
	Right	—	0.04"	0.83"	—	—
Rear Ride Height	Left	—	0.28"	1.06"	—	—
	Right	—	0.28"	1.06"	—	—
Frame Angle						—



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18014031/R1vbn2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 17-09-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 9116R	Veh. Inspected	SCL 2199Z
Policy No.		Coverage (\$)	0.00
Claim No.	D18005761MFSH	Excess (\$)	0.00
Assign From	LURENE	Assign Date	01/08/2018

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ SLK 280	c.c	2997
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	WDB1714542F161753	Colour	BLUE
Odometer	132828	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	265/35 R18	BRIDGESTONE	6 mm
L/H Front Tyre	265/35 R18	BRIDGESTONE	6 mm
R/H Rear Tyre	265/35 R18	BRIDGESTONE	6 mm
L/H Rear Tyre	265/35 R18	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	27/07/2018	Inspection Date	02/08/2018
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCL 2199Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FENDER LH	BENT	945.00	945.00
1	SIDE SKIRT LH	SCRATCHED	915.00	915.00
15	SIDE SKIRT CLIPS @\$4.00	NECESSARY	60.00	60.00
1	FRONT DOOR LH	BENT	3,665.00	3,665.00
1	FRONT DOOR LOCK LH	SERVICEABLE	375.00	-
1	FRONT DOOR CATCH LH	SERVICEABLE	305.00	-
1	REAR WHEEL RIM LH 265/35/R18 (AMG)	SCRATCHED	1,840.00	1,840.00
1	FRONT DOOR STEP RUBBER LH	CUT	290.00	290.00
1	REAR WHEEL BEARING LH	NECESSARY	390.00	390.00
1	FRONT WINDOW REGULATOR LH (NPA)	NOT NECESSARY	-	-
1	FRONT POWER WINDOW MOTOR LH (NPA)	NOT NECESSARY	-	-
1	FRONT DOOR WEATHERSTRIP LH (NPA)	NOT NECESSARY	-	-
1	REAR WHEEL HUB LH	BENT	330.00	330.00
1	REAR ABSORBER LH (NPA)	SERVICEABLE	-	-
1	REAR ABSORBER MOUNTING LH (NPA)	SERVICEABLE	-	-
1	REAR LOWER ARM LH	BENT	290.00	290.00
1	REAR UPPER ARM LH (NPA)	SERVICEABLE	-	-
1	REAR BRAKE CALIBER LH (NPA)	SERVICEABLE	-	-
1	REAR DISC BRAKE LH (NPA)	SERVICEABLE	-	-
1	REAR AXLE SHAFT (NPA)	SERVICEABLE	-	-
1	REAR AXLE (NPA)	SERVICEABLE	-	-
1	REAR AXLE OIL (NPA)	SERVICEABLE	-	-
1	REAR FENDER LH (NPA)	TO REPAIR SEE LABOUR	-	-
LESS 10% DISCOUNT			-940.50	-872.50
			8,464.50	7,852.50
LABOUR				
TO REPAIR REAR FENDER LH & TO REALIGN ACCIDENT AFFECTED AREAS. TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS.			950.00	600.00
TO SPRAY PAINT ON ACCIDENT DAMAGED PARTS.			850.00	700.00

Report Ref No. CS/FCI18014031/R1vbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE FRONT DOOR LH MECHANISM, FRONT POWER WINDOW & REGULATOR AND CHECK WIRING.		80.00	60.00
	TO CHECK REAR WHEEL ALIGNMENT.		80.00	60.00
	TO CHECK REAR WHEEL RIM & CONDUCT BALANCING.		50.00	50.00
	TO RUST PROOF AFFECTED AREAS.		60.00	60.00
			2,070.00	1,530.00
	GRAND TOTAL		10,534.50	9,382.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,500.00

Report Ref No. CS/FCI18014031/R1vbn2

MARKET VALUE: \$85,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$46,094.00=NETT VALUE: \$38,906.00

MOHAMMED RASUL BIN MOHD YUNUS
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.