

22/07/2018

ASS. REC. BY:

REF: CS/CTI18014044/Kqd3

Special Instructions:

Survivor:
Kenneth
Mehmen

ASSIGNMENT (Office)

From (Person):

Chang Ben Sun

of

CTI

Date/Time: 1/8/2018

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLF 5832J

Insured:

SGL 3641J

at Workshop m/s

Comfort Delano

Tel:

63837890/6383 7362

of

205 Brandeell Rd

Policy No:

DMPCSN 1660961701

Claim No:

SNM18D03687C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

28/07/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

5:45pm 1/8/18

Person Contacted:

Andrew

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

called No answer. (3x)

SLF 5832J - CS/CTI18002502/T1qd3e2

DUA: 4/2/2018

SGL 3641J - X

Kenneth Analyzed Final Fig \$5689.60. (Red \$3533.56, 38%)

ASS. REC. BY:

REF:

C721

31/8/2016

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or NoLum Sum: 1.13.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLI-5832J Yr Regn: 08, 16Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: 1 Honda Vezel c.c. 1.4 P8Colour: M. Black A/C: Insured / Std / NI / NASp. Reading: 173394 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RUI 1115163Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: Road Stone 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or DAVARI

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 9 mmL/Bal. 7 mm L/Bal. 9 mmD.O.A. 28/7/18 D.O.I. 2/8/18

Survey held at _____

Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

3/8 File pass to Catherine

RECEIVED 22 NOV 2018

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + R.S. \$

Fees

Others

TOTAL

220

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format:

Lump Sum / I.B.I. (\$)

MER-TP

5689.60




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18014044/Kqd3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 02-08-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGL 3641J	Veh. Inspected	SLF 5832J	
Policy No.	DMPCSN1660961701	Coverage (\$)	0.00	
Claim No.	SNM18D03687C02	Excess (\$)	0.00	
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	02/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/07/2018	Inspection Date	02/08/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 205 BRADDELL ROAD Blk C, 3rd Floor SINGAPORE 579701.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Aug 2018		01 Aug 2018 15:56 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	YUEN KI KIN, KENNETH, ID: S8414543B		
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Vehicle Reg. No.:	SLF5832J	Date of Loss:	28/07/2018 11:00 - :59
Claim Type:	TP / SNM18D03687C02	Policy/Cover Note No.:	DMPCSN1660961701 (Comprehensive)
Vehicle Reg. No. (Insured):	SGL3641J	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road, 579701 Toa Payoh - Tel: 63837168 /63837118		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/08/2018]		
Driver/Custodian (Insured):	YUEN KI KIN, KENNETH (34 / Male), NRIC: S8414543B		
Adj Asg. Remarks:	EST \$8993.64, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/07/2018 12:31
Date Of Accident	28/07/2018 11:55
Exact Location Of Accident	LOWER DELTA RD BESIDE JUNCTION BT PURMEI RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF5832J
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-87180969

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	
Cover Note Number	

Driver

Name of Driver	WEE NGIAP KIAN
NRIC No	S1735633Z
Date Of Birth	17/01/1966
Occupation	OUTDOOR
Date Of Driving Pass	22/11/1997
Driving Experience	20 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-89180969
Fax Number	
Contact Number	
Email Address	NGIAP147@HOTMAIL.COM

Address	BLK 96 LORONG 3 TOA PAYOH #15-42
Postcode	310096
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : PASSENGER 1 GENDER: : MALE
Passenger 2	NAME: : PASSENGER 2 GENDER: : MALE
Passenger 3	NAME: : PASSENGER 3 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGL3641J
Vehicle Make/Model/Colour	TOYOTA VIOS
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	YUEN KAI KIN
NRIC/Passport Number	S8414543B
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along middle lane of lower delta Road
 when approached approaching ST. Pirrama Road. between the yellow box
 front vehicle suddenly stopped I follow to stop
 suddenly vehicle SGL 36413 hit my car from
 behind my car move forward but didn't hit the front car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
 Date & Time:



Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Signature: [Signature]
 Date: 20/7/18

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

(Signature)

Driver's Signature
(If driver is not the policyholder)
Date & Time:

(Signature)

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



HOTLINE TEL: (65) 6419-3000
FAX: (65) 6415-3723

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1969

ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1969 (MALAYSIA)

M.Z.400

		(The below excess is subject to GST)	
COMPREHENSIVE COMMERCIAL MOTOR		ALL CLAIMS EXCESS	S\$2000.00
CERTIFICATE NO.	SLF5832J	WINDSCREEN EXCESS	S\$100.00
1) VEHICLE REGISTRATION NO.		SUM INSURED	Market Value
2) NAME OF INSURED		INSURING WITH COE/PARF	Yes
3) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT		SLF5832J	
4) DATE OF EXPIRY OF INSURANCE		LCRF Pte Ltd	
5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE*		25 February 2018	
		24 February 2019	
Any person who is driving on the Insured's order or with their permission.			
If You or Your Authorised Driver is below the age of 21 years old and/or has less than 1 year driving experience, the excess is S\$3,500(All Claims).			
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.			
6) LIMITATION AS TO USE*			
1) Use for social, domestic, pleasure purposes and business purposes of Insured			
2) Use for social, domestic, pleasure purposes and business purposes of any person whom the vehicle is hired.			
3) Use for the carriage of passengers for hire or reward by any person to whom the vehicle is hired.			
The Policy does not cover: 1) Use for tuition, driving test, racing, pace-making, reliability trial or speed-testing. 2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle. 3) Use for any purpose in connection with the Motor Trade.			
LOSS OF USE		Not Included	
HIRE PURCHASE COMPANY		Refer to Policy Terms and Conditions	

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued in Singapore 13 Feb 2018

AIG Asia Pacific Insurance Pte. Ltd.

030080-000
Aon Singapore Pte Ltd
2 Shenton Way
#26-01 SGX Centre 1
SINGAPORE 068804

Manila

AUTHORISED REPRESENTATIVE

SSPAHN

ORIGINAL

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1735633Z



WEE NGIAM KIAN

王業強

Race
CHINESE
Date of Birth
17-01-1966 Sex
M
Country of Birth
SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE

S1735633Z



WEE NGIAM KIAN

Birth Date: 17 Jan 1966
Issue Date: 16 Oct 2017



NRIC No: S1735633Z



Blood Group: B+ Date of issue: 26-08-1993

APT BLK 96 LORONG 3 TOA PAYOH #15-42
SINGAPORE 310096

NRIC No: S1735633Z

Date: 30/12/2011

No: 6905223

1223773 YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Vehicle Description	Effective Date
Class 3	Motor cars with unladen weight \leq 3000kg with \leq 7 passengers, exclusive of driver; and other motor vehicles with unladen weight \leq 2500kg	22 Nov 1997



NP 428A

Accident Photo



ACCIDENT REPAIR ESTIMATE

ACCIDENT REPAIR ESTIMATES/P3

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLF5832J Case Owner : WILLIAM

Make & Model : HONDA VEZEL 1.5X CVT Year Manufacture : 2016

Chassis No : RU11115163 Engine No : L15B4035169

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear number plate with casing	1	<i>Sm</i>			\$ 45.00	X
2	Rear number plate lamp LH	1	<i>Sm</i>	\$ 35.60			X
3	Rear number plate lamp RH	1	<i>Sm</i>	\$ 35.60			X
4	Rear bumper	1	<i>B</i>	\$ 762.70			✓
5	Rear bumper corner LH	1	<i>Sm</i>	\$ 195.00			X
6	Rear bumper corner RH	1	<i>Sm</i>	\$ 195.00			X
7	Rear bumper reflector LH	1		\$ 135.00			? X SVC
8	Rear bumper reflector RH	1	<i>Sm</i>	\$ 135.00			X
9	Rear bumper retainer LH	1	<i>Sm</i>	\$ 17.50			X
10	Rear bumper retainer RH	1	<i>Sm</i>	\$ 17.50			X
11	Rear bumper clips	8	<i>na</i>	\$ 31.20			✓
12	Taillamp LH	1	<i>Sm</i>	\$ 474.60			X
13	Taillamp RH	1	<i>Sm</i>	\$ 474.60			X
14	Tailgate	1	<i>B</i>	\$ 1,100.90			✓
15	Tailgate badge logo	1	<i>na</i>	\$ 27.10			X
16	Tailgate emblem - VEZEL	1	<i>na</i>	\$ 42.90	48.90		✓
17	Tailgate weatherstrip	1	<i>na</i>	\$ 96.80			✓
18	Tailgate lamp LH	1	<i>Sm</i>	\$ 424.40			X
19	Tailgate lamp RH	1	<i>Sm</i>	\$ 424.40			X
20	Tailgate upper lock	1		\$ 96.60			? XR
21	Tailgate outer garnish	1	<i>Sm</i>	\$ 189.60	315.70		X ✓
22	Tailgate inner lower trimboard	1		\$ 153.40			? X SVC
23	Rear windscreen glass moulding upper	1	<i>na</i>	\$ 38.50			
24	Rear windscreen glass moulding lower	1	<i>na</i>	\$ 38.50			
25	Rear windscreen glass moulding LH	1	<i>na</i>	\$ 35.60			
26	Rear windscreen glass moulding RH	1	<i>na</i>	\$ 35.60			
27	Rear windscreen sealant	1			<i>na</i> \$ 40.00		✓
28	Rear windscreen inner seal	1			<i>na</i> \$ 30.00		✓
29	Rear end panel	1		\$ 365.70	451.70		? ✓ BFA
30	Rear end panel inner garnish	1	<i>na</i>	\$ 98.30			✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLF5832J Case Owner : WILLIAM

Make & Model : HONDA VEZEL 1.5X CVT Year Manufacture : 2016

Chassis No : RU11115163 Engine No : L15B4035169

Sales Order : 0 Supplier : 0

Order By : 0 Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
31	Reverse sensor set	1			<i>sin</i>	\$ 280.00	<i>2005m</i>
32	Rear view camera (original)	1	<i>CRA</i>	\$ 1,020.70			✓
33	0	1					
34	0	1					
35	0	1					
36	0	1					
37	0	1					
38	0	1					
39	0	1					
40	0	1					
41	0	1					
42	0	1					
43	0	1					
44	0	1					
45	0	1					
46	0	1					
47	0	1					
48	0	1					
49	0	1					
50	0	1					
51	0	1					
52	0	1					
53	0	1					
54	0	1					
55	0	1					
56	0	1					
57	0	1					
58	0	1					
59	0	1					
60	0	1					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Supplementary

VEHICLE NO.: **SLF5832J**
 MAKE: HONDA
 MODEL: VEZEL 1.5X CVT
 YEAR OF MAKE: 2016
 CHASSIS NO.: RU11115163

#REF!

PAGE 1
 COST / LIST

S/N	Parts Description	PART NUMBER	Qty	Remarks	
				COST	LIST
1	Cargo tool tray ★		1	CM	286.90 ✓
2					
3					
4					
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					
24					
25					
26					
27					
28					
29					
30					

Spark Car Care
ComfortDelGro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLF5832J Case Owner : WILLIAM

Make & Model : HONDA VEZEL 1.5X CVT Year Manufacture : 2016

Chassis No : RU11115163 Engine No : L15B4035169

Sales Order : 0 Supplier : 0

Order By : 0 Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
31	Reverse sensor set	1			<i>pin</i>	\$ 280.00	<i>2005m</i>
32	Rear view camera (original)	1	<i>CRA</i>	\$ 1,020.70			<i>✓</i>
33	0	1					
34	0	1					
35	0	1					
36	0	1					
37	0	1					
38	0	1					
39	0	1					
40	0	1					
41	0	1					
42	0	1					
43	0	1					
44	0	1					
45	0	1					
46	0	1					
47	0	1					
48	0	1					
49	0	1					
50	0	1					
51	0	1					
52	0	1					
53	0	1					
54	0	1					
55	0	1					
56	0	1					
57	0	1					
58	0	1					
59	0	1					
60	0	1					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLF5832J Case Owner : WILLIAM

Make & Model : HONDA VEZEL 1.5X CVT Year Manufacture : 2016

Chassis No : RU11115163 Engine No : L15B4035169

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear number plate with casing	1	<i>Sm</i>			\$ 45.00	X
2	Rear number plate lamp LH	1	<i>Sm</i>	\$ 35.60			X
3	Rear number plate lamp RH	1	<i>Sm</i>	\$ 35.60			X
4	Rear bumper	1	<i>Bt</i>	\$ 762.70			✓
5	Rear bumper corner LH	1	<i>Sm</i>	\$ 195.00			X
6	Rear bumper corner RH	1	<i>Sm</i>	\$ 195.00			X
7	Rear bumper reflector LH	1	<i>Sm</i>	\$ 135.00			X
8	Rear bumper reflector RH	1	<i>Sm</i>	\$ 135.00			X
9	Rear bumper retainer LH	1	<i>Sm</i>	\$ 17.50			X
10	Rear bumper retainer RH	1	<i>Sm</i>	\$ 17.50			X
11	Rear bumper clips	8	<i>Sm</i>	\$ 31.20			✓
12	Taillamp LH	1	<i>Sm</i>	\$ 474.60			X
13	Taillamp RH	1	<i>Sm</i>	\$ 474.60			X
14	Tailgate	1	<i>Bt</i>	\$ 1,100.90			✓
15	Tailgate badge logo	1	<i>Sm</i>	\$ 27.10			X
16	Tailgate emblem - VEZEL	1	<i>Sm</i>	\$ 42.90	<i>48.90</i>		✓
17	Tailgate weatherstrip	1	<i>Sm</i>	\$ 96.80			✓
18	Tailgate lamp LH	1	<i>Sm</i>	\$ 424.40			X
19	Tailgate lamp RH	1	<i>Sm</i>	\$ 424.40			X
20	Tailgate upper lock	1	<i>R</i>	\$ 96.60			X
21	Tailgate outer garnish	<i>McM</i> 1	<i>Bt</i>	\$ 189.60	<i>315.70</i>		X
22	Tailgate inner lower trimboard	1	<i>Sm</i>	\$ 153.40			X
23	Rear windscreen glass moulding upper	1	<i>Mc</i>	\$ 38.50			✓
24	Rear windscreen glass moulding lower	1	<i>Mc</i>	\$ 38.50			✓
25	Rear windscreen glass moulding LH	1	<i>Mc</i>	\$ 35.60			✓
26	Rear windscreen glass moulding RH	1	<i>Mc</i>	\$ 35.60			✓
27	Rear windscreen sealant	1			<i>Mc</i> \$ 40.00		✓
28	Rear windscreen inner seal	1			<i>Mc</i> \$ 30.00		✓
29	Rear end panel	1	<i>Bt</i>	\$ 365.70	<i>451.70</i>		✓
30	Rear end panel inner garnish	1	<i>Mc</i>	\$ 98.30			✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Labour

Vehicle No. : **SLF5832J**

Case Owner : **WILLIAM**

Make & Model : **HONDA VEZEL 1.5X CVT**

Year of Manufacture : **2016**

S/No	Labour Description	Estimated Price	Adjusted Price
1	To remove/refit rear windscreen to facilitate repairs.	\$120.00	✓
2	To transfer tailgate parts and fittings to new tailgate.	\$120.00	801
3	To remove/refit boot compartment trims and garnish to facilitate repairs.	\$180.00	801 / 1901
4	Labour charges to repair and panel beat LH rear fender, RH rear fender, bootfloor/spare tyre panel, cutting/welding and replacing damaged parts. (PER DAY \$240)	\$960.00	720 / 2700
5	To replace reverse sensor set.	\$120.00	801
6	To check wiring functions.	\$40.00	201
7	To putty, apply primer & spray-paint the rear bumper, tailgate, rear end panel, taillamp panel LH, taillamp panel RH, bootfloor/spare panel and affected areas. (PER PANEL \$250)	\$1,500.00	7501
8	To apply rust-proofing on repaired/replaced panels.	\$200.00	601
To: Kenneth			1930
	Parts	4075.10	
	+ Suppl	286.90	
	=	4362.00	
	- 20%	872.40	
	=	3489.60	
	+ SN	270.00	
	+ Labour	2170.00	1930
	=	5929.60	
	15/10/18	5689.60	

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18014044/KQD3N2

Date: 26/11/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN1660961701	
Claimant Vehicle No :	SLF5832J	Insured Vehicle No :	SGL3641J	
Date of Loss:	28/07/2018	Nature of Claim:	TP	Claim No: SNM18D03687C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF5832J	Engine No:	HIDDEN
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU11115163
Reg. Date:	31/08/2016 (Man. Year: 2016)	Odometer:	173394 km
Colour:	Metallic Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Roadstone 7 mm	Rear Left Side:	Davanti 9 mm
Front Right Side:	Roadstone 7 mm	Rear Right Side:	Davanti 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,157.64	3,759.60	2,398.04	38.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,240.00	1,930.00	1,310.00	40.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	9,397.64	5,689.60	3,708.04	39.46
+ GST 7.00/7.00% (\$\$)	657.83	398.27	259.56	39.46
Nett Amount (\$\$)	10,055.47	6,087.87	3,967.60	39.46

INSPECTION

Date of Assignment:	01/08/2018	
Date Inspected:	02/08/2018	Inspected At: ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road Singapore 579701
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Nov 2018)
Parts: M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLF5832J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR NUMBER PLATE LAMP LH	Serviceable	35.60 FL	*- FL
2	1	*REAR NUMBER PLATE LAMP RH	Serviceable	35.60 FL	*- FL
3	1	*REAR BUMPER	Bent	762.70 FL	*762.70 FL
4	1	*REAR BUMPER CORNER LH	Serviceable	195.00 FL	*- FL
5	1	*REAR BUMPER CORNER RH	Serviceable	195.00 FL	*- FL
6	1	*REAR BUMPER REFLECTOR LH	Serviceable	135.00 FL	*- FL
7	1	*REAR BUMPER REFLECTOR RH	Serviceable	135.00 FL	*- FL
8	1	*REAR BUMPER RETAINER LH	Serviceable	17.50 FL	*- FL
9	1	*REAR BUMPER RETAINER RH	Serviceable	17.50 FL	*- FL
10	8	*REAR BUMPER CLIPS	Necessary	31.20 FL	*31.20 FL
11	1	*TAILLAMP LH	Serviceable	474.60 FL	*- FL
12	1	*TAILLAMP RH	Serviceable	474.60 FL	*- FL
13	1	*TAILGATE	Bent	1,100.90 FL	*1,100.90 FL
14	1	*TAILGATE BADGE LOGO	Not Necessary	27.10 FL	*- FL
15	1	*TAILGATE EMBLEM-VEZEL	Necessary	48.90 FL	*48.90 FL
16	1	*TAILGATE WEATHERSTRIP	Cut	96.80 FL	*96.80 FL
17	1	*TAILGATE LAMP LH	Serviceable	424.40 FL	*- FL
18	1	*TAILGATE LAMP RH	Serviceable	424.40 FL	*- FL
19	1	*TAILGATE UPPER LOCK	Repair	96.60 FL	*- FL
20	1	*TAILGATE OUTER GARNISH	Mtg Cracked	315.70 FL	*315.70 FL
21	1	*TAILGATE INNER LOWER TRIMBOARD	Serviceable	153.40 FL	*- FL
22	1	*REAR WINDSCREEN GLASS MOULDING UPPER	Necessary	38.50 FL	*38.50 FL
23	1	*REAR WINDSCREEN GLASS MOULDING LOWER	Necessary	38.50 FL	*38.50 FL
24	1	*REAR WINDSCREEN GLASS MOULDING LH	Necessary	35.60 FL	*35.60 FL
25	1	*REAR WINDSCREEN GLASS MOULDING RH	Necessary	35.60 FL	*35.60 FL
26	1	*REAR END PANEL	Bent	451.70 FL	*451.70 FL
27	1	*REAR END PANEL INNER GARNISH	Dented	98.30 FL	*98.30 FL
28	1	*REAR VIEW CAMERA (ORIGINAL)	Cracked	1,020.70 FL	*1,020.70 FL
29	1	*REAR NUMBER PLATE WITH CASING	Serviceable	45.00 FS	*- FS
30	1	*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
31	1	*REAR WINDSCREEN INNER SEAL	Necessary	30.00 FS	*30.00 FS
32	1	*SET REVERSE SENSOR	Scratched	280.00 FS	*200.00 FS
33	1	*CARGO TOOL TRAY	Cracked	286.90 FL	*286.90 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,598.30	4,632.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,440.66	872.40
Total Parts (\$\$)	6,157.64	3,759.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIRS	New	120.00	120.00
2	TO TRANSFER TAILGATE PARTS AND FITTINGS TO NEW TAILGATE	New	120.00	80.00
3	TO REMOVE/REFIT BOOT COMPARTMENT TRIMS AND GARNISH TO FACILITATE REPAIRS	New	180.00	100.00
4	LABOUR CHARGES TO REPAIR AND PANEL BEAT LH REAR FENDER,RH REAR FENDER,BOOTFLOOR/SPARE TYRE PANEL,CUTTING/WELDING AND REPLACING DAMAGED PARTS	New	960.00	720.00
5	TO REPLACE REVERSE SENSOR SET	New	120.00	80.00
6	TO CHECK WIRING FUNCTIONS	New	40.00	20.00
7	TO PUTTY,APPLY PRIMER & SPRAY-PAINT THE REAR BUMPER,TAILGATE,REAR END PANEL,TAILLAMP PANEL LH,TAILLAMP PANEL RH,BOOTFLOOR/SPARE PANEL AND AFFECTED AREAS	New	1,500.00	750.00
8	TO APPLY RUST-PROOFING ON REPAIRED/REPLACED PANELS	New	200.00	60.00
Gross Labour Cost (\$\$)			3,240.00	1,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >