

(08/11/13)

Surveyor:

Tanjun

REF:

INC NS/INC18014057/Tijber

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: GBB 9700U

Policy No. 5074913424-02 01.11.17

Claims No. MT/1004956-003

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHB382S Yr Regn: 2014, Sep

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c 1798

Colour: Maroon A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STDKN364405748503

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 27

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Achilles

Front C Rear C

R/Bal. mm R/Bal. mm

L/Bal. mm L/Bal. mm

D.O.A. 27/7/18 D.O.I. 30/7/18

Survey held at SHRT WL

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHB 382S - NS/INC15021336/15/11/1302
	GBB 9700U - X
17/10/18 @ 2:55pm	confirmed with Pol Sumn is \$5000, 4 days.
	CRP # 9096-60, 65%.
	RECEIVED 15 OCT 2018

Date/Time, File Pass to?

☐ : Preli. Report

1) 15/10/18

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$) S + RS SI☐ : Interview (\$) Photos☐ : Tech. Invs (\$) Others☐ : Weekend (\$)

Report Format: TP

Lump Sum / I.B.I. (\$) 5000

Survey Fee: 160

Transportation:

S + RS SI

Photos

Others

TOTAL

160



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18014057/T1qb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 02-08-2018

189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 9700U	Veh. Inspected	SHB 382S
Policy No.	5074913424-02	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	30/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	27/07/2018	Inspection Date	30/07/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

TP Claims against NTUC Income: Follow-Through Survey

Date : 15/10/2018

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate
1	MT/1004956-003	SMRT TAXIS PTE LTD	SHB 382S	GBB 9700U	27/07/2018	13:00	\$ 14,096.60
2	MT/1015044-002	COMFORT TRANSPORTATION PTE LTD	SH 6352C	SIP 6707C	09/10/2018	12:05	\$ 1,725.84

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="27/07/2018 13:42"/>
Vehicle No.(For Motor)	<input type="text" value="GBB9700U"/>	Certificate Number	<input type="text"/>

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5074913424-02		MEGA GAS ENTERPRISE PTE LTD	200205814Z	GFT	Comprehensive	GBB9700U	GBB9700U	01/11/2017	

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 12 October 2018 2:57 PM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Rasul (LKKAuto); Taufikh (LKKAuto); Naz (LKKAuto); Guo Qiang (LKKAuto)
Cc: SUR; CS A Team; Bryan Ang (LKKAuto)
Subject: RE: Pending for finalization

Dear Poh Suan,

WITHOUT PREJUDICE

SHB 382S – confirm Lump Sum \$5,000.00 and 4 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>

Sent: Wednesday, 10 October 2018 2:26 PM

To: Rasul (LKKAuto) <Rasul@lkkauto.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>; Naz (LKKAuto) <Naz@lkkauto.com>; Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>

Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Bryan Ang (LKKAuto) <bryanang@lkkauto.com>

Subject: Pending for finalization

Hi All,

Please finalize the below cases with me as soon as possible.

Thanks & Regards

Poh Suan

S/N	Acc Ref No	Vehicle No	Model	Job Completed	Estimated Amt (\$)	Surveyor	Insurance Company
1	TAX/04/18/2030	SHB5611Z	Prius4	01/08/18	\$55,257.34	Sebastian	AXA
2	TAX/07/18/2108	SHB1156Y	Prius4	26/07/18	\$2,991.64	Sathya	III
3	TAX/07/18/2131	SHB382S	Prius	02/08/18	\$9,350.00	Taufikh	NTUC
4	TAX/06/18/2099	SHC4870T	Prius4	25/07/18	\$5,621.62	Sathya	AIG
5	TAX/08/18/2076	SHB371Z	Prius	30/08/18	\$4,950.00	NAZ	SOMPO
6	TAX/07/18/2070	SHF272E	Prius4	21/07/18	\$1,225.90	Sathya	AIG
7	TAX/07/18/2124	SHB1426T	Prius	02/08/18	\$1,500.00	Guoqiang	AIG
8	TAX/08/18/2079	SHC4865J	Prius4	29/08/18	\$895.02	Naz	AIG
9	TAX/07/18/2133	SHB5332D	Prius	11/08/18	\$7,760.67	Taufikh	AIG
10	TAX/07/18/2165	SHC4382K	Prius4	11/08/18	\$1,950.00	Naz	AIG
11	TAX/08/18/2078	SHB5251D	Prius	03/09/18	\$6,515.51	NAZ	MSIG
12	TAX/08/18/2087	SHB1063G	Prius4	04/09/18	\$3,887.97	Taufikh	AIG
13	TAX/10/18/2007	SHB5253Z	Prius4	05/10/18	\$1,403.28	Naz	AIG

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHB382S
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR6085325
Chassis No.:	JTDKN36U405748503
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,920.00
Original Registration Date:	08 Sep 2014
First Registration Date:	08 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$8,088.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Sep 2022
PARF Rebate Amount:	\$6,066.00
Intended COE Rebate Details	
COE Expiry Date:	07 Sep 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,704.00
COE Rebate Amount:	\$24,691.00
Total Rebate Amount:	\$30,757.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 15 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/07/2018 15:10
Date Of Accident	27/07/2018 13:00
Exact Location Of Accident	CASHEW ROAD TOWARDS PETIR ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB382S
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	ABDUL JALEEL BIN KADER MYDIN
NRIC No	S6909383C
Date Of Birth	03/03/1969
Occupation	OUTDOOR
Date Of Driving Pass	01/07/2007
Driving Experience	11 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING STRAIGHT ALONG CASHEW ROAD TOWARDS PETIR ROAD. SUDDENLY A VEHICLE GBB9700U CAME OUT FROM THE CAR PARK ON MY LEFT, THIRD PARTY SUDDEN ACTION DID NOT GIVE ME AMPLE TIME TO REACT AND MY TAXI COLLIDED ONTO THE RIGHT PORTION OF THE VEHICLE.

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB9700U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	CHEN BO
NRIC/Passport Number	G8517852R
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LYD

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Date: 27/7/18
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Jehul 27/7/18
Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature] 27/7/2018
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB382S
 Ref. No : TAX/07/18/2131
 Reg. Date : 08/09/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : ABDUL JALEEL BIN KADER MYDIN
 Type of Accident : HEAD TO SIDE
 Date / Time of Accident : 27/07/2018 01:00:00 PM
 Accident Reported Date / Time : 27/07/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024097255
 Special Instruction to ARC, if any :
 TOWED \$40 / GBB9700U
 Prepared Date : 27/07/2018 03:51:15 PM



LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749

'wp'
30/7/18

Lumpsum

Resurvey after repair

sur@lkkauto.com

4 days

6/8/18

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U405748503

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 1,872.00	0.00
Total Material Charges	: 6,087.86	6,087.86
Other Charges	: 396.00	0.00
TOTAL	: 9,369.86	0.00
Lum Sum Total	: 9,350.00	0.00
No. of Repair Days	: 7.00	0.00
Prepared / Adjusted By	:	
Arc / Surveyor Sing Off Date	: 28/07/2018 01:43:49 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 28/07/2018 01:43:49 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	1,014.00	0.00
Total Labour	1,014.00	0.00 <i>Good Work</i>

300

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER LH	378.00	0.00 X
TO RESPRAY FRONT FENDER RH	378.00	0.00 X
TO REPSRAY FRONT HOOD	378.00	0.00 200
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0.00 100
TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00 X
Total Spray Painting & Panel Beating	1,872.00	0.00 500

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	56.00	0.00 /
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 X
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	396.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
53801-17050		6505557	FENDER FRT/RH ✕	1	723.40	25.00	542.55	Replace	Replace ✕ <i>nn</i>	No
75374-17051			NAME PLATE (HYBRID) ✕	1	51.90	25.00	38.92	Replace	Replace ✕ <i>nn</i>	No
53301-17060		6505555	HOOD PANEL	1	748.10	25.00	561.07	Replace	Replace <i>RP</i>	No
53410-17070			HOOD HINGE RH ✓	1	55.90	25.00	41.92	Replace	Replace ✕ <i>nn</i>	No
53420-17070			HOOD HINGE LH ✕	1	55.90	25.00	41.92	Replace	Replace <i>xnn</i>	No
52119-17930		6505517	BUMPER FRT ✓	1	482.00	25.00	361.50	Replace	Replace <i>de</i>	No
52161-6010			BUMPER CLIPS ✓	10	1.61	25.00	12.07	Replace	Replace <i>de</i>	No
52116-17040		6505516	BUMPER SUPPORT F/LH ✓	1	76.40	25.00	57.30	Replace	Replace <i>de</i>	No
52611-17080		6505518	BUMPER ENERGY ABSORBER FRT ✓	1	78.80	25.00	59.10	Replace	Replace <i>de</i>	No
52021-17023		6505539	BUMPER REINFORCEMENT FRT ✓	1	498.40	25.00	373.80	Replace	Replace <i>bt</i>	No
57014-7030			ARM SUB-ASSY, FR BUMPER LH ✓	1	250.40	25.00	187.80	Replace	Replace <i>bt</i>	No
57013-7030			ARM SUB-ASSY, FR BUMPER RH ✓	1	250.40	25.00	187.80	Replace	Replace <i>bt</i>	No
53294-7030		6505561	DEFLECTOR, RADIATOR LH ✕	1	77.00	25.00	57.75	Replace	Replace ✕ <i>nn</i>	No
52114-7140			BRACKET, FR BUMPER	1	110.40	25.00	82.80	Replace	Replace ✕ <i>nn</i>	No
			NUMBER PLATE ✓	1	15.00	0.00	15.00	Replace	Replace <i>bt</i>	No
			NUMBER PLATE FRAME ✓	1	12.00	0.00	12.00	Replace	Replace <i>de</i>	No
52128-7903			COVER, FR BUMPER HOLE LH ✓	1	18.50	25.00	13.87	Replace	Replace <i>mis</i>	No
53102-7020		6505541	BUMPER GRILLE SUB-ASSY, LOWER ✓	1	311.10	25.00	233.32	Replace	Replace <i>one</i>	No
52113-7180			WIRE, ENGINE ROOM, NO.3 ✕	1	242.00	10.00	217.80	Replace	Replace ✕ <i>nn</i>	No
52220-2230		6505438	FOG LAMP LH ✕	1	280.10	10.00	252.09	Replace	Replace ✕ <i>nn</i>	No
52121-7050			LENS & BODY, FR TURN LH ✓	1	511.80	10.00	460.62	Replace	Replace <i>one</i>	No
52129-7040			BRACKET, FR TURN UPPER LH ✓	1	24.40	25.00	18.30	Replace	Replace <i>dis</i>	No
52129-7060			BRACKET, FR TURN CENTER LH ✓	1	58.20	25.00	43.65	Replace	Replace <i>de</i>	No
52129-7050			BRACKET, FR TURN LOWER LH ✓	1	26.00	25.00	19.50	Replace	Replace <i>dis</i>	No
53101-7010		6505638	EMBLEM FRONT ✓	1	86.50	25.00	64.87	Replace	Replace <i>out</i>	No
53395-7020			HOOD END PANEL SEAL ✕	1	35.50	25.00	26.62	Replace	Replace ✕ <i>nn</i>	No
53289-7032			COVER, RADIATOR ✕	1	122.80	25.00	92.10	Replace	Replace ✕ <i>nn</i>	No
53111-7040		6505573	GRILLE, RADIATOR ✓	1	310.60	25.00	232.95	Replace	Replace <i>dis</i>	No
53113-7040			GRILLE RADIATOR LOWER NO.2 ✕	1	94.60	25.00	70.95	Replace	Replace ✕ <i>nn</i>	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	Recommendation	Approved	Attached
76851-47020		6505616	BUMPER LIP FRT ✓	1	139.60	25.00	104.70	Replace	Replace	No
52618-47050		6505540	BUMPER FRT ABSORBER LOWER ✓	1	127.70	25.00	95.77	Replace	Replace	No
51410-12105			UNDER COVER CENTER	1	448.30	25.00	336.22	Replace	Replace	No
53802-47050		6505558	FENDER FRT/LH ✓	1	723.40	25.00	542.55	Replace	Replace	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No
53876-47030		6505554	FENDER LINER FRT/LH ✓	1	171.70	25.00	128.77	Replace	Replace	No
53852-47020			FENDER LINER PAD, FR WHEEL. LH ✓	1	49.30	25.00	36.97	Replace	Replace	No
81170-47500		6505436	HEAD LAMP LH ✓	1	945.20	10.00	850.68	Replace	Replace	No
53201-47902			SUPPORT SUB-ASSY ✓	1	1,460.40	25.00	1,095.30	Replace	Replace	No
TOTAL MATERIALS								7,609.89	7,609.82	
TOTAL MATERIALS(Discounted)								6,087.86	6,087.86	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

14096.60

13968.90

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	TAX/07/18/2131	Date of Collection	31/7/18
Vehicle No	SHB 3825	Date of Request	2/8/18
Vehicle Model	TAX/07/18/2131	Number of Days to Extend	2 DAYS

REQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price
1	0457,58,59	Grille Radiator		
2	0451,52,53,54	Arm Sub Assy Frt Bumper LH		\$310.60 del ✓
3	0455,56	Arm Sub Assy Frt Bumper RH		\$250.40 ht ✓
4	0440,41,42	Bumper Frt Absorber, Lower		\$250.40 ht ✓
5	0446,47,48,49	Head Lamp RH		\$127.70 del ✓
6	50			\$945.20 ord ✓
7				
8				

I, (Name)

CHIA

<<<Please submit photographs for damaged parts>>>

add 1 day

(Position) ADVISOR

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

CHIA

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC / Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Service Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63655502
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 01/10/2018

User ID : PohSuan

	57014-47030	ARM SUB-ASSY, FR BUMPER LH	1.00	\$250.40	25.00	\$187.80	Replace	Replace	/
	57013-47030	ARM SUB-ASSY, FR BUMPER RH	1.00	\$250.40	25.00	\$187.80	Replace	Replace	/
	52114-47140	BRACKET, FR BUMPER	0.00	\$110.40	25.00	\$0.00	Replace	Check	X
	81529-47060	BRACKET, FR TURN CENTER LH	1.00	\$58.20	25.00	\$43.65	Replace	Replace	/
	81529-47050	BRACKET, FR TURN LOWER LH	1.00	\$26.00	25.00	\$19.50	Replace	Replace	/
	81529-47040	BRACKET, FR TURN UPPER LH	1.00	\$24.40	25.00	\$18.30	Replace	Replace	/
	52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.07	Replace	Replace	/
6505516	52611-47080	BUMPER ENERGY ABSORBER FRT	1.00	\$78.80	25.00	\$59.10	Replace	Replace	/
6505517	52119-47930	BUMPER FRT	1.00	\$462.00	25.00	\$361.50	Replace	Replace	/
6505540	52618-47050	BUMPER FRT ABSORBER LOWER	1.00	\$127.70	25.00	\$95.78	Replace	Replace	/
6505541	53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	1.00	\$311.10	25.00	\$233.32	Replace	Replace	/
6505616	76851-47020	BUMPER LIP FRT	0.00	\$139.60	25.00	\$0.00	Replace	Check	X
6505539	52021-47023	BUMPER REINFORCEMENT	1.00	\$498.40	25.00	\$373.80	Replace	Replace	/
6505516	52116-47040	BUMPER SUPPORT F/LH	1.00	\$76.40	25.00	\$57.30	Replace	Replace	/
	52128-47903	COVER, FR BUMPER HOLE LH	1.00	\$18.50	25.00	\$13.87	Replace	Replace	/
	53289-47032	COVER, RADIATOR	0.00	\$122.80	25.00	\$0.00	Replace	Check	X
6505561	53294-47030	DEFLECTOR, RADIATOR LH	0.00	\$77.00	25.00	\$0.00	Replace	Check	X
6505638	75310-47010	EMBLEM FRONT	1.00	\$86.50	25.00	\$64.87	Replace	Replace	/
6505558	53802-47050	FENDER FRT/LH	0.00	\$723.40	25.00	\$0.00	Replace	Not Given	X
6505557	53801-47050	FENDER FRT/RH	0.00	\$723.40	25.00	\$0.00	Replace	Not Given	X
6505554	53876-47030	FENDER LINER FRT/LH	1.00	\$171.70	25.00	\$128.77	Replace	Replace	/
	53852-47020	FENDER LINER PAD, FR WHEEL LH	0.00	\$49.30	25.00	\$0.00	Replace	Check	X
6505438	81220-12230	FOG LAMP LH	0.00	\$280.10	10.00	\$0.00	Replace	Check	X
	53113 - 47040	GRILLE RADIATOR LOWER NO.2	0.00	\$94.60	25.00	\$0.00	Replace	Check	X
6505573	53111-47040	GRILLE, RADIATOR	1.00	\$310.60	25.00	\$232.95	Replace	Replace	/
6505436	81170-47500	HEAD LAMP LH	1.00	\$945.20	10.00	\$850.68	Replace	Replace	/
6505437	81130-47500	HEAD LAMP RH	1.00	\$945.20	10.00	\$850.68	Replace	Replace	/
	53395-47020	HOOD END PANEL SEAL	0.00	\$35.50	25.00	\$0.00	Replace	Check	X
	53420-47070	HOOD HINGE LH	0.00	\$55.90	25.00	\$0.00	Replace	Not Given	X
	53410-47070	HOOD HINGE RH	0.00	\$55.90	25.00	\$0.00	Replace	Not Given	X
6505555	53301-47060	HOOD PANEL	1.00	\$748.10	100.00	\$0.00	Replace	Repair	/
	81521-47050	LENS & BODY, FR TURN LH	1.00	\$511.80	10.00	\$460.62	Replace	Replace	/
	75374-47051	NAME PLATE (HYBRID)	0.00	\$51.90	25.00	\$0.00	Replace	Not Given	X
	75374-47051	NAME PLATE (HYBRID)	0.00	\$51.90	25.00	\$0.00	Replace	Not Given	X
		NUMBER PLATE	1.00	\$15.00	0.00	\$15.00	Replace	Replace	/
		NUMBER PLATE FRAME	1.00	\$12.00	0.00	\$12.00	Replace	Replace	/
	53201-47902	SUPPORT SUB-ASSY	1.00	\$1,460.40	25.00	\$1,095.30	Replace	Replace	/
	51410-12105	UNDER COVER CENTER	0.00	\$448.30	25.00	\$0.00	Replace	Not Given	X
	82113-47180	WIRE, ENGINE ROOM, NO.3	0.00	\$242.00	10.00	\$0.00	Replace	Check	X
Total				\$10,672.41		\$5,374.66			

5374.66
+ 300.00
+ 550.00
6224.66
- 208
4919.73
L/s \$5000/-

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock	Part Name	Quantity	List Price \$	Discount (%)	Final Price	ARC Check	Surveyor Check
-------------	---------	-------	-----------	----------	---------------	--------------	-------------	-----------	----------------

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Service Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 01/10/2018


User ID : PohSuan

Section A - Accident Details	
Registration Number	SHB382S
Case Reference Number	TAX/07/18/2131
Registration Date	08/09/14
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	ABDUL JALEEL BIN KADER MYDIN
Type of Accident	HEAD TO SIDE
Accident Date and Time	27/07/18 1:00 PM
Accident Reported Date and Time	27/07/18 2:48 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	000024097255
Special Instruction to ARC, if any	TOWED \$40 / GBB9700U - NTUC - LKK Before paint photo and after paint photo, FOR CHECK ITEM and REPLACE ITEM. PLEASE CALL SURVEYOR TAUFIKH, HP 9749 5749/ EMAIL:
Prepared Date and Time	27/07/2018 3:51 PM
Chassis Number	JTDKN36U405748503
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$300.00
Total Spray Cost	\$1,872.00	\$500.00
Total Spare Part Cost	\$6,316.48	\$5,374.66
Total Other Cost	\$340.00	(\$1,174.66)
TOTAL COST	\$9,542.46	\$5,000.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	7.0	4
Prepared / Adjusted By	Taxi Estimator Team	TAUFIKH (LKK)
ARC / Surveyor Sign Off Date	28/07/2018 1:43 PM	30/07/2018 4:48 PM
Signature	M	LKK

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REPAIR LH FRONT PORTION			\$1,014.00				\$300.00		
Total Labour			\$1,014.00				\$300.00		
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
TO RESPRAY FRONT FENDER LH			\$378.00				\$0.00		
TO RESPRAY FRONT FENDER RH			\$378.00				\$0.00		
TO REPSRAY FRONT HOOD			\$378.00				\$200.00		
TO REPSRAY FRONT BUMPER			\$378.00				\$200.00		
TO RESPRAY FRONT BUMPER LOWER GRILLE			\$180.00				\$100.00		
TO RESPRAY FRONT SUPPORT PANEL			\$180.00				\$0.00		
Total Spray Painting & Panel Beating			\$1,872.00				\$500.00		
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
TO CHECK WIRING AND SYSTEM FUNCTION			\$80.00				\$30.00		
TO APPLY RUST-PROOFING ON AFFECTED AREA			\$100.00				\$0.00		
TO REPLACE SUNDRY PARTS			\$100.00				\$20.00		
TO WASH AND VACUUM			\$60.00				\$0.00		
Lump Sum Adjustment by Surveyor			\$0.00				(\$1,224.66)		
Total Other Costs			\$340.00				(\$1,174.66)		
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price	Estimator	Surveyor Approved






National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18014057/T1qbe2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 08-11-2018	
Code: INC4				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 9700U	Veh. Inspected	SHB 382S	
Policy No.	5074913424-02	Coverage (\$)	0.00	
Claim No.	MT/1004956-003	Excess (\$)	0.00	
Assign From		Assign Date	30/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JTDKN36U405748503	Colour	MAROON	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	ACHILLES	6 mm	
L/H Front Tyre	195/65 R15	ACHILLES	6 mm	
R/H Rear Tyre	195/65 R15	ACHILLES	6 mm	
L/H Rear Tyre	195/65 R15	ACHILLES	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/07/2018	Inspection Date	30/07/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 382S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BUMPER FRT (DISC 25%)	DEFORMED	482.00	361.50
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.07
1	BUMPER SUPPORT F/LH (DISC 25%)	DEFORMED	76.40	57.30
1	BUMPER ENERGY ABSORBER FRT (DISC 25%)	DEFORMED	78.80	59.10
1	BUMPER REINFORCEMENT FRT (DISC 25%)	BENT	498.40	373.80
1	ARM SUB-ASSY, FR BUMPER LH (DISC 25%)	BENT	250.40	187.80
1	ARM SUB-ASSY, FR BUMPER RH (DISC 25%)	BENT	250.40	187.80
1	COVER, FR BUMPER HOLE LH (DISC 25%)	MISSING	18.50	13.87
1	BUMPER GRILLE SUB-ASSY, LOWER (DISC 25%)	CRACKED	311.10	233.32
1	BRACKET, FR TURN UPPER LH (DISC 25%)	DISTORTED	24.40	18.30
1	BRACKET, FR TURN CENTER LH (DISC 25%)	DEFORMED	58.20	43.65
1	BRACKET, FR TURN LOWER LH (DISC 25%)	DISTORTED	26.00	19.50
1	EMBLEM FRONT (DISC 25%)	CUT	86.50	64.87
1	GRILLE, RADIATOR (DISC 25%)	DISTORTED	310.60	232.95
1	BUMPER FRT ABSORBER LOWER (DISC 25%)	DEFORMED	127.70	95.78
1	FENDER LINER FRT/LH (DISC 25%)	TORN	171.70	128.77
1	SUPPORT SUB-ASSY (DISC 25%)	BENT	1,460.40	1,095.30
1	LENS & BODY, FR TURN LH (DISC 10%)	CRACKED	511.80	460.62
1	HEAD LAMP LH (DISC 10%)	CUT	945.20	850.68
1	NUMBER PLATE (SN)	BENT	15.00	15.00
1	NUMBER PLATE FRAME (SN)	DEFORMED	12.00	12.00
1	HEAD LAMP RH (DISC 10%)	CRACKED	945.20	850.68
1	FENDER FRT / RH	NOT NECESSARY	723.40	-
1	NAME PLATE (HYBRID)	NOT NECESSARY	51.90	-
1	HOOD HINGE RH	NOT NECESSARY	55.90	-
1	HOOD HINGE LH	NOT NECESSARY	55.90	-
1	DEFLECTOR, RADIATOR LH	NOT NECESSARY	77.00	-
1	BRACKET, FR BUMPER	NOT NECESSARY	110.40	-
1	WIRE, ENGINE ROOM, NO.3	NOT NECESSARY	242.00	-
1	FOG LAMP LH	NOT NECESSARY	280.10	-

Report Ref No. NS/INC18014057/T1qbe2

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	HOOD END PANEL SEAL	NOT NECESSARY	35.50	-
1	COVER, RADIATOR	NOT NECESSARY	122.80	-
1	GRILLE RADIATOR LOWER NO.2	NOT NECESSARY	94.60	-
1	BUMPER LIP FRT	NOT NECESSARY	139.60	-
1	UNDER COVER CENTER	NOT NECESSARY	448.30	-
1	FENDER FRT / LH	NOT NECESSARY	723.40	-
1	NAME PLATE (HYBRID)	NOT NECESSARY	51.90	-
1	FENDER LINER PAD, FR WHEEL LH	NOT NECESSARY	49.30	-
1	HOOD PANEL	TO REPAIR SEE LABOUR	748.10	-
			10,686.90	5,374.66
	LABOUR			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF HOOD PANEL.		1,014.00	300.00
	SPRAY PAINT.		1,872.00	500.00
	TOWING CHARGE.		56.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	30.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.	NOT NECESSARY	100.00	-
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			3,282.00	850.00
GRAND TOTAL			13,968.90	6,224.66
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				5,000.00

Report Ref No. NS/INC18014057/T1qbe2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.