

INSURANCE

INS. CASE OWNER:

CC 6 /AIG1801

4060, [2] 1/18

LKK
IDAC

Surveyor:

Tan Fik

DOI:

ASSIGNMENT

1/8/18

Date / Time:

1/8/18

Registered in Merimen:

1/8/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLB 837TH

Name of Insured:

TAN FIAN PEMU

Insured Tel No.:

HP:

8771387

Excess See II :SS

D.O.A.:

26/7/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLN b18TH



INSRS:

WSP:

Tel:

Liability:

RMKS:

pegasus



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

6/8/18

TH

6/1/2020
Khorhwa

SLN b18TH-X

SLB 837TH-1

File pass to MK to close.

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call Of:

After call Itr to Of: /e-mail only

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to Of:

Authorisation To Act:

Release Voucher:

Final Repair Bill

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

R1P SS 2,914.40

(3 days) Reduction:

71 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : 27

If NO or B 28, Ass. Lia :

Repair Cost: (w/ GST)

SS 3,115.41

(01 READ END TP)

Loss of Rental (LOR):

SS 400

(4 days)

x \$ 100

Loss of Use (LOU):

SS -

(5 - 5 days)

Loss of Income (LOI):

SS -

(5 - 5 days)

LOR only

LOU only

LOR + LOU

LOR + LCI

[Tick only one]

GIA/LTA Search

SS 7.99

Medical:

SS -

1) Claim status: Normal/Reject/Private Settle

Disbursement:

SS -

(e.g. Tow/ Independent)

2) Report Format:

Legal Cost:

SS -

3) Survey fee:

\$320

Total:

SS 3,525.90

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 3,525.90

Name 1:

PEGASUS ENGINEERING & TRADING PTE LTD

Payee 2: (Strike if N.A.)

SS -

Name 2:

Payee 3: (Strike if N.A.)

SS -

Name 3:

COPY SENT
8/1/2020

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 91% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLN61854 Yr Regn: 2017 MayType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Magde 3 cc 1496Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 104605 T/Radio: Insured / Std / NI / NAEng/No: JMB5N22AS40/5/900

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: 25/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Triangle

Front: _____ Rear: _____

R/Bal. 0 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 1/8/18 @ 1640.Survey held at RegionsDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

C/P \$2,914.40 / Red \$6,996.40 / 71%

3 days + 1 Sunday = 4 days

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/AIG18014060/T1ub3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 02-08-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLB 8377H	Veh. Inspected	SLN 6185U
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	02/08/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer		Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	28/07/2018	Inspection Date	01/08/2018
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

PEGASUS
ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 538216 Officer in Charge : QUAY SIEW TENG Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573980 Attn : Tel : Fax No. :
---	--

Quotation No. : QO18/08-1004	Quotation Date : 01/08/2018	Terms : 30 DAYS
Vehicle No. : SLN6185U	Chassis No. : JM6BN22A1H0151800	Third Party Insurer :
Model : MAZDA 3	Date of Accident : 28/07/2018	
Remarks : THIRD PARTY INSURER: AIG, INSURED'S VEH NO: SLB8377, DOA: 28.07.2018		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER	1	1,075.0000	1,075.00
2	REAR BUMPER REINFORCEMENT	1	538.0000	538.00
3	REAR BUMPER REFLECTOR	2	51.0000	102.00
4	REAR BUMPER SIDE RETAINER	2	92.0000	184.00
5	REAR BUMPER SIDE HOLDER	2	74.0000	148.00
6	REAR BUMPER SIDE HOLDER RIVET	4	6.0000	24.00
7	REAR BUMPER TOW COVER	1	18.0000	18.00
8	REAR BUMPER CLIPS	10	5.0000	50.00
9	BOOTLID	1	958.0000	958.00
10	BOOTLID SKYACTIV BADGE	1	64.0000	64.00
11	BOOTLID REFLECTOR	2	530.0000	1,060.00
12	BOOTLID MAZDA 3 BADGE	1	54.0000	54.00
13	BOOTLID CENTRE LOGO BADGE	1	75.0000	75.00
14	BOOTLID RUBBER STOPPER	2	30.0000	60.00
15	BOOTLID INNER TRIM COVER	1	131.0000	131.00
16	BOOTLID INNER TRIM COVER CLIPS	8	40.0000	320.00
17	BOOTLID HINGE	2	298.0000	592.00
18	BOOTLID COVER CLIPS	5	30.0000	150.00
19	BOOTLID LOCKTOP	1	163.0000	163.00
20	BOOTLID LOCK STRIKER BOTTOM	1	38.0000	38.00
21	BOOTLID WEAHTERSTRIP	1	135.0000	135.00
22	BOOTLID KEYLESS SENSOR	1	89.0000	89.00
23	LESS 20% (ITEM 1-22)	1	-1,215.2000	-1,215.20

Revery
 on
 02/08/18
 Per

2193.00
 438.60
 1754.40

G/F 0.00

Page 1 of 2

PEGASUS
ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 539218 Officer in Charge : QUAY SIEW TENG Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573880 Attn : Tel : Fax No :
--	--

Quotation No. : QO18/08-1004	Quotation Date : 01/08/2018	Terms : 30 DAYS
Vehicle No. : SLN8185U	Chassis No. : JM6BN22A8HD151900	Third Party Insurer :
Model : MAZDA 3	Date of Accident : 28/07/2018	
Remarks : THIRD PARTY INSURER: AIG, INSURED'S VEH NO: SLB8377, DOA: 28.07.2018		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
24	REAR LICENSE PLATE			B/F 0.00
25	REAR BUMPER PARKING SENSOR	1	80.0000	X m 80.00
26	TO RUST-PROOFING OF THE AFFECTED AREAS	1	450.0000	200 m 450.00
27	TO TRANSFER OF BOOTLID FITTINGS, ATTACHEMENTS AND PERFORM WATER SEEPAGE TEST	1	250.0000	30 250.00
28	TO REINSTALL OF REAR BUMPER PARKING SENSOR	1	150.0000	X m 150.00
29	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	120.0000	30 120.00
30	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	1,800.0000	400 1,800.00
		1	2,200.0000	500 2,200.00

1160

s/parts — # 1,734.40
 Add. labor — # 1,160.00
 P/P — # 2,914.40

3 days

7/10 email to Vian

Tanjoh 12495749
 'wp'
 1/8/18 @ 1640
 Resing before part
 over 2 hours to 10am
 03 days

Tanji. 205/6/2018

Sub Total	9,910.80
GST(7.00%)	693.78
Total (SGD)	10,604.58

Please conduct the survey at
 Pegasus Engineering @ 74 Kian Teck Road Singapore 628800



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :	Customer :
PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 539216 Officer in Charge : QUAY SIEW TENG Tel : Email :	GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :

Quotation No. : QO18/08-1004	Quotation Date : 01/08/2018	Terms : 30 DAYS
Vehicle No. : SLN6185U	Chassis No. : JM6BN22A8H0151900	Third Party Insurer :
Model : MAZDA 3	Date of Accident : 28/07/2018	
Remarks : THIRD PARTY INSURER: AIG, INSURED'S VEH NO: SLB8377, DOA: 28.07.2018		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER	1	1,075.0000	de 1,075.00
2	REAR BUMPER REINFORCEMENT	1	538.0000	? 538.00
3	REAR BUMPER REFLECTOR	2	51.0000	x 102.00
4	REAR BUMPER SIDE RETAINER	2	92.0000	? 184.00
5	REAR BUMPER SIDE HOLDER	2	74.0000	x 148.00
6	REAR BUMPER SIDE HOLDER RIVET	4	6.0000	x 24.00
7	REAR BUMPER TOW COVER	1 x 14-x	18.0000	RM-AT 36.00 16
8	REAR BUMPER CLIPS	10	5.0000	net 50.00
9	BOOTLID	1	958.0000	Rx 958.00
10	BOOTLID SKYACTIV BADGE	1	64.0000	net 64.00
11	BOOTLID REFLECTOR	2	530.0000	x 1,060.00
12	BOOTLID MAZDA 3 BADGE	1	54.0000	net 54.00
13	BOOTLID CENTRE LOGO BADGE	1	75.0000	net 75.00
14	BOOTLID RUBBER STOPPER	2	30.0000	x 60.00
15	BOOTLID INNER TRIM COVER	1	131.0000	x 131.00
16	BOOTLID INNER TRIM COVER CLIPS	8	40.0000	x 320.00
17	BOOTLID HINGE	2	296.0000	x 592.00
18	BOOTLID COVER CLIPS	6	30.0000	x 180.00
19	BOOTLID LOCKTOP	1	163.0000	x 163.00
20	BOOTLID LOCK STRIKER BOTTOM	1	38.0000	x 38.00
21	BOOTLID WEAHTERSTRIP	1	135.0000	et 135.00
22	BOOTLID KEYLESS SENSOR	1	89.0000	x 89.00
23	LESS 20% (ITEM 1-22)	1	-1,215.2000	-1,215.20

C/F 0.00

PEGASUS **ENGINEERING & TRADING PTE LTD**

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 539216 Officer in Charge : QUAY SIEW TENG Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :
--	---

Quotation No. : QO18/08-1004	Quotation Date : 01/08/2018	Terms : 30 DAYS
Vehicle No. : SLN6185U	Chassis No. : JM6BN22A8H0151900	Third Party Insurer :
Model : MAZDA 3	Date of Accident : 28/07/2018	
Remarks : THIRD PARTY INSURER: AIG, INSURED'S VEH NO: SLB8377, DOA: 28.07.2018		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
24	REAR LICENSE PLATE	1	80.0000	X 80.00
25	REAR BUMPER PARKING SENSOR	1	450.0000	200 ^{new} 450.00
26	TO RUST-PROOFING OF THE AFFECTED AREAS	1	250.0000	30 250.00
27	TO TRANSFER OF BOOTLID FITTINGS, ATTACHEMENTS AND PERFORM WATER SEEPAGE TEST	1	150.0000	X 150.00
28	TO REINSTALL OF REAR BUMPER PARKING SENSOR	1	120.0000	30 120.00
29	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	1,800.0000	400 1,800.00
30	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	2,200.0000	300 2,200.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjin 17495749
 WP
 1/8/18 1640
 Resurvey before part
 sur @ lkkauto.com
 03 days
 Tanjin 205/6000

Sub Total	9,910.80
GST(7.00%)	693.76
Total (SGD)	10,604.56

Please conduct the survey at
 Pegasus Engineering @ 74 Kian Teck Road Singapore 628800

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	7200G

Vehicle Details

Vehicle No.:	SLN6185U
Vehicle to be Exported:	No
Intended De-registration Date:	01 Aug 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SEDAN 1.5 AT EU6
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	P520443384
Chassis No.:	JM6BN22A8H0151900
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$14,476.00
Original Registration Date:	11 May 2017
First Registration Date:	11 May 2017
Transfer Count:	0
Actual ARF Paid:	\$9,476.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 May 2027
PARF Rebate Amount:	\$7,107.00

Intended COE Rebate Details

COE Expiry Date:	10 May 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,000.00
COE Rebate Amount:	\$45,625.00
Total Rebate Amount:	\$52,732.00

The information contained herein is correct as at 01 Aug 2018

OK

SAVE AS TO COSTS

Dear Sir / Madam,

Thank you for your email.

For AIG cases, no original doc is required. Soft copy will do.

Hi Khanchna,

Kindly assist.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Pauline Ngu <pauline.pegasusengrg@gmail.com>

Sent: Monday, 25 November, 2019 9:51 AM

To: Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>

Cc: Pegasus Engineering <ar_claims@pegasusengrg.com.sg>; Lionel Chua <lionelchua@pegasusengrg.com.sg>; Soon Tat Ng <ngsoontat@vendaengrg.com.sg>; lohcl.pegasusengrg <lohcl.pegasusengrg@gmail.com>

Subject: LOD - Third party claim - Our ref: SLN6185U Your ref: SLB8377H on 28/07/2019

WITHOUT PREJUDICE

Dear Sir/Madam,

Refer to the above accident.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf.

Please inform us the officer in charge as well.

Kindly let me know if you need any hard copy for the LOD, if not we will be sending by email only. Kindly advise.

Thank You

Best Regards,

Pauline

Pegasus Engineering & Trading Pte Ltd

74 Kian Teck Road S628800

Office: 65137748

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Friday, 29 November 2019 9:48 AM
To: Pauline Ngu
Cc: Pegasus Engineering; Lionel Chua; Soon Tat Ng; lohcl.pegasusengrg; Admin A
Subject: RE: LOD - Third party claim - Our ref: SLN6185U Your ref: SLB8377H on 28/07/2018 ***
LKK REF: CC6/AIG18014060/T1kb3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows:

1. Cost of Repair (w/GST)	\$ 3,118.41
2. Loss of Rental/ Loss of Income (4 days x \$100)	\$ 400.00
3.LTA Search Fee	\$ 7.49
Total	\$ 3,525.90

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Monday, 25 November 2019 11:35 AM
To: Pauline Ngu <pauline.pegasusengrg@gmail.com>; Khanchna (LKK Auto) <khanchna@lkkauto.com>
Cc: Pegasus Engineering <ar_claims@pegasusengrg.com.sg>; Lionel Chua <lionelchua@pegasusengrg.com.sg>; Soon Tat Ng <ngsoontat@vendaengrg.com.sg>; lohcl.pegasusengrg <lohcl.pegasusengrg@gmail.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: LOD - Third party claim - Our ref: SLN6185U Your ref: SLB8377H on 28/07/2019 *** LKK REF: CC6/AIG18014060/T1kb3

'WITHOUT PREJUDICE'

Khanchna (LKK Auto)

From: Pauline Ngu <pauline.pegasusengrg@gmail.com>
Sent: Thursday, 26 December 2019 5:20 PM
To: Khanchna (LKK Auto)
Cc: Pegasus Engineering; Lionel Chua; Soon Tat Ng; lohcl.pegasusengrg; Admin A
Subject: Re: LOD - Third party claim - Our ref: SLN6185U Your ref: SLB8377H on 28/07/2018 ***
LKK REF: CC6/AIG18014060/T1kb3

Without Prejudice

Dear Khanchna,

We accepted your offer.
Kindly let us have your discharge voucher for completion.

The above email should not be construed as an admission of liability on the part of whomsoever is concerned

Have a nice day!

Many thanks.

Best Regards,

Pauline

Pegasus Engineering & Trading Pte Ltd

74 Kian Teck Road

Singapore 628800

Tel : 6513 7749

Fax : 6251 3161

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jul 2018 Edit Reg		01 Aug 2018 00:00 Edit Adj Rpt	S\$2,914.40 Edit Estimates	S\$2,914.40 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	TAN KIAM PENG , ID: 57045868C								
Main Claimant:	GRAB RENTALS PTE LTD , Co. Reg. No.: 201617200G								
Vehicle Reg. No.:	SLN6185U	Date of Loss:	28/07/2018 16:00 - :59 14 Months and 17 Days From LTA Reg Date (Man Yr)						
Claim Type:	TP / 7131804689SG	Policy/Cover Note No.:	2100461390 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLB8377H	Policy No. (Claimant):	A29069766MKF						
		Excess:							
Repairer:	Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10, 539216 Defu Lane - Tel: 68581846								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 14/08/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLN6185U (7131804689SG)
[SLB8377H]

TP

GRAB RENTALS PTE LTD

Jul 28 2018 4:00PM

[TAN KIAM PENG]

Pegasus Engineering & Trading Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
------------------	--	---------------	--	--------------------	--	--------------	--	--------------	--	--	--

Letters/Correspondences										1 per page v		☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print		
1	[Draft]	Third Party Express Settlement – Payment Breakdown								Edit		

Photos/Images										3 per page v		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print		
1	29/11/19 10:08	General View								Load JPG ☒		
2	29/11/19 10:08	General View								Load JPG ☒		
3	29/11/19 10:08	General View								Load JPG ☒		
4	29/11/19 10:08	General View								Load JPG ☒		
5	29/11/19 10:08	General View								Load JPG ☒		
6	29/11/19 10:08	General View								Load JPG ☒		
7	29/11/19 10:08	General View								Load JPG ☒		
8	29/11/19 10:08	General View								Load JPG ☒		
9	29/11/19 10:08	General View								Load JPG ☒		
10	29/11/19 10:08	General View								Load JPG ☒		
11	29/11/19 10:08	General View								Load JPG ☒		
12	29/11/19 10:08	General View								Load JPG ☒		
13	29/11/19 10:08	General View								Load JPG ☒		
14	29/11/19 10:08	General View								Load JPG ☒		
15	29/11/19 10:08	General View								Load JPG ☒		
16	29/11/19 10:08	General View								Load JPG ☒		
17	29/11/19 10:08	General View								Load JPG ☒		
18	29/11/19 10:08	General View								Load JPG ☒		
19	29/11/19 10:08	General View								Load JPG ☒		
20	29/11/19 10:08	General View								Load JPG ☒		
21	29/11/19 10:08	General View								Load JPG ☒		
22	29/11/19 10:08	General View								Load JPG ☒		
23	29/11/19 10:08	General View								Load JPG ☒		
24	29/11/19 10:08	General View								Load JPG ☒		
25	29/11/19 10:08	General View								Load JPG ☒		
26	29/11/19 10:08	General View								Load JPG ☒		
27	29/11/19 10:08	General View								Load JPG ☒		
28	29/11/19 10:09	Reinspection Photo								Load JPG ☒		
29	29/11/19 10:09	Reinspection Photo								Load JPG ☒		
30	29/11/19 10:09	Reinspection Photo								Load JPG ☒		
31	29/11/19 10:09	Reinspection Photo								Load JPG ☒		
32	29/11/19 10:09	Reinspection Photo								Load JPG ☒		
33	29/11/19 10:09	Reinspection Photo								Load JPG ☒		
34	29/11/19 10:09	Reinspection Photo								Load JPG ☒		
35	29/11/19 10:09	Reinspection Photo								Load JPG ☒		
36	29/11/19 10:09	Reinspection Photo								Load JPG ☒		

Documentation										1 per page v		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print		
1	03/08/18 09:06	TP ESTIMATE- MARKED								Load PDF		

Letters/Correspondences				1 per page	☒
No	Finalized On			Thumbnail	Print
LKK Auto Consultants Pte Ltd (HQ)					
2	03/08/18 09:06	TP GIA REPORT		Load PDF	
3	03/09/19 09:10	EMAIL TO OI		Load PDF	
4	10/01/20 08:59	WORKSHOP INVOICE		Load PDF	
5	10/01/20 08:59	AUTHORISATION TO ACT FORM		Load PDF	
6	10/01/20 08:59	Release Voucher		Load PDF	
7	10/01/20 08:59	RENTAL RATES		Load PDF	
8	10/01/20 08:59	LTA SEARCH		Load PDF	
9	10/01/20 08:59	LOD		Load PDF	
AIG Asia Pacific Insurance Pte. Ltd. (SG)					
No	Finalized On			Thumbnail	Print
1	03/08/18 10:18	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLB8377H (Insd veh)	Model:	MAZDA 3 1.5 (A)
	SLN6185U (TP veh)		
Date of Accident:	28/07/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	10,604.56
Final Repair Cost	:	\$	3,118.41
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	400.00 4 days
LTA / GIA Search Fee	:	\$	7.49
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	3,525.90

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability _____ 100 _____ (%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Pegasus Engineering & Trading Pte Ltd	:	\$ 3,525.90
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

10 Jan
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18014060/T1KA3Q2

Date: 10/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100461390
Claimant
Vehicle No : SLN6185U **Insured Vehicle No :** SLB8377H
Date of Loss: 28/07/2018 **Nature of Claim:** TP **Claim No:** 7131804689SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLN6185U**
 Make & Model: MAZDA 3, 1.5 (A) Engine No: P520443384
 Reg. Date: 11/05/2017 (Man. Year: 2017) Chassis No: JM6BN22A8H0151900
 Colour: Blue Odometer: 164605 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Triangle 6 mm Rear Left Side: Triangle 6 mm
 Front Right Side: Triangle 6 mm Rear Right Side: Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,390.80	1,954.40	3,436.40	63.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,520.00	960.00	3,560.00	78.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,910.80	2,914.40	6,996.40	70.59
+ GST 7.00/7.00% (S\$)	693.76	204.01	489.75	70.59
Nett Amount (S\$)	10,604.56	3,118.41	7,486.15	70.59
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		3,525.90		

INSPECTION

Date of Assignment: 01/08/2018
 Date Inspected: 01/08/2018 Inspected At: Pegasus Engineering & Trading Pte Ltd (HQ)
 51 DEFU LANE 10
 Singapore 539216
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,075.00 FL	*1,075.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	538.00 FL	*538.00 FL
3	2		*REAR BUMPER REFLECTOR	Not Necessary	102.00 FL	*- FL
4	2		*REAR BUMPER SIDE RETAINER	Bent	184.00 FL	*184.00 FL
5	2		*REAR BUMPER SIDE HOLDER	Not Necessary	148.00 FL	*- FL
6	4		*REAR BUMPER SIDE HOLDER RIVET	Not Necessary	24.00 FL	*- FL
7	1		*REAR BUMPER TOW COVER	N/S Not Necessary / O/S Cut	36.00 FL	*18.00 FL
8	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
9	1		*BOOTLID	Repair	958.00 FL	*- FL
10	1		*BOOTLID SKYACTIV BADGE	Necessary	64.00 FL	*64.00 FL
11	2		*BOOTLID REFLECTOR	Not Necessary	1,060.00 FL	*- FL
12	1		*BOOTLID MAZDA 3 BADGE	Necessary	54.00 FL	*54.00 FL
13	1		*BOOTLID CENTRE LOGO BADGE	Necessary	75.00 FL	*75.00 FL
14	2		*BOOTLID RUBBER STOPPER	Not Necessary	60.00 FL	*- FL
15	1		*BOOTLID INNER TRIM COVER	Not Necessary	131.00 FL	*- FL
16	8		*BOOTLID INNER TRIM COVER CLIPS	Not Necessary	320.00 FL	*- FL
17	2		*BOOTLID HINGE	Not Necessary	592.00 FL	*- FL
18	6		*BOOTLID COVER CLIPS	Not Necessary	180.00 FL	*- FL
19	1		*BOOTLID LOCKTOP	Not Necessary	163.00 FL	*- FL
20	1		*BOOTLID LOCK STRIKER BOTTOM	Not Necessary	38.00 FL	*- FL
21	1		*BOOTLID WEATHERSTRIP	Cut	135.00 FL	*135.00 FL
22	1		*BOOTLID KEYLESS SENSOR	Not Necessary	89.00 FL	*- FL
23	1		*REAR LICENSE PLATE	Not Necessary	80.00 FS	*- FS
24	1		*REAR BUMPER PARKING SENSOR	Not Working	450.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,606.00	2,393.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,215.20	438.60
Total Parts (\$\$)	5,390.80	1,954.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST -PROOFING OF THE AFFECTED AREAS	New	250.00	30.00
2	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	150.00	0.00
3	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	120.00	30.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,800.00	400.00
5	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,200.00	500.00
Gross Labour Cost (\$\$)			4,520.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >