

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE

INDIA

VEHICLE NO: SH 8141G

DATE : 31.07.2018

MAKE :

TEL NO : 6542 5119

MODEL : TOYOTA PRIUS

FAX NO : 6542 6039

LKK

	PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
	RADIATOR GRILLE <i>broken</i>			\$ 438.00	<i>✓</i>
	RADIATOR GRILLE EMBLEM <i>new</i>			\$ 88.00	<i>✓</i>
	LAMP ASSY, FOG, LH <i>broken</i>			\$ 920.00	<i>✓</i>
	FRONT BUMPER COVER <i>broken</i>			\$ 499.90	<i>✓</i>
	FRONT BUMPER REINFORCEMENT <i>Replaced</i>			\$ 696.40	<i>✓</i>
	FRONT BUMPER REINFORCEMENT ABSORBER <i>new</i>			\$ 115.70	<i>✗</i>
	FRONT BUMPER SPONGE <i>torn</i>			\$ 78.80	<i>✓</i>
	FRONT BUMPER CENTRE GRILLE <i>broken</i>			\$ 301.90	<i>✓</i>
	FRONT BUMPER SIDE RETAINER, LH <i>SVC</i>			\$ 77.00	<i>✗</i>
	ENGINE UNDER COVER (RR) <i>torn</i>			\$ 457.40	<i>✓</i>
	COVER, FRONT BUMPER HOLE, LH <i>new</i>			\$ 28.38	<i>✓</i>
	REINFORCEMENT SUB-ASSY, FRONT BUMPER LOWER <i>new</i>			\$ 236.10	<i>✓</i>
	SUPPORT FR BUMPER, LH <i>new</i>			\$ 81.70	<i>✗</i>
	FRONT BUMPER CENTRE FRAME <i>new</i>			\$ 236.90	<i>✗</i>
	BRACKET, FRONT BUMPER SIDE, LH <i>new</i>			\$ 82.30	<i>✗</i>
	ABSORBER, FRONT BUMPER, LOWER (SPONGE LOWER) <i>new</i>			\$ 127.70	<i>✗</i>
	UNIT ASSY, HEADLAMP, LH (LED) <i>broken</i>			\$ 3,455.00	<i>✓</i>
	HEAD LAMP PANEL (LH) <i>Replaced</i>			\$ 213.50	<i>✓</i>
	TOP PANEL SIDE <i>new</i>			\$ 69.20	<i>✓</i>
	BRACKET, HEADLAMP MOUNTING, LH <i>SVC</i>			\$ 25.50	<i>✗</i>
	RADIATOR ASSY <i>new</i>			\$ 1,841.80	<i>✗</i>
	RADIATOR FAN COWLING ASSY <i>new</i>			\$ 661.30	<i>✗</i>
	RADIATOR BOTTOM MOUNTING <i>new</i>			\$ 27.50	<i>✗</i>
	STAY, RADIATOR SUPPORT, LH <i>new</i>			\$ 65.70	<i>✗</i>
	RADIATOR FAN BLADE (LH) <i>new</i>			\$ 233.10	<i>✗</i>
	RADIATOR FAN MOTOR (LH) <i>new</i>			\$ 543.70	<i>✗</i>
	DEFLECTOR, RADIATOR SIDE, LH <i>new</i>			\$ 77.00	<i>✗</i>
	CONDENSER ASSY, W/RECEIVER <i>new</i>			\$ 1,336.60	<i>✓</i>
	FENDER SUB-ASSY, FRONT LH <i>Replaced</i>			\$ 945.30	<i>✓</i>
	FRONT HOUSING ASSY, LH <i>new</i>			\$ 958.30	<i>✗</i>
	FRONT FENDER SHIELD, LH <i>deformed</i>			\$ 196.60	<i>✓</i>
	FRONT FENDER SHIELD CLIP <i>new</i>			\$ 3.80	<i>✓</i>
	FRONT FENDER HYBRID EMBLEM, LH <i>new</i>			\$ 53.50	<i>✓</i>
	GUSSET, FRONT FENDER APRON, LOWER LH <i>new</i>			\$ 34.90	<i>✗</i>
	MEMBER, FRONT APRON TO COWL SIDE, UPPER LH <i>new</i>			\$ 138.40	<i>✗</i>
	MEMBER, FRONT APRON TO COWL SIDE, LOWER FRONT LH <i>new</i>			\$ 82.30	<i>✗</i>
	FRONT WHEEL RIM (LH) <i>distorted</i>			\$ 1,555.10	<i>✓</i>
	FRONT WHEEL HUB CAP (LH) <i>new</i>			\$ 177.70	<i>✓</i>
	FRONT WHEEL HUB BEARING (LHH) <i>new</i>			\$ 560.10	<i>✓</i>
	FRONT SHOCK ABSORBER (LH) <i>distorted</i>			\$ 401.80	<i>✓</i>
	ABSORBER TOP MOUNTING, LH <i>new</i>			\$ 196.20	<i>✗</i>
	ABSORBER TOP MOUNTING, RH <i>new</i>			\$ 196.20	<i>✗</i>
	FRONT SUSPENSION LOWER ARM (RH) <i>distorted</i>			\$ 637.50	<i>✓</i>
	FRONT DRIVE SHAFT (LH) <i>distorted</i>			\$ 1,186.20	<i>✓</i>
	RACK & PINION ASSY <i>distorted</i>			\$ 1,621.30	<i>✓</i>
	BAR, STABILIZER <i>distorted</i>			\$ 360.00	<i>✓</i>

SH 8141G

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.